



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4649C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP RH (N)	CRACKED	328.00	328.00
1	FRONT FENDER RH (N)	CRACKED	356.00	356.00
1	FRONT BUMPER SIDE HOLDER RH (N)	NECESSARY	45.00	45.00
1	FRONT DOOR WING MIRROR WITH FRAME RH (N)	BROKEN	485.00	485.00
1	FRONT DOOR WING MIRROR COVER RH (N)	MISSING	97.00	97.00
1	FRONT DOOR WING MIRROR GLASS RH (N)	MISSING	103.00	103.00
	LESS 10% DISCOUNT		-141.40	-141.40
			1,272.60	1,272.60
	<u>LABOUR</u>			
	TO DISMANTLE + RENEW ABOVE PARTS.		400.00	380.00
	TO SPRAY PAINT (INCLUDING FRONT BUMPER).		500.00	450.00
			900.00	830.00
	GRAND TOTAL		2,172.60	2,102.60
RECOMMENDED COST OF REPAIRS				2,102.60

Report Ref No. CS/GAI18001131/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.