

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III18001134/R1EA3Q2**Date:** 16/11/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKC6254Z	<b>Insured Vehicle No :</b>	SHB4402S
Date of Loss: 14/01/2018	Nature of Claim: TP	Claim No: MCT18010399

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKC6254Z</b>		
Make & Model:	HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A)	Engine No:	G4FGBU342899
Reg. Date:	15/09/2011 (Man. Year: 2011)	Chassis No:	KMHDH41CMCU285244
Colour:	Brown	Odometer:	183285 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,554.64	1,460.48	1,094.16	42.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,060.00	750.00	41.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,364.64</b>	<b>2,520.48</b>	<b>1,844.16</b>	<b>42.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,364.64</b>	<b>2,000.00</b>	<b>2,364.64</b>	<b>54.18</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	16/01/2018	
Date Inspected:	17/01/2018 Inspected At:	Boon Automobile Service (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-267 Singapore 569536
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKC6254Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	460.40 FL	*460.40 FL
2	2		*REAR BUMPER SIDE RETAINER (RH&LH)	Necessary	56.00 FL	*56.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Deformed	350.20 FL	*350.20 FL
4	2		*TAIL LAMP (LH&RH)	Not Necessary	700.20 FL	*- FL
5	1		*END PANEL	Repair	380.00 FL	*- FL
6	2		*REFLECTOR (RH&LH)	Cracked	84.00 FL	*84.00 FL
7	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
8	1		*REAR BODYKIT	Necessary	680.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,960.80</b>	<b>1,650.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	406.16	190.12
<b>Total Parts (\$)</b>	<b>2,554.64</b>	<b>1,460.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRING CHARGES ,TAIL LAMP & REVERSE SENSOR	New	80.00	60.00
2	TO MOUNT VEHICLE ON JIG/CELETTE BENCH IN ORDER TO RE-ALIGN CHASSIS MEMBERS CHARGES	New	350.00	0.00
3	TO KNOCK AND REPAIR END PANEL .TO INSTALL & DISMANTLE TAIL LAMPS ,BUMPER,RETAINERS ,REINFORCEMENT ,REFLECTORS ,BODYKIT STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPLACING OF ALL DAMAGED PARTS AND ALIGN SAME PANEL BEATING OTHER AFFECTED PARTS	New	680.00	450.00
4	TO PUTTY AND SPRAY PAINTING REAR BODY KIT ,END PANEL & REAR BUMPER AND ALL AFFECTED PART FROM THE ACCIDENT	New	700.00	550.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,810.00</b>
				<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >