


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB88H  
Ref. No : BUS/01/18/5019  
Reg. Date : 17/07/2009  
Vehicle Type : BUS -12M  
Make : MBOC500 (MERCEDES)  
Model : MERCEDES MBOC500  
Name of Driver : Prabu Kannappan  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 10/01/2018 08:18:00 PM  
Accident Reported Date / Time : 15/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : IDAC  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 01/01/2000  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024094174  
Special Instruction to ARC,if any :

SMB88H - rear right bumper cracked  
FW1364B - (TP) Insured with NTUC  
Before paint photo  
after paint photo.

Prepared Date : 16/01/2018 02:16:06 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,120.00	1,590.00
Total Spray Painting Charges :	860.00	760.00
Total Material Charges :	894.24	894.24
Other Charges :	0.00	-500.00
<b>TOTAL :</b>	<b>3,874.24</b>	<b>2,744.24</b>
<b>Lum Sum Total :</b>	<b>3,850.00</b>	<b>2,750.00</b>
No. of Repair Days :	4.00	3.00
Prepared / Adjusted By :		LKK GUO QIANG
Arc / Surveyor Sing Off Date :	22/01/2018 11:06:46 AM	23/01/2018 11:31:26 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/01/2018 05:53:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	2,120.00	1,590.00
<b>Total Labour</b>	<b>2,120.00</b>	<b>1,590.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	860.00	760.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>860.00</b>	<b>760.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	0.00	-500.00
<b>Total Other Costs</b>	<b>0.00</b>	<b>-500.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	VE	6008191	REAR REFLECTOR LIGHT L/H	0	5.14	10.00	0.00	Replace	Not given	No
	REAR	6009369	REAR BUMPER RH	1	1,242.00	10.00	1,117.80	Replace	Replace	No
5027		6010235	RH SKIRT PANEL R12	1	2,430.20	100.00	0.00	Replace	Repair	No
	REAR	6009365	PANEL, REAR: FIBREGLASS, FOR MB OC500 BUS	1	2,173.50	100.00	0.00	Replace	Repair	No
TOTAL MATERIALS							1,117.80	1,117.80		
TOTAL MATERIALS(Discounted)							894.24	894.24		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									