

Process

ASSIGN BY

REF: CS/CTI18001183/TI+d302

Special Treatment

Merimen

Taufik

ASSIGNMENT (Office)

From (Person)

Jowyn Tay

to

CTI

Date/Time

19/01/2018 @ 10:59am

Estimated Cost

Bill to

OD

CF / WS / IP RES / OD RES / EV / INV / MV / CS

To Inspect Vehicle No.

SLQ 800B

Insured

to Workshop no.

SMRT

Tel

6866 2628 / 6555 5556

at

60 woodlands Ind. Park C4

Policy No.

DMPCSN3097231701

Claim No.

SNM18D00335C01

Sum Insured

Excess

\$1250.00

Make of Veh.

(Client's Record)

DOA 16/01/2018

CA

REV

REP. / REV 24 HRS

Ref. to Insurance

Date/Time

12:43pm @ 19/1/18

Person Connected

Esther

Veh.

IN/OUT

Date/Time

Assessment

✓

Ref.

SLQ 800B-X

27/1/18 @ 1.44pm went to Jowyn Tay via Merimen.

27/1/18 @ 4.40pm Susan Teo informed C/A at \$11800 via Merimen.

27/1/18 @ 4.57pm informed Esther C/A on US basis & ETS \$1250 by email.

lump sum \$6300 (Red: 10,102.40 (61%))

Taufik

CTI

SL 8800B

2009/Dec

Estimated Cost

OD/WS/TP/RES/OD/RES/EVA/INVA/MV

Insured Vehicle No

Insured Vehicle No

Insured

Insured

Policy No

Damage No

Sum Insured

Excess

91250

Claims Record

Name of Insured

Policy Condition

Remarks: The veh had commenced its repair at the time of inspection.

☒	
NS	OS

Salvage/Market Value

935K

CAD Accident Report

Consistent? Yes or No

GA - PP Seen

Consistent? Yes or No

Est. Repairs

days

Real? Yes or No

Est. Sum

Rs

3 year? Yes or No

CA REP. 24 HRS

WP

Date

Person Contacted

Vehicle IN/OUT

Date/Time

Action/Inspection

Name

Mercedes Benz S180

1699

Color

Silver

St. Register

57452

Engine

CNO

WDD24523225534994

Gen. Cond. Good Fair Poor Burnt

Breeding Inorder Jammed/Leaked Burnt or

Breake Inorder Jammed/Leaked Burnt or

Mod. No. 69- STD A/R 17

Type Size

R

215/45R17

BS DUN EXNOVA GY FS LIZA MID/OHTSU PR. SUMI

TOYO/YOKO or

Continental

Front

Rear

R.Bal

6

R.Bal

6

L.Bal

6

L.Bal

6

C.O.A.

C.O.

Survey needed

Des. of Damages Front Rear OS NS UD Roof/hood

The U.O. Chassis/frame Body Structure affected due to accident

RECEIVED 7 MAR 2010

Time Re-Insured

1/3 Typist

☐

Prel. Report

Final Report

Days Of Repair

8

Resurvey No. of Time

1

Time Fee

220

Add Fee:

☐

Insured

☐

Insured

☐

Insured

☐

Insured

Report Form

OD

Time

5

6300/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018 Sendback Est	19 Jan 2018 10:24 S\$16,402.40	19 Jan 2018 10:59 Assign			New Assignment Cancel Case

Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			
Insured: WONG BOON HWEE DAVIN, ID: S7522299H			
Vehicle Reg. No.:	SLQ800B	Date of Loss:	16/01/2018 17:00 - :59
Claim Type:	OD / SNM18D00335C01	Policy/Cover Note No.:	DMPCSN3097231701 (Comprehensive) Coverage: 17/12/2017 - 16/12/2018
		Excess:	S\$1,250.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2018]		
Driver/Custodian:	HO LI YAN, JENNY (/ Female), NRIC: S8236827B		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$1,250.00 APPLIES.		
ASSOCIATED MAIL RECEIVED			
There is no mail for this case.		View All	Compose Case Mail
ALL ASSOCIATED TASKS			
		View All	Search Tasks Create New Task Complete
No results.			

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 22 January 2018 4:51 PM
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Cc: SUR
Subject: VEHICLE SLQ 800B (DOA: 16/01/2018)

Dear Esther,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 800B on Lump Sum basis (excess \$1,250/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Jan 2018 10:16	Clim Veh Model Changed	(201109) MERCEDES-BENZ B170 1.7 (A).	[R] Tey Chor Keng
2	19 Jan 2018 10:16	Clim Created	Reg No: SLQ800B. Policy No: DMPCSN3097231701. Acct Date: 2018/01/16. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: SMRT Automotive Services Pte Ltd (Woodlands)	[R] Tey Chor Keng
3	19 Jan 2018 10:24	Clim Submitted	16402.40.	[R] Tey Chor Keng
4	19 Jan 2018 10:57	Clim Registration Modified	Excess: -> 1250.00.	[I] Jowyn Tay
5	19 Jan 2018 10:59	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$1,250.00 APPLIES.	[I] Jowyn Tay
6	19 Jan 2018 10:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/30	[I] Jowyn Tay
7	19 Jan 2018 10:59	Adj Mandate Set	Approved:0.00.	[I] Jowyn Tay
8	19 Jan 2018 12:32	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	19 Jan 2018 14:08	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
10	22 Jan 2018 13:39	Adj Rpt Initiated		[A] SHIAU CHAN
11	22 Jan 2018 13:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/30	[A] SHIAU CHAN
12	22 Jan 2018 13:44	Adj Mandate Request	Cur.Reg:14914.04:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	22 Jan 2018 16:40	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/30	[I] Susan Teo
14	22 Jan 2018 16:40	Adj Mandate Set	Approved:11800.00.	[I] Susan Teo

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1699779	19/01/2018 10:16	Motor	SMRT Automotive Services Pte Ltd (Woodlands)	SMRT Automotive Services Pte Ltd (Woodlands)	SLQ800B		xx.xx
1701511	22/01/2018 13:39	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLQ800B		10.70

1/22/2018,

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 22 Jan 2018

Preliminary Advice

Vehicle No	: SLQ800B	Accident Date	: 16/01/2018
Make	: MERCEDES-BENZ B170	Policy No.	: DMPCSN3097231701
Assignment Date	: 19/01/2018	Excess	: S\$1,250.00
Date of Inspection	: 19/01/2018	Est. Duration of Repair	: 8.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,402.40
Revised Amount	:S\$	8,380.84
Check Items (Estimated)	:S\$	6,533.20
Total	:S\$	14,914.04
Lump Sum Repair	:S\$	11,950.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	18,997.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,003.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2299H

Vehicle Details

Vehicle No.: SLQ800B

Vehicle to be Exported: No

Intended De-registration Date: 22 Jan 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: B180

Primary Colour: Blue

Manufacturing Year: 2009

Engine No.: 26694030708537

Chassis No.: WDD2452322J534994

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$27,982.00

Original Registration Date: 17 Dec 2009

First Registration Date: 17 Dec 2009

Transfer Count: 1

Actual ARF Paid: \$27,982.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 Dec 2019

PARF Rebate Amount: \$15,390.00

Intended COE Rebate Details

COE Expiry Date: 16 Dec 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$19,003.00

COE Rebate Amount: \$3,607.00

Total Rebate Amount: \$18,997.00

The information contained herein is correct as at 22 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/01/2018 08:37
Date Of Accident 16/01/2018 17:50
Exact Location Of Accident PENJURU ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLQ800B
Insured/Policyholder
Name Of Registered Owner WONG BOON HWEE DAVIN
NRIC No S7522299H
Email Address DAVINWONGBH@GMAIL.COM
Mobile Phone No (LOCAL) +65-90033218
Alternative Phone No OTHERS-90033213

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model B180

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPCSN3097231701
Cover Note Number

Driver

Name of Driver HO LI YAN, JENNY
NRIC No S8236827B
Date Of Birth 27/10/1982
Occupation INDOOR
Date Of Driving Pass 11/06/2005
Driving Experience 12 YEARS AND 7 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-90033213
Fax Number
Contact Number
Email Address JENHO27@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

17/JAN/2018
0845 HRS.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Photo




Accident Photo



Accident Photo



Accident Photo



REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)
 Parts: 144 MERCEDES-BENZ B170 1.7 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SMRT Automotive Services Pte Ltd/SLQ800B/19/01/2018 10:24
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*AIR GUIDE PANEL	0.00	0.00	nn X 185.00 F
2	1	NA	*AIR INTAKE GRILLE	0.00	0.00	nn X 135.00 F
3	1	NA	*BONNET	0.00	0.00	bt ✓ 362.39 F
4	1	NA	*BONNET LANDING PANEL	0.00	0.00	dis ✓ 680.00 F
5	1	NA	*BONNET SUPPORT	0.00	0.00	del ✓ 13.43 F
6	1	NA	*CONTROL CABLE	0.00	0.00	X 95.00 F
7	1	NA	*ELECTRIC FAN	0.00	0.00	X 1,500.00 F
8	1	NA	*EXPANSION TANK	0.00	0.00	X 155.00 F
9	1	NA	*EXPANSION TANK HOSE	0.00	0.00	X 45.00 F
10	1	NA	*FAN SHROUD	0.00	0.00	X 180.00 F
11	1	NA	*FRONT BUMPER	0.00	0.00	de ✓ 728.00 F
12	1	NA	*FRONT NUMBER PLATE	0.00	0.00	dd ✓ 30.00 F
13	1	NA	*FRONT STAR EMBLEM	0.00	0.00	clt ✓ 80.00 F
14	1	NA	*FRONT WASHER JET	0.00	0.00	*240.00 F X nn
15	1	NA	*FRT BUMPER CLAMP KIT	0.00	0.00	nel ✓ 50.00 F
16	1	NA	*FRT BUMPER GRILLE	0.00	0.00	*136.50 F
17	1	NA	*FRT LWR BUMPER SUPP	0.00	0.00	*66.82 F } nn
18	1	NA	*FRT LWR CROSSMEMBER	0.00	0.00	*600.00 F
19	1	NA	*FRT NO PLATE BACKG	0.00	0.00	nn X 65.00 F
20	1	NA	*FRT NO PLATE BACKG	0.00	0.00	de ✓ 28.40 F
21	1	NA	*FRT SCREEN SUPPORTS	0.00	0.00	*9.45 F
22	1	NA	*FRT/CTR IMPACT DAMP	0.00	0.00	*600.00 F
23	1	NA	*HIGH TONE HORN	0.00	0.00	*105.00 F } nn
24	1	NA	*INTERCOOLER	0.00	0.00	*1,250.00 F
25	1	NA	*L/F BUMPER GRILLE	0.00	0.00	*62.40 F
26	1	NA	*L/F BUMPER TRIM	0.00	0.00	nel ✓ 95.00 F
27	1	NA	*L/F COVER	0.00	0.00	*75.00 F
28	1	NA	*L/F RAIL	0.00	0.00	*35.00 F } nn
29	1	NA	*L/F W-HOUSE FRT CVR	0.00	0.00	*26.42 F
30	1	NA	*L/F W-HOUSE RR COVER	0.00	0.00	*35.76 F
31	1	NA	*L/F WING	0.00	0.00	bt ✓ 650.00 F
32	1	NA	*L/F WING BRACKET FRT	0.00	0.00	nel ✓ 55.00 F
33	1	NA	*L/F WING COVER	0.00	0.00	*5.17 F nn
34	1	NA	*L/F WIPER ARM	0.00	0.00	*26.73 F nn
35	1	NA	*L/HEADLAMP COVER	0.00	0.00	de ✓ 5.11 F
36	1	NA	*L/OUTER COVER	0.00	0.00	*37.54 F nn
37	1	NA	*L/UPPER BEARING	0.00	0.00	*45.00 F nn
38	1	NA	*L/WING BRACKET REAR	0.00	0.00	nel ✓ 27.95 F
39	1	NA	*L/WING CLAMP KIT	0.00	0.00	*F nn
40	1	NA	*LEFT BONNET HINGE	0.00	0.00	bt ✓ 60.00 F
41	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	crq ✓ 950.00 F
42	1	NA	*LOW TONE HORN	0.00	0.00	*105.00 F nn
43	1	NA	*LOWER BONNET LOCK	0.00	0.00	bt ✓ 125.00 F
44	1	NA	*OUTER TEMP SENSOR	0.00	0.00	nn ✓ 125.00 F
45	1	NA	*R/F BUMPER GRILLE	0.00	0.00	*62.40 F nn
46	1	NA	*R/F BUMPER TRIM	0.00	0.00	nel ✓ 95.00 F
47	1	NA	*R/F COVER	0.00	0.00	*75.00 F
48	1	NA	*R/F RAIL	0.00	0.00	*35.00 F } nn
49	1	NA	*R/F W-HOUSE FRT CVR	0.00	0.00	*26.42 F
50	1	NA	*R/F W-HOUSE RR COVER	0.00	0.00	*35.76 F
51	1	NA	*R/F WING	0.00	0.00	bt ✓ 650.00 F
52	1	NA	*R/F WING BRACKET FRT	0.00	0.00	nel ✓ 55.00 F
53	1	NA	*R/F WING COVER	0.00	0.00	*5.17 F } nn
54	1	NA	*R/F WIPER ARM	0.00	0.00	*26.73 F
55	1	NA	*R/HEADLAMP COVER	0.00	0.00	de ✓ 5.11 F
56	1	NA	*R/LWR RADIATOR HOSE	0.00	0.00	*78.00 F
57	1	NA	*R/OUTER COVER	0.00	0.00	*37.54 F } nn
58	1	NA	*R/UPPER BEARING	0.00	0.00	*7.49 F
59	1	NA	*R/WING BRACKET REAR	0.00	0.00	nel ✓ 27.95 F
60	1	NA	*R/WING CLAMP KIT	0.00	0.00	*F } nn
61	1	NA	*RADIATOR	0.00	0.00	*950.00 F

SMRT Automotive Services Pte Ltd/SLQ800B/19/01/2018 10:24. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
62	1	NA	*RADIATOR COVER	0.00	0.00	*600.00 F
63	1	NA	*RIGHT BONNET HINGE	0.00	0.00	*25.03 F
64	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	*950.00 F
65	1	NA	*SCREW	0.00	0.00	*1.38 F
66	1	NA	*SCREW	0.00	0.00	*1.38 F
67	1	NA	*SCREW	0.00	0.00	*1.38 F
68	1	NA	*SCREW	0.00	0.00	*1.38 F
69	1	NA	*SCREW	0.00	0.00	*2.28 F
70	1	NA	*SCREW	0.00	0.00	*2.28 F
71	1	NA	*SET WIPER BLADES	0.00	0.00	*43.70 F
72	1	NA	*SPECIALIST AUDATEX FEE	0.00	0.00	*42.00 F
73	1	NA	*SUNDRY PARTS	0.00	0.00	*277.07 F 100
74	1	NA	*UPPER BONNET LOCK	0.00	0.00	*80.00 F
75	1	NA	*UPPER VENT HOSE	0.00	0.00	*35.00 F 3mm
Sub Total (\$\$)						14,172.52
+ Margin on L,N Items 5.00% (\$\$)						708.63
Total Parts (\$\$)						14,881.15

F=Franchise part.

SMRT Automotive Services Pte Ltd/SLQ800B/19/01/2018 10:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
Labour Items			
1	Total Paint Labour		
2	Total Paint Materials	New	432.40✓
3	Total Panel/Mechanical Labour	New	219.45✓
		New	381.30
			869.40
Gross Labour Cost (\$\$)			1,521.25

SMRT Automotive Services Pte Ltd/SLQ800B/19/01/2018 10:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705

For Surveyor Marking

Claim Reference: WL/JAN2018/009
Assessment Number: CTI10128
Version: SMRTAUTO/2
Date Calculated: 19/01/2018 01:29

Full Report - V1
Registration: SLQ800B
Printed: 19/01/2018 09:37

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	yew chung smrt	Date of Incident:	16/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	WL/JAN2018/009	Estimated Repair Time:	
Policy Number:	DMPCSN3097231701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	MERCEDES	FROM VIN J 705000	AIR CONDITIONING
Model:	B Class	PARKTRONIC SYSTEM	BI-XENON HEADLAMPS
Sub Model:	B 180 CDI	CHROME PACKAGE	TWO COAT METALLIC
Model Sheet Number:	322 32	PREPARE OFF VEHICLE	
Registration:	SLQ800B		
Registration Month:	December		
Registration Year:	2009		
VIN Number:			
Manufacture Month:	December		
Manufacture Year:	2009		
Odometer:	Not Known		
Colour:			
Engine Number:			
Fuel Level:	%		



Tayik 97495749
Revert Not Authorised
19/1/18 @ 1630
Lumpsum
Recovery after repair
Sur @ 14k auto.com
8 days.

Ex \$1250

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
	Date of Inspection:	16/01/2018
Brakes Pedal Travel:		
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

SMRT AUTOMOTIVE SERVICES PTE LTD**Claim Reference: WL/JAN2018/009****Full Report - V1****Assessment Number: CTI10128****Registration: SLQ800B****Version: SMRTAUTO/2****Printed: 19/01/2018 09:37****Date Calculated: 19/01/2018 01:29****Addresses****Cost Summary**

Total Labour	\$1,301.80
Total Paint/Material	\$219.45
Total Parts	\$14,823.19
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$16,386.44
7 % GST:	\$1,147.05
Grand Total Inc GST:	\$17,533.49

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$46.00/HR**

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	9.20
60-1081 01	SET UP ANGLE ADAPTER KIT ON CHASSIS JIG (FOR VEHICLE WITH RUNNING GEAR ATTACHED)	8.0	36.80
60-1091 01	REMOVE ANGLE ADAPTER KIT FROM CHASSIS JIG (FOR VEHICLE WITH RUNNING GEAR ATTACHED)	5.0	23.00
60-3600 01	DO ADD/WORK 1 (VEHICLE WITH HEADLAMP WASHER SYSTEM)	3.0	13.80
88-1051 01)	RENEW FRONT NUMBER PLATE (REMOVED)	2.0	9.20
88-1102 03	R + R FRONT BUMPER CPL INCLUDES: R + R FRONT PARTITION SECTIONS	9.0	41.40
88-1105 03	DIS + ASS FRONT BUMPER (BUMPER REMOVED) AFTER CHECK: RENEW PARTS IF NECESSARY	7.0	32.20
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	9.20
88-2506 02	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS	18.0	82.80
88-2657 02	RENEW BONNET HINGE/S	5.0	23.00
82-4613 01)	RENEW BOTH XENON HEADLAMPS (BUMPER REMOVED)	3.0	13.80
20-9220 02)	R + R RIGHT LOWER RADIATOR HOSE	7.0	32.20
88-4108 02	RENEW FRONT WINGS (BUMPER REMOVED) INCLUDES: R + R A-PILLAR TRIMS	14.0	64.40

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/JAN2018/009

Assessment Number: CTI10128

Version: SMRTAUTO/2

Date Calculated: 19/01/2018 01:29

Full Report - V1

Registration: SLQ800B

Printed: 19/01/2018 09:37

88-4712 02	R + R L/F WING COVER	2.0	9.20
88-4717 02	R + R R/F WING COVER	2.0	9.20
88-4702 02)	RENEW L/F PARTITION SECTION (REMOVED)	1.0	4.60
88-4704 02)	RENEW R/F PARTITION SECTION (REMOVED)	1.0	4.60
20-1140 02	DRAIN + REFILL COOLANT	6.0	27.60
09-6820 02)	R + R CHARGE AIR COOLER (BUMPER REMOVED)	2.0	9.20
20-4008 01	RENEW RADIATOR (RADIATOR CARRIER REMOVED)	6.0	27.60
94-5305 02	R + R ACOUSTIC ENCAPSULATION CPL	5.0	23.00
60-1301 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE TRUSSING INCLUDES: R + R AIR INTAKE PIPE AND BONNET CABLE, DETACH + REFIT PARTIAL PARTITION DOES NOT INCLUDE: R + R BUMPER, HEADLAMPS AND BONNET LOCK	7.0	32.20
20-6461 01	R + R FAN UNIT	7.0	32.20
20-6465 01	RENEW FAN UNIT PARTS (REMOVED)	3.0	13.80
62-1266 01	RENEW FRONT CROSSMEMBER AND REINFORCEMENT BETWEEN WHEELHOUSES CPL	15.0	69.00
82-7200 02)	DETACH + REFIT WASHER RESERVOIR	3.0	13.80
82-6955 02	R + R WIPER ARMS AND WIPER BLADES	5.0	23.00
20-5410 01	R + R COOLANT EXPANSION TANK	7.0	32.20
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	FRONT COVER CAVITY PROTECTION	2.0	9.20
NO NUMBER	LOWER + LIFT ENGINE AND FRONT AXLE BRACKET	18.0	82.80
09-1030 01	R + R AIR FILTER CPL	5.0	23.00
9973	CARRY OUT TEST DRIVE	5.0*	23.00

LABOUR COST

Total Work Units	189.0	
Panel / Mechanical Labour	18.3HRS	\$841.80
Visual Alignment Labour	0.2HRS	\$9.20
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.4HRS	18.40
Sub Total	18.9HRS	\$869.40
Paint Labour	9.4HRS	\$432.40
Total Labour	28.3HRS	\$1,301.80

PAINT WORK

Guide Number Description		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
		WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	24.0	
741	L/F WING NEW PART PAINTING	9.0	
742	R/F WING NEW PART PAINTING	9.0	
475	LEFT BONNET HINGE SURFACE PAINT	4.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/JAN2018/009

Assessment Number: CTI10128

Version: SMRTAUTO/2

Date Calculated: 19/01/2018 01:29

Full Report - V1

Registration: SLQ800B

Printed: 19/01/2018 09:37

283	FRONT BUMPER NEW PART PAINT K1R	14.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	64.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	94.0	
	Total Paintwork Labour	9.4HRS	\$432.40
	MATERIAL COST - PAINT		Cost Price
	New Part Painting		\$111.98
	New Part Painting - Plastic K1R		\$69.37
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$0.50
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$219.45
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$219.45

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	dd ✓ 30.00*
258	1	FRT NO PLATE BACKG	KNPL0		0%	de ✓ 65.00*
259	1	FRT NO PLATE BACKG	169 880 0144		0%	de ✓ 28.40U
283	1	FRONT BUMPER	169 885 2825		0%	de ✓ 728.00*
293	1	FRT BUMPER GRILLE	169 885 0123		0%	de ✓ 136.50*
303	1	L/F BUMPER GRILLE	169 885 2322		0%	de ✓ 62.40*
304	1	R/F BUMPER GRILLE	169 885 2422		0%	de ✓ 62.40*
313	1	L/F BUMPER TRIM	169 885 1374		0%	rec ✓ 95.00*
314	1	R/F BUMPER TRIM	169 885 1474		0%	rec ✓ 95.00*
319	1	FRT/CTR IMPACT DAMP	169 885 0137		0%	de ✓ 600.00*
320	1	FRT LWR BUMPER SUPP	169 885 0136		0%	de ✓ 66.82U
351	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	★	0%	rec ✓ 50.00*
381	1	OUTER TEMP SENSOR	007 542 1318		0%	un ✓ 125.00*
405	1	RADIATOR COVER	169 880 0783		0%	cre ✓ 600.00*
432	1	FRONT STAR EMBLEM	207 817 0316		0%	ant ✓ 80.00*
471	1	BONNET	169 880 0257		0%	bt ✓ 362.39U
475	1	LEFT BONNET HINGE	169 880 0328		0%	bt ✓ 60.00*
476	1	RIGHT BONNET HINGE	169 880 0428		0%	bt ✓ 25.03U
492	1	UPPER BONNET LOCK	169 880 0160		0%	bt ✓ 80.00*
493	1	LOWER BONNET LOCK	169 880 0560		0%	bt ✓ 125.00*
495	1	BONNET SUPPORT	169 887 0272		0%	de ✓ 13.43U
500	1	CONTROL CABLE	169 880 0259		0%	de ✓ 95.00*
559	1	L/HEADLAMP COVER	169 821 0336		0%	de ✓ 5.11U
560	1	R/HEADLAMP COVER	169 821 0436		0%	de ✓ 5.11U
561	1	LEFT HEADLAMP ASSY	169 820 6961		0%	cre ✓ 950.00*
562	1	RIGHT HEADLAMP ASSY	169 820 7061		0%	cre ✓ 950.00*
741	1	L/F WING	169 880 0718		0%	bt ✓ 650.00*
742	1	R/F WING	169 880 0818		0%	bt ✓ 650.00*
745	1	L/F WING COVER	169 889 0725		0%	de ✓ 5.17U
746	1	R/F WING COVER	169 889 0825		0%	de ✓ 5.17U
747	1	L/WING BRACKET REAR	169 880 1114		0%	rec ✓ 27.95U
748	1	R/WING BRACKET REAR	169 880 1114		0%	rec ✓ 27.95U

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/JAN2018/009

Full Report - V1

Assessment Number: CTI10128

Registration: SLQ800B

Version: SMRTAUTO/2

Printed: 19/01/2018 09:37

Date Calculated: 19/01/2018 01:29

763	1	L/F WING BRACKET FRT	169 885 0314	0%	acc	55.00*
764	1	R/F WING BRACKET FRT	169 885 0414	0%	acc	55.00*
765	1	L/F RAIL	169 882 0327	0%	?	35.00*
766	1	R/F RAIL	169 882 0427	0%	?	35.00*
789	1	L/WING CLAMP KIT	USE SINGLE PARTS	0%	?	0.00
790	1	R/WING CLAMP KIT	USE SINGLE PARTS	0%	?	0.00
791	1	SCREW	001 990 9614	0%	X	1.38U
792	1	SCREW	001 990 9614	0%	X	1.38U
793	1	SCREW	001 990 9614	0%	X	1.38U
794	1	SCREW	001 990 9614	0%	X	1.38U
795	3	SCREW	000 990 0211	0%	X	2.28U
796	3	SCREW	000 990 0211	0%	X	2.28U
833	1	L/F W-HOUSE FRT CVR	169 698 2530	0%	X	26.42U
834	1	R/F W-HOUSE FRT CVR	169 698 2630	0%	X	26.42U
835	1	L/F W-HOUSE RR COVER	169 698 2730	0%	X	35.76U
836	1	R/F W-HOUSE RR COVER	169 698 2830	0%	X	35.76U
1001	1	FRT LWR CROSSMEMBER	169 620 1734	0%	?	600.00*
1017	1	BONNET LANDING PANEL	169 620 1634	0%	dis	680.00*
1392	1	AIR INTAKE GRILLE	169 836 0018	0%	X	185.00*
1393	1	L/F COVER	169 830 0375	0%	X	75.00*
1394	1	R/F COVER	169 830 0275	0%	X	75.00*
1415	7	FRT SCREEN SUPPORTS	169 671 0196	0%	X	9.45U
1447	1	FRONT WASHER JET	169 860 0492	0%	X	240.00*
1453	1	L/F WIPER ARM	169 820 1144	0%	X	26.73U
1454	1	R/F WIPER ARM	169 820 1444	0%	X	26.73U
1459	1	SET WIPER BLADES	169 820 1900	0%	X	43.70U
1745	1	L/OUTER COVER	169 690 3987	0%	X	37.54U
1746	1	R/OUTER COVER	169 690 4087	0%	X	37.54U
7751	1	AIR GUIDE PANEL	169 505 0330	0%	?	185.00*
7761	1	RADIATOR	169 500 1803	0%	?	950.00*
7765	1	L/UPPER BEARING	169 504 0114	0%	?	45.00*
7766	1	R/UPPER BEARING	169 504 0114	0%	?	7.49U
7767	1	FAN SHROUD	169 505 0255	0%	?	180.00*
7773	1	R/LWR RADIATOR HOSE	169 501 1182	0%	?	78.00*
7787	1	EXPANSION TANK	169 500 0049	0%	?	155.00*
7788	1	UPPER VENT HOSE	169 501 1225	0%	?	35.00*
7789	1	EXPANSION TANK HOSE	169 501 0982	0%	?	45.00*
7792	1	ELECTRIC FAN	169 820 3542	0%	?	1,500.00*
8730	1	INTERCOOLER	169 500 0900	0%	?	1,250.00*
9645	1	HIGH TONE HORN	006 542 4420	0%	X	105.00*
9646	1	LOW TONE HORN	006 542 2720	0%	X	105.00*

f: OEM Parts
g: Original
h: Secondhand
p: Parallel
x: Exchange

Sub Total
Mark Up From Cost (5 %)
Sundry Parts (2 %)
Total Parts

\$13,853.45
\$692.67
\$277.07
\$14,823.19

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

SMRT AUTOMOTIVE SERVICES PTE LTD**Claim Reference: WL/JAN2018/009****Full Report - V1****Assessment Number: CTI10128****Registration: SLQ800B****Version: SMRTAUTO/2****Printed: 19/01/2018 09:37****Date Calculated: 19/01/2018 01:29**

Final Calculation

Total Parts		\$14,823.19
--------------------	--	--------------------

Labour		
---------------	--	--

Total Panel/Mechanical	\$841.80
------------------------	----------

Total Paintwork	\$432.40
-----------------	----------

Total Visual Alignment work	\$9.20
-----------------------------	--------

Corr Prot Internal 4 WU	\$18.40
-------------------------	---------

Total Labour		\$1,301.80
---------------------	--	-------------------

Additional Costs

Corr Prot Materials External	\$0.00
------------------------------	--------

Cost of Specialist	\$42.00
--------------------	---------

Total of Additional Costs		\$42.00
----------------------------------	--	----------------

Total Paint/Material Costs		\$219.45
-----------------------------------	--	-----------------

Grand Total Excludes GST		\$16,386.44
---------------------------------	--	--------------------

GST @ 7 %		\$1,147.05
-----------	--	-------------------

Grand Total Includes GST		\$17,533.49
---------------------------------	--	--------------------

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM18D00335C01
Assessment Number: CTI10128
Version: CHINATAI/2

Full Report - V1
Registration: SLQ800B
Printed: 22/01/2018 13:23

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	16/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00335C01	Estimated Repair Time:	
Policy Number:	DMPCSN3097231701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 180 CDI
Model Sheet Number:	322 32
Registration:	SLQ800B
Registration Month:	December
Registration Year:	2009
VIN Number:	
Manufacture Month:	December
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM VIN J 705000	AIR CONDITIONING
PARKTRONIC SYSTEM	BI-XENON HEADLAMPS
CHROME PACKAGE	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	16/01/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

**Addresses****Cost Summary**

Total Labour	\$1,269.60
Total Paint/Material	\$219.45
Total Parts	\$13,382.99
Total of Additional Costs	\$42.00
Repair Cost Exc GST:	\$14,914.04
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,250.00
After Deduction -	
Grand Total Exc GST:	\$13,664.04
7 % GST:	\$956.48
Grand Total Inc GST:	\$14,620.52

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	9.20
60-1081 01	SET UP ANGLE ADAPTER KIT ON CHASSIS JIG (FOR VEHICLE WITH RUNNING GEAR ATTACHED)	8.0	36.80
60-1091 01	REMOVE ANGLE ADAPTER KIT FROM CHASSIS JIG (FOR VEHICLE WITH RUNNING GEAR ATTACHED)	5.0	23.00
60-3600 01	DO ADD/WORK 1 (VEHICLE WITH HEADLAMP WASHER SYSTEM)	3.0	13.80
88-1051 01)	RENEW FRONT NUMBER PLATE (REMOVED)	2.0	9.20
88-1102 03	R + R FRONT BUMPER CPL INCLUDES: R + R FRONT PARTITION SECTIONS	9.0	41.40
88-1105 03	DIS + ASS FRONT BUMPER (BUMPER REMOVED) AFTER CHECK: RENEW PARTS IF NECESSARY	7.0	32.20
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	9.20
88-2506 02	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS	18.0	82.80
88-2657 02	RENEW BONNET HINGE/S	5.0	23.00
82-4613 01)	RENEW BOTH XENON HEADLAMPS (BUMPER REMOVED)	3.0	13.80
20-9220 02)	R + R RIGHT LOWER RADIATOR HOSE	7.0	32.20
88-4108 02	RENEW FRONT WINGS (BUMPER REMOVED)	14.0	64.40

	INCLUDES: R + R A-PILLAR TRIMS		
88-4712 02	R + R L/F WING COVER	2.0	9.20
88-4717 02	R + R R/F WING COVER	2.0	9.20
20-1140 02	DRAIN + REFILL COOLANT	6.0	27.60
09-6820 02)	R + R CHARGE AIR COOLER (BUMPER REMOVED)	2.0	9.20
20-4008 01	RENEW RADIATOR (RADIATOR CARRIER REMOVED)	6.0	27.60
94-5305 02	R + R ACOUSTIC ENCAPSULATION CPL	5.0	23.00
60-1301 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE TRUSSING	7.0	32.20
	INCLUDES: R + R AIR INTAKE PIPE AND BONNET CABLE, DETACH + REFIT PARTIAL PARTITION DOES NOT INCLUDE: R + R BUMPER, HEADLAMPS AND BONNET LOCK		
20-6461 01	R + R FAN UNIT	7.0	32.20
20-6465 01	RENEW FAN UNIT PARTS (REMOVED)	3.0	13.80
62-1266 01	RENEW FRONT CROSSMEMBER AND REINFORCEMENT BETWEEN WHEELHOUSES CPL	15.0	69.00
82-7200 02)	DETACH + REFIT WASHER RESERVOIR	3.0	13.80
20-5410 01	R + R COOLANT EXPANSION TANK	7.0	32.20
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	FRONT COVER CAVITY PROTECTION	2.0	9.20
NO NUMBER	LOWER + LIFT ENGINE AND FRONT AXLE BRACKET	18.0	82.80
09-1030 01	R + R AIR FILTER CPL	5.0	23.00
9973	CARRY OUT TEST DRIVE	5.0*	23.00

LABOUR COST

Total Work Units	182.0	
Panel / Mechanical Labour	17.6HRS	\$809.60
Visual Alignment Labour	0.2HRS	\$9.20
Corrosion Protection		
Corrosion Protection Internal Labour	0.4HRS	18.40
Sub Total	18.2HRS	\$837.20
Paint Labour	9.4HRS	432.40
Total Labour	27.6HRS	\$1,269.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	24.0	
741	L/F WING NEW PART PAINTING	9.0	
742	R/F WING NEW PART PAINTING	9.0	
475	LEFT BONNET HINGE SURFACE PAINT	4.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
LABOUR COST - PAINT			
	TIME(PAINT)	64.0	
	Preparation Main Work Plastic	5.0	

Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	94.0	
Total Paintwork Labour	9.4HRS	\$432.40
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$111.98
New Part Painting - Plastic K1R		\$69.37
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$0.50
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$219.45
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$219.45

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	30.00*
258	1	FRT NO PLATE BACKG	KNPL0		0%	65.00*
259	1	FRT NO PLATE BACKG	169 880 0144		0%	28.40U
283	1	FRONT BUMPER	169 885 2825		0%	728.00*
313	1	L/F BUMPER TRIM	169 885 1374		0%	95.00*
314	1	R/F BUMPER TRIM	169 885 1474		0%	95.00*
319	1	FRT/CTR IMPACT DAMP	169 885 0137		0%	600.00*
320	1	FRT LWR BUMPER SUPP	169 885 0136		0%	66.82U
351	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	50.00*
381	1	OUTER TEMP SENSOR	007 542 1318		0%	125.00*
405	1	RADIATOR COVER	169 880 0783		0%	600.00*
432	1	FRONT STAR EMBLEM	207 817 0316		0%	80.00*
471	1	BONNET	169 880 0257		0%	362.39U
475	1	LEFT BONNET HINGE	169 880 0328		0%	60.00*
476	1	RIGHT BONNET HINGE	169 880 0428		0%	25.03U
492	1	UPPER BONNET LOCK	169 880 0160		0%	80.00*
493	1	LOWER BONNET LOCK	169 880 0560		0%	125.00*
495	1	BONNET SUPPORT	169 887 0272		0%	13.43U
500	1	CONTROL CABLE	169 880 0259		0%	95.00*
559	1	L/HEADLAMP COVER	169 821 0336		0%	5.11U
560	1	R/HEADLAMP COVER	169 821 0436		0%	5.11U
561	1	LEFT HEADLAMP ASSY	169 820 6961		0%	950.00*
562	1	RIGHT HEADLAMP ASSY	169 820 7061		0%	950.00*
741	1	L/F WING	169 880 0718		0%	650.00*
742	1	R/F WING	169 880 0818		0%	650.00*
745	1	L/F WING COVER	169 889 0725		0%	5.17U
746	1	R/F WING COVER	169 889 0825		0%	5.17U
747	1	L/WING BRACKET REAR	169 880 1114		0%	27.95U
748	1	R/WING BRACKET REAR	169 880 1114		0%	27.95U
763	1	L/F WING BRACKET FRT	169 885 0314		0%	55.00*
764	1	R/F WING BRACKET FRT	169 885 0414		0%	55.00*
765	1	L/F RAIL	169 882 0327		0%	35.00*
766	1	R/F RAIL	169 882 0427		0%	35.00*
789	1	L/WING CLAMP KIT	USE SINGLE PARTS		0%	0.00
790	1	R/WING CLAMP KIT	USE SINGLE PARTS		0%	0.00
791	1	SCREW	001 990 9614		0%	0.00F
792	1	SCREW	001 990 9614		0%	0.00F

793	1	SCREW	001 990 9614	0%	0.00F
794	1	SCREW	001 990 9614	0%	0.00F
795	3	SCREW	000 990 0211	0%	0.00F
796	3	SCREW	000 990 0211	0%	0.00F
1001	1	FRT LWR CROSSMEMBER	169 620 1734	0%	600.00*
1017	1	BONNET LANDING PANEL	169 620 1634	0%	680.00*
1393	1	L/F COVER	169 830 0375	0%	75.00*
1394	1	R/F COVER	169 830 0275	0%	75.00*
1415	7	FRT SCREEN SUPPORTS	169 671 0196	0%	9.45U
7751	1	AIR GUIDE PANEL	169 505 0330	0%	185.00*
7761	1	RADIATOR	169 500 1803	0%	950.00*
7765	1	L/UPPER BEARING	169 504 0114	0%	45.00*
7766	1	R/UPPER BEARING	169 504 0114	0%	7.49U
7767	1	FAN SHROUD	169 505 0255	0%	180.00*
7773	1	R/LWR RADIATOR HOSE	169 501 1182	0%	78.00*
7787	1	EXPANSION TANK	169 500 0049	0%	155.00*
7788	1	UPPER VENT HOSE	169 501 1225	0%	35.00*
7789	1	EXPANSION TANK HOSE	169 501 0982	0%	45.00*
7792	1	ELECTRIC FAN	169 820 3542	0%	1,500.00*
8730	1	INTERCOOLER	169 500 0900	0%	1,250.00*
f: OEM Parts			Saving		\$10.08
g: Original			Sub Total		\$12,650.47
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$13,382.99
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
Corr Prot Internal	0%	\$18.40
Total Extras		\$60.40

Final Calculation

Total Parts	\$13,382.99
Labour	
Total Panel/Mechanical	\$809.60
Total Paintwork	\$432.40
Total Visual Alignment work	\$9.20
Corr Prot Internal 4 WU	\$18.40
Total Labour	\$1,269.60
Additional Costs	
Corr Prot Materials External	\$0.00
Cost of Specialist	\$42.00
Total of Additional Costs	\$42.00
Total Paint/Material Costs	\$219.45
Repair Costs Excludes GST	\$14,914.04
Deductions	
Deduction for Excess (Fixed)	-\$1,250.00
Total Deductions	-\$1,250.00
Grand Total Excludes GST (After Deduction)	\$13,664.04
GST @ 7 %	\$956.48
Grand Total Includes GST (After Deduction)	\$14,620.52

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM18D00335C01
Assessment Number: CTI10128
Version: CHINATAI/4
Date Calculated: 28/02/2018 08:30

Full Report - V1
Registration: SLQ800B
Printed: 28/02/2018 16:31

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	16/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00335C01	Estimated Repair Time:	
Policy Number:	DMPCSN3097231701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 180 CDI
Model Sheet Number:	322 32
Registration:	SLQ800B
Registration Month:	December
Registration Year:	2009
VIN Number:	
Manufacture Month:	December
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM VIN J 705000	AIR CONDITIONING
PARKTRONIC SYSTEM	BI-XENON HEADLAMPS
CHROME PACKAGE	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	16/01/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$814.20
Total Paint/Material	\$219.45
Total Parts	\$6,849.79
Total of Additional Costs	\$42.00
Repair Cost Exc GST:	\$7,925.44
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,250.00
After Deduction -	
Grand Total Exc GST:	\$6,675.44
7 % GST:	\$467.28
Grand Total Inc GST:	\$7,142.72

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
60-3600 01	DO ADD/WORK 1 (VEHICLE WITH HEADLAMP WASHER SYSTEM)	3.0	13.80
88-1051 01)	RENEW FRONT NUMBER PLATE (REMOVED)	2.0	9.20
88-1102 03	R + R FRONT BUMPER CPL INCLUDES: R + R FRONT PARTITION SECTIONS	9.0	41.40
88-1105 03	DIS + ASS FRONT BUMPER (BUMPER REMOVED) AFTER CHECK: RENEW PARTS IF NECESSARY	7.0	32.20
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	9.20
88-2506 02	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS	18.0	82.80
88-2657 02	RENEW BONNET HINGE/S	5.0	23.00
82-4613 01)	RENEW BOTH XENON HEADLAMPS (BUMPER REMOVED)	3.0	13.80
88-4108 02	RENEW FRONT WINGS (BUMPER REMOVED) INCLUDES: R + R A-PILLAR TRIMS	14.0	64.40
60-1301 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE TRUSSING INCLUDES: R + R AIR INTAKE PIPE AND BONNET CABLE, DETACH + REFIT PARTIAL PARTITION DOES NOT INCLUDE: R + R BUMPER,	7.0	32.20

62-1320 01	HEADLAMPS AND BONNET LOCK	13.0	59.80
	RENEW FRONT TRUSSING CPL BETWEEN		
	WHEELHOUSES		
LABOUR COST			
	Total Work Units	83.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	8.3HRS	\$381.80
	Paint Labour	9.4HRS	\$432.40
	Total Labour	17.7HRS	\$814.20

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	24.0	
475	LEFT BONNET HINGE SURFACE PAINT	4.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	
741	L/F WING NEW PART PAINTING	9.0	
742	R/F WING NEW PART PAINTING	9.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
LABOUR COST - PAINT			
	TIME(PAINT)	64.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	94.0	
	Total Paintwork Labour	9.4HRS	\$432.40
MATERIAL COST - PAINT			
	New Part Painting		\$111.98
	New Part Painting - Plastic K1R		\$69.37
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$0.50
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$219.45
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$219.45

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	30.00*
259	1	FRT NO PLATE BACKG	169 880 0144		0%	28.40*
283	1	FRONT BUMPER	169 885 2825		0%	728.00*
313	1	L/F BUMPER TRIM	169 885 1374		0%	95.00*
314	1	R/F BUMPER TRIM	169 885 1474		0%	95.00*
351	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	50.00*
405	1	RADIATOR COVER	169 880 0783		0%	600.00*
432	1	FRONT STAR EMBLEM	207 817 0316		0%	80.00*
471	1	BONNET	169 880 0257		0%	362.39*
475	1	LEFT BONNET HINGE	169 880 0328		0%	60.00*
476	1	RIGHT BONNET HINGE	169 880 0428		0%	25.03*

492	1	UPPER BONNET LOCK	169 880 0160	0%	80.00*
493	1	LOWER BONNET LOCK	169 880 0560	0%	125.00*
495	1	BONNET SUPPORT	169 887 0272	0%	13.43*
559	1	L/HEADLAMP COVER	169 821 0336	0%	5.11*
560	1	R/HEADLAMP COVER	169 821 0436	0%	5.11*
561	1	LEFT HEADLAMP ASSY	169 820 6961	0%	950.00*
562	1	RIGHT HEADLAMP ASSY	169 820 7061	0%	950.00*
741	1	L/F WING	169 880 0718	0%	650.00*
742	1	R/F WING	169 880 0818	0%	650.00*
747	1	L/WING BRACKET REAR	169 880 1114	0%	27.95*
748	1	R/WING BRACKET REAR	169 880 1114	0%	27.95*
763	1	L/F WING BRACKET FRT	169 885 0314	0%	55.00*
764	1	R/F WING BRACKET FRT	169 885 0414	0%	55.00*
1017	1	BONNET LANDING PANEL	169 620 1634	0%	680.00*
f: OEM Parts		Sub Total			\$6,428.37
g: Original		Mark Up From Cost		(5 %)	\$321.42
h: Secondhand		Sundry Parts		(Fixed)	\$100.00
p: Parallel		Total Parts			\$6,849.79
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
	Total Extras	\$42.00

Final Calculation

Total Parts	\$6,849.79
Labour	
Total Panel/Mechanical	\$381.80
Total Paintwork	\$432.40
Total Labour	\$814.20
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$42.00
Total of Additional Costs	\$42.00
Total Paint/Material Costs	\$219.45
Repair Costs Excludes GST	\$7,925.44
Deductions	
Deduction for Excess (Fixed)	-\$1,250.00
Total Deductions	-\$1,250.00
Grand Total Excludes GST (After Deduction)	\$6,675.44
GST @ 7 %	\$467.28
Grand Total Includes GST (After Deduction)	\$7,142.72

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018 Sendback Est	19 Jan 2018 10:24 S\$16,402.40	19 Jan 2018 10:59 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:

WONG BOON HWEE DAVIN, ID: S7522299H

Vehicle Reg. No.:

SLQ800B

Date of Loss:

16/01/2018 17:00 - :59

Claim Type:

OD / SNM18D00335C01

Policy/Cover Note No.:

DMPCSN3097231701 (Comprehensive)
Coverage: 17/12/2017 - 16/12/2018

Excess:

S\$1,250.00

Repairer:

SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/01/2018]

Driver/Custodian:

HO LI YAN, JENNY (/ Female), NRIC: S8236827B

Adj Asg. Remarks:

PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$1,250.00 APPLIES.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

• CHINA_TAIPING (22/01/2018): Alert - Adj Mandate Approved (S\$11800.00) - SLQ800B - Claim Handler: Jowyn Tay

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

SLQ800B (SNM18D00335C01)
OD
Jan 16 2018 5:00PM
[WONG BOON HWEE DAVIN]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page		
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print
1	19/01/18 10:24	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/01/18 13:43	Adjuster Immediate Advice		Load HTM	
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/03/18 10:57	General View		Load PDF	
2	12/03/18 10:57	Reinspection Photo		Load PDF	
Documentation			1 per page		
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print
1	19/01/18 10:26	Singapore Accident Statement		Load PDF	
2	19/01/18 10:26	IC		Load TIF	
3	19/01/18 10:26	DL & IC		Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 14:44	Revised Estimate		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/01/18 13:43	ESTIMATE		Load PDF	
2	22/01/18 13:43	REVISED AUDATEX		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

3/12/2018

Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118001183/T1TD3E2

Date: 12/03/2018

REFERENCE

Insured/Claimant: WONG BOON HWEE DAVIN

Policy No: DMPCSN3097231701

Date of Loss: 16/01/2018

Nature of Claim: OD

Claim No: SNM18D00335C01

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLQ800B**

Make & Model: MERCEDES-BENZ B170, 1.7 (A)

Engine No: 26694030708537

Reg. Date: 17/12/2009 (Man. Year: 2009)

Chassis No: WDD2452322J534994

Colour: Silver

Odometer: 57452 km

Engine Capacity: 1699 cc

Market Value/New Car Price: S\$35,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,881.15	6,891.79	7,989.36	53.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,521.25	1,033.65	487.60	32.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,402.40	7,925.44	8,476.96	51.68
Approved Total (Overridden) (S\$)		6,300.00		
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	16,402.40	5,050.00	11,352.40	69.21
+ GST 7.00/7.00% (S\$)	1,148.17	353.50	794.67	69.21
Nett Amount (S\$)	17,550.57	5,403.50	12,147.07	69.21

INSPECTION

Date of Assignment: 19/01/2018 Present Location:

SMRT Automotive Services Pte Ltd (Woodlands)

Date Inspected: 19/01/2018 Inspected At:

60 Woodlands Industrial Park E4

Estimated Period of Repair: 8.0 days

Singapore 757705

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2018)
Parts:	144 MERCEDES-BENZ B170 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ800B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR GUIDE PANEL (WCP)	Not Necessary	185.00 F	*- F
2	1	NA	*AIR INTAKE GRILLE (WCP)	Not Necessary	185.00 F	*- F
3	1	NA	*BONNET (WCP)	Bent	362.39 F	*362.39 F
4	1	NA	*BONNET LANDING PANEL (WCP)	Distorted	680.00 F	*680.00 F
5	1	NA	*BONNET SUPPORT (WCP)	Deformed	13.43 F	*13.43 F
6	1	NA	*CONTROL CABLE (WCP)	Not Necessary	95.00 F	*- F
7	1	NA	*ELECTRIC FAN (WCP)	Not Necessary	1,500.00 F	*- F
8	1	NA	*EXPANSION TANK (WCP)	Not Necessary	155.00 F	*- F
9	1	NA	*EXPANSION TANK HOSE (WCP)	Not Necessary	45.00 F	*- F
10	1	NA	*FAN SHROUD (WCP)	Not Necessary	180.00 F	*- F
11	1	NA	*FRONT BUMPER (WCP)	Deformed	728.00 F	*728.00 F
12	1	NA	*FRONT NUMBER PLATE (WCP)	Dented	30.00 F	*30.00 F
13	1	NA	*FRONT STAR EMBLEM (WCP)	Cut	80.00 F	*80.00 F
14	1	NA	*FRONT WASHER JET (WCP)	Not Necessary	240.00 F	*- F
15	1	NA	*FRT BUMPER CLAMP KIT (WCP)	Necessary	50.00 F	*50.00 F
16	1	NA	*FRT BUMPER GRILLE (WCP)	Not Necessary	136.50 F	*- F
17	1	NA	*FRT LWR BUMPER SUPP (WCP)	Not Necessary	66.82 F	*- F
18	1	NA	*FRT LWR CROSSMEMBER (WCP)	Not Necessary	600.00 F	*- F
19	1	NA	*FRT NO PLATE BACKG (WCP)	Not Necessary	65.00 F	*- F
20	1	NA	*FRT NO PLATE BACKG (WCP)	Deformed	28.40 F	*28.40 F
21	1	NA	*FRT SCREEN SUPPORTS (WCP)	Not Necessary	9.45 F	*- F
22	1	NA	*FRT/CTR IMPACT DAMP (WCP)	Not Necessary	600.00 F	*- F
23	1	NA	*HIGH TONE HORN (WCP)	Not Necessary	105.00 F	*- F
24	1	NA	*INTERCOOLER (WCP)	Not Necessary	1,250.00 F	*- F
25	1	NA	*L/F BUMPER GRILLE (WCP)	Not Necessary	62.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	NA	*L/F BUMPER TRIM (WCP)	Necessary	95.00 F	*95.00 F
27	1	NA	*L/F COVER (WCP)	Not Necessary	75.00 F	*- F
28	1	NA	*L/F RAIL (WCP)	Not Necessary	35.00 F	*- F
29	1	NA	*L/F W-HOUSE FRT CVR (WCP)	Not Necessary	26.42 F	*- F
30	1	NA	*L/F W-HOUSE RR COVER (WCP)	Not Necessary	35.76 F	*- F
31	1	NA	*L/F WING (WCP)	Bent	650.00 F	*650.00 F
32	1	NA	*L/F WING BRACKET FRT (WCP)	Necessary	55.00 F	*55.00 F
33	1	NA	*L/F WING COVER (WCP)	Not Necessary	5.17 F	*- F
34	1	NA	*L/F WIPER ARM (WCP)	Not Necessary	26.73 F	*- F
35	1	NA	*L/HEADLAMP COVER (WCP)	Deformed	5.11 F	*5.11 F
36	1	NA	*L/OUTER COVER (WCP)	Not Necessary	37.54 F	*- F
37	1	NA	*L/UPPER BEARING (WCP)	Not Necessary	45.00 F	*- F
38	1	NA	*L/WING BRACKET REAR (WCP)	Necessary	27.95 F	*27.95 F
39	1	NA	*L/WING CLAMP KIT (NPA)(WCP)	Not Necessary	0.00 F	*- F
40	1	NA	*LEFT BONNET HINGE (WCP)	Bent	60.00 F	*60.00 F
41	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	950.00 F	*950.00 F
42	1	NA	*LOW TONE HORN (WCP)	Not Necessary	105.00 F	*- F
43	1	NA	*LOWER BONNET LOCK (WCP)	Bent	125.00 F	*125.00 F
44	1	NA	*OUTER TEMP SENSOR (WCP)	Not Necessary	125.00 F	*- F
45	1	NA	*R/F BUMPER GRILLE (WCP)	Not Necessary	62.40 F	*- F
46	1	NA	*R/F BUMPER TRIM (WCP)	Necessary	95.00 F	*95.00 F
47	1	NA	*R/F COVER (WCP)	Not Necessary	75.00 F	*- F
48	1	NA	*R/F RAIL (WCP)	Not Necessary	35.00 F	*- F
49	1	NA	*R/F W-HOUSE FRT CVR (WCP)	Not Necessary	26.42 F	*- F
50	1	NA	*R/F W-HOUSE RR COVER (WCP)	Not Necessary	35.76 F	*- F
51	1	NA	*R/F WING (WCP)	Bent	650.00 F	*650.00 F
52	1	NA	*R/F WING BRACKET FRT (WCP)	Necessary	55.00 F	*55.00 F
53	1	NA	*R/F WING COVER (WCP)	Not Necessary	5.17 F	*- F
54	1	NA	*R/F WIPER ARM (WCP)	Not Necessary	26.73 F	*- F
55	1	NA	*R/HEADLAMP COVER (WCP)	Deformed	5.11 F	*5.11 F
56	1	NA	*R/LWR RADIATOR HOSE (WCP)	Not Necessary	78.00 F	*- F
57	1	NA	*R/OUTER COVER (WCP)	Not Necessary	37.54 F	*- F
58	1	NA	*R/UPPER BEARING (WCP)	Not Necessary	7.49 F	*- F

Report was unsubmitted during this print-out.

3/12/2018

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1	NA	*R/WING BRACKET REAR (WCP)	Necessary	27.95 F	*27.95 F
60	1	NA	*R/WING CLAMP KIT (NPA)(WCP)	Not Necessary	0.00 F	*- F
61	1	NA	*RADIATOR (WCP)	Not Necessary	950.00 F	*- F
62	1	NA	*RADIATOR COVER (WCP)	Cracked	600.00 F	*600.00 F
63	1	NA	*RIGHT BONNET HINGE (WCP)	Bent	25.03 F	*25.03 F
64	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	950.00 F	*950.00 F
65	1	NA	*SCREW (WCP)	Not Necessary	1.38 F	*- F
66	1	NA	*SCREW (WCP)	Not Necessary	1.38 F	*- F
67	1	NA	*SCREW (WCP)	Not Necessary	1.38 F	*- F
68	1	NA	*SCREW (WCP)	Not Necessary	1.38 F	*- F
69	1	NA	*SCREW (WCP)	Not Necessary	2.28 F	*- F
70	1	NA	*SCREW (WCP)	Not Necessary	2.28 F	*- F
71	1	NA	*SET WIPER BLADES (WCP)	Not Necessary	43.70 F	*- F
72	1	NA	*SPECIALIST AUDATEX FEE		42.00 F	*42.00 FS
73	1	NA	*SUNDRY PARTS	Necessary	277.07 F	*100.00 FS
74	1	NA	*UPPER BONNET LOCK (WCP)	Bent	80.00 F	*80.00 F
75	1	NA	*UPPER VENT HOSE (WCP)	Not Necessary	35.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	14,172.52	6,570.37
+ Margin on L,N Items 5.00/5.00% (\$\$)	708.63	321.42
Total Parts (\$\$)	14,881.15	6,891.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	432.40	432.40
2	Total Paint Materials	New	219.45	219.45
3	Total Panel/Mechanical Labour	New	869.40	381.80
Gross Labour Cost (S\$)			1,521.25	1,033.65

Report was unsubmitted during this print-out.

< END OF ESTIMATES >