

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CTI18001188/WD3E2**Date:** 14/05/2018REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3044591601

**Claimant Vehicle  
No :** FBL6433H**Insured Vehicle  
No :** SKA6449P

Date of Loss: 15/04/2017

Nature of Claim: TP

Claim  
No: SNM17D02229C02DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBL6433H**

Make &amp; Model: YAMAHA YZF-R3, 321cc ABS

Engine No: H402E0044845

Reg. Date: 19/01/2017 (Man. Year: 2016)

Chassis No: MH3RH071000006257

Colour: Blue

Odometer: 18927 km

Engine Capacity: 321 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120-60-17

Rear Tyre Size: 160-50-17

Front Left Side: Firestone 5 mm

Rear Left Side: Firestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 18/01/2018

Date Inspected: 19/01/2018 Inspected At:

Looi's Motor Enterprise Pte. Ltd. (HQ)  
No 55 Kaki Bukit Place, Eunos Techpark  
Singapore 416230

Estimated Period of Repair: 0.0 days

**Adjuster:** Teo Cheng Ming Wilson**Manager:** Nivitha Govindasamy*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 14 May 2018)

**Parts:** N/A YAMAHA YZF-R3 321cc ABS (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBL6433H)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**