

CWS

Kenneth

ASSIGNMENT (Office)

From (Person)

Aung Yin Ming

of FCI

Date/Time: 18/01/18 @ 6.24pm

Estimated Cost:

Bill to:

OD ☒ TP WS IP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No:

SLT 3760 Y

Insured:

SHC0604 Y

at Workshop no:

K Kim Hin Auto

Tel:

64527018

of 160 Sin Ming Drive #02-20

Policy No:

Claim No:

D18000554 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/01/2018

23/01/2018 @ After 10 am.

CA / REV / REP: / REV 24 HRS

'wp'

R.O.D. Independent

Date/Time: 9.19am @ 19/1/2018

Person Contacted:

Shuman

Vehicle ID: ☒

Date/Time

Action/Instructions

☒ ☐

SLT 3760 Y - X

SHC0604 Y - CS/FCI16024291/Kgh3n2

D.O.A. 17/12/2016

25/1-

Revert prev.

16/4 @ 4000 confirm by email (Red: 1660 : 80%)

ASS. REC. BY:

REF:

1-021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

24/1 File pass to Catherine

RECEIVED 16 APR 2018

Date/Time, File Pass to?

11/6/4 Typist

Date/Time, File Return to?



Prel. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TP

400

Veh No:

SLT 37604

Yr Regn:

12, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Zay

Allian

c.c

1496

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

121295

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

N87260

3037357

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Dun

205/50R16

R: Member

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

4

mm

L/Bal.

6

mm

L/Bal.

4

mm

D.O.A.

16/1/18

D.O.I.

23/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

110
50
11
171



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001192/Ktd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 604Y	Veh. Inspected	SLT 3760Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18000554MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MING)	Assign Date	19/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/01/2018	Inspection Date	
Survey held at	160SIN MING DRIVE # 02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000554MFSH

Date: 25/1/2018

Our Ref: CS/FCI18001192/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 3760Y

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/1/2018 at the premises of M/s K Kim Hin Auto, and have the following to report: -

Workshop Estimate Amount	: S\$ 2,060.00
Revised Estimate Amount	: S\$ 400.00
"Check" Items Amount	: S\$ 1,140.00
Market Value	: S\$ -
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-01-2018	Our Ref No. D18000554MFSH
Accident Date	16-01-2018	Claim Type. Third Party
Insured Vehicle	SHC0604Y	Third Party Vehicle. SLT3760Y
Survey Location	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
Contact Person.	SHUMAN	
Contact No.	64527018/ 0	Fax No. 64583895
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/233995)



PRI Documents



Close



PRI Header Details

Claim No	D18000554MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & K. KIM HI
Workshop Name	K. KIM HIN AUTO PTE LTD (Contact Person : SHUMAN)	Survey Location & Contact Details	160 Sin Ming Drive #02-20SIN MING AUTOCITY Mobile: 0 , Phone: 64527018 , Fax: 64583895 EmailId: ADMIN1@KKIMHIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM *		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0604Y	TP Vehicle No	SLT3760Y
PRI Recieved Date	18-01-2018 05:07:45 PM	Surveyor Appointed Date	18-01-2018 06:22:47 PM	Surveyor Accept Date	19-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 25 January 2018 5:38 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;
AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000554MFSH/1
Attachments: PRELI ADVISED SLT 3760Y.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLT 3760Y**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 19 January 2018 9:21 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
<sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000554MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 18 January 2018 6:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000554MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	42861
Vehicle Details	
Vehicle No.:	SLT3760Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZD283144
Chassis No.:	NZT2603037357
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$17,843.00
Original Registration Date:	22 Dec 2008
First Registration Date:	22 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$17,843.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2018
PARF Rebate Amount:	\$8,921.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,200.00
COE Rebate Amount:	\$573.00
Total Rebate Amount:	\$9,494.00

The information contained herein is correct as at 18 Jan 2018

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29463

Vehicle Insured : SHC 604 Y
Accident Date : 16-Jan-2018

Date : 20-Jan-2018

Our Ref : 180044 (FIRST) / SHUMAN

PAGE : 1

HENG PECK HIAN LILIAN (MS)
Singapore

Not Withheld

ESTIMATED COST OF REPAIR FOR TOYOTA ALLION 1.5A (2008) SLT3760Y

1 pc rear bumper
10 pcs rear bumper clips

@ S\$ 5.50

R 1,465.00 *X*
nn 55.00 *X*

1,520.00

Less 25% : -380.00

1,140.00

1 pc reverse sensor

sn 220.00 *sn X*

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

300.00 *1801*

To putty and respray on affected
portions.

400.00 *2201*

Total : S\$ 2,060.00

Singapore Dollars Two Thousand and Sixty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001192/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 604Y	Veh. Inspected	SLT 3760Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18000554MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	18/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALLION (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZT2603037357	Colour	METALLIC SILVER	
Odometer	121295	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	DUNLOP	6 mm	
L/H Front Tyre	205/50 R16	DUNLOP	6 mm	
R/H Rear Tyre	205/50 R16	MEMBAT	4 mm	
L/H Rear Tyre	205/50 R16	MEMBAT	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/01/2018	Inspection Date	23/01/2018	
Survey held at	160 SIN MING DRIVE # 02-20			
Repairer	K KIM HIN AUTOMOTIVE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3760Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,465.00	-
10	REAR BUMPER CLIPS @\$5.50	NOT NECESSARY	55.00	-
	LESS 25% DISCOUNT		-380.00	-
			1,140.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
			220.00	-
	<u>LABOUR</u>			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		300.00	180.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		400.00	220.00
			700.00	400.00
	GRAND TOTAL		2,060.00	400.00
RECOMMENDED COST OF REPAIRS				400.00

Report Ref No. CS/FCI18001192/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.