

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

AXA
22/01 Mon
after 11am.

*Not Authorised
L1 Lp @ 1500
Resurvey After Repair
3 days*

15/01/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA AXIO - SLN6327C

1pc	rear tailgate
1pc	rear tailgate "COROLLA" emblem
1pc	rear tailgate "AXIO" emblem
1pc	rear tailgate "TOYOTA" logo
1pc	rear tailgate "G" emblem
1pc	rear LH taillamp
1pc	rear LH taillamp lower bracket
1pc	rear bumper
1pc	rear bumper LH side retainer
1pc	rear bumper LH reflector
1pc	rear bumper LH side garnish
1pc	rear end panel

<i>R</i>	\$ 1,218.45	<i>X</i>
<i>mc</i>	\$ 83.10	<i>—</i>
<i>mc</i>	\$ 83.90	<i>—</i>
<i>mc</i>	\$ 61.10	<i>—</i>
<i>mc</i>	\$ 63.90	<i>✓</i>
<i>ngcm</i>	\$ 374.75	<i>?</i>
<i>cm</i>	\$ 132.10	<i>+</i>
<i>Buc</i>	\$ 561.60	<i>—</i>
<i>dis</i>	\$ 132.10	<i>—</i>
<i>sn</i>	\$ 141.45	<i>Y</i>
<i>sn</i>	\$ 182.10	<i>X</i>
<i>R</i>	\$ 781.10	<i>X</i>

less 25%

\$ 3,815.65
\$ 953.91
\$ 2,861.74

1set rear parking sensor

sn s.nett \$ 280.00 *X*

wiring
tuffkote
spray painting
labour charges
Total

\$ 50.00 *15%*
mc \$ 60.00 *X*
\$ 800.00 *4401*
\$ 900.00 *3501*
\$ 4,951.74



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: