

ASS. REC. BY:

REF: C3/CT18001225 / Agber

Special Instruction:

SIGNATOR: Madamen

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 19/12/2018 4:38pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: ABC 4626H Insured:

at Workshop m/s SMRT Tel: 6555 5556

of 60 Woodlands Ind Park Est

Policy No: DMCVSN3065.8717000 Claim No: SNM18D00125C01

Sum Insured: Excess: \$ 450.00

Make of Veh: D.O.A. 09/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

22/01/2018 @ Lee Sheng (Blk 1 Kaki Bukit Ave 6 # 01-60) H.O.D. Endorsement:

Date/Time: 19/01/2018 5:20pm Person Contacted: Esther Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	ABC 4626H - x
23/1/18 @ 2:23pm	visit to Irene Tay via Madamen.
23/1/18 @ 4:26pm	Susan Teo informed C/A at B22602.07 via Madamen.
24/1/18 @ 9:24a	informed Esther C/A & Ex: \$ 450 by email.
28/2/18	confirmed with Esther final fig \$ 17308.81, 8 days. (Led \$ 7943.26, 312.)

Date 22/01/18

GBG4626H

2017 August

Estimated Cost

Type M/Car/M Cycle Bus Gory Taxi/Prime Mover

TP/WS TP RES OD RES EVA/IN/VM

Truck/Trailer or

To inspect Vehicle No GBG 4626 H
at Workshop/MS Lee Sheng SMRT

Make Nissan NV200 Chassis 1597

Colour Black

of BIK 1, Kaki Bkt Ave 6 # 01-60

So Reading 10101

Insured

Eng No

Policy No

Ch No VM20115453

Claims No

Gen Cond Good Fair Poor Burnt

Sum Insured Excess TBA

Steering In order / Jammed / Leaked / Burnt or

Clients Record

Brake In order / Jammed / Leaked / Burnt or

Make of Veh


Modif SRim / STD A/Rim or

(Policy Condition)

Tyre Size F: 165/80R14

R: 165/80R14

Remark: The veh had commenced its repair at the time of inspection.



BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI

TOYO-YOKO or

Est. or Market Value: 70K.

Front

Rear

DAD Accident Report Consistent? : Yes or No

R.Bal. 06 mm P.Bal. 06 mm

DIA PP Seen Consistent? : Yes or No

L.Bal. 06 mm L.Bal. 06 mm

Est. Repair: 8 days Res: Yes or No

D.O.A. D.C. 22/01/18

Sum Surg: % B/val: Yes or No

Survey held at: to SMRT

CA REV REP. / 24 HRS

Des. of Damages Rear OS NS UIC Roof hood or

Date Person Contacted

The UIC Chassis frame Body Structure affected due to collision

Date Time Action/ Instruction

OD Chiu.

RECEIVED 22 JAN 2018

Date Time File Pass to Prelim. Report

Days Of Repair: 8

76260

01/3/18 Final Report

Resurvey No. of Trip: 1

Sum. Fee

Date Time File Returned

Add Fee: Site Insp. \$

Temp. Fee

Report Format

WER-OD

17508.81

- Site Insp. \$
- Night \$
- Test \$
- Rep. \$

270
270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18001225/Aqb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 19-01-2018	
		Code : CTI	
1. Policy Particulars : OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBG 4626H
Policy No.	DMCVSN30658717000	Coverage (\$)	0.00
Claim No.	SNM18D00125C01	Excess (\$)	450.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	19/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Engine No.	HIDDEN	Accident Date	07/01/2018
		Inspection Date	19/01/2018
Survey held at	BLK 1 KAKI BUKIT AVE 6 #01-60		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)			
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jan 2018 Sendback Est	19 Jan 2018 15:19 S\$25,452.07	19 Jan 2018 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS	
Insured:	M/S ETONG ALUMINIUM ENGINEERING PTE LTD, Co. Reg. No.: 21207626D
Vehicle Reg. No.:	GBG4626H
Date of Loss:	07/01/2018 15:00 - :59
Claim Type:	OD / SNM18D00125C01
Policy/Cover Note No.:	DMCVSN30658717000 (Comprehensive) Coverage: 17/08/2017 - 16/08/2018
Excess:	S\$450.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2018]
Driver/Custodian:	MEI JILONG (/ Male), NRIC: S8775780C
Adj Asp. Remarks:	PLEASE ASSIST TO SURVEY AND REVERT
ASSOCIATED MAIL RECEIVED	
There are no mail for this case.	
ALL ASSOCIATED TASKS	
No results.	

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 1 March 2018 3:48 PM
To: 'Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)'
Subject: FINALISE OF GBG 4626H (DOA: 07/01/2018)

Dear Esther,

As spoken with you yesterday.

Confirm final fig \$17,508.81 before excess \$450.00 & GST and 8 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 24 January 2018 9:24 AM
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Cc: SUR
Subject: VEHICLE GBG 4626H (DOA: 07/01/2018)

Dear Esther,

As instructed by our client, please proceed to repair the insured vehicle **GBG 4626H (Excess \$450/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Action	Remarks	By
1	19 Jan 2018 11:35	Clim Veh Model Changed	(205175) NISSAN NV200 1.6 DX-2 (A).	[R] Tey Chor Keng
2	19 Jan 2018 11:35	Clim Created	Reg No: GBG4626H. Policy No: DMCVSN30658717000. Acct Date: 2018/01/07. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: SMRT Automotive Services Pte Ltd (Woodlands)	[R] Tey Chor Keng
3	19 Jan 2018 12:15	Clim Submitted	26469.79.	[R] Tey Chor Keng
4	19 Jan 2018 15:18	Ins Sent Back Est	MARKUP TO CHANGE TO 5%	[I] Chong Boon Sen
5	19 Jan 2018 15:19	Clim Submitted	25452.07.	[R] Tey Chor Keng
6	19 Jan 2018 16:38	Clim Registration Modified	Excess: -> 450.00.	[I] Irene Tay Hui Ping
7	19 Jan 2018 16:38	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE ASSIST TO SURVEY AND REVERT	[I] Irene Tay Hui Ping
8	19 Jan 2018 16:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/30	[I] Irene Tay Hui Ping
9	19 Jan 2018 16:38	Adj Mandate Set	Approved:0.00.	[I] Irene Tay Hui Ping
10	19 Jan 2018 17:08	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
11	19 Jan 2018 17:38	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
12	23 Jan 2018 13:45	Adj Rpt Initiated		[A] SHIAU CHAN
13	23 Jan 2018 14:22	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/30	[A] SHIAU CHAN
14	23 Jan 2018 14:23	Adj Mandate Request	Cur Req:22602.07:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	23 Jan 2018 17:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/30	[I] Susan Teo
16	23 Jan 2018 17:26	Adj Mandate Set	Approved:22602.07.	[I] Susan Teo

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	App Type	Bill Name	Bill Name (Original)	Policy No.	Amount
1699960	19/01/2018 11:35	Motor	SMRT Automotive Services Pte Ltd (Woodlands)	SMRT Automotive Services Pte Ltd (Woodlands)	GBG4626H	xx.xx
1702937	23/01/2018 13:45	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBG4626H	10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 23 Jan 2018

Preliminary Advice

Vehicle No	: GBG4626H	Accident Date	: 07/01/2018
Make	: NISSAN NV200	Policy No.	: DMCVSN30658717000
Assignment Date	: 19/01/2018	Excess	: S\$450.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 8.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,452.07
Revised Amount	:S\$	14,236.75
Check Items (Estimated)	:S\$	8,365.32
Total	:S\$	22,602.07

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	40,944.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,056.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 7626D

Vehicle Details

Vehicle No.: GBG4626H
Vehicle to be Exported: No
Intended De-registration Date: 23 Jan 2018
Vehicle Make: NISSAN
Vehicle Model: NV200 VANETTE
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: HR16100704D
Chassis No.: VM20115453
Maximum Power Output: -
Open Market Value: \$20,834.00
Original Registration Date: 17 Aug 2017
First Registration Date: 17 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$1,042.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Aug 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$42,809.00
COE Rebate Amount: \$40,944.00
Total Rebate Amount: \$40,944.00

The information contained herein is correct as at 23 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate** as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2018 16:42
Date Of Accident	07/01/2018 15:40
Exact Location Of Accident	PIE THOMSON FLYOVER TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG4626H
Insured/Policyholder	
Name Of Registered Owner	M/S ETONG ALUMINIUM ENGINEERING PTE LTD
Co Reg No	21207626D
Email Address	ETONG.JILONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91124769
Alternative Phone No	OFFICE-65155220
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200-1.6 DX (A)
Exact Purpose for which vehicle was being used at time of accident	BUSINESS
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN30658717000
Cover Note Number	

Driver	
Name of Driver	MEI JILONG
NRIC No	S8775780C
Date Of Birth	19/08/1987
Occupation	INDOOR
Date Of Driving Pass	14/08/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91124769
Fax Number	
Contact Number	
EMail Address	ETONG.JILONG@GMAIL.COM

Address BLK 790 WOODLAND AVE 6
 #05-651
 Postcode 730790
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : LUAN SIMIN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU744J
 Vehicle Make/Model/Colour JAGUAR/ F-PACE
 Details Of Properties BUMPER
 Vehicle Category PRIVATE CAR
 Name of Driver CHOONG KUOK LOON
 NRIC/Passport Number S9233154G
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJN3566Y
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	REAR BUMPER
Vehicle Category	PRIVATE CAR
Name of Driver	WANG TEE HAU DAVE
NRIC/Passport Number	S0263503H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. **The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.**
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
 Date & Time: 08/01/2018
 4:30 PM

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 08/01/2018

Reporting Centre Personnel's Signature
 Name: NURAZAH OSMAN
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07th Jan 2018 about 3.40 PM, I drive company van G86 462 LA to office for weekly meeting, at Thomson area. I saw there was Road work at Lane 1, so I change lane to lane 2. I saw there was a bit jam in front so I slow down the speed, but suddenly the front SUV (SLU 744 J) stop, I immediately press the break but it was too late my van hit the front car (SLU 744 J) and the air bag also come out, after I come out from my van, I realised there was another car (SUN 35 02 Y) also hit. We (the three car drivers) exchanged contact number and recorded each other's IC. there was no body injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 08/01/2018
4:35 PM

Driver's Signature

(if driver is not the policyholder)

Date & Time: 08/01/2018
4:35 PM

THE CHINA MOTOR SALES PTE LTD
 010 001 111 1111
 111 111 111 111
 111 111 111 111
 111 111 111 111

Reporting Centre Personnel's Signature

Name: ALI ALI ALI
NRIC/FIN No.:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

M2300/C
N SM
AN0472A
COMPREHENSIVE
AUTOSAFE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMCVSNJ065871700	Engine No : HR16100704D
		Chassis No: VM20115453
1. Index Mark and Registration Number of Vehicle	GBG4626H	
2. Name of Policy Holder	M/S ETONG ALUMINIUM ENGINEERING PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations Ordinance or Enactment	17 AUGUST 2017 (11:20 HOURS)	EX SECT. IS\$450.00 EX ON WINDSCREENS\$100.00
4. Date of Expiry of Insurance	16 AUGUST 2018	
5. Persons or Classes of Persons entitled to drive *		

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

- (1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
 - (2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
 - (3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES.
- THE POLICY DOES NOT COVER:
- (1) USE FOR HIRE OR REWARD OR RACING, FACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING.
 - (2) USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPPLED VEHICLE.

HIRE PURCHASE CO. : UNITED OVERSEAS BANK LIMITED AS HP OWNER

* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under those headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

COI INSURANCE AGENCY PTE LTD
10006
10006
10006
10006
10006

Countersigned By: _____
Authorised Officer

Authorised Signatory

AUTHORISATION LETTER Pg. 1



懿通铝业工程私人有限公司
ETONG ALUMINIUM ENGINEERING PTE LTD

Nissan Bukit Timah Service Center
913 Bukit Timah Road Singapore 589623
08th Jan 2018

Car Accident at PIE on 07th Jan 2018

We refer to the above accident, hereby authorize Mei Ji Long (S8775780C) to make the accident report.

Sincerely yours,

Chen Li Xin

Managing Director

Etong Aluminium Engineering Pte Ltd

Telephone : +65 6515 5220

Facsimile : +65 6515 5320

Email : etong@etong.com.sg

Address : 48 Toh Guan Road East

#03-140/141/142

Enterprise Hub Singapore 608586

bizSAFE
S E C U R E

EQAIIC
S E C U R E

SMRT Automotive Services Pte Ltd (Co.Reg.No:199004280Z)

60 Woodlands Industrial Park E4

Singapore 757705

Tel: 68662628 Fax: 63687421 Email: feiyuan@smrt.com.sg;wongkokwah@smrt.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WL/JAN2018/010
Policy No:	DMCVSN30658717000	Date of Loss:	07/01/2018
Vehicle Reg. No.:	GBG4626H	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	M/S ETONG ALUMINIUM ENGINEERING PTE LTD		
Driver:	MEI JILONG		
Make/Model:	NISSAN NV200, 1.6 DX-2 (A)	Vehicle Reg. Date:	17/08/2017
Vehicle Colour:	BLACK		
Engine No:	HR16100704D	Chassis No:	VM20115453
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	28		
Description of Accident/Loss	PLEASE REFER TO THE ATTACHED SAS REPORT.		
Remarks:	PLEASE CONTACT ESTHER AT TEL 6555-5556 TO ARRANGE FOR SURVEY.		

Present Location: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)

COST OF CLAIMS	Amount
Parts	21,372.07
Miscellaneous Items	930.00
Labour	1,600.00
Paintwork Labour	1,500.00
Towing	50.00
Gross Total (S\$)	25,452.07
+ GST 7.00% (S\$)	1,781.64
Nett Amount (S\$)	27,233.71

This claim is handled by: TEY CHOR KENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS	
Reference	
Part Source:	(Last Synchronised: 19 Jan 2018)
Parts:	N/A NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET <i>Deleted</i>	0.00	0.00	*500.00 F	✓
2	1		*HINGE RH <i>Best</i>	0.00	0.00	*50.00 F	✓
3	1		*HINGE LH	0.00	0.00	*50.00 F	✓
4	1		*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*375.00 F	✓
5	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*125.00 F	✓
6	1		*FRONT BUMPER RETAINER RH <i>3mm</i>	0.00	0.00	*125.00 F	✓
7	1		*FRONT BUMPER TOWING COVER <i>Missing</i>	0.00	0.00	*25.00 F	✓
8	1		*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*350.00 F	✓
9	1		*FRONT BUMPER FOAM <i>could</i>	0.00	0.00	*181.25 F	✓
10	1		*FRONT GRILLE <i>could</i>	0.00	0.00	*250.00 F	✓
11	1		*FRONT GRILLE MOULDING <i>Deleted</i>	0.00	0.00	*187.50 F	✓
12	1		*FRONT GRILLE EMBLEM <i>me</i>	0.00	0.00	*50.00 F	✓
13	1		*FRONT HEADLAMP LOWER GARNISH RH <i>Deleted</i>	0.00	0.00	*193.75 F	✓
14	1		*FRONT HEADLAMP LOWER GARNISH LH <i>Deleted</i>	0.00	0.00	*193.75 F	✓
15	1		*HEADLAMP RH <i>could</i>	0.00	0.00	*281.25 F	✓
16	1		*HEADLAMP LH	0.00	0.00	*281.25 F	✓
17	1		*BONNET LOCK <i>only d</i>	0.00	0.00	*50.00 F	✓
18	1		*BONNET CABLE <i>me new</i>	0.00	0.00	*43.75 F	X
19	1		*SUPPORT PANEL ASSY <i>?</i>	0.00	0.00	*250.00 F	?
20	1		*HEADLAMP PANEL LH <i>from ?</i>	0.00	0.00	*81.25 F	?
21	1		*HEADLAMP PANEL RH	0.00	0.00	*81.25 F	?
22	1		*AIR CON CONDENSER <i>Deleted</i>	0.00	0.00	*687.50 F	✓
23	1		*RADIATOR <i>?</i>	0.00	0.00	*600.00 F	?
24	2		*AIR CON CONDENSER PIPE <i>?</i>	0.00	0.00	*437.50 F	?
25	2		*AIR CON CONDENSER HOSE <i>?</i>	0.00	0.00	*437.50 F	?
26	1		*RADIATOR TOP HOSE <i>twisted</i>	0.00	0.00	*43.75 F	✓
27	1		*RADIATOR LOWER HOSE <i>me</i>	0.00	0.00	*56.25 F	X
28	1		*RADIATOR FAN SHROUD <i>?</i>	0.00	0.00	*93.75 F	✓
29	1		*RADIATOR FAN MOTOR <i>?</i>	0.00	0.00	*250.00 F	?
30	1		*RADIATOR FAN BLADE <i>?</i>	0.00	0.00	*81.25 F	?
31	1		*DEFLECTOR RADIATOR RH <i>?</i>	0.00	0.00	*68.75 F	?
32	1		*DEFLECTOR RADIATOR LH <i>Deleted</i>	0.00	0.00	*68.75 F	✓
33	1		*AIR CLEANER INLET DUCT <i>Deleted</i>	0.00	0.00	*75.00 F	✓
34	1		*AIR INLET DUCT HOSE <i>me Deleted</i>	0.00	0.00	*93.75 F	✓
35	1		*AIR CLEANER ASSY <i>?</i>	0.00	0.00	*568.75 F	?
36	1		*RADIATOR SPARE TANK <i>Deleted</i>	0.00	0.00	*87.50 F	✓
37	1		*COOLANT <i>me</i>	0.00	0.00	*25.00 F	✓
38	1		*FRONT FUSE BOX ASSY <i>?</i>	0.00	0.00	*243.75 F	?
39	1		*BATTERY <i>?</i>	0.00	0.00	*150.00 F	?
40	1		*BATTERY TRAY <i>?</i>	0.00	0.00	*22.50 F	?
41	1		*BATTERY BRACKET <i>?</i>	0.00	0.00	*62.50 F	?
42	1		*INTAKE MANIFOLD <i>?</i>	0.00	0.00	*968.70 F	?

SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*ALTERNATOR ?	0.00	0.00	*1,987.00 F ?
44	1		*AIR CON COMPRESSOR ?	0.00	0.00	*909.90 F ?
45	1		*WIPER WASHER JAR <i>fixed</i>	0.00	0.00	*156.25 F ✓
46	1		*FRONT FENDER RH <i>fixed</i>	0.00	0.00	*375.00 F ✓
47	1		*FRONT FENDER INNER SHIELD RH <i>new</i>	0.00	0.00	*106.25 F ✓
48	1		*FRONT FENDER LH <i>fixed</i>	0.00	0.00	*375.00 F ✓
49	1		*FRONT FENDER INNER SHIELD LH <i>new</i>	0.00	0.00	*106.25 F ✓
50	1		*FRONT FENDER LAMP RH <i>new</i>	0.00	0.00	*37.50 F ✓
51	1		*FRONT FENDER LAMP LH	0.00	0.00	*37.50 F ✓
52	1		*FRONT QUARTER GLASS RH <i>new</i>	0.00	0.00	*250.00 F ✓
53	1		*FRONT QUARTER GLASS LOWER GARNISH RH <i>new</i>	0.00	0.00	*56.25 F ✓
54	1		*FRONT QUARTER GLASS LH <i>new</i>	0.00	0.00	*250.00 F ✓
55	1		*FRONT QUARTER GLASS LOWER GARNISH LH <i>new</i>	0.00	0.00	*56.25 F ✓
56	1		*QUARTER GLASS GLUM <i>new</i>	0.00	0.00	*50.00 F ✓
57	1		*DASHBOARD AIR BAG <i>Activated</i>	0.00	0.00	*1,875.00 F ✓
58	1		*STEERING AIR BAG	0.00	0.00	*1,687.50 F ✓
59	1		*STEERING CLOCK WIRE <i>Activated</i>	0.00	0.00	*218.75 F ✓
60	1		*AIR BAG CONTROL UNIT <i>Activated</i>	0.00	0.00	*937.50 F ✓
61	1		*FRONT SEAFETY BELT RH <i>Activated</i>	0.00	0.00	*625.00 F ✓
62	1		*FRONT SAFETY BELT LH <i>Act?</i>	0.00	0.00	*625.00 F ?
63	2		*AIR BAG SENSOR <i>Activated</i>	0.00	0.00	*750.00 F ✓
64	1		*FRONT NUMBER PLATE <i>fixed</i>	0.00	0.00	*20.00 F ✓
65	1		*FRONT NUMBER PLATE CASING <i>fixed</i>	0.00	0.00	*15.00 F ✓

F=Franchise part.

Sub Total (S\$)	20,354.35
+ Margin on L,N Items 5.00% (S\$)	1,017.72
Total Parts (S\$)	21,372.07

SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	ALIGNMENT	80.00 +
2	1	TO REMOVE & REFIX DASHBOARD /REPLACE AIR BAG ETC	350.00 300
3	1	TO REMOVE & REFIX ENGINE TO FACILITATE REPAIR	450.00 +
4	1	WIRING	50.00 30
Sub Total (S\$)			930.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO SPRAY PAINTING ON FRONT BONNET/FENDER LH & RH / BUMPER /SUPPORT / BUMPER REINFORCEMENT ETC	New	1,500.00 900
Labour Items			
2	TO REMOVE & REFIX / ALIGN CHASSIS /WELDING ETC	New	1,000.00 600
Gross Labour Cost (S\$)			3,100.00

SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lim
P/P 22/01/18
Not Authorised

Excess : To be advised.
08 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMRT Automotive Services Pte Ltd (Co.Reg.No:199004280Z)

60 Woodlands Industrial Park E4

Singapore 757705

Tel: 68662628 Fax: 63687421 Email: feiyuan@smrt.com.sg;wongkokwah@smrt.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WL/JAN2018/010
Policy No:	DMCVSN30658717000	Date of Loss:	07/01/2018
Vehicle Reg. No.:	GBG4626H	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES

Insured/Claimant: M/S ETONG ALUMINIUM ENGINEERING PTE LTD

Driver: MEI JILONG

Make/Model:	NISSAN NV200, 1.6 DX-2 (A)	Vehicle Reg. Date:	17/08/2017
Vehicle Colour:	BLACK		
Engine No:	HR16100704D	Chassis No:	VM20115453
Odometer:	0 KM		

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) 28

Description of Accident/Loss PLEASE REFER TO THE ATTACHED SAS REPORT.

Remarks: PLEASE CONTACT ESTHER AT TEL 6555-5556 TO ARRANGE FOR SURVEY.

Present Location: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)

COST OF CLAIMS	Amount
Parts	21,372.07
Miscellaneous Items	930.00
Labour	1,600.00
Paintwork Labour	1,500.00
Towing	50.00
Gross Total (S\$)	25,452.07
+ GST 7.00% (S\$)	1,781.64
Nett Amount (S\$)	27,233.71

This claim is handled by: TEY CHOR KENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jan 2018)
 Parts: N/A NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET <i>Replaced</i>	0.00	0.00	*500.00F	✓
2	1		*HINGE RH <i>3 Bent</i>	0.00	0.00	*50.00F	✓
3	1		*HINGE LH	0.00	0.00	*50.00F	✓
4	1		*FRONT BUMPER <i>Dislatched</i>	0.00	0.00	*375.00F	✓
5	1		*FRONT BUMPER RETAINER LH <i>3mm</i>	0.00	0.00	*125.00F	✓
6	1		*FRONT BUMPER RETAINER RH	0.00	0.00	*125.00F	✓
7	1		*FRONT BUMPER TOWING COVER <i>Miscary</i>	0.00	0.00	*25.00F	✓
8	1		*FRONT BUMPER REINFORCEMENT <i>Bent</i>	0.00	0.00	*350.00F	✓
9	1		*FRONT BUMPER FOAM <i>could</i>	0.00	0.00	*181.25F	✓
10	1		*FRONT GRILLE <i>could</i>	0.00	0.00	*250.00F	✓
11	1		*FROT GRILLE MOULDING <i>Replaced</i>	0.00	0.00	*187.50F	✓
12	1		*FRONT GRILLE EMBLEM <i>in</i>	0.00	0.00	*50.00F	✓
13	1		*FRONT HEADLAMP LOWER GARNISH RH <i>3 Replaced</i>	0.00	0.00	*193.75F	✓
14	1		*FRONT HEADLAMP LOWER GARNISH LH	0.00	0.00	*193.75F	✓
15	1		*HEADLAMP RH <i>3 could</i>	0.00	0.00	*281.25F	✓
16	1		*HEADLAMP LH	0.00	0.00	*281.25F	✓
17	1		*BONNET LOCK <i>changed</i>	0.00	0.00	*50.00F	✓
18	1		*BONNET CABLE <i>Not New Bent</i>	0.00	0.00	*43.75F	X
19	1		*SUPPORT PANEL ASSY <i>Bent</i>	0.00	0.00	*250.00F	✓
20	1		*HEADLAMP PANEL LH <i>from Bent</i>	0.00	0.00	*81.25F	✓
21	1		*HEADLAMP PANEL RH	0.00	0.00	*81.25F	✓
22	1		*AIR CON CONDENSER <i>Replaced</i>	0.00	0.00	*687.50F	✓
23	1		*RADIATOR <i>Bent</i>	0.00	0.00	*600.00F	✓
24	2		*AIR CON CONDENSER PIPE <i>new</i>	0.00	0.00	*437.50F	X
25	2		*AIR CON CONDENSER HOSE <i>new</i>	0.00	0.00	*437.50F	X
26	1		*RADIATOR TOP HOSE <i>twisted</i>	0.00	0.00	*43.75F	✓
27	1		*RADIATOR LOWER HOSE <i>new</i>	0.00	0.00	*56.25F	X
28	1		*RADAITOR FAN SHROUD <i>could</i>	0.00	0.00	*93.75F	✓
29	1		*RADAITOR FAN MOTOR <i>3rd</i>	0.00	0.00	*250.00F	✓
30	1		*RADIATOR FAN BLADE <i>3rd</i>	0.00	0.00	*81.25F	✓
31	1		*DEFLECTOR RADIATOR RH <i>Replaced</i>	0.00	0.00	*68.75F	✓
32	1		*DEFLECTOR RADIATOR LH <i>Replaced</i>	0.00	0.00	*68.75F	✓
33	1		*AIR CLEANER INLET DUCT <i>Replaced</i>	0.00	0.00	*75.00F	✓
34	1		*AIR INLET DUCT HOSE <i>new Replaced</i>	0.00	0.00	*93.75F	X
35	1		*AIR CLEANER ASSY <i>ext</i>	0.00	0.00	*568.75F	✓
36	1		*RADIATOR SPARE TANK <i>Replaced</i>	0.00	0.00	*87.50F	✓
37	1		*COOLANT <i>in</i>	0.00	0.00	*25.00F	✓
38	1		*FRONT FUSE BOX ASSY <i>Replaced</i>	0.00	0.00	*243.75F	✓
39	1		*BATTERY <i>Replaced</i>	0.00	0.00	*150.00F	✓
40	1		*BATTERY TRAY <i>Replaced</i>	0.00	0.00	*22.50F	✓
41	1		*BATTERY BRACKET <i>new</i>	0.00	0.00	*62.50F	X
42	1		*INTAKE MANIFOLD <i>new</i>	0.00	0.00	*968.70F	X

SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*ALTERNATOR <i>Not in</i>	0.00	0.00	*1,987.00 F ✓
44	1		*AIR CON COMPRESSOR <i>Not in</i>	0.00	0.00	*909.90 F ✓
45	1		*WIPER WASHER JAR <i>Not in</i>	0.00	0.00	*156.25 F ✓
46	1		*FRONT FENDER RH <i>Not in</i>	0.00	0.00	*375.00 F ✓
47	1		*FRONT FENDER INNER SHIELD RH <i>Not in</i>	0.00	0.00	*106.25 F ✓
48	1		*FRONT FENDER LH <i>Not in</i>	0.00	0.00	*375.00 F ✓
49	1		*FRONT FENDER INNER SHIELD LH <i>Not in</i>	0.00	0.00	*106.25 F ✓
50	1		*FRONT FENDER LAMP RH <i>Not in</i>	0.00	0.00	*37.50 F ✓
51	1		*FRONT FENDER LAMP LH <i>Not in</i>	0.00	0.00	*37.50 F ✓
52	1		*FRONT QUARTER GLASS RH <i>Not in</i>	0.00	0.00	*250.00 F ✓
53	1		*FRONT QUARTER GLASS LOWER GARNISH RH <i>Not in</i>	0.00	0.00	*56.25 F ✓
54	1		*FRONT QUARTER GLASS LH <i>Not in</i>	0.00	0.00	*250.00 F ✓
55	1		*FRONT QUARTER GLASS LOWER GARNISH LH <i>Not in</i>	0.00	0.00	*56.25 F ✓
56	1		*QUARTER GLASS GLUM <i>Not in</i>	0.00	0.00	*50.00 F ✓
57	1		*DASHBOARD AIR BAG <i>Activated</i>	0.00	0.00	*1,875.00 F ✓
58	1		*STEERING AIR BAG <i>Activated</i>	0.00	0.00	*1,687.50 F ✓
59	1		*STEERING CLOCK WIRE <i>Activated</i>	0.00	0.00	*218.75 F ✓
60	1		*AIR BAG CONTROL UNIT <i>Activated</i>	0.00	0.00	*937.50 F ✓
61	1		*FRONT SEAFETY BELT RH <i>Activated</i>	0.00	0.00	*625.00 F ✓
62	1		*FRONT SAFETY BELT LH <i>Activated</i>	0.00	0.00	*625.00 F ✓
63	2		*AIR BAG SENSOR <i>Activated</i>	0.00	0.00	*750.00 F ✓
64	1		*FRONT NUMBER PLATE <i>Not in</i>	0.00	0.00	*20.00 F ✓
65	1		*FRONT NUMBER PLATE CASING <i>Not in</i>	0.00	0.00	*15.00 F ✓

F=Franchise part.

Sub Total (S\$)	20,354.35
+ Margin on L,N Items 5.00% (S\$)	1,017.72
Total Parts (S\$)	21,372.07

SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

14551.25

+ 5% : 15278.81

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	ALIGNMENT	80.00 +
2	1	TO REMOVE & REFIX DASHBOARD /REPLACE AIR BAG ETC	360.00 300
3	1	TO REMOVE & REFIX ENGINE TO FACILITATE REPAIR	450.00 +
4	1	WIRING	50.00 30
330			Sub Total (\$\$) 930.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO SPRAY PAINTING ON FRONT BONNET/FENDER LH & RH / BUMPER /SUPPORT / BUMPER REINFORCEMENT ETC	New	1,500.00 900
<u>Labour Items</u>			
2	TO REMOVE & REFIX / ALIGN CHASSIS /WELDING ETC	New	1,600.00 1000
1900			Gross Labour Cost (\$\$) 3,100.00

SMRT Automotive Services Pte Ltd/GBG4626H/19/01/2018 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total: 1750881 (P/P)
 Adrian Ling
 P/P 22/01/18
 not Authorised
 Excess: To be advised.
 08 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jan 2018 Sendback Est	19 Jan 2018 15:19 S\$25,452.07	19 Jan 2018 16:38 Edit Adj Rpt	S\$17,508.81 Edit Estimates	S\$17,508.81 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	M/S ETONG ALUMINIUM ENGINEERING PTE LTD, Co. Reg. No.: 21207626D		
Vehicle Reg. No.:	GBG4626H	Date of Loss:	07/01/2018 15:00 - :59
Claim Type:	OD / SNM18D00125C01	Policy/Cover Note No.:	DMCVSN30658717000 (Comprehensive) Coverage: 17/08/2017 - 16/08/2018
		Excess:	S\$450.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/01/2018]		
Driver/Custodian:	MEI JILONG (/ Male), NRIC: S8775780C		
Adj Asg. Remarks:	PLEASE ASSIST TO SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
• CHINA_TAIPING (23/01/2018): Alert - Adj Mandate Approved (S\$22602.07) - GBG4626H - Claim Handler: Irene Tay ...		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

GBG4626H (SNM18D00125C01)

OD

Jan 7 2018 3:00PM

[M/S ETONG ALUMINIUM ENGINEERING PTE LTD]

SMRT Automotive Services Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print
1	19/01/18 15:19	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/01/18 14:22	Adjuster Immediate Advice	1	Load HTM	
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	26/02/18 10:03	General View	1	Load JPG	<input checked="" type="checkbox"/>

31	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
32	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
33	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
34	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
35	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
36	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
37	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
38	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
39	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
40	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
41	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
42	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
43	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
44	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
45	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
46	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
47	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
48	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
49	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
50	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
51	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
52	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
53	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
54	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
55	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
56	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
57	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
58	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
59	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
60	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
61	26/02/18 10:03	General View		Load JPG	<input checked="" type="checkbox"/>
62	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	26/02/18 10:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

79	26/02/18 10:03	Reinspection Photo		Load JPG	
80	26/02/18 10:03	Reinspection Photo		Load JPG	
81	26/02/18 10:03	Reinspection Photo		Load JPG	
82	26/02/18 10:03	Reinspection Photo		Load JPG	
83	26/02/18 10:03	Reinspection Photo		Load JPG	
84	26/02/18 10:03	Reinspection Photo		Load JPG	
85	26/02/18 10:03	Reinspection Photo		Load JPG	
86	26/02/18 10:03	Reinspection Photo		Load JPG	
87	26/02/18 10:03	Reinspection Photo		Load JPG	
88	26/02/18 10:03	Reinspection Photo		Load JPG	
89	26/02/18 10:03	Reinspection Photo		Load JPG	
90	26/02/18 10:03	Reinspection Photo		Load JPG	
91	26/02/18 10:03	Reinspection Photo		Load JPG	
92	26/02/18 10:03	Reinspection Photo		Load JPG	
93	26/02/18 10:03	Reinspection Photo		Load JPG	
94	26/02/18 10:03	Reinspection Photo		Load JPG	
95	26/02/18 10:03	Reinspection Photo		Load JPG	
96	26/02/18 10:03	Reinspection Photo		Load JPG	
97	26/02/18 10:03	Reinspection Photo		Load JPG	
98	26/02/18 10:03	Reinspection Photo		Load JPG	
99	26/02/18 10:03	Reinspection Photo		Load JPG	
100	26/02/18 10:03	Reinspection Photo		Load JPG	
101	26/02/18 10:03	Reinspection Photo		Load JPG	
102	26/02/18 10:03	Reinspection Photo		Load JPG	
103	26/02/18 10:03	Reinspection Photo		Load JPG	
104	26/02/18 10:03	Reinspection Photo		Load JPG	
105	26/02/18 10:03	Reinspection Photo		Load JPG	
106	26/02/18 10:03	Reinspection Photo		Load JPG	
107	26/02/18 10:03	Reinspection Photo		Load JPG	
108	26/02/18 10:03	Reinspection Photo		Load JPG	
109	26/02/18 10:03	Reinspection Photo		Load JPG	
110	26/02/18 10:03	Reinspection Photo		Load JPG	
111	26/02/18 10:03	Reinspection Photo		Load JPG	
112	26/02/18 10:03	Reinspection Photo		Load JPG	
113	26/02/18 10:03	Reinspection Photo		Load JPG	
114	26/02/18 10:03	Reinspection Photo		Load JPG	
115	26/02/18 10:03	Reinspection Photo		Load JPG	
116	26/02/18 10:03	Reinspection Photo		Load JPG	
117	26/02/18 10:03	Reinspection Photo		Load JPG	
118	26/02/18 10:03	Reinspection Photo		Load JPG	
119	26/02/18 10:03	Reinspection Photo		Load JPG	
120	26/02/18 10:03	Reinspection Photo		Load JPG	
121	26/02/18 10:03	Reinspection Photo		Load JPG	
122	26/02/18 10:03	Reinspection Photo		Load JPG	
123	26/02/18 10:03	Reinspection Photo		Load JPG	
124	26/02/18 10:03	Reinspection Photo		Load JPG	
125	26/02/18 10:03	Reinspection Photo		Load JPG	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118001225/AQBE2
Date: 06/03/2018

REFERENCE

Insured/Claimant: M/S ETONG ALUMINIUM ENGINEERING PTE LTD
Policy No: DMCVSN30658717000
Date of Loss: 07/01/2018
Nature of Claim: OD
Claim No: SNM18D00125C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG4626H**
Make & Model: NISSAN NV200, 1.6 DX-2 (A) **Engine No:** HR16100704D
Reg. Date: 17/08/2017 (Man. Year: 2017) **Chassis No:** VM20115453
Colour: Black **Odometer:** 10101 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 165/80 R14 **Rear Tyre Size:** 165/80 R14
Front Left Side: Toyo 6 mm **Rear Left Side:** Toyo 6 mm
Front Right Side: Toyo 6 mm **Rear Right Side:** Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,372.07	15,278.81	6,093.26	28.51
Miscellaneous Items	930.00	330.00	600.00	64.52
Labour	1,600.00	1,000.00	600.00	37.50
Paintwork Labour	1,500.00	900.00	600.00	40.00
Towing	50.00	0.00	50.00	100.00
Calculated Gross Total (S\$)	25,452.07	17,508.81	7,943.26	31.21
- Excess (S\$)	0.00	450.00	-450.00	
(S\$)	25,452.07	17,058.81	8,393.26	32.98
+ GST 7.00/0.00% (S\$)	1,781.64	0.00	1,781.64	100.00
Nett Amount (S\$)	27,233.71	17,058.81	10,174.90	37.36

INSPECTION

Date of Assignment: 19/01/2018 **Present Location:** SMRT Automotive Services Pte Ltd (Woodlands)
Date Inspected: 22/01/2018 **Inspected At:** 60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 06 Mar 2018)
Parts:	N/A NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG4626H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Distorted	500.00 F	*500.00 F
2	1		*HINGE RH	Bent	50.00 F	*50.00 F
3	1		*HINGE LH	Bent	50.00 F	*50.00 F
4	1		*FRONT BUMPER	Distorted	375.00 F	*375.00 F
5	1		*FRONT BUMPER RETAINER LH	Necessary	125.00 F	*125.00 F
6	1		*FRONT BUMPER RETAINER RH	Necessary	125.00 F	*125.00 F
7	1		*FRONT BUMPER TOWING COVER	Missing	25.00 F	*25.00 F
8	1		*FRONT BUMPER REINFORCEMENT	Bent	350.00 F	*350.00 F
9	1		*FRONT BUMPER FOAM	Cracked	181.25 F	*181.25 F
10	1		*FRONT GRILLE	Cracked	250.00 F	*250.00 F
11	1		*FRONT GRILLE MOULDING	Deformed	187.50 F	*187.50 F
12	1		*FRONT GRILLE EMBLEM	Necessary	50.00 F	*50.00 F
13	1		*FRONT HEADLAMP LOWER GARNISH RH	Deformed	193.75 F	*193.75 F
14	1		*FRONT HEADLAMP LOWER GARNISH LH	Deformed	193.75 F	*193.75 F
15	1		*HEADLAMP RH	Cracked	281.25 F	*281.25 F
16	1		*HEADLAMP LH	Cracked	281.25 F	*281.25 F
17	1		*BONNET LOCK	Damaged	50.00 F	*50.00 F
18	1		*BONNET CABLE	Not Necessary	43.75 F	*- F
19	1		*SUPPORT PANEL ASSY	Bent	250.00 F	*250.00 F
20	1		*HEADLAMP PANEL LH	Bent	81.25 F	*81.25 F
21	1		*HEADLAMP PANEL RH	Bent	81.25 F	*81.25 F
22	1		*AIR CON CONDENSER	Dented	687.50 F	*687.50 F
23	1		*RADIATOR	Bent	600.00 F	*600.00 F
24	2		*AIR CON CONDENSER PIPE	Not Necessary	437.50 F	*- F
25	2		*AIR CON CONDENSER HOSE	Not Necessary	437.50 F	*- F
26	1		*RADIATOR TOP HOSE	Twisted	43.75 F	*43.75 F
27	1		*RADIATOR LOWER HOSE	Not Necessary	56.25 F	*- F
28	1		*RADIATOR FAN SHROUD	Cracked	93.75 F	*93.75 F
29	1		*RADIATOR FAN MOTOR	Damaged	250.00 F	*250.00 F
30	1		*RADIATOR FAN BLADE	Damaged	81.25 F	*81.25 F
31	1		*DEFLECTOR RADIATOR RH	Deformed	68.75 F	*68.75 F
32	1		*DEFLECTOR RADIATOR LH	Deformed	68.75 F	*68.75 F
33	1		*AIR CLEANER INLET DUCT	Deformed	75.00 F	*75.00 F
34	1		*AIR INLET DUCT HOSE	Deformed	93.75 F	*93.75 F
35	1		*AIR CLEANER ASSY	Cut	568.75 F	*568.75 F
36	1		*RADIATOR SPARE TANK	Deformed	87.50 F	*87.50 F
37	1		*COOLANT	Necessary	25.00 F	*25.00 F
38	1		*FRONT FUSE BOX ASSY	Deformed	243.75 F	*243.75 F
39	1		*BATTERY	Deformed	150.00 F	*150.00 F
40	1		*BATTERY TRAY	Deformed	22.50 F	*22.50 F
41	1		*BATTERY BRACKET	Not Necessary	62.50 F	*- F
42	1		*INTAKE MANIFOLD	Not Necessary	968.70 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*ALTERNATOR	Not Necessary	1,987.00 F	*- F
44	1		*AIR CON COMPRESSOR	Not Necessary	909.90 F	*- F
45	1		*WIPER WASHER JAR	Deformed	156.25 F	*156.25 F
46	1		*FRONT FENDER RH	Buckled	375.00 F	*375.00 F
47	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	106.25 F	*- F
48	1		*FRONT FENDER LH	Buckled	375.00 F	*375.00 F
49	1		*FORNT FENDER INNER SHIELD LH	Not Necessary	106.25 F	*- F
50	1		*FRONT FENDER LAMP RH	Not Necessary	37.50 F	*- F
51	1		*FRONT FENDER LAMP LH	Not Necessary	37.50 F	*- F
52	1		*FRONT QUARTER GLASS RH	Not Necessary	250.00 F	*- F
53	1		*FRONT QUARTER GLASS LOWER GARNISH RH	Not Necessary	56.25 F	*- F
54	1		*FRONT QUARTER GLASS LH	Not Necessary	250.00 F	*- F
55	1		*FRONT QUARTER GALSS LOWER GARNISH LH	Not Necessary	56.25 F	*- F
56	1		*QUARTER GLASS GLUM	Necessary	50.00 F	*50.00 F
57	1		*DASHBOARD AIR BAG	Activated	1,875.00 F	*1,875.00 F
58	1		*STEERING AIR BAG	Activated	1,687.50 F	*1,687.50 F
59	1		*STEERING CLOCK WIRE	Activated	218.75 F	*218.75 F
60	1		*AIR BAG CONTROL UNIT	Activated	937.50 F	*937.50 F
61	1		*FRONT SEAFETY BELT RH	Activated	625.00 F	*625.00 F
62	1		*FRONT SAFETY BELT LH	Activated	625.00 F	*625.00 F
63	2		*AIR BAG SENSOR	Activated	750.00 F	*750.00 F
64	1		*FRONT NUMBER PLATE	Cracked	20.00 F	*20.00 F
65	1		*FRONT NUMBER PLATE CASING	Cracked	15.00 F	*15.00 F

F=Franchise part.

Sub Total (S\$)	20,354.35	14,551.25
+ Margin on L,N Items 5.00/5.00% (S\$)	1,017.72	727.56
Total Parts (S\$)	21,372.07	15,278.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ALIGNMENT	80.00	0.00
2	1	TO REMOVE & REFIX DASHBOARD /REPLACE AIR BAG ETC	350.00	300.00
3	1	TO REMOVE & REFIX ENGINE TO FACILITATE REPAIR	450.00	0.00
4	1	WIRING	50.00	30.00
Sub Total (\$\$)			930.00	330.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO SPRAY PAINTING ON FRONT BONNET/FENDER LH & RH / BUMPER /SUPPORT / BUMPER REINFORCEMENT ETC	New	1,500.00	900.00
Labour Items				
2	TO REMOVE & REFIX / ALIGN CHASSIS /WELDING ETC	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			3,100.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >