



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Mr LEE KWAY LIANG	Cust No/Name /Mr LEE KWAY LIANG
BLK 248 BISHAN ST 22	Reg No/Reg Date SKR574K / 14/01/201
#20-362	Date In/Mileage / 0
SINGAPORE 570248	Chassis No MMBSTA13AFH001227
Contact No Mobile: 96273528	Engine No 3A92UBX9462
	Make/Model MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim A06 / BK

Account No	Terms	Date/Time Printed	GSE	Operator	WIP No			
CSM00041	Cash	23/01/2018/ 09:18		465 / Tay Jian Ye	20040			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								22003300.00
TO RENEW REAR BUMPER , BOOTLID, WELD AND CUT END PANEL , FLOOR PANEL								
REPAIR REAR BOTH FENDER								150 200.00
E PNT88000								✓ 50.00
TO TRANSFER REAR BOOTLID MECHASIM AND TRIM TO NEW PART								
E PNT88000								150 200.00
TO REMOVE AND REFIT REAR PARKING SENSOR								
E PNT88000								2100 2940.00
TO REMOVE AND REFIT REAR BOOT TRIMS TO FACILIATE REPAIR								
E PNT98000								30 50.00
PAINT WORK SPRAY REAR BUMPER, BOOTLID, END PANEL, FLOOR PANEL,								
REAR BOTH FENDER								✓ 200.00
A 54900099								
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								80 120.00
A 10028901								150 200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								✓ 50.00
USING HI-SCAN PRO TEST								
M SUNDRY								150 200.00
TO APPLY ANTI COROSSION ON AFFECTED PORTION								✓ 50.00
M SUNDRY								150 200.00
TO APPLY BODY SEALANT ON AFFECTED PORTION								✓ 50.00
M SUNDRY								150 200.00
TO SUPPLY C&C LOGO								150 200.00
M SUNDRY								150 200.00
TO SUPPLY REVERSE SENEOR								150 200.00
M SUNDRY								150 200.00
SUNDRIES								150 200.00
M	BRACKET,RR BUMPER,LH		1.00	27.00	00.00		27.00	
M	BRACKET,RR BUMPER,RH		1.00	27.00	00.00		27.00	
M	FACE,RR BUMPER		1.00	740.00	00.00		740.00	
M	CLIP,FR BUMPER		10.00	3.00	00.00		30.00	
M	HINGE,TRUNK LID,LH		1.00	201.00	00.00		201.00	
M	HINGE,TRUNK LID,RH		1.00	201.00	00.00		201.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr LEE KWAY LIANG	Cust No/Name /Mr LEE KWAY LIANG
BLK 248 BISHAN ST 22	Reg No/Reg Date SKR574K / 14/01/201
#20-362	Date In/Mileage / 0
SINGAPORE 570248	Chassis No MMBSTA13AFH001227
Contact No Mobile: 96273528	Engine No 3A92UBX9462
	Make/Model MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	23/01/2018/ 09:18		465 / Tay Jian Ye	20040
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M WEATHERSTRIP, TRUNK LID		1.00	155.00	00.00	155.00
M PANEL, TRUNK LID		1.00	865.00	00.00	865.00
M LATCH, TRUNK LID		1.00	216.00	00.00	216.00
I BUMPER RR REFLECTOR LH		1.00	21.00	00.00	21.00
M BUMPER RR REFLECTOR RH		1.00	21.00	00.00	21.00
M LAMP ASSY, COMB, RR RH		1.00	332.00	00.00	332.00
M MARK, THREE-DIA		1.00	43.00	00.00	43.00
M MARK, ATTRAGE		1.00	21.00	00.00	21.00
M PANEL, RR END		1.00	0.00	00.00	0.00
M DUCT, RR VENTILATOR		1.00	29.00	00.00	29.00
M COVER, RR VENTILATOR		1.00	38.00	00.00	38.00
M ANT, KEYLESS OPERATION, RR		1.00	84.00	00.00	84.00
M BUZZER, KEYLESS OPERATIO, RR		1.00	88.00	00.00	88.00
M TRIM, RR END		1.00	65.00	00.00	65.00
M BOARD, TRUNK ROOM FLOOR		1.00	193.00	00.00	193.00
M FLOOR, RR		1.00	947.00	00.00	947.00
M LAMP ASSY, COMB, RR LH		1.00	332.00	00.00	332.00
M LAMP ASSY, COMB, RR RH		1.00	332.00	00.00	332.00

Estimate

SURVEYOR NAME: Tanjun 92495749SURVEYOR SIGNATURE: [Signature]DATE: 23/1/18 @ 1715REMARKS: Resurvey before paint7-8 days
sur @ 1/18/18 com

Confirm

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

Nett 12,588.00
7% GST on 12588.00 881.16
Total Payable 13,469.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.