

10/1/18

10/1/18

CS/EGII18001349/4td3e2

MARCUS

ASSIGNMENT 10/1/18

From/To: Yee Pei Li

EGII

22/1/18 @ 4:03pm

Estimated Cost

Yee Li

OD (TH)WS/TIRIS/OD RUS/INA INV/MV/C

To: Inspector Vehicle No.

GBC 8320J

Vehicle

GBB 29564

to: Working on

Liu's Brother

File

67411730

at No. 1, Kaki Bkt Ave 6 #01-01 Autobay

Policy No.

Claim No.

DSM CV1800081

Sum Insured

Excess

Make of Veh.

4/11/2017 12/01/2018

Client's Record

CA / REV / REP. / REV 24 HRS

lup

10/1/18

Date/Time: 5:57pm @ 22/1/18

Terms Continued

jacelyn

10/1/18

Date/Time

Action/Assignment

✓ 10/1/18

GBC 8320J -X

GBB 29564 -X

TABLE 1. Mean and standard deviation of the 1000 random numbers generated by the computer.

350

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 22 January 2018 4:03 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB2956U / TP : GBC8320J/LKK / DOA : 04.11.2017 (DSMCV1800081)
Attachments: GBB2956U - SAS.pdf; 2ND VEH GBC8320J - SAS.pdf; 1ST VEH GBE2314G - SAS.pdf; 2ND VEH GBC8320J - PRS FORM.pdf; Re: Request for 3rd party survey GBC8320J Claims against GBB2956U (DSMC... (26.0 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 22.01.2018
Our Reference: GBB 2956U/SE/pl
Your Reference: GBC 8320T

To: LIU'S BROTHER AUTO

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBC 8320T
Insured's Vehicle: GBB 2956U
Date Of Accident: 12.01.2018


We acknowledge receipt of your request for PRS on: 22.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG18001349/Utd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 23-01-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 2956U	Veh. Inspected	GBC 8320J
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800081	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/11/2017	Inspection Date	23/01/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMCV1800081
Our Ref: CS/EGI18001349/Utd3

Date: 31/1/2018

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. GBC 8320J.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/1/2018 at the premises of M/s Liu's Brother and have the following to report:-

Workshop Estimate Amount	: S\$ <u>87,141.50</u>
Revised Estimate Amount	: S\$ <u>17,000.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
At rear and front portion.



Repair days: 16 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 31 January 2018 10:01 AM
To: Admin-D (LKKAuto); 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments
Cc: SUR
Subject: RE: GBB2956U / TP : GBC8320J/LKK / DOA : 04.11.2017 (DSMCV1800081)
Attachments: PRELI ADVISED GBC 8320J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBC 8320J**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 22 January 2018 5:58 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments
<assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB2956U / TP : GBC8320J/LKK / DOA : 04.11.2017 (DSMCV1800081)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 22 January 2018 4:03 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBB2956U / TP : GBC8320J/LKK / DOA : 04.11.2017 (DSMCV1800081)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 17:33
Date Of Accident	12/01/2018 14:50
Exact Location Of Accident	CLEMENTI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC8320J
Insured/Policyholder	
Name Of Registered Owner	STVE PTE LTD
Co Reg No	198703585C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85224907

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087422MFCV
Cover Note Number	N.A.

Driver

Name of Driver	MUHAMAD FARID ARIFFIN BIN AHMAT
NRIC No	G2412365R
Date Of Birth	19/06/1993
Occupation	OUTDOOR
Date Of Driving Pass	13/06/2017
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-85224907
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Vehicle Make/Model/Colour	NISSAN/ CABSTAR
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KULANTHAIVELU SELVAM
NRIC/Passport Number	G8343415K
Contact Number	98657780
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I (GBC8320J) WAS STATIONARY AT A TRAFFIC LIGHT ALONG CLEMENTI ROAD ON THE FIRST LANE WHEN SUDDENLY A VAN (GBB2956U) HIT ME FROM THE BACK. DUE TO THE IMPACT, MY VAN MOVE FORWARD AND HIT A LORRY IN FRONT OF ME. IT WAS A THREE VEHICLES COLLISION. NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

15 January 2018 at 2:29 PM

Date/Time

15 January 2018 at 2:29 PM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3585C

Vehicle Details

Vehicle No.:	GBC8320J
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1KD2334707
Chassis No.:	JTFHT02P000125446
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	13 Dec 2013
First Registration Date:	13 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$1,291.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3585C

Vehicle Details

Vehicle No.: GBC8320J

Vehicle to be Exported: No

Intended De-registration
Date: 23 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE MANUAL

Primary Colour: Silver

Manufacturing Year: 2013

Engine No.: 1KD2334707

Chassis No.: JTFHT02P000125446

Maximum Power Output: -

Open Market Value: \$25,820.00

Original Registration Date: 13 Dec 2013

First Registration Date: 13 Dec 2013

Transfer Count: 0

Actual ARF Paid: \$1,291.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Dec 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$55,002.00

COE Rebate Amount: \$32,368.00

Total Rebate Amount: \$32,368.00

The information contained herein is correct as at 23 Jan 2018

OK

SGCARMART.COM

Login Sign

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

**Post an Advertisement**

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Toyota Altis 1.6A

\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

click here to view
our **PRISTINE USED CARS**
at GRB

Browse by Category

Sort by Date Posted

5 vehicles

hiace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh 1
Search Selection	hiace		Any	Any	2013	Any	Any	

**Toyota Hiace Commuter****\$68,800****\$11,620 /yr****26-Dec-2013****2,982 cc****-****Fuel Type:** Diesel

Super Good Condition. No Repair Needed. Only One Unit In Our Stock Now. Super High Demand In The Market. Faster Grab In Before It Gc Loan And High Trade In. Call To Arrange Viewing!

ABWIN Bus Pte Ltd

Posted: 22-Jan-2018 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace****\$49,800****\$9,520 /yr****18-Apr-2013****2,982 cc****110,235 km****Fuel Type:** Diesel

In House Loan Available. Downpayment \$5000. Very Well Maintained By Owner. Quality Parts Used For Servicing. A Strong And Reliable Go For Your Businesses Needs. Always Serviced On Time And ...

Don Motoring

Posted: 21-Jan-2018 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace Commuter****\$66,000****\$11,670 /yr****19-Sep-2013****2,982 cc****-****Fuel Type:** Diesel

High Loan Available! P.I Model. Power Doors, Replaced Car Mats, Major Servicing Done. Handover In Mid March.

Posted: 17-Jan-2018 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace****\$65,800****\$12,640 /yr****08-Apr-2013****2,982 cc****-****Fuel Type:** Diesel

In House Finance Available, Kindly Please Call For Viewing. Thanks.

Posted: 10-Jan-2018 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

**Toyota Hiace****\$50,800****\$9,610 /yr****07-May-2013****2,982 cc****45,000 km****Fuel Type:** Diesel

No Repair Needed, Price Negotiable, Nice And Well Maintenance, Excellent Condition, Servicing Done Regularly, Original Paint, Low Mileage, Driver.

Posted: 05-Jan-2018 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

A-Assurance
Assurance in Insurance
Car Insurance Expiring?
 We get you the cheapest insurance renewal
[Click to get quote](#)

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

R129 SL320 Final Edition 2001.


 2 Owners With 51540 Km Since New.
 Direct Owner StarAd

click here to view our **PRISTINE USED CARS** at GREAT PRICES





Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

hiace

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	hiace		Any	Any	2014	Any	Any	Any	Available
	Toyota	Hiace	\$54,800	\$9,140 /yr	22-Jan-2014	2,982 cc	-	Van	Available
Fuel Type: Diesel Season Parking At Multi-Storey Carpark \$110. Enter All Multi-Storey Carpark Above 1.9m. Call Us Now! ABWIN Bus Pte Ltd Posted: 23-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota	Hiace	\$57,800	\$8,690 /yr	17-Sep-2014	2,982 cc	-	Van	Available
Fuel Type: Diesel Extremely Well Maintained Toyota Hiace. 1 Owner With Full Servicing Record With Borneo Motors. All Wear & Tear Replaced. Seats And Paintwork In Original Condition, View To Believe. Car (S) Pte Ltd Posted: 22-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota	Hiace	\$59,800	\$8,920 /yr	07-Oct-2014	2,982 cc	100,000 km	Van	Available
Fuel Type: Diesel 5 Door Toyota Hiace From Borneo Motor. Serviced And Maintained At Borneo Motor. Original Condition. No Touch Up Of Paint Work And Interior Is As Good As New. See To Believe! In House Loan And Trade In... Abwin Trading Posted: 22-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota	Hiace Commuter	\$69,000	\$10,060 /yr	27-Nov-2014	2,982 cc	-	Bus	Available
Fuel Type: Diesel Vehicle In Good Condition, Foldable Rear Seats, Auto Door. Call Now For More Info. Inhouse Loan Available. Prime Motor & Leasing Posted: 17-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									

Car Buying

Car Selling



Car Aftermarket

Car Ownership

On The Move

Lifestyle



	Toyota	Hiace	\$55,500	\$8,480 /yr	08-Aug-2014	2,982 cc	107,000 km	Van	Available
Fuel Type: Diesel Borneo Motor Maintained. New Paint. Just Change Timing Belt And Battery. Accident Free. Very Good Condition. Best Value And Lowest Appreciation. No Agent Please. Posted: 08-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota	Hiace	\$54,800	\$8,850 /yr	03-Apr-2014	2,982 cc	86,000 km	Van	Available
Fuel Type: Diesel Think One Automobile & Trading Posted: 27-Nov-2017 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417882

ROB No: 52291793J Tel: 6741 1750 731 Fax: 6744 5746 Email: liubro@ymail.com

Invoice/Ref No: GBC8320J180112

Estimate

Customer

Page 01 - 02

Name: ERGO Insurance Pte Ltd

Date: 20-01-18

Address: Motor Claims Department

Vehicle No: GBC8320J

5 Temasek Boulevard #04-01

Model/Make: Toyota Hiace

Suntec Tower Five

Singapore 038985

Manual

not Allowed
note
23/1/18
1/5 \$17.000
Total photo After repair
16 day.

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Body 1969.30</i>	\$ 2,050.00	
2	Tailgate Lock <i>Twil/gm</i>	\$ 359.00	
3	Tailgate Lock Striker <i>11</i>	\$ 20.50	X
4	Tailgate Weather Strip <i>Twil</i>	\$ 387.30	X
5	Tailgate Suspension 02 pcs (@ \$335.20) <i>11</i>	\$ 670.40	X
6	Tailgate Inner Trim Board <i>70.2</i>	\$ 165.30	X
7	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 50.00	X
8	Tailgate Number Plate Lamp 02 pcs (@ \$128.60) <i>11</i>	\$ 257.20	X
9	Tailgate Number Plate Lamp Outer Garnish <i>groend</i>	\$ 346.50	
10	Tailgate "Toyota Logo" Motif <i>neu 60.50</i>	\$ 70.50	
11	Tailgate "Hiace" Emblem <i>neu 66.20</i>	\$ 75.00	
12	Tailgate "Toyota" Sticker <i>neu 68.10</i>	\$ 95.00	
13	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 14.00	SN 105.W
14	Tailgate "8 pax" Sticker <i>neu</i>	\$ 14.00	SN 105.W
15	Tailgate Windscreen Moulding <i>neu 110.10</i>	\$ 219.00	
16	Tailgate Windscreen Sealant <i>neu</i>	\$ 50.00	SN 405.W
17	Tail Lamps 02 pcs (@ \$365.10) <i>0/5 BND N/5</i>	\$ 730.20	12
18	Tail Lamp Panel Rh <i>Body 245.10</i>	\$ 936.20	1 PC
19	Corner Panel 02 pcs (@ \$75.00) <i>0/5 Twil</i>	\$ 150.00	
20	Corner Panel Garnish Bracket 02 pcs (@ \$31.50) <i>NS</i>	\$ 63.00	X
21	Bumper <i>2.5</i>	\$ 496.40	
22	Bumper Clips 1 set <i>neu</i>	\$ 48.00	SN 405.W
23	Bumper Side Bracket 02 pcs (@ \$202.00) <i>But 65x20130</i>	\$ 404.00	
24	Bumper Reverse Sensor <i>CR</i>	\$ 220.00	SN 2005.W
25	Exhaust Pipe <i>Body 971.00</i>	\$ 1,466.60	
26	Exhaust Pipe Mounting 02 pcs (@ \$42.50) <i>11</i>	\$ 85.00	X
27	End Panel Inner <i>Body 936.20</i>	\$ 936.20	
28	End Panel Outer <i>Body 566.10</i>	\$ 566.10	
29	End Panel Top Plate <i>But 499.10</i>	\$ 299.50	
30	End Panel Sealant <i>neu 269.50</i>	\$ 50.00	SN 5.W
31	Floor Panel <i>R</i>	\$ 1,855.90	X
32	Floor Panel Beam <i>NS</i>	\$ 277.80	X
33	Floor Panel Top Plywood <i>CR</i>	\$ 400.00	SN 3005.W
34	Spare Tyre Carrier <i>But</i>	\$ 250.60	
35	Spare Tyre Holder <i>11</i>	\$ 345.10	X
36	Fender Rh <i>Body 1,419.70</i>	\$ 1,419.70	
37	Fender Inner Panel Rh <i>R</i>	\$ 1,145.10	X
38	Fender Air Garnish Rh <i>CR 15.50</i>	\$ 1,069.10	
39	Number Plate (Metal Plate) <i>But 35.00</i>	\$ 35.00	SN 155.W
40	Front Bumper <i>20/70.11 671.10</i>	\$ 796.80	
41	Bumper Bracket 02 pcs (@ \$68.50) <i>11</i>	\$ 137.00	X
42	Bumper Clips 1 set <i>neu</i>	\$ 48.00	SN 405.W
43	Bumper Grille <i>Twil</i>	\$ 155.80	
44	Bumper Reinforcement <i>D</i>	\$ 380.40	
C/F Balance --->		\$ 19,611.20	

25%

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

M/s Liu's Brother Auto Engrg Wks



105328

705



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417882

ROB No: 52,291,793.1 Tel: 6741 1730 - 731 Fax: 6744 5716 Email: bbro@bba.com

Invoice/Ref No: GBC8320J180112

Estimate

Customer

Page 01 - 02

Name: ERGO Insurance Pte Ltd

Date: 20-01-18

Address: Motor Claims Department

Vehicle No: GBC8320J

5 Temasek Boulevard #04-01

Model/Make: Toyota Hiace

Suntec Tower Five

Singapore 038985

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 19,611.20	
45	Bonnet <i>2/3uc 835.30</i>	\$ 872.90	<i>✓</i>
46	Bonnet Lock <i>1/1 58.50</i>	\$ 88.90	<i>✓</i>
47	"Toyota" Molif <i>1/1</i>	\$ 75.00	<i>✓</i>
48	Head Lamp 02 pcs (@ \$704.10) <i>one</i>	\$ 1,408.20	<i>✓</i>
49	Head Lamp Clip 1 set <i>1/1</i>	\$ 65.00	<i>X</i>
50	Head Lamp Grille 02 pcs (@ \$141.60) <i>MS</i>	\$ 283.20	<i>X</i>
51	Air Cleaner <i>one</i>	\$ 649.70	<i>✓</i>
52	Top Panel <i>1/1 348.10</i>	\$ 976.00	<i>✓</i>
53	Centre Panel <i>MS</i>	\$ 1,466.30	<i>X</i>
54	Side Panel 02 pcs (@ \$296.10) <i>1/1</i>	\$ 592.20	<i>X</i>
55	Inter Cooler <i>20/Pur</i>	\$ 1,514.00	<i>✓</i>
56	Inter Cooler Clip 1 set <i>1/1</i>	\$ 40.00	<i>SN X</i>
57	Inter Cooler Cowling <i>1/1</i>	\$ 157.00	<i>X</i>
58	Wiper Tank <i>1/1</i>	\$ 56.80	<i>✓</i>
59	Radiator Spare Tank <i>1/1</i>	\$ 1,546.90	<i>X</i>
60	Air Con Condenser <i>1/1 2110.20</i>	\$ 1,431.90	<i>✓</i>
61	Aircon Pipe "Big" <i>1/1</i>	\$ 631.90	<i>X</i>
62	Aircon Pipe "Small" <i>1/1</i>	\$ 297.50	<i>X</i>
63	Radiator <i>1/1 25%</i>	\$ 2,372.30	<i>X</i>
64	Radiator Tank Cowling <i>1/1</i>	\$ 352.50	<i>X</i>
65	Radiator Coolant <i>1/1</i>	\$ 45.00	<i>SN 305.~</i>
66	Corner Panel Lh <i>1/1</i>	\$ 296.10	<i>X</i>
67	Aircon Blower <i>1/1</i>	\$ 799.20	<i>✓</i>
68	Washer Unit <i>1/1 1466.10</i>	\$ 1,919.40	<i>✓</i>
	"Corporate" Advertisement Sticker	\$ 800.00	<i>SN 4505.~</i>
	Remove and refix rear Bumper distance sensor	\$ 100.00	<i>50</i>
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	<i>60</i>
	To trace & check wiring and lighting to proper function	\$ 300.00	<i>30</i>
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 180.00	<i>60</i>
	Remove & reinstall Rear Windscreen Glass to facilitate repairs	\$ 120.00	<i>100</i>
	Remove and replace rear floor board to facilitate repairs	\$ 140.00	<i>X</i>
	Labor for Rear Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 3,800.00	<i>1800</i>
	To putty & spray painting & including touch up paint on accident affected area	\$ 2,000.00	<i>1500</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 200.00	<i>120</i>
	Labor for Front Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	<i>600</i>
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 300.00	<i>100</i>
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc ...	\$ 400.00	<i>160</i>
	To remove & replace radiator and conduct pressure test & bleed system	\$ 150.00	<i>X</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 87,141.50

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

SDLS:



42919 10

M/s Liu's Brother Auto Engrg Wks

17937.90

21298.7
15574.77

10370

SN-1184
1600-4580
21738.77




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18001349/Utd3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 06-02-2018		
Code : EGI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 2956U	Veh. Inspected	GBC 8320J	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800081	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTFHT02P000125446	Colour	BLUE	
Odometer	124214	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	WEST LAKE	6 mm	
L/H Front Tyre	195 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2018	Inspection Date	23/01/2018	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 8320J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BADLY DENTED	2,050.00	1,969.30
1	REAR TAILGATE LOCK	TWISTED / JAMMED	359.00	359.00
1	REAR TAILGATE LOCK STRIKER	NOT NECESSARY	20.50	-
1	REAR TAILGATE WEATHERSTRIP	TWISTED	387.30	387.30
2	REAR TAILGATE SUSPENSION @\$335.20	NOT NECESSARY	670.40	-
1	REAR TAILGATE INNER TRIM BOARD	TORN	165.30	165.30
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
2	REAR TAILGATE NUMBER PLATE LAMP @\$128.60	NOT NECESSARY	257.20	-
1	REAR TAILGATE NUMBER PLATE LAMP OUTER GARNISH	GRAZED	346.50	346.50
1	REAR TAILGATE "TOYOTA LOGO" MOTIF	NECESSARY	70.50	60.50
1	REAR TAILGATE "HIACE" EMBLEM	NECESSARY	75.00	66.20
1	REAR TAILGATE "TOYOTA" STICKER	NECESSARY	95.00	68.10
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	219.00	110.10
2	REAR TAIL LAMPS @\$365.10	O/S BROKEN	730.20	365.10
1	REAR TAIL LAMP PANEL RH	BADLY DENTED	936.20	345.10
2	REAR CORNER PANEL @\$75.00	O/S TWISTED	150.00	75.00
2	REAR CORNER PANEL GARNISH BRACKET @\$31.50	NO SUCH PARTS	63.00	-
1	REAR BUMPER	DISTORTED	496.40	496.40
2	REAR BUMPER SIDE BRACKET @\$202.00	BENT	404.00	130.00
1	REAR EXHAUST PIPE	BENT / TWISTED	1,466.60	971.00
2	REAR EXHAUST PIPE MOUNTING @\$42.50	NOT NECESSARY	85.00	-
1	REAR END PANEL INNER	BADLY DENTED	936.20	936.20
1	REAR END PANEL OUTER	BADLY DENTED	566.10	499.10
1	REAR END PANEL TOP PLATE	BENT	299.50	269.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,855.90	-
1	REAR FLOOR PANEL BEAM	NO SUCH PARTS	277.80	-
1	REAR SPARE TYRE CARRIER	BENT	250.60	250.60
1	REAR SPARE TYRE HOLDER	NOT NECESSARY	345.10	-
1	REAR FENDER RH	BADLY DENTED / BUCKLED	1,419.70	1,419.70

Report Ref No. CS/EG118001349/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER PANEL RH	TO REPAIR SEE LABOUR	1,145.10	-
1	REAR FENDER AIR GARNISH RH	CRACKED	1,069.10	35.50
1	FRONT BUMPER	DENTED / TORN	796.80	671.10
2	FRONT BUMPER BRACKET @\$68.50	NOT NECESSARY	137.00	-
1	FRONT BUMPER GRILLE	TWISTED	155.80	155.80
1	FRONT BUMPER REINFORCEMENT	DENTED	380.40	380.40
1	FRONT BONNET	DENTED / BUCKLED	872.90	835.30
1	FRONT BONNET LOCK	TWISTED	88.90	88.90
1	FRONT "TOYOTA" MOTIF	NECESSARY	75.00	58.50
2	FRONT HEAD LAMP @\$704.10	CRACKED	1,408.20	1,408.20
1	SET FRONT HEAD LAMP CLIP	NOT NECESSARY	65.00	-
2	FRONT HEAD LAMP GRILLE @\$141.60	NO SUCH PARTS	283.20	-
1	FRONT AIR CLEANER	CRACKED	649.70	649.70
1	FRONT TOP PANEL	BENT	976.00	348.10
1	FRONT CENTRE PANEL	NO SUCH PARTS	1,466.30	-
2	FRONT SIDE PANEL @\$296.10	TO REPAIR SEE LABOUR	592.20	-
1	FRONT INTER COOLER	DENTED / PUNCTURE	1,514.00	1,514.00
1	FRONT INTER COOLER COWLING	NOT NECESSARY	157.00	-
1	FRONT WIPER TANK	DEFORMED	56.80	56.80
1	FRONT RADIATOR SPARE TANK	NOT NECESSARY	1,546.90	-
1	FRONT RADIATOR AIR CON CONDENSER	BENT / PUNCTURE	1,431.90	1,431.90
1	FRONT AIRCON PIPE "BIG"	NOT NECESSARY	631.90	-
1	FRONT AIRCON PIPE "SMALL"	NOT NECESSARY	297.50	-
1	FRONT RADIATOR	BENT / PUNCTURE	2,372.30	2,110.20
1	FRONT RADIATOR TANK COWLING	NOT NECESSARY	352.50	-
1	FRONT CORNER PANEL LH	REPEATED	296.10	-
1	FRONT AIRCON BLOWER	CRACKED	799.20	799.20
1	FRONT HEATER UNIT	CRACKED	1,919.40	1,466.10
	LESS 25% DISCOUNT		-	-5,324.93
			36,585.10	15,974.77

Report Ref No. CS/EGI18001349/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	14.00	10.00
1	REAR TAILGATE "8 PAX" STICKER (SN)	NECESSARY	14.00	10.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	CRACKED	220.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL TOP PLYWOOD (SN)	CRACKED	400.00	300.00
1	REAR NUMBER PLATE (METAL PLATE) (SN)	BENT	35.00	15.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	40.00
1	SET FRONT INTER COOLER CLIP (SN)	NOT NECESSARY	40.00	-
1	FRONT RADIATOR COOLANT (SN)	NECESSARY	45.00	30.00
1	"COROPRATE" ADVERTISEMENT STICKER (SN)	NECESSARY	800.00	450.00
			1,764.00	1,185.00
	LABOUR			
	TO REMOVE & REPLACE RADIATOR AND CONDUCT PRESSURE TEST & BLEED SYSTEM.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REAR BUMPER DISTANCE SENSOR.		100.00	50.00
	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM.		80.00	60.00
	TO TRACE & CHECK WIRING AND LIGHTING FOR PROPER FUNCTION.		300.00	30.00
	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS.		180.00	60.00
	REMOVE & REINSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS.		120.00	100.00
	REMOVE AND REPLACE REAR FLOOR BOARD TO FACILITATE REPAIRS.	NOT NECESSARY	140.00	-
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR FENDER INNER PANEL RH AND FRONT SIDE PANEL.		3,800.00	1,800.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		2,000.00	1,500.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		200.00	120.00

Report Ref No. CS/EGI18001349/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOR FOR FRONT PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		1,800.00	600.00
	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES.		300.00	100.00
	REMOVE & REINSTALL DASHBOARD, METER INSTRUMENT, DISCONNECT WIRING & ETCS...		400.00	160.00
			9,570.00	4,580.00
GRAND TOTAL			47,919.10	21,739.77

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				17,000.00
--	--	--	--	-----------

Report Ref No. CS/EG18001349/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.