Medimen Rolly Assignment (Office) From (Ferson): JOLI floth of CTI Deserte 17 11 18 @ 3-18 pm Estimated Cost: OD (FF) WS/TP RES/OD RES/EVA/INV/MV/CS To Inspect Vehicle No: SGV3132 Insured GBC 7948 E at Workship m/s Performance Tel 63 190174 of 303 Alexandra Road Policy No: DMCVSN 3076691700 Claim No: SNM18 D 0025 9C02	ASS. REC. BY:	REF: CS C711800	01387/Rladzer	DET 1 COL
Estimated Cost: OD (TP) WS/TP RES/OD RES/EVA/INV/MV/CS To Inspect Vehicle No: SGV3132 Insured GBC 7948 E at Workshop m/s Performance of 303 Alexandra Road Policy No: DMCVSN 3076691700 Claim No: SNM18 D 0025 9C02	Mariana Rasul	ASSIGNMENT		
Estimated Cost: OD (IP) WS/TP RES/OD RES/EVA/INV/MV/CS To Inspect Vehicle No: SGV3132 insured: GBC 7948 E SIL Werkshop m/s Performance of 303 Alexandra Road Foliov No: DMCVSN 3076691700 Claim No: SNM18 D 0025 902	From (Ferson) joe Gol	C1	I Des	17/1/18 @3.18pm
To Inspect Vehicle No: SGV3132 Insured GBC7948 E Tel: 63190174 Tel: 63190174 Folloy No: DMCVSN3076691700 Claim No: SNM18D0025902	Estimated Cost:	93	ill to:	
Performance 53190174 of 303 Alexandra Road Folloy No. DMCVSN3076691700 Claim No. SNM18D00259002	OD TP WS+TP RES / OD)	RES/EVA/EVV/MV/CS		C
303 Alexandra Road Folloy No. DMCVSN 3076691700 Claim No. SNM18000259002	To Inspect Vehicle No:	SGV3132	insuredi	GBC7948E
Folloy No. DMCVSN 3076691700 Claim No. SNM18000259002	nii Werkelsop m/s	Performance	Tel	53190174
Folloy No. DMCVSN 3076691700 Claim No. SNM18000259002	303 1	exundra Road		
	Folicy No: DMCVSN30	76691700	Chim No. SNM18	000259002
dun insural: Excess:	Sum Insureă:		Excess:	
Make of Veh: D.O.A. 13 01 18			D.0	13/01/18
CA / REV / REP. / REV 24 HRS wp?		(400)		•
HIG D Endorsmen	17 LILIA 2 J	4 HRS	a 1.	O D Endometra
Date/Time 17/1/18 @ 3 40pm Person Contacted Caroline Vend DI	Date (time (11111 6) 3 4 (Person Contacted	Cololine	TUCKI
Date/Time Action/Instruction / Tall, F	Diate/Time Action/Instructi	1		+
SGV3132-CC3/CT118001387/Rlea3 D.O.A:13101/18			blam 2	N-0-4-13/01/18
G8C7948E-CC3/CT118001387/Rlea3 D.O.A:13/01/18				
07/5/804m confirmed with Caroline foral fig \$ 14286.69, 8 days.	07/5/804m contra	nd wolf C. 1110	foral An Giller	18/ 69 8 days
(Ont 10 1/2 15 21/0/)	1001 61	2/415 240/)	111 11 19 19 19	00.01, 00.01
(led \$7367.15, 34%)	CHAC DI	709.12, 7770)		

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	16 Jan 2018		17 Jan 2018 15:18 Edit Adj Rpt	J			Pending for Survey Report Cancel Case	
	Main	Refere	nce	Claim Details		Documents	Show All	
CLAIM SU	JBFOLDER DETA	AILS	NAME AND ADDRESS OF THE OWNER,			[Created by in	nsurer]	
Insured:		1.0000000000000000000000000000000000000	F PTE LTD, Co. R	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW				
Main Claim			HENG, ID: S140					
Vehicle Reg	g. No.:	SGV313Z		Date of Loss	:	13/01/2018 18:	:00 - :59	
Claim Type:		TP / SNM1	TP / SNM18D00259C02		Policy/Cover Note No.:		DMCVSN3076691700 (Comprehensive)	
Vehicle Reg. No. (Insured):		GBC7948E		Policy No. (C	Policy No. (Claimant): VP.		VPA/P1919088	
			Excess:					
Repairer:			Motors Limited		lexandra Road, S	lime Darby Perform	nance Centre, 159941	
Handling I	nsurer:	China Taipin	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Joel Goh]					
Claimant's	Insurer:	AXA Insurar	ice Pte Ltd (HQ)	- Tel: 6338 7288				
Adjuster:		26/01/2018		d (HQ) - Tel: 6256-3	3561 [Handled	by MOHD RASUL] [Final Rpt du	
Driver/Cus	todian (Insured):	ANBALAGAN I	MURUGADASS (25	/ Male), NRIC: g2	500460x, Tel:	+6584607648		
Adj Asg. R	emarks:	EST- \$19,760	.81 , ASSIGN LKK	AS SJE.				
ASSOCIA	TED MAIL RECE	IVED				View All	Compose Case Mail	
There are	no mail for this ca	se.						
ALL ACC	OCIATED TASKS	·=						
ALL ASSI		- 11.27			View All Sear	ch Tasks Create	New Task Complete	
Due Dat	e Priority T	ype Task Gro	up Subject	Handler Assign	ned By Con	apleted On C	reated On Done	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

190		III DANSED STANDAY OF STANDAY OF STANDAY	ationale Des Experts En Auton	AUGUSTA DE LA LA LINE DE LA CONTRACTOR D		
CHII	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CS/CTI180014	18/R1qd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 24-01-2018 Code: CTI			
1.		Policy Particula	rs :- THIRD PARTY CLA	M		
	Insured Veh.	GBC 7948E	Veh. Inspected	SGV 313Z		
	Policy No.	DMCVSN3076691700	Coverage (\$)	0.00		
	Claim No.	SNM18D00259C02	Excess (\$)	0.00		
	Assign From	MERIMEN (JOEL GOH)	Assign Date	24/01/2018		
2.		Vehicle Pa	rticulars & Condition			
	Make & Model		c.c	0		
	Engine No. HIDDEN Year of Reg.					
	Chassis No. Colour					
	Odometer - Steering					
	Brakes		Modification			
	General					
3.		Cond	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descri	ption of Damages			
5.	Engine No.	HIDERY Gene	eral Information			
	Accident Date	13/01/2018	Inspection Date	18/01/2018		
	Survey held at	PERFORMANCE MOTORS L				
	200000	303 ALEXANDRA ROAD SINGAPORE 159941				
400	a. Remarks					

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 2 May 2018 4:00 PM

To:

PBSP; Rasul (LKKAuto)

Cc:

SUR

Subject:

RE: URGENT REMINDER: FINAL REPORT / SGV313Z

Dear Caroline,

Confirm final fig \$14,286.69 before GST and 8 repair days.

Kindly send the relevant documents to China Taiping Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Friday, 27 April 2018 12:01 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: URGENT REMINDER: FINAL REPORT / SGV313Z

URGENT REMINDER

From: PBSP

Sent: Wednesday, 18 April 2018 5:24 PM

To: Rasul; SUR

Subject: FINAL REPORT / SGV313Z

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,737.00 Total Parts : 8,549.69

Total Labour & Parts: 14,286.69

Repair days: 9 days (CSA indicated 6 + additional 3 days for replacing tail end panel and mount on speed bench)

Ťhank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	15/01/2018 09:58
Date Of Accident	13/01/2018 18:10
Exact Location Of Accident	BRADDELL RD TWDS BISHAN FLYOVER
Country/State of Loss	SINGAPORE
M. P. All	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGV313Z
Insured/Policyholder	
Name Of Registered Owner	CHIA LAIN HENG
NRIC No	S1403826D
Email Address	LAINHENG@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96635779
Alternative Phone No	OFFICE-96667859
Vehicle Particulars	
Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1919088
Cover Note Number	
Driver	

Name of Driver SIM POH CHOO NRIC No S1554258F Date Of Birth 07/09/1962 Occupation INDOOR Date Of Driving Pass 14/05/1985 **Driving Experience**

32 YEARS AND 7 MONTHS

Gender **FEMALE**

Mobile Number (LOCAL) +65-96635779

Fax Number

Contact Number

EMail Address REJOICINGINHOPE7@GMAIL.COM Address

21 GOLDHILL PLACE

Postcode

308929

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: CHRISTOPHER CHIA

GENDER:

: MALE

Passenger 2

NAME:

: LOZARE RUTHCEL ARAND

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

BUKIT TIMAH NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC7948E

Vehicle Make/Model/Colour

LORRY GREY

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ANBALAGAN MURUGADASS

NRIC/Passport Number

G2500460X

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LOZARE RUTHCEL ARAND

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGV313Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (c) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Policyholder's Signature Date & Time:

15 JAN 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

15 JAN 2018

Reporting Centre Personnel's Signature

Name

NRIC/FIN No.:

15 JAN 2010

	,
~-	
	7
	J [P]]) >
	711111>
3913132	
	>
GBC7948E	
SLK 3407P	
DESCRIBE CIRCUMSTANC	CES OF THE ACCIDENT
refer to police	R report
DECLARATION I/We declare the foregoing particle.	articulars are true in every respect. MERINA CHIA SAN SA Performance Motors Limite 303 Alexandra Rada Sime barby Performance Cer Congapore 159941

15 JAN 2010

Page 5 of 42





Police Station Of Origin: Bukit Timah N.P.C 1 Duke's Road SINGAPORE 268914 Tel No: 1800-4629999 1 of 4 Report No. T/20180114/2109

REPORT	OF A	TRAFFIC	ACCIDENT

Date/Time Report Made: 14/01/2018 19:07			Vide Report No.:	Station Diary No. 56	
Informan	t's Partic	ulars		经产品 经通过 医胆管胆管 医胆管 医	
Name of SIM POH	Informant: CHOO		Address: 21 GOLDHILL PLACE	SINGAPORE 308929	
ID Type / ID No.: NRIC NO / S1554258F			Contact No.: Home/Office: Mobile: 96667859		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Age: Date of Birth: Female 55 07/09/1962			Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Housewife			Driving Licence Information: Class: 3 Date of Expiry:		

General Infor	mation of the Acci	dent		125	2 利益 支持使制制度		
Type of Accident:	Injury Others	Injury		others Drive: Accident:)	Type of Location: Y-Junction
Location: Along Road 1 BRADDELL F		vover					
Weather: Drizzling			Surface:	Road	d Speed Limit:		
Traffic Flow: One Way			Control: ontrolled	Traffi Light	ic Volume:		
Type of Collis Between Mov	ion: ring Vehicles - Head	To Rear			one conveyed by ulance:		

Details of V	Details of Vehicle Involved					
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBC7948E	Lorry				Seriously Damaged	6
SGV313Z	Car				Seriously Damaged	2
SLK3407R	Car				No Damage	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 4 Report No. T/20180114/2109

Police Station Of Origin: Bukit Timah N.P.C 1 Duke's Road SINGAPORE 268914 Tel No: 1800-4629999

CONTINUATION OF REPORT

Driver				5145	(Taristi	THE PARTY OF THE P
Name	SIM POH CHOO			ID No.		S1554258F
Related Vehicle	SGV313Z (Car)			Contact No.		96667859
Hospital/Clinic	NIL			Class of Class: 3 Driving Date of E Licence & Expiry Date		Class: 3 Date of Expiry: NIL
Date Treatment	NIL	NIL Date Di			NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of			t
Passenger		A STORES				
Name	LOZARE RUTHCEL	LOZARE RUTHCEL ARANO				G8522062X
Related Vehicle	SGV313Z (Car)			Contact No.		NIL
Hospital/Clinic	KHOO TECK PUAT HOSPITAL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	13/01/2018		Date Disc	harge	13/01	/2018
No. of Days grant	ed Medical Leave	NIL	Degree of		Serio	

Brief Details.

On 13/01/2018 at about 1810hrs, I was driving along Lane 1 of Braddell Road near Peck San Theng towards Bishan Flyover. A vehicle (SLK3407R) was in front of my vehicle signaling right but the driver drove to the left lane and drove back to my lane coming to a complete stop along the divider of Bishan Flyover.

I slowed my vehicle as I was afraid that the mentioned vehicle would overtake me instead, as such my vehicle was banged by another vehicle (GBC7948E) which was travelling behind me, causing my vehicle's rear screen and boot damaged badly. However the red vehicle did not stop to take a look and drove off to Bishan Flyover. But I felt that the red vehicle had caused the accident. There were in-car camera footages saved. My vehicle was then towed away.

Both of us exchanged particulars and agreed to settle the matter with the insurance company.

I wish to state that there was no Government property damaged but my helper seated at the rear passenger seat suffered a neck injury and was brought to Khoo Teck Puat Hospital. She was examined by the doctor at Khoo Teck Puat Hospital and informed that she suffered muscle strained and need to stay at home for observation and rest.

On 14/01/2018 at about 0700hrs, my helper vomited and informed that her vision was blur for distant sight. Both my 4th and 5th finger are strained and the pain comes on and off. At this point of time, I do not feel much pain and will seek the doctor if needed to. My son was seated at the front passenger seat and he seemed alright.



T/20180114/2109

Police Station Of Origin: Bukit Timah N.P.C 1 Duke's Road SINGAPORE 268914 Tel No: 1800-4629999

3 of 4 Report No. T/20180114/2109

CONTINUATION OF REPORT

Particulars of the driver who exchanged particulars with: Anbalagan Murugadass G2500460X **GBC7948E**

I am lodging this report for Traffic Police follow-up purposes.





Police Station Of Origin: Bukit Timah N.P.C 1 Duke's Road SINGAPORE 268914 Tel No: 1800-4629999

4 of 4 Report No. T/20180114/2109

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 1 CHAN WEI JIE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/01/2018 19:07
Officer In Charge Of Case: TP / AEIT / SSI 2 YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case: Signature:
Authentication Stamp NP168	note Police Force

Map data @2018 Google 100 m.L.



Page 10 of 42



BMW Dealer

Estimate No.

Date Estimated

Performance Motors Limited

45519

: 16/01/2018

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

: b1

(Per panel).

Sundries.

280, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)



150.00

GST REG. NO : M2 - 0020081 - X

ESTIMATE

76 JAN 2018

Page No. : 1 of 3

Prepared I			J
Chia Lair	TE REPAIR FOR - n Heng ill Place	- ACCOUNT - 40000 Cash Sales - Service Singapore	
Singapore	308929		
REGN. NO. SGV313Z	CHASSIS NO. REGN. DATE 5H48413 31/03/201		MILEAGE 0
	DESCRIPTION To replace rear bumper, bootlid including attachr etc and to knock out dented area caused by acci		(700 3,400,00
	To paint rear bumper, bootlid and tail end panel		(%0 \$ 2,666.00
	To tow accident vehicle to PML workshop.		195.00
	To supply rear emboss number plate.		50 83.00
	To remove and install boot compartment carpet a to facilitate repairs.	and garnish	230 271.00
	To check electrical wiring systems at the front se for proper function including adjustments of head		(50 177.00
	To replace rear windscreen glass including conduleak tests.	uct water	649.00
	To vacuum car interior to remove shattered glass (nett price)	debris	224.00
	To supply and install front or rear windscreen solo	ar film.	∧n× 531.00
	To transfer lock mechanism from old to new boot including conduct checks on new bootlid central I system for proper function.		45(531.00
	To replace front seat crash-active head restraint air bags including reset and conduct check for full	nction.	(50° 118.00
	To carry out body cavity preservation.		(00) 118.00

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel 63190528 (AfterSale 63190533/530 (Motorrad)

(AfterSales)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated

Prepared By

: b1 45519

: 16/01/2018

DECOUPING RING PDC TORQUE CONVERTER

CHASSIS NO.

: Merina Chia San San

MODEL

MILEAGE

0

Page No. : 2 of 3

REGN. NO. SGV313Z

5H48413

REGN. DATE 31/03/2017

X1 sDrive18i

Total Labour 1: 9.526.00 DESCRIPTION QTY PRIC VALUE Screw 3 0.75 2.25 SCREW SELF TAPPING 2 2.20 1.10 BLIND RIVET NUT M6 2.60 10.40 4 1,171.20 **BOOTLID** 1,171.20 1 74.05 **BOOTLID LH HINGE** 74.05 1 **BOOTLID RH HINGE** 74.05 74.05 1 REAR LH BUMPER MOUNT 141.65 141.65 REAR RH BUMPER MOUNT 141.65 141.65 RR BUMPER CARRIER 445.75 445.75 35.70 MOUNTING SMART OPENER 35.70 wt K REAR TRIM UNDERRIDE PROTECTION (X L 97.40 97.40 CPATT RR BUMPER LH CORNER MOUNTING 141.65 141.65 RR BUMPER RH CORNER MOUNTING 141.65 141.65 REAR BUMPER PANEL PRIMED 705.80 705.80 DE 222.35 REAR BUMPER MIDDLE TRIM PANEL (PDC) 1 222.35 REAR BUMPER TRIM BOTTOM (LINES) 1 211.75 SCA 211.75 ne - 1.60 EMBLEM GROMMET 2 0.80 BMW PLAQUE WITH ADHESIVE FILM 67.80 67.80 LETTERING X1 61.05 61.05 STRIKER BOOT LID 54.40 54.40 BOOT LID/TAILGATE PUSH BOTTON ICAM 46.05 46.05 SPINDLE DRIVE 2 333.90 667.80 7 Retaining br 25.25 25.25 7 Retaining br 25.25 25.25 LOCK TRUNK LID 222.45 222.45 1 7 SOFT CLOSE AUTOMATIC 572.30 572.30 1 32.50 BUMP STOP 10 3.25 nn 132.60 REAR BUMPER TOWING EYE COVER 1 32.60 832.15 REAR WINDOW (ESG) 1 832.15 XSVL7. 28.00 HOOK AND LOOP FASTENER 10 2.80 LOADING SILL COVER 1 137.00 137.00 **BOOTLID SEALING** 119.20 119.20 1 MM Guide, headr 2 39.50 79.00 REAR LH REFLECTOR 1 35.40 35.40 gre cat \$35.40 43.00 REAR RH REFLECTOR 35.40 REAR WIPER BLADE 43.00 x82 7. 309.85 REAR WINDOW WIPER MOTOR 309.85 REAR WINDOW WIPER ARM 59.40 59.40 out 10.50 WIPER ARM COVER 10.50 SPRAY NOZZLE 25.50 25.50 254.85 REAR LH LIGHT IN TRUNK LID 254.85 254.85 REAR RH LIGHT IN TRUNK LID 1 254.85 XSUL7. REAR LH LIGHT IN THE SIDE PANEL 364.00 364.00 REAR RH LIGHT IN THE SIDE PANEL 364.00 CRA 364.00 THIRD STOPLAMP 176.70 176.70 NUMBER-PLATE LIGHT LED 2 24.85 49.70

4

5.05

20.20

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel 63190528 (AfterSal 63190533/530 (Motorrad Fax. 64796601 (AfterSal 64796624 (Motorrad

(Motorrad) (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1

45519

: 16/01/2018

Page No. : 3 of 3

0

Date Estimated Prepared By

: Merina Chia San San

CHASSIS NO.

REGN. DATE

MODEL.

MILEAGE

REGN. NO. SGV313Z

5H48413

31/03/2017

X1 sDrive18i

DESCRIPTION

(DG) CLEANER R1 (100ML)

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

(DG/SL) GLASS PRIMER 30ML (VP206)

PRIC QTY 23.85 131.55 2 27.85 1

263.10 27.85

Total Parts

8,942.05

VALUE

23.85

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21698.14

Labour 1 Parts

9,526.00 8,942.05

Labour 2 Excess

0.00 0.00

1,292.76

Total GST @ 7%

19,760.81

Grand Total

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No		SEV 313Z	
Chassis No	:	5H 48413	1238468
SA Name		Mering	
		2017	

Model Year

Quotation No : 0000480026 Date : 22/01/2018 Time : 08:52:54 Page : 1

Partsman : p971om1 nel 00 : 003438501

			STK POC		SELLING		NET
SIN	PART NUMBER	DESCRIPTION	CT AT SOH		PRICE		PRICE
00 May 16	F	****	THE WAY BY A	PARK	******	CARR BE	K-13-13-13-13
1	72117401714	(DG) FRT RH UPPER	P_/	1.	298.15	ACT.	298.15
			/)

CSA Signature Date Time	Parts Total Labour Charges		298.15
	Sub Total Add 7% GST		
Customer's Name or Contact Person	TOTAL AMOUNT	4	

- Note: (1) The above quotation is vased on visual inspection only and may change pased on further checks.
 - (2) The validity of this quotation is 14 days from the above date.
 - (x) Parts are subject to availability.
 - (4) Any prices change is without prior notice.

he quotation is acceptable to you, please confirm your authorization for oroceed with the jou on the uncerstanding that prior approval will be from you before we carry out any further repair or replacement of

01.9

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No Chassis No CSA Name Model Year		56V313Z 5H48413 Mering 2017	123	38	468	Date Time Page	sman	No :	000048 30/01/ 13:42: p971om 003444	2018 03 1
S/N PEUT NUME 1 721174017	5 805	DESCRIPTION (DB) FRT LH UP			AT SOH	ISS, QTX		LING PRICE	01S	PRICE 38.15

CSA Signature	1
Date	2
Time	3
Customer's Name or Contact Person	

Parts Total : 298.15 Labour Charges :

Sub Total

8 7% 8ST :

TOTAL AMOUNT :

Note: (1) The above quotation is based on visual inspection only and may change

- hased on further shecks.
 (2) The validity of this quotation is 14 days from the above date.
- (8) Parts are subject to availability.
- 4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for us to proceed with the job on the uncerstanding that prior approval will be obtained from you before we carry out any further repair or replacement of

1 2	3 ==		The second second second			
Integrated Service Technical Application	ice Technical				•	×
VIN 5H48413	Vehicle X/F48/off-	road vehicle/X1 sDriv	Vehicle XYF48/off-road vehicle/X1 sDrive18i/B38/AUTO/ECE/RU/2016/11	RL/2016/11	KL 15: 1	14.8 V KL 30: 14.8 V
Operations	Vehicle information	Vehicle management	Service plan	Favourites	Workshop/ Operating fluids	Measuring devices
Repair/ maintenance	Troubleshooting	Service functions	Software update	Control Unit Replacement	Vehicle modification	
Fault memory	Fault patterns	Function	Component Structure	Text Search	SAE fault code input	
Code	Description			Mileage	Existent	Class
804876	Output, rear left indicator faulty	ulty		8151	No.	4
80487F	Output, left rear fog light faulty	ılty		8151	oN.	
804880	Output, right rear fog light faulty	aulty		8151	°Z	
804881	Left reversing light output faulty	Anthy		8151	No	
804882	Right reversing light output faulty	faulty		8151	oN.	
8048A1	Rear wiper. Relay sticking			8150	Š	
8048A3	Rear wiper. Either a fault or wiper		reset contact does not activate (rear wiper is blo	iper is blo 8150	No	
930AB6	Crash message stored			8149	o _N	
930B05	Retractor tensioner, driver: Short	Short circuit to negative	9	8149	No	
930808	Retractor tensioner, front passenger. Short circuit to negative	assenger. Short circuit	to negative	8149	yes	
B7F85A	Headunit connection to aerial amplifier: Line disconnection, FM1 aerial	ial amplifier. Line disco	onnection, FM1 aerial	8150	o N	
B7F85B	Aerial amplifier connection to aerial: Line disconnection, FM1 aerial	to aerial: Line disconn	ection, FM1 aerial	8149	ON.	
Number of fault memories:	25 / 25	No. fault patterns: 0	Filter. Default			
Show fault code	node Delete fault memory	Filter fault memory	Totales Core	Chouse completely	Dull'A moneymen	Calculate teet plan

8

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No.

b1 45519

Date Estimated :

16/01/2018

Prepared By

Merina Chia San San

REPAIR FOR -

- ACCOUNT -

135

Page Nb. :

Chia Lain Heng

21 Goldhill Place

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 308929

REGN NO

CHASSIS NO

REGN DATE

MODEL

M LEAGE

SGV313Z

5H48413

31/03/2017

X1 sDrive18i

0

DESCRIPTION

ORIGINAL PRICE

DISC. %

NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
				RA/
TAIL PANEL *	401.75	1.00		401.75
EXPANDING NUT *	1.00	4.00		4.00
REAR WINDOW SHELF (SCHWARZ) *	459.00	1.00		459.00
LH TRIM C/D PILLAR (GRAU) *	194.60	1.00		194.60
RH TRIM C/D PILLAR (GRAU) *	191.10	1.00		191.10at
REAR BUMPER HEAT INSULATION *	66.20	1.00		66.20 Rf
LOWER TAIL LID TRIM PANEL (SCHWARZ) *	169.55	1.00		169.55
LH TRUNK LID PANEL TRIM (EVERESTGRA*	32.40	1.00		32.40ct
RH TRUNK LID PANEL TRIM (EVERESTGRA *	32.40	1.00		32.40cm
AEROBLADE (SCHWARZ) *	357.00	1.00		357.00 W
EXPANDING RIVET *	1.35	20.00		27 00
PLUG BLACK D=5MM *	0.90	10.00		90000
(DG) FRT LH UPPER BELT (SCHWARZ) *	298.15	1.00		298.15
	298.15	1.00		298.15 MI
(DG) FRT RH UPPER BELT (SCHWARZ) *	0.55	30.00		16.50 New
BLIND RIVET AVIBVLB *	0.55	10.00		5.50 W
BLIND RIVET AVIBVLB *	281.55	1.00		281.55
(DG/SL) BODY ADHESIVE K5B (195ML) *				22.00
# PUNCH RIVET N4 *	0.55	40.00		67.60 N
# (S/L) SEAM SEAL 300ML *	33.80	2.00		07.00

3M S/F PREMIUM RR WINDSCHEEN URA) A Rear Wiper Blade Lut)

Total Labour: 2,933.45 Total Parts: 2,933.45 Total Labour & Parts: 252.34 3, 185.79 44.60 3,230.39

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45519

Dat e Est i mat ed : 16/01/2018

Prepared By :

Merina Chia San San

REPAIR FOR -

Chia Lain Heng 21 Goldhill Place - ACCOUNT -

135

Page No. :

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 308929

EGN NO		TEGN DATE 31/03/2017	MCDEL X1 sDrive18i		M LEA	Œ
DESCRIPTION			ORIGIN	AL PRICE	DISC. %	NETT
boot lid and attac sill cover, rear Rh panel include to	oumper and attachments, to chments, LH/RH trim C/D p H light in trunk lid, rear RH l pull and straighten on acci at dents caused by the acci	oillar, loading ight in side dent areas		1700.00		1,700.00
To spray paint re	ear bumper, boot lid and tai	l end panel		1805.00		1,805.00
To tow accident	vehicle to PML workshop.			195.00		195.00
To supply rear e	emboss number plate.			83.00		83.00
To remove and i	install boot compartment c ate repairs	arpet and		230.00		230.00
To check electri for proper functi	ical wiring systems at the fron including adjustments o	ont section of headlights.		150.00		150.00
To replace rear water leak tests	windscreen glass include c	onducting		649.00		649.00
To vacuum car i (nett price)	nterior to remove shattered	d glass debris		224.00		224.00
	mechanism from old to ne ting checks on new boot lid er function			451.00		451.00
To carry out boo (For cut panel)	dy cavity preservation.			100.00		100.00
Sundries.				150.00		150.00
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET N 3M S/F PREMIL	IUT M6 JM RR WINDSCREEN		2.60 252.34	4.00 1.00		10.40 252.3

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

BOOTLID # TAIL PANEL * # EXPANDING NUT * RR BUMPER CARRIER MOUNTING SMART OPENER REAR TRIM UNDERRIDE PROTECTION (X L RR BUMPER LH CORNER MOUNTING RR BUMPER RH CORNER MOUNTING REAR BUMPER PANEL PRIMED REAR BUMPER MIDDLE TRIM PANEL (PDC) REAR BUMPER TRIM BOTTOM (LINES) EMBLEM GROMMET BMW PLAQUE WITH ADHESIVE FILM	1,171.20 401.75 1.00 445.75 35.70 97.40 141.65 141.65 705.80 222.35 211.75 0.80 67.80	1.00 1.00 4.00 1.00 1.00 1.00 1.00 1.00	1,171.20 401.75 4.00 445.75 35.70 97.40 141.65 141.65 705.80 222.35 211.75 1.60 67.80
LETTERING X1	61.05	1.00	61.05
BUMP STOP	3.25	10.00	32.50
REAR WINDOW (ESG)	832.15	1.00	832.15 459.00 Up cut
# REAR WINDOW SHELF (SCHWARZ) *	459.00	1.00	
# LH TRIM C/D PILLAR (GRAU) *	194.60	1.00	194.60 Mark
# RH TRIM C/D PILLAR (GRAU) *	191.10	1.00	191.10 (hart)
LOADING SILL COVER	137.00	1.00	137.00 66.20 Unde
# REAR BUMPER HEAT INSULATION *	66.20	1.00	169.55 4761
# LOWER TAIL LID TRIM PANEL (SCHWARZ) *	169.55	1.00	
# LH TRUNK LID PANEL TRIM (EVERESTGRA*	32.40	1.00	32.40 Unde/ 32.40 Unde/
# RH TRUNK LID PANEL TRIM (EVERESTGRA *	32.40	1.00	32.40 Wals
# AEROBLADE (SCHWARZ) *	357.00	1.00	357.00 ml
# EXPANDING RIVET *	1.35	20.00	9.00 May
# PLUG BLACK D=5MM *	0.90	10.00	6 44.60 Up aut
REAR WIPER BLADE	44.60	1.00	
REAR WINDOW WIPER ARM	59.40	1.00	59.40
WIPER ARM COVER	10.50	1.00	10.50
REAR RH LIGHT IN TRUNK LID	254.85	1.00	254.85
REAR RH LIGHT IN THE SIDE PANEL	364.00	1.00	364.00
# (DG) FRT LH UPPER BELT (SCHWARZ) *	298.15	1.00	298.15
# (DG) FRT RH UPPER BELT (SCHWARZ) *	298.15	1.00	298.15
# BLIND RIVET AVIBVLB *	0.55	30.00	/ 16.50 (B) NO
# BLIND RIVET AVIBVLB *	0.55	10.00	5.50 Mu
# (DG/SL) BODY ADHESIVE K5B (195ML) *	281.55	1.00	/ 281.55 (M) NET
# PUNCH RIVET N4 *	0.55	40.00	22.00 chiles
(DG) CLEANER R1 (100ML)	23.85	1.00	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85
# (S/L) SEAM SEAL 300ML *	33.80	2.00	67.60 Chall
TOTAL OUT THE OUT THE			

SUPPLEMENTARY ITEMS

Total Labour:	5,737.00
Total Parts :	8,549.69
Total Labour & Parts :	14,286.69
Deduction for Excess:	0.00
Total Repair Costs less Excess:	14,286.69
GST @7%:	1,000.07
Grand Total:	15,286,76

...CLAIM SUBFOLDER...(Pending for Survey Report)

ATM SUBF	OLDER TRA	CKING		1.1:0-4		Adi Si	bmitted	Ins Auth'ed	Status		
Case	Notified	Est Submitted	Adj Assigned 17 Jan 2018 15:18	Adj Rpt S\$14,28		5\$14	286.69		Pending Report Cancel C		vey
Main	16 Jan 2018		Edit Adj Rpt	Edit Esti	mates	View	Rpt		Cancer		w All
-	1ain	R	eference	C	aim Det		1	Documents		Sho	WAII
	BFOLDER D	FTAILS					[Created	by insurer]			
nsured:	YUAN XI	ANG PTE LTD,	Co. Reg. No.: -								
Main Claimant:		IN HENG, ID: S				Lanna	13/01/201	8 18:00 - :59	TA Rea Da	ite (Man	Yr)]
ehicle Reg	SGV31	3Z			Date of	111201100		and 13 Days From		ite (rion	
No.: Claim Type	: TP / SN	IM18D00259C0	2		Policy/C		DMCVSN3	076691700 (Comp	orenensive)		
Vehicle Re	-										
No. (Insured):	(Car 10 10 - CO 11 1 C				Excess	:	S\$0.00		roods Alexan	dra - Te	1:
Repairer:	Perform	nance Motors Lin 72/63190174	nited (Alexandra)	303 Alexand	ira Road,	Sime I	Darby Perfo	rmance Centre, 1	59941 Alexan	ura re	
Handling Insurer:	China T	aiping Insuranc	(Singapore) Pte	Ltd. (HQ)	- Tel: 63	89 611	1 [Handl	ed by Joel Gonj			
Claimant's Insurer:	AXA In	surance Pte Ltd	(HQ) - Tel: 6338 72 te Ltd (HQ) - Tel:	288	fHand	ed by I	MOHD RAS	SUL] [Final R	pt due 26/	01/201	.8]
Adjuster:	LKK Au	to Consultants F	te Ltd (HQ) - Tel:	6230-3301	ii Li idire.						
Driver/Cu dian (Insured)		GAN MURUGADAS	S (25 / Male), NR	IC: G25004	60X, Te	el: +65	84607648				
Adj Asg. Remarks:	EST- \$	19,760.81 , ASSIG	N LKK AS SJE.						/iew All	Compose	Case Mail
ASSOCI	ATED MAIL	RECEIVED						_			
There are	no mail for	this case.						1	Create New	Task	Complete
ALL AS		_	ask Group Sut	oject Ha	ndler	Assi	View All gned By	Search Tasks Completed C		ted On	Done

Claim Documents

*SGV313Z (SNM18D00259C02)

[GBC7948E]

TP

CHIA LAIN HENG

Jan 13 2018 6:00PM

[YUAN XIANG PTE LTD]

Performance Motors Limited

Vide	90		1 per p	page 🔻	~
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	15/01/18 10:12	Video - Accident [Linked Accident Report Documents]	0	Load AVI	
Ass	essment Reports		1 per	page 🔽	☑
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	15/01/18 10:17	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per	page 🔻	V
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
2	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
3	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
4	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
5	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
6	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
7	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	6	Load JPG	V
8	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
9	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
10	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
11	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
12	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
13	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
14	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
15	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
16	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
17	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
18	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
19	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
20	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
21	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
22	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V

deo	1 per page V				
		Performance Motors Limited (Alexandra)	0	Thumbnail Load JPG	Print
	Finalized On 15/01/18 10:11	Accident Photo [Linked Accident Report Documents]			V
4	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG Load JPG	Z Z
5	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
6	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0		V
7	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	
8	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Z
9	15/01/18 10:11	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
	15/01/18 10:11	Accident Photo	0	Load JPG	☑
30		[Linked Accident Report Documents] Accident Photo	0	Load JPG	✓
31	15/01/18 10:11	[Linked Accident Report Documents] Accident Photo	0	Load JPG	✓
32	15/01/18 10:11	[Linked Accident Report Documents]		Thumbnail	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load JPG	<u>~</u>
1	02/05/18 16:06	Odometer Reading	0	Load JPG	✓
2	02/05/18 16:06	Chassis Number	0	Load JPG	V
3	02/05/18 16:06	General View General View	0	Load JPG	V
4	02/05/18 16:06	General View General View	0	Load JPG	V
5	02/05/18 16:06	General View	0	Load JPG	V
6	02/05/18 16:06	General View	0	Load JPG	V
7	02/05/18 16:06	General View	0	Load JPG	-
8	02/05/18 16:06	General View	0	Load JPG	-
9	02/05/18 16:06	General View	0	Load JPG	-
10	02/05/18 16:06	General View	0	Load JPG	_
11	02/05/18 16:06	General View	0		-
12	02/05/18 16:06	General View	0		
13	02/05/18 16:06	General View	0		-
14		General View	0		_
15		General View	0	Load JPG	_
16		General View	•		-
17		General View	•		
18		General View	•	The second second	-
19		General View	•		_
20		General View			
21		General View		S 10 70-46	-
22		General View			
23		General View		20 minutes	-
24		General View			-
2		General View		Load JP	
2		General View		Load JP	
	8 02/05/18 16:06				
	9 02/05/18 16:06				
	02/05/18 16:06	Consent Views		Load JF	_
	02/05/18 16:06	110		_	
-	32 02/05/18 16:06				_
	33 02/05/18 16:06			_	
-	33 02/03/18 16:00			Load J	
1	35 02/05/18 16:00			_	PG

Vid	90		1 per page	∠
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbn	ail Prin
37	02/05/18 16:06	General View	1 Load JP	G ✓
38	02/05/18 16:06	General View	1 Load JP	G
39	02/05/18 16:06	General View	■ Load JP	G ✓
10	02/05/18 16:06	General View	€ Load JP	G ✓
11	02/05/18 16:06	General View	1 Load JP	G ✓
12	02/05/18 16:06	General View	1 Load JP	G ∡
43	02/05/18 16:06	General View	1 Load JP	G ✓
44	02/05/18 16:06	General View	1 Load JP	G ✓
45	02/05/18 16:06	General View	1 Load JP	G ✓
46	02/05/18 16:06	General View	Load JP	G ✓
47	02/05/18 16:06	General View	1 Load JP	G √
48	02/05/18 16:06	General View	1 Load JP	G ✓
49	02/05/18 16:06	General View	1 Load JP	G 👿
50	02/05/18 16:06	General View	Load JP	G 🔽
51	02/05/18 16:06	General View	Load JP	G 🔽
52	02/05/18 16:06	General View	Load JP	
53	02/05/18 16:06	General View	Load JP	G 🔽
54	02/05/18 16:06	General View	Load JP	-
55	02/05/18 16:06	General View	Load JP	_
56	02/05/18 16:06	General View	Load JP	-
57	02/05/18 16:06	General View	Load JP	
58	02/05/18 16:06	General View	1 Load JP	
59		General View	1 Load JP	
	02/05/18 16:06	General View	1 Load JP	
60	02/05/18 16:06	General View	■ Load JP	-
61	02/05/18 16:06	General View	■ Load JP	-
62	02/05/18 16:06	General View	■ Load JP	-
63	02/05/18 16:06		1 Load JP	
64	02/05/18 16:06	General View	■ Load JP	
65	02/05/18 16:06	General View	1 Load JP	-
66	02/05/18 16:06	General View	1 Load JP	
67	02/05/18 16:06	General View	€ Load JP	
68	02/05/18 16:06	General View	1 Load JP	
69	02/05/18 16:06	General View	1 Load JP	
70	02/05/18 16:06	General View		_
71	02/05/18 16:06	General View		
72	02/05/18 16:07	Reinspection Photo	1 Load JP	
73	02/05/18 16:07	Reinspection Photo	1 Load JF	
74	02/05/18 16:07	Reinspection Photo	1 Load JP	
75	02/05/18 16:07	Reinspection Photo	1 Load JF	
76	02/05/18 16:07	Reinspection Photo	1 Load JF	-
77	02/05/18 16:07	Reinspection Photo	1 Load JF	_
78	02/05/18 16:07	Reinspection Photo	1 Load JF	
79	02/05/18 16:07	Reinspection Photo	1 Load JF	7
80	02/05/18 16:07	Reinspection Photo	1 Load JF	
81	02/05/18 16:07	Reinspection Photo	① Load JF	
82	02/05/18 16:07	Reinspection Photo	Load JF	_
83	02/05/18 16:07	Reinspection Photo	1 Load JF	_
84	02/05/18 16:07	Reinspection Photo	① Load JF	200
85	02/05/18 16:07	Reinspection Photo	€ Load JF	
86	02/05/18 16:07	Reinspection Photo	1 Load JF	PG S

tel -			1 per p	ge 🗸	Print	
ide	20	Performance Motors Limited (Alexandra)	0	Load JPG	V	
	Finalized On 02/05/18 16:07	Reinspection Photo	0	Load JPG	V	
	02/05/18 16:07	Reinspection Photo		Load JPG	V	-
-	02/05/18 16:07	Reinspection Photo	0	Load JPG	V	-
		Reinspection Photo	0		V	_
0	02/05/18 16:07	Reinspection Photo	0	Load JPG	₹	
1	02/05/18 16:07	Reinspection Photo	0	Load JPG	-	_
2	02/05/18 16:07	Reinspection Photo	0	Load JPG	V	
3	02/05/18 16:07	Reinspection Photo	0	Load JPG	V	-
14	02/05/18 16:07	Reinspection Photo	0	Load JPG	V	-
5	02/05/18 16:07	Reinspection Photo	0	Load JPG	∀	
96	02/05/18 16:07	Reinspection Photo	0	Load JPG	-	_
97	02/05/18 16:07		0	Load JPG	-	-
98	02/05/18 16:07	Reinspection Photo	0	Load JPG	-	
99	02/05/18 16:07	Reinspection Photo	0	Load JPG	_	
100		Reinspection Photo	0	Load JPG	_	_
101	02/05/18 16:07	Reinspection Photo	0	Load JPG	-	/
102	02/05/18 16:07	Reinspection Photo	0	Load JPC	111	Z
103	02/05/18 16:07	Reinspection Photo	0	Load JPC	6	/
104	4 02/05/18 16:07	Reinspection Photo	0	Load JPC	3 6	Y
105	5 02/05/18 16:07	Reinspection Photo	0	Load JP	5 6	V
10	6 02/05/18 16:07	Reinspection Photo	0	Load JP	3 E	V
10	7 02/05/18 16:07	Reinspection Photo	0	Load JP	G [√
10	8 02/05/18 16:07	Reinspection Photo	6	Load JP	G [✓
10	9 02/05/18 16:07	Reinspection Photo	6	Load JP	G [√
11	0 02/05/18 16:07	Reinspection Photo	0	Load JP	G I	V
11	1 02/05/18 16:07	Reinspection Photo			G I	V
11	12 02/05/18 16:07	Reinspection Photo			G	V
11	13 02/05/18 16:07	Reinspection Photo			G	V
	14 02/05/18 16:07	Reinspection Photo			_	V
-	15 02/05/18 16:07	Reinspection Photo	-			~
	16 02/05/18 16:07	Reinspection Photo		Load J	-	V
	17 02/05/18 16:07	Reinspection Photo		Load J		V
-	18 02/05/18 16:07	Reinspection Photo				V
-	19 02/05/18 16:07	Reinspection Photo				V
-	20 02/05/18 16:07	Reinspection Photo				V
		Reinspection Photo			-	V
-	21 02/05/18 16:07	Reinspection Photo		Load 3		V
	22 02/05/18 16:07	Reinspection Photo		Load :	-	Y
-	02/05/18 16:07	Reinspection Photo		Load .		Y
- 1-	124 02/05/18 16:07	Reinspection Photo		Load		2
-	125 02/05/18 16:07	Reinspection Photo		1 Load	_	-
-	126 02/05/18 16:07	Reinspection Photo		1 Load		5
	127 02/05/18 16:07	-1.4		1 Load		5
- 1-	128 02/05/18 16:07			1 Load		6
	129 02/05/18 16:07			1 Load	11.7.1	5
	130 02/05/18 16:07	- Al Photo		1 Load		[
	131 02/05/18 16:07	nt ata		Load	JPG	[
	132 02/05/18 16:07	The state of the s		1 Load	_	E
	133 02/05/18 16:07			1 Load		1
	134 02/05/18 16:07			1 Load	JPG	
	135 02/05/18 16:0	Reinspection Photo		1 Load	JPG	

Vide	10		1 per p	page 🔻	4
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
137	02/05/18 16:07	Reinspection Photo	0	Load JPG	✓
138	02/05/18 16:07	Reinspection Photo	Ð	Load JPG	✓
139	02/05/18 16:07	Reinspection Photo	0	Load JPG	V
140	02/05/18 16:07	Reinspection Photo	0	Load JPG	✓
141	02/05/18 16:07	Reinspection Photo	0	Load JPG	V
142	02/05/18 16:07	Reinspection Photo	0	Load JPG	✓
143	02/05/18 16:07	Reinspection Photo	0	Load JPG	V
144	02/05/18 16:07	Reinspection Photo	0	Load JPG	✓
145	02/05/18 16:07	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/01/18 15:17	OI GIA REPORT	0	Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	15/01/18 10:09	Sketch Plan [Linked Accident Report Documents]	0	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/08/18 10:31	Supplementary	0	Load PDF	

Linked Accident Report Documents

			View View in Br	man 1
Vide	0		T per page	☑
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbn	
1	15/01/18 10:12	Video - Accident	1 Load AV	I
Asse	essment Reports		1 per page	<u> </u>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbn	
1	15/01/18 10:17	Accident Statement	1 Load HT	М
Pho	tos/Images		3 per page	✓ ✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbn	ail Print
1	15/01/18 10:11	Accident Photo	Load JP	G ✓
2	15/01/18 10:11	Accident Photo	Load JP	_
3	15/01/18 10:11	Accident Photo	Load JP	
4	15/01/18 10:11	Accident Photo	Load JP	G ✓
5	15/01/18 10:11	Accident Photo	Load JP	
6	15/01/18 10:11	Accident Photo	■ Load JP	G ✓
7	15/01/18 10:11	Accident Photo	■ Load JP	
8	15/01/18 10:11	Accident Photo	1 Load JP	G ☑
9	15/01/18 10:11	Accident Photo	1 Load JP	-
10	15/01/18 10:11	Accident Photo	1 Load JP	
11	15/01/18 10:11	Accident Photo	1 Load JP	G ✓
12	15/01/18 10:11	Accident Photo	1 Load JP	
13	15/01/18 10:11	Accident Photo	1 Load JP	- hand
14	15/01/18 10:11	Accident Photo	Load JP	G ☑
15	15/01/18 10:11	Accident Photo	Load JF	G ☑
16	15/01/18 10:11	Accident Photo	■ Load JF	
17	15/01/18 10:11	Accident Photo	1 Load JF	
18	15/01/18 10:11	Accident Photo	■ Load JF	G 🗹
19	15/01/18 10:11	Accident Photo	1 Load JF	_
20	15/01/18 10:11	Accident Photo	1 Load JF	
21	15/01/18 10:11	Accident Photo	1 Load JF	G 🔽

Vid	Video		1 per p	age 🗸	V
	770	Performance Motors Limited (Alexandra)	-	Thumbnail	Print
No 22	Finalized On 15/01/18 10:11	Accident Photo	0	Load JPG	V
23	15/01/18 10:11	Accident Photo	Ð	Load JPG	V
24	15/01/18 10:11	Accident Photo	0	Load JPG	~
25	15/01/18 10:11	Accident Photo	0	Load JPG	~
26	15/01/18 10:11	Accident Photo	0	Load JPG	V
27	15/01/18 10:11	Accident Photo	0	Load JPG	✓
28	15/01/18 10:11	Accident Photo	0	Load JPG	¥
29	15/01/18 10:11	Accident Photo	0	Load JPG	V
30	15/01/18 10:11	Accident Photo	0	Load JPG	V
31	15/01/18 10:11	Accident Photo	0	Load JPG	V
32	15/01/18 10:11	Accident Photo	0	Load JPG	✓
				Text	
Do	cumentation		1 per	_	V
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	15/01/18 10:09	Sketch Plan	0	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18001418/R1QD3E2

Date:

23/08/2018

No:

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMCVSN3076691700

Claimant Vehicle

SGV313Z No:

Insured Vehicle No:

GBC7948E

Date of Loss:

13/01/2018

Nature of Claim: TP

Claim

SNM18D00259C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGV313Z

Make & Model:

BMW X1, 1.5 SDRIVE 18I (A)

Engine No:

G351H435B38A15A

Reg. Date:

31/03/2017 (Man. Year: 2017) Blue

Chassis No: Odometer:

WBAHS120005H48413 8149 km

Colour: Engine Capacity:

1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

225/50 R18

Rear Tyre Size:

225/50 R18

Front Left Side:

Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,405.44	8,782.69	3,622.75	29.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,293.00	5,504.00	3,789.00	40.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,698.44	14,286.69	7,411.75	34.16
+ GST 7.00/7.00% (S\$)	1,518.89	1,000.07	518.82	34.16
Nett Amount (S\$)	23,217.33	15,286.76	7,930.57	34.16

INSPECTION

Date of Assignment:

17/01/2018

Date Inspected:

18/01/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

8.0 days

Adjuster Report

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 5 Adjuster Report

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 23 Aug 2018) Part Source: MRM-SG

BMW X1 1.5 SDRIVE 18I (A) (Catalogue:Merimen Singapore 1.0) Parts: M1-SUV

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SGV313Z)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

ec	ommen	ded Parts	Condition	Repairer's	Amount
0. (Qty Part N	o. Particulars	Scratched	83.00 FS	*83.00 FS
	1	*REAR EMBOSS NUMBER PLATE	Necessary	150.00 FS	*150.00 FS
	1	*SUNDRIES	Not Necessary	2.25 FS	*-FS
	3	*SCREW	Not Necessary	2.20 FS	*- FS
-	2	*SCREW SELF TAPPING	Necessary	10.40 FS	*10.40 FS
	4	*BLIND RIVET NUT M6	Bent	1,171.20 FS	*1,171.20 FS
	1	*BOOTLID	Serviceable	74.05 FS	*-FS
	1	*BOOTLID LH HINGE	Serviceable	74.05 FS	*-FS
	1	*BOOTLID RH HINGE	Serviceable	141.65 FS	*- FS
	1	*REAR LH BUMPER MOUNT	Serviceable	141.65 FS	*-FS
0	1	*REAR RH BUMPER MOUNT	Bent	445.75 FS	*445.75 FS
1	1	*RR BUMPER CARRIER	Necessary	35.70 FS	*35.70 FS
2	1	*MOUNTING SMART OPENER	Cut	97.40 FS	*97.40 FS
3	1	*REAR TRIM UNDERRIDE PROTECTION (X L	Cracked	141.65 FS	*141.65 FS
4	1	*RR BUMPER LH CORNER MOUNTING	Cracked	141.65 FS	*141.65 FS
15	1	*RR BUMPER RH CORNER MOUNTING	Deformed	705.80 FS	*705.80 FS
6	1	*REAR BUMPER PANEL PRIMED	Deformed	222.35 FS	*222.35 FS
17	1	*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Scratched	211.75 FS	*211.75 FS
18	1	*REAR BUMPER TRIM BOTTOM (LINES)	Necessary	1.60 FS	*1.60 FS
19	2	*EMBLEM GROMMET	Necessary	67.80 FS	*67.80 FS
20	1	*BMW PLAQUE WITH ADHESIVE FILM	Necessary	61.05FS	*61.05 FS
21	1	*LETTERING X1	Serviceable	54.40 FS	*- FS
22	1	*STRIKER BOOT LID	Serviceable	46.05 FS	*- FS
23	1	*BOOTLID / TAILGATE PUSH BOTTON ICAM	Serviceable	667.80 FS	*- FS
24	2	*SPINDLE DRIVE	Serviceable	25.25 FS	*- FS
25	1	*RETAINING BR	Serviceable	25.25 FS	*- FS
26	1	*RETAINING BR	Serviceable	222.45FS	*- FS
27	1	*LOCK TRUNK LID	Serviceable	572.30 FS	
28	1	*SOFT CLOSE AUTOMATIC	Necessary	32.50 FS	
29	10	*BUMP STOP	Not Necessary		
30	1	*REAR BUMPER TOWING EYE COVER	Necessary	832.15 FS	
31	1	*REAR WINDOW (ESG)	Serviceable	28.00 FS	
32	10	*HOOK AND LOOP FASTENER	Deformed	137.00 FS	
33	1	*LOADING SILL COVER	Serviceable	119.20 FS	
34	1	*BOOTLID SEALING	Serviceable	79.00 FS	
35	2	*GUIDE, HEADR	Serviceable	35.40 FS	
36	1	*REAR LH REFLECTOR	Serviceable	35.40 FS	
37	1	*REAR RH REFLECTOR	Serviceable	43.00 FS	
38	1	*REAR WIPER BLADE	Serviceable	309.85 FS	
39	1	*REAR WINDOW WIPER MOTOR	Serviceable	303.031	

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR WINDOW WIPER ARM	Scratched	59.40 FS	*59.40 FS
41	1		*WIPER ARM COVER	Cut	10.50 FS	*10.50 FS
42	1		*SPRAY NOZZLE	Serviceable	25.50 FS	*-FS
43	1		*REAR LH LIGHT IN TRUNK LID	Serviceable	254.85 FS	*-FS
44	1		*REAR RH LIGHT IN TRUNK LID	Broken	254.85 FS	*254.85 FS
45	1		*REAR LH LIGHT IN THE SIDE PANEL	Serviceable	364.00 FS	*- FS
46	1		*REAR RH LIGHT IN THE SIDE PANEL	Cracked	364.00 FS	*364.00 FS
47	1		*THIRD STOPLAMP	Serviceable	176.70 FS	*-FS
48	2		*NUMBER-PLATE LIGHT LED	Serviceable	49.70 FS	*- FS
49	4		*DECOUPING RING PDC TORQUE CONVERTER	Serviceable	20.20 FS	*- FS
50	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
51	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
52	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
53	1		*TAIL PANEL	Bent	401.75 FS	*401.75 FS
54	4		*EXPANDING NUT	Necessary	4.00 FS	*4.00 FS
55	1		*REAR WINDOW SHELF (SCHWARZ)	Scratched	459.00 FS	*459.00 FS
56	1		*LH TRIM C/D PILLAR (GRAU)	Cut	194.60 FS	*194.60 FS
57	1		*RH TRIM C/D PILLAR (GRAU)	Cut	191.10 FS	*191.10 FS
58	1		*REAR BUMPER HEAT INSULATION	Bent	66.20 FS	*66.20 FS
59	1		*LOWER TAIL LID TRIM PANEL (SCHWARZ)	Deformed	169.55 FS	*169.55 FS
60	1		*LH TRUNK LID PANEL TRIM (EVERESTGRA	Cut	32.40 FS	*32.40 FS
61	1		*RH TRUNK LID PANEL TRIM (EVERESTGRA	Cut	32.40 FS	*32.40 FS
62	1		*AEROBLADE (SCHWARZ)	Cut	357.00 FS	*357.00 FS
63	20		*EXPANDING RIVET	Necessary	27.00 FS	*27.00 FS
64	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
65	1		*(DG) FRT LH UPPER BELT (SCHWARZ)	Activated	298.15FS	*298.15 FS
66	1		*(DG) FRT RH UPPER BELT (SCRWARZ)	Activated	298.15FS	*298.15 FS
67	1		*BLIND RIVET AVIBVLB (30PCS)	Necessary	16.50 FS	*16.50 FS
68	10		*BLIND RIVET AVIBVLB	Necessary	5.50 FS	*5.50 FS
69	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
70	1		*PUNCH RIVET N4 (40PCS)	Necessary	22.00 FS	*22.00 FS
71	2		*(S/L) SEAM SEAL 300ML	Necessary	67.60 FS	*67.60 FS
72	1		*3M S/F PREMIUM RR WINDSCREEN	Cracked	252.34 FS	*252.34 FS
73	1		*REAR WIPER BLADE	Cut	44.60 F	*44.60 F
	anchise	part. S=Spo	Nett.		10000000000000	
				Total Parts (S\$)	12,405.44	8,782.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

ticulars	Lab.Type	Repairer's	Amount
<u>ems</u>			
REPLACE REAR BUMPER, BOOTLID INCLUDING FACHMENTS ETC AND TO KNOCK OUT DENTED AREA USED BY ACCIDENT	New	3,400.00	1,700.00
PAINT REAR BUMPER, BOOTLID AND TAIL END PANEL	New	2,666.00	1,805.00
TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
REPLACE REAR WINDSCREEN GLASS INCLUDING NDUCT WATER LEAK TESTS	New	649.00	649.00
VACUUM AIR INTERIOR TO REMOVE SHATTERED GLASS BRIS	New	224.00	224.00
SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN LAR FILM	New	531.00	0.00
TRANSFER LOCK MECHANISM FROM OLD TO NEW OTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID NTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
REPLACE FRONT SEAT CRASH-ACTIVE HEAD STRAINT AIR BAGS INCLUDING RESET AND CONDUCT ECK FOR FUNCTION	New	531.00	0.00
CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
REMOVE AND INSTALL BOOT COMPARTMENT CARPET D GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT CTION FOR PROPER FUNCTION INCLUDING JUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labou	r Cost (S\$)	9,293.00	5,504.00
Gross Labou			9,293.00
till e F T F N / B S L T ON I S E (I C (C	REPLACE REAR BUMPER, BOOTLID INCLUDING ACHMENTS ETC AND TO KNOCK OUT DENTED AREA ISED BY ACCIDENT PAINT REAR BUMPER, BOOTLID AND TAIL END PANEL TOW ACCIDENT VEHICLE TO PML WORKSHOP REPLACE REAR WINDSCREEN GLASS INCLUDING IDUCT WATER LEAK TESTS VACUUM AIR INTERIOR TO REMOVE SHATTERED GLASS IRIS SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN AR FILM TRANSFER LOCK MECHANISM FROM OLD TO NEW DITLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID ITRAL LOCKING SYSTEM FOR PROPER FUNCTION REPLACE FRONT SEAT CRASH-ACTIVE HEAD STRAINT AIR BAGS INCLUDING RESET AND CONDUCT CK FOR FUNCTION CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) OF GARNISH TO FACILITATE REPAIRS CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT STION FOR PROPER FUNCTION INCLUDING IUSTMENTS OF HEADLIGHTS Gross Labour	REPLACE REAR BUMPER, BOOTLID INCLUDING ACHMENTS ETC AND TO KNOCK OUT DENTED AREA SED BY ACCIDENT PAINT REAR BUMPER, BOOTLID AND TAIL END PANEL POW ACCIDENT VEHICLE TO PML WORKSHOP REPLACE REAR WINDSCREEN GLASS INCLUDING IDUCT WATER LEAK TESTS VACUUM AIR INTERIOR TO REMOVE SHATTERED GLASS SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN AR FILM TRANSFER LOCK MECHANISM FROM OLD TO NEW OTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID ITRAL LOCKING SYSTEM FOR PROPER FUNCTION REPLACE FRONT SEAT CRASH-ACTIVE HEAD CHERAINT AIR BAGS INCLUDING RESET AND CONDUCT CCK FOR FUNCTION CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) REMOVE AND INSTALL BOOT COMPARTMENT CARPET OF GARNISH TO FACILITATE REPAIRS CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New CTION FOR PROPER FUNCTION INCLUDING	REPLACE REAR BUMPER, BOOTLID INCLUDING New 3,400.00 ACHMENTS ETC AND TO KNOCK OUT DENTED AREA SED BY ACCIDENT PAINT REAR BUMPER, BOOTLID AND TAIL END PANEL New 2,666.00 TOW ACCIDENT VEHICLE TO PML WORKSHOP New 195.00 REPLACE REAR WINDSCREEN GLASS INCLUDING New 649.00 RIDUCT WATER LEAK TESTS VACUUM AIR INTERIOR TO REMOVE SHATTERED GLASS New 224.00 RIS SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN New 531.00 AR FILM TRANSFER LOCK MECHANISM FROM OLD TO NEW DITLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID INTRAL LOCKING SYSTEM FOR PROPER FUNCTION CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) CHECK FOR FUNCTION CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT New 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT NEW 177.00 CHEC

< END OF ESTIMATES >