



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR SAM LAIN EQUIPMENT SERVICES PTE LTD
25 WOODLANDS INDUSTRIAL PAEK E2
SINGAPORE 757459

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : YP 3886 K (QBE)
OUR REF : TP 5861
VEHICLE NO : YL 6813 Y
MAKE/MODEL : ISUZU NHR69
DATE OF ACCIDENT : 18.01.18

SURVEY BY

DATE : 22.01.18

2 PCS FRONT WINDSCREEN GLASS MOULDING	128.60	S\$	257.20	all
1 PC WIPER GARNISH			296.50	all
1 PC WIPER GARNISH "ISUZU" STICKER			162.80	all
1 PC WIPER GARNISH MOULDING			116.20	all
1 PC WIPER LINK			89.60	?
1 PC WIPER MOTOR			395.70	?
1 PC FRONT PANEL			419.50	bt
1 PC FRONT GRILLE			315.60	Ry
1 PC AIR-CON BLOWER UNIT			2,651.80	?
1 PC AIR-CON COOLING COIL			2,490.50	?
		S\$	7,195.40	
	LESS 10%		719.54	
		S\$	6,475.86	
1 SET FRONT WINDSCREEN GLASS SEALANT		S\$	40.00	S/NETT
1 PC WIPER GARNISH "NHR" STICKER			28.00	"all"
		S\$	68.00	
TO DISMANTLE AND REFIX FRONT WINDSCREEN GLASS		S\$	140.00	120.
TO DISMANTLE AND REFIX DASHBOARD			300.00	200 photo &
TO REMOVE AIR-CON COOLING COIL, BLOWER UNIT AND TOP-UP AIR-CON GAS			120.00	100
TO CHECK WIRING FUNCTION			30.00	✓
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL			100.00	40.
LABOUR CHARGES			800.00	600
TO PUTTY AND SPRAY PAINTING CHARGES			600.00	400
		S\$	8,633.86	

SIN DOLLARS: EIGHT THOUSAND SIX HUNDRED THIRTY-THREE AND CENTS EIGHTY-SIX ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplemental items are surveyed and
is subject to final approval by Insurance Company
Acknowledged by:
Signature:
Date:

Tanjah 97495749
WP
24/1/18 @ 11am
Lumpun
Resurvey after repair
surveillance.com
6 days.