



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7183Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RADIATOR GRILLE	CRACKED	294.35	294.35
1	RADIATOR GRILLE H EMBLEM	SERVICEABLE	113.65	-
1	FRONT BUMPER COVER	DEFORMED	562.30	562.30
1	FRONT BUMPER SPONGE	SERVICEABLE	142.20	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	526.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @ \$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @ \$24.60	SERVICEABLE	49.20	-
1	HEADLAMP (RH)	GRAZED	1,388.00	1,388.00
1	FRONT FENDER (RH)	DENTED	619.00	619.00
1	FRONT WHEEL HUB CAP (RH)	GRAZED	150.70	150.70
1	BOOT LID	TO REPAIR SEE LABOUR	1,681.40	-
1	BOOT LID RUBBER	SERVICEABLE	115.80	-
1	BOOT LID LOCK UPPER	SERVICEABLE	137.90	-
1	BOOT LID LOCK LOWER	SERVICEABLE	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE	NECESSARY	41.00	41.00
1	BOOT LID LAMP (LH)	SERVICEABLE	556.80	-
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID LOWER GARNISH	TO REPAIR SEE LABOUR	398.00	-
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	CRACKED	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$180.00	TO REPAIR SEE LABOUR	360.00	-
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	CRACKED	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (LH)	CRACKED	32.00	32.00
1	TAIL LAMP (LH)	SERVICEABLE	565.60	-
1	REAR PANEL	TO REPAIR SEE LABOUR	592.30	-

Report Ref No. CC3/EQI18001428/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR PANEL GARNISH	SERVICEABLE	57.70	-
1	REAR PANEL LOWER PANEL	TO REPAIR SEE LABOUR	495.50	-
1	EXHAUST PIPE INSULATOR, LH	SERVICEABLE	58.55	-
1	EXHAUST SILENCER, LH	BENT	954.00	954.00
1	EXHAUST PIPE HANGER, LH	BENT	58.55	58.55
1	EXHAUST PIPE CENTRE	BENT	1,150.30	1,150.30
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	164.40	-
1	FUEL LID COVER	SERVICEABLE	98.50	-
1	REAR WHEEL HUB-CAP (LH)	SERVICEABLE	150.70	-
1	REAR BUMPER SIDE BRACKET (LH)	CRACKED	49.00	49.00
1	MUFFLER ASSY - FRONT	BENT	263.43	263.43
	LESS 20% DISCOUNT		-2,706.60	-1,421.44
			10,826.38	5,685.74
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	FRONT NO PLATE TRIM COVER (SN)	SERVICEABLE	30.00	-
1	FRONT DOOR COLOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	BOOT LID CITY CAB LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			295.70	105.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID, BOOTLID LOWER GARNISH, REAR BUMPER REINFORCEMENT BRACKET (LH/RH), REAR PANEL AND REAR PANEL LOWER PANEL.		1,650.00	1,000.00
	SPRAY PAINTING CHARGE.		1,600.00	1,260.00
	WIRING CHARGE.		100.00	20.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.		50.00	50.00
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00

Report Ref No. CC3/EQI18001428/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX EXHAUST PIPE.		250.00	50.00
			4,020.00	2,440.00
GRAND TOTAL			15,142.08	8,230.74
RECOMMENDED COST OF REPAIRS				8,230.74

Report Ref No. CC3/EQI18001428/K1ea3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.