

ASSIGNMENT (Office)

Menmen <sup>Result</sup> From (Person): Monica Chung of MSIG Date/Time: 23/1/18 @ 4.59 pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ☒ TP WS ☐ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 9907Y Insured: XEQ298M

at Workshop no: Performance Tel: 63190174

of 303 Alexandra Road

Policy No: A288 744 41 MKC Claim No: 547141

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ DOA: 19/01/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>1 up</sup> 30.01.2018 R.O.D. Equipment: \_\_\_\_\_

Date/Time: 10:33am @ 24/1/18 Person Contacted: Caroline Vehicle ID: 011

Date/Time	Action/Inspection	By
	<input checked="" type="checkbox"/>	Man

SLB 9907Y - X

XEQ298M - X

31/10/18 sent prot form menmen

confirm \$8506.00, 7 days (Red: \$2144.05, 20%).

Rome

MSIG

9144C

30/01/18

SLB 99074

2016 APR

0 WS THREE CO RES EVAL INV M

SLB 99074

Performance

303 Alexandra Rd

B.M.W 216D ACTIVE

1496

BLUE

46900

WBA 2832080 V259885

Gen. Cond. Good

Steering Jammed / Leaked / Burnt

Brake Jammed / Leaked / Burnt

Mod. Nil STD Air

Tyre Size 205/60 R16

BS/DUN/EXNOVA/GY/RS/LIZ/MID/OHTSU/PR/SUM

TOYO/YOKO

CONTINENTAL


Front	Rear
6	6
6	6
DOA 19/01/18	DOA 30/01/18

Survey Ref: PERFORMANCE

Check Damages FR Rear OS UIC Rooted

Asst

The UIC Chassis frame Body Structure affected due to collision



RECEIVED 26 MAR 2018

Damage Report

☐ Prel. Report  
☒ Final Report

Days Of Repair 1

Resurvey No. of Trk 1

typist

Add Fee

1	2	3	4	5	6	7	8	9	10
---	---	---	---	---	---	---	---	---	----

TP

8506.00

300
10

310

## Catherine Chong (LKK Auto)

---

**From:** Monica Chung <Monica\_Chung@sg.msig-asia.com>  
**Sent:** Wednesday, 24 January, 2018 3:38 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM; Nivitha (LKK Auto)  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SLB9907Y AND XE9298M ON 19/01/2018  
Our Ref: 547141

Dear both,

Please request our surveyor to check for damage consistency. Our insured driver mentioned that the cushion chair board dropped and hit around the left side rear door/tyre area of third party's vehicle. He said that he was not possible that the board hit the front bumper. Please refer to the photos taken by the insured's boss in the accident report on the damages.

Thanks.

Regards,

**Monica Chung**  
Assistant Executive, Claims Services (Motor)  
Direct line +65 6594 2552 | Direct fax +65 6225 7402 | [monica\\_chung@sg.msig-asia.com](mailto:monica_chung@sg.msig-asia.com)



**MSIG**



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on



A member of **MS&AD** INSURANCE GROUP

---

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Tuesday, January 23, 2018 2:39 PM  
**To:** Rashitha Binte Shahuthuman <rashitha\_shahuthuman@sg.msig-asia.com>  
**Cc:** Monica Chung <Monica\_Chung@sg.msig-asia.com>  
**Subject:** Re: REQ FOR DIRECT SETTLEMENT- SLB9907Y AND XE9298M ON 19/01/2018

Dear Rashita,

We agree to use the surveyor below as per the SJE:

LKK Auto Consultants Pte Ltd

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Rashitha Binte Shahuthuman <rashitha\_shahuthuman@sg.msig-asia.com>  
**Sent:** Tuesday, 23 January 2018 1:02:01 PM  
**To:** PBSP

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2018		23 Jan 2018 16:59 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	<b>HONG TECK HUAT CLEANING SERVICES, Co. Reg. No.: 52862551M</b>		
Main Claimant:	<b>TONG MEI LING, ID: S7439144C</b>		
Vehicle Reg. No.:	<b>SLB9907Y</b>	Date of Loss:	19/01/2018 10:00 - :59
Claim Type:	<b>TP / 547141</b>	Policy/Cover Note No.:	A28874449MKC (Comprehensive) Coverage: 10/01/2018 - 23/11/2018
Vehicle Reg. No. (Insured):	<b>XE9298M</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 24/01/2018]</b>		
Driver/Custodian (Insured):	GUO JIMIN (), NRIC: G5381908M, Tel: +6597979298		
Adj Asg. Remarks:	ON WP		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001432/R1rd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 24-01-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 9298M	Veh. Inspected	SLB 9907Y
Policy No.	A28874449MKC	Coverage (\$)	0.00
Claim No.	547141	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	24/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	19/01/2018	Inspection Date	18/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 31 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: XE9298M	Accident Date	: 19/01/2018
TP Vehicle No	: SLB9907Y	Assignment Date	: 23/01/2018
Make	: BMW 216D	Est. Duration of Repair	: 7.00
Date of Inspection	: 30/01/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,650.05
Revised Amount	:S\$	8,315.20
Check Items (Estimated)	:S\$	1,062.85
Total	:S\$	9,378.05

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/01/2018 10:28
Date Of Accident	19/01/2018 10:15
Exact Location Of Accident	PIE TOWARDS KPE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB9907Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TONG MEI LING
NRIC No	S7439144C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98570201
Alternative Phone No	OTHERS-98570201

### Vehicle Particulars

Manufacturer	BMW
Model	216D-1.5 D ACTIVE TOURER (F45) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V16579/VPC2/R00
Cover Note Number	

### Driver

Name of Driver	CHONG KENG FUNG
NRIC No	S7440442A
Date Of Birth	27/11/1974
Occupation	INDOOR
Date Of Driving Pass	22/10/2001
Driving Experience	16 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98501122
Fax Number	
Contact Number	
Email Address	JAMESCHONGKF@GMAIL.COM

Address	BLK 646 JALAN TENAGA # 07-117 SINGAPORE
Postcode	410646
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TONG MEI LING GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE9298M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	M416
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time:

20/1/18  
10:27am

  
Driver's Signature

(If driver is not the policyholder)

Date & Time:

  
Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jia Min

### Sketch Plan #2

### SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving from Ennes towards Juvang on P/E and was entering into the lane that leads to KPE City direction. As I was driving past the truck, the debris it was carrying fell from the truck and hit our car. The front bumper, fog light, side doors on the left, windows front and back and side mirrors are all scratched and slightly dented.

Right after the accident, we stopped the car and ask for the driver's phone number and reported to the police on the accident as debris were strewn all over the highway.

## DECLARATION

If We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 15-day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature \_\_\_\_\_

**Date & Time:**

20/1/0

Driver's Signature

(If driver is not the policyholder)

**Date & Times:**

Reporting Centre Personnel's Signature

Names:

NRIC/FIN No.:

The Mission

DATE

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

23 JAN 2018

Estimate No. : b1 45598  
Date Estimated : 22/01/2018  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -  
Tong Mei Ling  
770 Bedok Reservoir Road  
#02-05

Singapore 479250

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB9907Y	V259885	28/04/2016	216d CAT	0

### DESCRIPTION

To replace front bumper & attachments, left wing mirror, both left door window 'B' column frame including to knock out dented area caused by the accident

2550 3,400.00

To respray front bumper, front left door, rear left door, rear left fender and left wing mirror cover

3390 3,767.00

To supply and install front window glass solar film.

164 425.00

To replace front door window glass including conduct water leak tests.

413.00

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

250 298.00

Sundries.

new 80.00

Total Labour 1: 8,380.00

### DESCRIPTION

BODY NUT  
LH VERTICAL STRUT  
FRT BUMPER BOTTOM CARRIER  
GRILLE BUMPER MIDDLE CLOSED (PDC)  
LH ROD  
LH SUPPORT FOG LAMP (GESCHLOSSEN)  
FRT BUMPER PANEL PRIMED (PMA)  
GRILLE SIDE OPEN LH (PDC)  
GROMMET  
LH LOWER HOUSING SECTION  
LH ADDITIONAL TURN INDICATOR LAMP  
FRT LH DOOR WINDOW GLASS  
# FRT LH DOOR COLUMN B COVER  
COVER COLUMN B DOOR REAR LH

QTY	PRIC	VALUE
10	0.90	9.00
1	47.00	47.00
1	140.10	140.10
1	96.20	96.20
1	19.50	19.50
1	49.70	49.70
1	821.50	821.50
1	95.65	95.65
2	0.75	1.50
1	23.35	23.35
1	60.30	60.30
1	193.05	193.05
1	58.50	58.50
1	59.35	59.35

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 45598  
Date Estimated : 22/01/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB9907Y	V259885	28/04/2016	216d CAT	0

## DESCRIPTION

CLIP  
FRT LH WHEEL ARCH COVER  
AIR DUCT  
UNDERBONNET SCREEN  
PLAQUE 82MM

QTY	PRIC	VALUE
10	1.30	13.00
1	129.40	129.40
1	185.90	185.90
1	199.25	199.25
1	67.80	67.80

Handwritten notes: *SWX*, *set*, *na/6950*

Total Parts : 2,270.05

Claims OD (3rd Party) / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&amp;Time 30/01/18 @ 1345 Excess S\$ \_\_\_\_\_

Surveyor's Name *Rahul* Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 6-7 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

11022.75

Labour 1	:	8,380.00
Parts	:	2,270.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	745.50
Grand Total	:	11,395.55

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## FINAL REPORT

Estimate No. : b1 45598  
Date Estimated : 22/01/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Tong Mei Ling  
770 Bedok Reservoir Road  
#02-05

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 479250

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLB9907Y	V259885	28/04/2016	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, LH fog lamp support, front LH door column 'B' cover, rear LH door column 'B' cover include making good the front LH door, rear LH door, rear LH fender and knocking out dents caused by the accident	2550.00		2,550.00	
To respray front bumper, front LH door, rear LH door, rear LH fender and LH wingmirror cover	3390.00		3,390.00	
To replace front LH door window glass include conducting water leak tests	413.00		413.00	
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250.00		250.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
3M S/F CRYSTALLINE FRONT SIDE DOOR (A)	336.45	1.00		336.45
FRT BUMPER BOTTOM CARRIER	143.60	1.00		143.60
LH SUPPORT FOG LAMP (GESCHLOSSEN)	50.95	1.00		50.95
FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00		842.00
LH ADDITIONAL TURN INDICATOR LAMP	61.80	1.00		61.80
FRT LH DOOR WINDOW GLASS	197.90	1.00		197.90
FRT LH DOOR COLUMN B COVER	59.95	1.00		59.95
COVER COLUMN B DOOR REAR LH	60.85	1.00		60.85
PLAQUE 82MM	69.50	1.00		69.50

### # SUPPLEMENTARY ITEMS

Total Labour :	6,683.00
Total Parts :	1,823.00
Total Labour & Parts :	8,506.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,506.00
GST @7%:	595.42
Grand Total :	9,101.42

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001432/R1RD3N2

Date: 27/03/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28874449MKC
Claimant Vehicle No :	SLB9907Y	Insured Vehicle No :	XE9298M
Date of Loss:	19/01/2018	Nature of Claim:	TP
		Claim No:	547141

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLB9907Y	Engine No:	38759418B37C15A
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Chassis No:	WBA2B32080V259885
Reg. Date:	28/04/2016 (Man. Year: 2015)	Odometer:	46900 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,147.75	1,903.00	1,244.75	39.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,875.00	6,603.00	1,272.00	16.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>11,022.75</b>	<b>8,506.00</b>	<b>2,516.75</b>	<b>22.83</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>771.59</b>	<b>595.42</b>	<b>176.17</b>	<b>22.83</b>
<b>Nett Amount (\$\$)</b>	<b>11,794.34</b>	<b>9,101.42</b>	<b>2,692.92</b>	<b>22.83</b>

## INSPECTION

Date of Assignment:	23/01/2018	
Date Inspected:	30/01/2018	Inspected At:
		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2018)
<b>Parts:</b>	M1-MPV	BMW 216D 1.5 D Active Tourer (F45) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB9907Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BODY NUT	Serviceable	9.00 FS	*- FS
2	1		*FRT BUMPER BOTTOM CARRIER	Bent	143.60 FS	*143.60 FS
3	1		*GRILLE BUMPER MIDDLE CLOSED (PDC)	Serviceable	96.20 FS	-
4	1		*LH ROD	Serviceable	19.50 FS	*- FS
5	1		*LH VERTICAL STRUT	Serviceable	47.00 FS	*- FS
6	1		*LH SUPPORT FOG LAMP (GESCHLOSSEN)	Cracked	50.95 FS	*50.95 FS
7	1		*FRT BUMPER PANEL PRIMED (PMA)	Scratched	842.00 FS	*842.00 FS
8	1		*GRILLE SIDE OPEN LH (PDC)	Serviceable	95.65 FS	*- FS
9	2		*GROMMET	Not Necessary	1.50 FS	*- FS
10	1		*LH LOWER HOUSING SECTION	Not Necessary	23.35 FS	*- FS
11	1		*LH ADDITIONAL TURN INDICATOR LAMP	Broken	61.80 FS	*61.80 FS
12	1		*FRT LH DOOR WINDOW GLASS	Scratched	197.90 FS	*197.90 FS
13	1		*FRT LH DOOR COLUMN B COVER	Scratched	59.95 FS	*59.95 FS
14	1		*COVER COLUMN B DOOR REAR LH	Scratched	60.85 FS	*60.85 FS
15	10		*CLIP	Serviceable	13.00 FS	*- FS
16	1		*FRT LH WHEEL ARCH COVER	Serviceable	129.40 FS	*- FS
17	1		*AIR DUCT	Serviceable	185.90 FS	*- FS
18	1		*UNDERBONNET SCREEN	Serviceable	199.25 FS	*- FS
19	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
20	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
21	1		*3M S/F CRYSTALLINE FRONT SIDE DOOR	Necessary	336.45 FS	*336.45 FS
22	1		*FRONT WINDOW GLASS SOLAR FILM	Not Necessary	425.00 FS	-

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>3,147.75</b>	<b>1,903.00</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS.LEFT WING MIRROR,BOTH LEFT DOOR WINDOW B COLUMN FRAME INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	3,400.00	2,550.00
2	TO RESPRAY FRONT BUMPER,FRONT LEFT DOOR,REAR LEFT DOOR,REAR LEFT FENDER AND LEFT WING MIRROR COVER	New	3,767.00	3,390.00
3	TO REPLACE FRONT DOOR WINDOW GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	413.00	413.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	295.00	250.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,875.00</b>	<b>6,603.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >