

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5045C -

AAD1801-219

*Not Autharised
L1 Sm 87*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5045C - JHOW

VF1ABL15AUC276053

RENAULT

LATITUDE

18.01.2018

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bur</i>	1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>nd</i>	768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i>	113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i>	135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i>	44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i>	43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i>	135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i>	44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i>	43.61	X
10	1	BUMPER BEAM REAR	\$	<i>B1</i>	777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$		225.95	?
12	1	BUMPER BEAM BRACKET RH REAR	\$		225.95	?
13	1	BOOT REAR	\$	<i>B1</i>	2,872.68	✓
14	1	BOOT FINISHER	\$	<i>Sn</i>	470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i>	323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i>	493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i>	493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Mc</i>	225.36	✓
19	1	BOOT BADGE	\$	<i>Mc</i>	225.36	✓
20	1	BOOT STRUT LH	\$	<i>Sn</i>	276.08	}
21	1	BOOT STRUT RH	\$	<i>Sn</i>	276.08	
22	1	BOOT HINGE LH	\$	<i>R</i>	367.84	
23	1	BOOT HINGE RH	\$	<i>R</i>	367.84	
24	1	BOOT INNER TRIM	\$	<i>Sn</i>	586.45	
25	1	BOOT SWITCH	\$	<i>Sn</i>	168.13	
26	1	BOOT LOCK	\$	<i>R</i>	202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i>	74.40	
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i>	50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i>	221.81	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i>	671.45	}
31	1	FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	
32	1	WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i>	671.45	
34	1	FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-219

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5045C -

35	1	WHEELARCH REAR RH	\$	Sn	543.47	}	X
36	1	TAILLAMP RH	\$	Sn	552.55		
37	1	TAILLAMP PANEL RH	\$	N	986.70		
38	1	TAILLAMP LH	\$	Sn	552.55		
39	1	TAILLAMP PANEL LH	\$	Sn	986.70		
40	1	OUTER PANEL REAR (End Panel)	\$	N	1,471.77		
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56		
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88		
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
44	1	EXHAUST REAR	\$	N	7,489.05		
45	1	EXHAUST CAP REAR	\$	N	230.49		

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	Short	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	} X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
20	1	TAILLAMP CLIP LH	\$	na	5.00	
21	2	REAR WINDSCREEN SELANT	\$	na	80.00	
22	1	WINDSCREEN MOULDING	\$	Sn	100.00	
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-219

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5045C -

25	1	SPARE TYRE	\$	<i>Sn</i> 330.00 <i>X</i>
----	---	------------	----	---------------------------

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>660/</i>
---	----	----------------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>500/</i>
---	----	----------------------

To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>30/</i>
---	----	-------------------

To reinstall rear bumper parking sensor.	\$	170.00 <i>60/</i>
--	----	-------------------

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60/</i>
--	----	-------------------

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
--	----	---------------------------

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
--	----	---------------------------

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
--	----	---------------------------

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
--	----	---------------------------

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
--	----	---------------------------

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
---	----	---------------------------

Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
-------------	----	---------------------------

To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
---	----	---------------------------

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
---	----	---------------------------

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-219

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5045C -

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

(PARTS BY PARTS)**Repair Days**~~15 Days~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey the installer spray painting
- To dent in, damaged (dent) during resurvey
- Parts left in place, part replacement
- Third party involvement, and the cost of parts
- No "No" to the repairer's cost
- Suitable to be repaired, and the cost of parts and
the cost of the repairer's cost, and the cost of any

And acknowledged by Repairer

Signature:

Date: