

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9706Y - AIG

AAD1801-232

Not Authored
6/1/18

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD9706Y - CANDY
KL1LA69RJB122762
CHEVROLET
EPICA 2.0
22.01.2018
AIG

PART			LIST		
1	1	Rear Bumper	\$	<i>Tn</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>Bu</i> 239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>CRA</i> 260.00	✓
4	1	Rear Bumper Side Retainer RH	\$	<i>CRA</i> 68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>mgem</i> 119.74	✓
7	1	Rear Bumper Reflectors LH	\$	<i>Sn</i> 119.74	X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	X
9	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00	X
10	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50	X
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00	X
12	1	Rear End Panel Outer	\$	<i>B</i> 623.76	✓
13	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84	X
14	1	Bootlid	\$	<i>R</i> 973.00	} X
15	1	Bootlid Inner trim board	\$	<i>Sn</i> 400.00	
16	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28	
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56	
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>na</i> 120.62	
19	1	Bootlid Logo	\$	<i>na</i> 138.84	
20	1	Bootlid 'EPICA LT' Badge	\$	<i>na</i> 119.84	
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97	
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40	
23	1	Bootlid Hinge RH	\$	<i>R</i> 120.00	
24	1	Bootlid Hinge LH	\$	<i>R</i> 120.00	
25	1	Rear Tail Lamp RH	\$	<i>Bro</i> 479.30	✓
26	1	Rear Tail Lamp Panel RH	\$	<i>B</i> 359.00	✓
27	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	X
28	1	Rear Fender RH	\$	<i>B</i> 1,145.00	✓
29	1	Rear Fender Inner Trim RH	\$	<i>Reform</i> 418.44	✓
30	1	Rear Fender Inner Cowling RH	\$	<i>CRA</i> 76.60	✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-232**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9706Y - AIG

31	1	Rear Fender Inner Wheel House Panel RH	\$	R	2,556.35	X
32	1	Rear Shock Absorber RH	\$		243.57	?
33	1	Rear Knuckle Arm RH	\$	R	350.00	✓
34	1	Upr Arm RH (Arm A-Upr RH)	\$	DIT	343.00	✓
35	1	Trailing Link RR RH (Link A-Trailing RR RH)	\$		90.00	?
36	1	Parallel Link RR (Link A-Parallel RR)	\$		93.00	?
37	1	Stabilizer Bar RR (Bar RR Stabilizer)	\$		97.00	?
38	1	Rear Axle Housing (Axle A-RR)	\$		711.00	?
39	2	Rear Fender Air Vent Lourve	\$	CRA	163.22	✓
40	1	Rear Exhaust Pipe	\$	R	1,110.00	X
41	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R	1,110.00	X
42	1	Shield -RR Muffler Protv	\$	Sh	66.00	X
43	1	Rear Exhaust Box (Box-DPF) (Centre)	\$	R	9,435.00	X
44	1	Rear Exhaust Mounting	\$	Sh	7.00	} X
45	1	Diesel Tank Cap (Cap A Fuel Filler)	\$	Sh	46.00	
46	1	Diesel Tank Door Panel (Door A Fuel Filler)	\$	Sh	75.00	
47	1	Rear Door RH	\$	R	1,133.00	
48	1	Rear door weatherstrip - 2nd Frame RH	\$	Sh	25.90	
49	1	Rear door top hinge RH	\$	R	35.00	
50	1	Rear door bottom hinge RH	\$	R	35.00	
51	1	Rear door inner lock RH	\$	R	425.00	
52	1	Rear door check / arrestor RH	\$	Sh	65.00	
53	1	Rear door lock striker / latch RH	\$	Sh	120.00	
54	1	Rear door outer weatherstrip moulding RH	\$	Sh	85.00	} X
55	1	Rear door outer handle RH	\$	Sh	60.00	
56	1	Rear door outer handle - rubber seal RH	\$	Sh	25.00	
57	1	Rear door channel weatherstrip / felt RH	\$	Sh	89.50	
58	1	Rocker Panel Garnish RH	\$	CRA	236.40	✓
59	1	Rocker Panel Outer RH	\$	R	600.00	X

TOTAL	\$	30,642.83
10%	\$	3,064.28
	\$	27,578.55

Specical Nett

- 1Set Licence Plate With Holder
- 1Set Bootlid inner trim board Clip
- 1Set Rear Bumper Parking Sensor
- 1Set Rear Bumper Fastener Clip

\$	Fm R	60.00	205A
\$	na	40.00	X
\$	nd	300.00	✓
\$	Ne	44.00	✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-232**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9706Y - AIG

5	1Set	Rear Fender Inner Trim Clip RH	\$	<i>Na</i>	30.00	✓
6	1Set	Rear Bumper End Dust Cover Clip	\$	<i>Na</i>	30.00	✓
7	1	Rear Boot Sticker 'Trans-cab'	\$	<i>na</i>	30.00	X
8	1	Rear Boot Sticker '6555-3333'	\$	<i>na</i>	30.00	X
9	1	Rear Exhaust Mounting	\$	<i>na</i>	10.00	X
10	2	Rear Windscreen Sealant	\$	<i>na</i>	80.00	<i>60sa</i>
11	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i>	100.00	<i>30sa</i>
12	1	Spare Tyre	\$	<i>sa</i>	180.00	} X
13	1	Spare Wheel Rim	\$	<i>sa</i>	126.74	
14	1	Rear Exhaust Heat Shield	\$	<i>R</i>	57.00	
15	1	Rear exhaust box - J hook	\$	<i>R</i>	25.00	
16	1	Rear exhaust box chrome pipe	\$	<i>sa</i>	791.00	
17	1	Rear Exhaust Mounting Bracket	\$	<i>R</i>	27.00	}
18	1	Centre Exhaust Pipe	\$	<i>R</i>	403.00	

TOTAL	\$	2,363.74
TOTAL PARTS	\$	29,942.29

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 5,400.00 *1500/*

To Check Electrical Lighting Concerned.

\$ 170.00 *40/*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *60/*

Putty And Spray Painting Of The Affected Portion.

\$ 5,600.00 *1000/*

To reinstall rear bumper parking sensor.

\$ 170.00 *60/*

To transfer of end panel fittings and conduct water
seepage test.

\$ 170.00

To transfer of luggage floor panel fittings and
conduct water seepage test.

\$ 170.00

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ 170.00 *120/*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-232**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9706Y - AIG

To transfer of boot fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
Towing fees	\$	120.00 <i>501</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>601</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 <i>1401</i>
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>201</i>

\$ 14,730.00**TOTAL \$ 44,672.29****Repair Days**

LKK Auto Consultants hence notify the Repairer of the following:

- To receive vehicle after spray painting
- To receive vehicle (2) during resurvey
- Parts provided and provide confirmation
- Third party survey on a "Without Prejudice" basis
- No ill feeling should be allowed
- Supply warranty only, must be genuine and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*20 Days**13 days*