



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 FORD MONDEO 1.5 (SLC2719P)

Date of Loss

13 January 2018

Time of Loss

22.50

Loss Description

SLC2719P (INSD) HIT SGV6191T & SJW1271M HIT SLC2719P (INSD)

Comment

Workshop Details

Total Rebate Amount

64201

Nett Loss Amount

\$55,799.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

31/07/2018



Days of work completion *

188



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SLC2719P

Registration State

SINGAPORE

Mileage

37639

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Purchase Date

dd/mm/yyyy



Registration Date *

09/05/2016



Age of Vehicle

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

TAN KIAN LOY

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... FORD

ASSESSMENT INFO... FORD

CATEGORY Model

POLICY INFORMAT... MONDEO 1.5

ASSESSMENT INFO... MONDEO HB TITANIUM 1.5 A/T GTDI

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WF0EXXWPCEFE03657

CATEGORY Date of Birth

FNOL INFORMATI... 28 July 1968

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 49

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... WF0EXXWPCEFE03657

CATEGORY Engine No

POLICY INFORMAT... FE03657

ASSESSMENT INFO... FE03657

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1498

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 120000

FNOL INFORMATI... 23

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Address

FNOL INFORMATI... BLK 739 TAMPINES STREET 72, 520739,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S6827792B

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

25/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/60R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

215/60R16

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts						
Add Approve Deny																
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:	
		1	1			FRONT BUMPER PLATE			Deformed	45				45	Review	
		2	1			FRONT NUMBER PLATE GARNISH			Deformed	80				80	Review	
		3	1			FRONT BUMPER LOGO			Necessary	68				68	Review	
		4	1			FRONT BUMPER GRILLE			Deformed	420				420	Review	
		5	8			FRONT BUMPER GRILLE CLIPS			Serviceable	0	0	0	0	0	Deny	
		6	1			FRONT BUMPER TOP GRILLE CHROME			Serviceable	0	0	0	0	0	Deny	
		7	10			FRONT BUMPER CLIPS LOWER			Necessary	12				120	Review	
		8	1			FRONT BUMPER LOWER GRILLE			Deformed	350				350	Review	
		9	1			FRONT BUMPER LOWER GRILLE CHROME			Serviceable	0	0	0	0	0	Deny	
		10	1			FRONT BUMPER TOW COVER			Serviceable	0	0	0	0	0	Deny	
		11	1			FRONT BUMPER			Deformed	1150				1150	Review	
		12	1			FRONT BUMPER REINFORCEMENT			Bent	290				290	Review	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
		13	1			FRONT BUMPER SPONGE			Deformed	198				198	Review
		14	1			FRONT FENDER RH			Bent	380				380	Review
		15	1			FRONT FENDER COWLING RH			Deformed	140				140	Review
		16	10			FRONT FENDER COWLING CLIPS RH			Necessary	9				90	Review
		17	1			FRONT FENDER VERTICAL SPONGE RH			Deformed	98				98	Review
		18	1			ROCKER GARNISH			Damaged	720				720	Review
		19	2			ROCKER GARNISH RUBBER RH			Serviceable	0	0	0	0	0	Deny
		20	10			ROCKER GARNISH CLIPS - 12 PCS			Necessary	10				100	Review
		21	1			R/F DOOR			Bent	2280				2280	Review
		22	1			R/F DOOR RUBBER			Damaged	115				115	Review
		23	2			R/F DOOR HINGE			Serviceable	0	0	0	0	0	Deny
		24	1			R/R DOOR			Bent	2100				2100	Review
		25	1			R/R DOOR RUBBER			Damaged	138				138	Review
		26	1			R/R DOOR EDGE RUBBER			Necessary	100				100	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
		27	2			R/R DOOR HINGES			Bent	150				300	Review
		28	1			RH CENTRE PILLAR (NPA)			Repair	0	0	0	0	0	Deny
		29	1			R/R FENDER (NPA)			Repair	0	0	0	0	0	Deny
		30	1			RH ROCKER PANEL (NPA)			Repair	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		TOWING CHARGE	50	0	0	Reviewing		1
		2		TO CUT / WELD CENTER PILLAR RH, ROCKER PANEL RH, TO REPAIR REAR FENDER RH, BONNET FRONT INNER PANEL RH, REMOVE AND REFIX DAMAGED PARTS. STRAIGHTEN AND REALIGN AFFECTED AREAS	1000	0	0	Reviewing		1
		3		TO SPRAY AFFECTED AREAS	1300	0	0	Reviewing		1
		4		TO REMOVE AND REFIX DOOR MECHANISM CHECK & TEST POWER, WINDOW AND CENTER LOCKING SYSTEM	120	0	0	Reviewing		1
		5		TO REMOVE AND REFIX CUSHION, SAFETY BELT CARPET AND OTHER ATTACHMENT PARTS	50	0	0	Reviewing		1
		6		TO CHECK WHEEL ALIGNMENT	80	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE	
			1	DAYS OF REPAIR : 10 DAYS	Reviewing			
			2	FRONT BUMPER CLIPS LH (5 PCS)	Reviewing	40	NECESSARY (SUPPLEMENTARY)	
			3	FRONT BUMPER CLIPS RH (5 PCS)	Reviewing	40	NECESSARY (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$11,562.00

Claim Amount \$11,562.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,600.00	\$2,600.00
Miscellaneous	\$80.00	\$80.00
Excess	-\$400.00	-\$400.00

Submit for Review