

CK130 488
S8110072 V

◀ Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2014 BMW 428 I (SKC178A)

Date of Loss

January 11, 2018

Time of Loss

10.00

Loss Description

PLEASE REFER TO THE SKETCH PLAN

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Target Date of Completion *

01/29/2018



Days of work completion *

5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjun 97495749.
Exp 400
Authorised
25/1/19 @ 1445
3 days
Resurvey before paint
sur @ lkkauto.com.



Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Parts

Add

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			HEADLAMP ASSY RH		out ✓		1500		1500	Reviewing	
	2	1			HEADLAMP LOWER BRACKET RH		X X		55		55	Reviewing	
	3	1			HEADLAMP WASHER COVER RH		mt ✓		32		32	Reviewing	
	4	1			HEADLAMP WASHER JET RH - CHECK		X		0		0	Reviewing	
	5	1			HEADLAMP TOP BRACKET RH		mt ✓		12		12	Reviewing	
	6	1			FRONT BUMPER		de ✓		900		900	Reviewing	
	7	1			FRONT BUMPER RETAINER RH		mt ✓		18		18	Reviewing	
	8	1			FRONT BUMPER SPONGE - CHECK		X		0		0	Reviewing	
	9	1			FRONT BUMPER REINFORCEMENT - CHECK		X		0		0	Reviewing	
	10	1			FRONT BUMPER LOGO		mt ✓		65		65	Reviewing	
	11	1			FOG LAMP ASSY RH - CHECK		X		0		0	Reviewing	
	12	1			FOG LAMP GARNISH RH		X		65		65	Reviewing	
	13	1			FRONT FENDER RH (REPAIR)		KY		0		0	Reviewing	

Labour

Add

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO KNOCK AND STRAIGHTEN HEADLAMP PANEL RH, FRONT FENDER RH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	0	500	0	Reviewing		
	2		SPRAY PAINT FRONT BUMPER, FRONT FENDER RH	0	0	400	Reviewing		
	3		DIAGNOSE CHECK AND RESET FRONT BUMPER SENSOR	0	150	0	Reviewing		

1/24/2018

Claim Portal

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	4		CHECK WIRING AND FOCUS HEADLIGHT	0	40 <i>30</i>	0	Reviewing		



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio
Parts & Labour	Miscellaneous	Summary	

Claim Amount
\$3,737.00

CATEGORY	Spare Parts
ESTIMATE	\$2,647.00
REVISED AMOUNT	\$2,647.00
CATEGORY	Labour
ESTIMATE	\$690.00
REVISED AMOUNT	\$690.00
CATEGORY	Paint
ESTIMATE	\$400.00
REVISED AMOUNT	\$400.00

Submit for Review