

INS. CASE OWNER:

Sharon

CC 6: CT118001470

1 K^b 53

LAK

IDAC

Surveyor:

KENNETH

DOI:

23/01/18

Date / Time:

23/01/18

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKX 569U

Claim No.:

SNM1700796049

Name of Insured:

SOOFAS LIMO SERVICES

Policy No.:

DMHCSN1721201700

Insured Tel No.:

HP:

Make / Model:

HONDA VIZEL - 1.5X (A)

Excess Sec II :S\$

D.O.A.:

26/12/17

Place of Accident:

OPEN CARPARK OF 8/274
TAMPINES ST 22

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MOHD RAMLI BIN MOHAMAD YUSOF

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Driver Tel No. : 9387 3007

(V / YES / NO)

Insured Liability:

% Final ? Yes / No

SJM 710H



INSRS:

WSP: WGI LOG

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
23/01/18 (jss)	20770H - X ; SKX 569U - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
13/4/18	RECALL TO (HAW TO 11/1/18)	Notification ltr (if non-pickup):	
16/4/18	RECALL TP CLAIM.	Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time: 25/01/18	Sent By: Shirley Hoon	Post-Repair Photos: <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
			Others: <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$ (days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% (Agreed / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia:	
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$ (days)	COPY SENT 25/1/18	
Loss of Use (LOU):	S\$ (\$ x days)		
Loss of Income (LOI):	S\$ (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search	S\$		
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format: WP	
Final Cost	S\$	3) Survey fee: 400	
Total:	S\$	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$	Name 1:	25/1/18 Chen
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

RECEIVED 27 APR 2018

COPY SENT
23/4/181) Claim status: Normal/Reject/Private Settle
2) Report Format: WP
3) Survey fee: 400JP
23/4/18

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Wei Kee

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 208 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STM 711014 Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Wish cc 1798Colour: M. D. Blue A/C: Insured / Std / NI / NASp. Reading: 183143 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W103601532Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / 8/Rim / STD A/Rim orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falke

Front

R/Bal: 2 mmL/Bal: 2 mmD.O.A: 26/12/17

Rear

R/Bal: 3 mmL/Bal: 3 mmD.O.A: 23/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/11 File pass to Catherine\$1300(red 1091 44 / 45.64%)

Date/Time, File Pass to?

☐

: Prell. Report

11

☐

: Final Report

Date/Time, File Return to?

21

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

\$ - RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CT118001470/Kys3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 569U	Veh. Inspected	SJM 7110H
Policy No.	DMHCSN1721301700	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/12/2017	Inspection Date	23/01/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 190607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI18001470/Kys3

Date: 25.01.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJM 7110H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.01.2018 at the premises of M/s Wei Lee Motor Works (Sin Ming) and have the following to report:-

Workshop Estimate Amount	: S\$	2,391.44
Revised Estimate Amount	: S\$	1,678.76
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~455 3986~~ 6458 0128
Business Regn No : 269436/00J

17, Jan 2018

China Taiping Insurance (S)PL
105 Cecil Street #18-00
The Octagon
S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SKX569U
Accident involving vehicle No: SJM7110H/SKX569U
DOA: 26/12/2017
PL: Blk 273 Tampines St 22 oper carpark

Dear officer incharge
Estimate cost of repair for vehicle No: SJM7110H
To supply

Description	Qty	Amount
Rear bumper	1 <i>BS</i>	470.70 ✓
Rear bumper reflector	1 <i>SN</i>	56.90 X
Bumper retainer, Lh	1 <i>P.Y</i>	57.05 ✓
Taillamp, Lh	1 <i>CM</i>	472.60 ✓
Bumper clip	<i>M</i>	38.00 ✓
	Parts	1,095.25
	Parts less 25%	273.81
		821.44

Reverse sensor
Remove damaged parts and attachments
Repair/reshape end panel, lid, rear fender and dented areas.
Renew/align above parts into position.
To spray paint.

CR 220.00 *2000*

650.00 *3000*

700.00 *4000*

LKK Auto Consultants hereby notify the Repairee of the following:

- To ensure full coverage spray coating
- To ensure damaged parts being repaired
- Parts prices are subject to confirmation
- Third party survey must be "without Payment" seen
- No single accident claim is allowed
- Supplementary claim must be recommended and is subject to final approval from Insurance Company

Amounted by Repairee
Signature:
Date:

2,391.44

Shirley Hiew (LKK Auto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 25 January 2018 1:07 PM
To: Shirley Hiew (LKK Auto)
Cc: Sharon Han
Subject: RE: Direct Settlement - Accident Involving SKX569U (OI : CTI - TBA) AND SJM7110H (TP : LKK REF - CC6/CTI18001470/Kys3) on 26/12/2017
Attachments: leeSZ_SNM17D07296C02-SKX569U-LKKDirectSettlementAccidentLtr_CLCR95.164.pdf, MSR117170068-01-SKX569U.pdf

Dear Shirley,

Pls refer to the above attachment.

Case Handler: Sharon Han

Thank you.

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Thursday, 25 January, 2018 9:22 AM

To: Claims Dept of CTI; Sharon Han

Cc: Jas Khine (LKKAuto); Thin Thin (LKKAuto); Admin A

Subject: Direct Settlement - Accident Involving SKX569U (OI : CTI - TBA) AND SJM7110H (TP : LKK REF - CC6/CTI18001470/Kys3) on 26/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SJM 7110H at M/s Wei Lee Motor Works - Sin Ming.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Bevan Lim (LKK Auto)

From: Bevan Lim (LKK Auto)
Sent: Friday, 13 April 2018 5:32 PM
To: 'claimsdept@sg.cntaiping.com'; Sharon Han
Cc: 'lucas.lee@sg.cntaiping.com'; 'Alfred Toh'; Vic (LKKAuto); Shu Pei (LKKAuto)
Subject: Your Ref:DMHCSN1721301700 Our Ref:CC6/CTI18001470/Kmb3 ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017
Attachments: SKX569U video.avi

Your Ref:DMHCSN1721301700
Our Ref:CC6/CTI18001470/Kmb3

Dear Sir/Madam,

ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017

We refer to the above matter.

OID reported TP who was parking beside him, Move out then OID move off too. TP suddenly reverse and collided to his vehicle.

TP reported that he was reversing and waiting for his passenger and OID coming out and collided to his vehicle.

We received OID's CCTV footage. Attached CCTV footage for your reference.

Based on the footage, TP was moving out of his lot, OID thereafter also move out of this lot. As OID move out, He stopped upon seeing TP vehicle reversing. TP vehicle then collided to OID vehicle.

In view of the above, we would like to reject TP claim as OI was stationary when TP was reversing without any signal and take caution during reversing resulted the collision.

For your approval/instruction if any.

Thank you.

Best Regards,
Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

Bevan Lim (LKK Auto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Friday, 13 April 2018 5:47 PM
To: Bevan Lim (LKK Auto); Admin A
Cc: Sharon Han; Adeline Chng; Alfred Toh; Hwang Shiang Yi; Chee So Chow; Hsiao Tong (LKKAuto)
Subject: Your Ref: SNM17D07296C02/9; Our Ref:CC6/CTI18001470/Kmb3 ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017
Attachments: SKX569U video.avi
Follow Up Flag: Follow up
Flag Status: Flagged

Your Ref:CC6/CTI18001470/Kmb3
Our Ref: SNM17D07296C02/9 (SKX569U)

Dear Bevan

We refer to your email pertaining to the above matter.

Please proceed to reject the third party property claim based on the video footage and let us have your bill for the services rendered.

Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID : +65 6389 6183
FAX: +65 6224 7175/6224 7478
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Bevan Lim (LKK Auto) [mailto:bevanlim@lkkauto.com]
Sent: Friday, April 13, 2018 5:32 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Sharon Han <sharon.han@sg.cntaiping.com>
Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Subject: Your Ref: SNM17D07296C02/9; Our Ref:CC6/CTI18001470/Kmb3 ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017

Your Ref:DMHCSN1721301700
Our Ref:CC6/CTI18001470/Kmb3

Dear Sir/Madam,

ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017

We refer to the above matter.

OID reported TP who was parking beside him, Move out then OID move off too. TP suddenly reverse and collided to his vehicle.

TP reported that he was reversing and waiting for his passenger and OID coming out and collided to his vehicle.

We received OID's CCTV footage. Attached CCTV footage for your reference.

Based on the footage, TP was moving out of his lot, OID thereafter also move out of this lot. As OID move out, He stopped upon seeing TP vehicle reversing. TP vehicle then collided to OID vehicle.

In view of the above, we would like to reject TP claim as OI was stationary when TP was reversing without any signal and take caution during reversing resulted the collision.

For your approval/instruction if any.

Thank you.


Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Bevan Lim (LKK Auto)

From: Bevan Lim (LKK Auto)
Sent: Monday, 16 April 2018 9:28 AM
To: 'weileemotorworks@gmail.com'
Cc: Vic (LKKAuto); Shu Pei (LKKAuto)
Subject: Your Ref: SJM 7110H Our Ref:CC6/CTI18001470/Kmb3 ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017
Attachments: SKX569U video.avi

Your Ref: SJM 7110H
Our Ref:CC6/CTI18001470/Kmb3

Dear Sir/Madam,

ACCIDENT INVOLVING SKX 569U AND SJM 7110H ON 26/12/2017

We refer to the above matter.

Our insured driver reported your client who was parking beside him, Move out then our insured driver move off too. Your client suddenly reverse and collided to his vehicle.

Your client reported that he was reversing and waiting for his passenger and our insured coming out and collided to his vehicle.

We received our insured's CCTV footage. Attached CCTV footage for your reference.

Based on the footage, your client was moving out of his lot, our insured thereafter also move out of this lot. As our insured move out, He stopped upon seeing your client's vehicle reversing. your vehicle then collided to our insured's vehicle.

We regret to inform you that we have our principal instruction to reject your client's claim as our insured was stationary when your client vehicle was reversing without any signal and take caution during reversing resulted the collision.

Thank you.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18001470/Kmb3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 02-05-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 569U	Veh. Inspected	SJM 7110H	
Policy No.	DMHCSN1721301700	Coverage (\$)	0.00	
Claim No.	SNM17D07296C02/9	Excess (\$)	0.00	
Assign From		Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDER12W103001532	Colour	METALLIC DARK BLUE	
Odometer	183143	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	FALKEN	2 mm	
L/H Front Tyre	225/45 R17	FALKEN	2 mm	
R/H Rear Tyre	225/45 R17	FALKEN	3 mm	
L/H Rear Tyre	225/45 R17	FALKEN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/12/2017	Inspection Date	23/01/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 7110H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	470.70	470.70
1	REAR BUMPER REFLECTOR	SERVICEABLE	56.90	-
1	BUMPER RETAINER ,LH	DISTORTED	57.05	57.05
1	TAILLAMP ,LH	CRACKED	472.60	472.60
1	BUMPER CLIP	NECESSARY	38.00	38.00
	LESS 25% DISCOUNT		-273.81	-259.59
			821.44	778.76
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	CUT	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	REMOVE DAMAGED PARTS AND ATTACHMENTS		650.00	300.00
	REPAIR/RESHAPE END PANEL ,LID,REAR FENDER AND DENTED AREAS.RENEW /ALIGN ABOVE PARTS INTO POSITION.			
	TO SPRAY PAINT.		700.00	400.00
			1,350.00	700.00
	GRAND TOTAL		2,391.44	1,678.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CC6/CT118001470/Kmb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.