



**EUROKARS HABITAT PTE LTD**  
**NO:12 SUNGEI KADUT, SINGAPORE 729648**  
**ESTIMATE COST OF REPAIRS**



<b>AXA INSURANCE PTE LTD</b> 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>	<b>NAME :</b> MR YEOW OOH KIONG <b>ADDRESS :</b> 132B HILLVIEW AVENUE # 06 - 03 SINGAPORE 669605 <b>TEL :</b> 97345419 (MR.MARK @ 92973079)	<b>WIP :</b> 16234 <b>EXCESS :</b> <b>DATE:</b> 24-Jan-18
--	---	---

<b>VEH NO :</b> SGS131Y	<b>DATE IN :</b>	<b>CONTACT PERSON :</b> JOBI THOMAS 6360 2446
<b>CHASSIS NO :</b> WMWXS720302E45870	<b>MILEAGE :</b>	<b>TYPE OF CLAIM :</b> THIRD PARTY CLAIM
<b>MODEL :</b> MINI COOPER F55	<b>DATE REG.:</b> 13-Jan-17	<b>POLICY NO. :</b>

**NATURE OF WORKS**

S/NO	Parts Description	QTY		REVISED	PRICES
1	REAR BUMPER ✓ Deform.	1	M51.12.7.380.036		\$ 929.88
2	REAR BUMPER GUIDE RH ✓ NEC.	1	M51.12.7.318.756		\$ 106.25
3	REAR BUMPER SENSOR HOLDER LH ✓ NEC	1	M51.12.7.385.661		\$ 28.38
4	REAR BUMPER SENSOR HOLDER RH ✓ NEC	1	M51.12.7.385.662		\$ 28.38
5	REAR BUMPER BLIND RIVET ✓	4	M07.14.7.411.141		\$ 14.52
6	REAR BUMPER CLIP ✓ } NEC	4	M07.14.2.754.954		\$ 6.24
7	REAR BUMPER C-CLIP ✓	6	B07.14.7.311.312		\$ 7.50
8	REAR BUMPER GASKET RING ✓	2	B51.12.7.256.354		\$ 4.50
9	REAR BUMPER GRILLE CHROME ✓ NEC	1	M51.12.7.365.073		\$ 186.19
10	REAR WHEEL ARCH RH ✓ Deform	1	M51.77.7.318.830		\$ 99.25
11	REAR BUMPER SPOILER X	1	M51.12.7.349.632		\$ 63.00
12	SPORT RIM ✓ Cut	1	M36.10.6.873.928		\$ 1,000.81
13	SPORT RIM CAP X	1	M36.13.6.857.149		\$ 31.69
<b>TOTAL PARTS</b>					\$ 2,506.59
<b>TOTAL PARTS COST</b>					\$ 2,506.59

**Labour Description**

1	TO REPLACE REAR BUMPER. TO REPAIR REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT. 840/day.				\$ 2,000.00 1680
2	TO RESPRAY REAR BUMPER AND REAR FENDER RH. 800/panel				\$ 1,800.00 1600
3	TO CARRY-OUT BODY CAVITY PRESERVATION.				\$ 250.00 150
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.		NETT	\$ 120.00	✓
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		NETT	\$ 560.00	✓
6	TO TRANSFER THE REVERSE SENSORS.			\$ 500.00 420	
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00	

180

8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00
			280
9	SUNDRIES.	NETT	\$ 100.00
			50
		TOTAL LABOUR	\$ - \$ 5,930.00
		TOTAL PARTS	\$ - \$ 2,506.59
		TOTAL	\$ - \$ 8,436.59
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ - \$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian

- Part by part repair -
- Photo Before Paint.

90036121

sebastianyeang@lkkanto.com.

6 days.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: