

22/03/2003

ASS. REC. BY:

REF:

C3/FCL17010420/mlrb-1

Special Instruction:

Survivor:

MCA

ASSIGNMENT (Office)

From (Person):

W3 Fung Yin Min

of

FCL

Date/Time:

30052017 941am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDD 8887L

Insured:

SHC 7904K

at Workshop m/s

Kum Chaw

Tel:

6453 6256

of

Blk 12 Sin Ming Ind Est # 01-71

Policy No:

Claim No:

D17005373MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/052017

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

30052017 947am

Person Contacted:

Mdm Lim

Vehicle-IN/OUT

Date/Time

Action/Instruction (X) Estimate

SDD 8887L - C3 / (M10303531 / Kbn

DIP - 03072003

SHC 7904K - X

Demantle Port: 01-062017

After repair: 06-062017

Submit LS \$1850 and 3 days (Red 3884.40, 672)

Surveyor

ASSIGNMENT

2005

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s KUM CHEW

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$23K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

PRS

Veh No: 200 8897L Yr Regn: FEB 2005

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MIT LANCER C.C. 1584

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 142812 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMY STCS3A5U 003084

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55/15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 2/1/2007 D.O.I. 2/1/2007

Survey held at Kum Chew 2.02pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 13072017

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) \$ + RS. \$1

) Photos

) Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$ _____)

120

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001675-9

MOTOR SURVEY ASSIGNMENT

Date	29-05-2017	Our Ref No. D17005373MFSH
Accident Date	25-05-2017	Claim Type. Third Party
Insured Vehicle	SHC7904K	Third Party Vehicle. SDD8887L
Survey Location	BLK 12 SIN MING IND. EST. SECTOR B #01-71	
Contact Person.	MDM LIM	
Contact No.	64536256/ 0	Fax No. 64557754
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KUM CHEW MOTOR WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/223377)

PRI Documents

Close X

PRI Header Details

Claim No	D17005373MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & KU
Workshop Name	KUM CHEW MOTOR WORKSHOP (Contact Person : MDM LIM)	Survey Location & Contact Details	BLK 12 SIN MING IND. EST. SECTOR B #01-71 Mobile: 0 , Phone: 64536256 , Fax: 6455775 EmailId: KUMCHEW1@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7904K	TP Vehicle No	SDD88
PRI Recieved Date	29-05-2017 09:23:20 PM	Surveyor Appointed Date	30-05-2017 09:42:31 AM	Surveyor Accept Date	30-05-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-05-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

KUM CHEW MOTOR WORKSHOP. Fcl

Blk 12 Sin Ming Industrial Estate Sector B

#01-71 Singapore 575656

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

FIRST CAPITAL INSURANCE LTD

36, ROBINSON ROAD #16-01

CITY HOUSE, SINGAPORE 068877.

motor_claims@first-insurance.com.sg

Attention : Motor Claim Department

Contact : 62222311/65073848(C) 65073852 Fax No. : 62244174/65073849(C)

Estimate : ES004132

Date : 01/06/2017

Vehicle Num. : SDD 8887 L

Make/Model : MIT. LANCER

Chassis/Eng# :

Accident Date : 25/05/2017

Claim No. :

Reference : KC/TP1477/1705-05

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS :				
1.	1 PC	REAR LID		X 545.00 <i>net</i>
2.	1 PC	REAR LID LOCK		X 60.00 <i>net</i>
3.	1 PC	REAR LID RUBBER		X 164.00 <i>net</i>
4.	1 PC	REAR BUMPER		✓ 655.00 <i>net</i>
5.	1 PC	REAR BUMPER BRACKET - CENTRE	2.00	✓ 12.00 <i>net</i>
6.	6 PCS	REAR BUMPER CLIP		✓ 40.00 <i>net</i>
7.	1 PC	REAR BUMPER BRACKET (SIDE)	2.00	✓ 36.00 <i>net</i>
8.	18 PCS	REAR BUMPER RIVET	397.00	X 794.00 <i>net</i>
9.	2 PCS	REAR LAMP	3.00	✓ 6.00 <i>net</i>
10.	2 PCS	REAR LAMP CLIP	58.00	X 116.00 <i>net</i>
11.	2 PCS	REAR LAMP PANEL		X 408.00 <i>net</i>
12.	1 PC	REAR END PANEL		✓ 93.00 <i>net</i>
13.	1 PC	REAR END PANEL GARNISH	3.00	✓ 18.00 <i>net</i>
14.	6 PCS	REAR END PANEL GARNISH CLIPS		
Nett Total S\$:				3,116.00
10.00% Discount S\$:				311.60
				2,804.40

SPECIAL NETT ITEMS :				
1.	1 SET	REAR REVERSE SENSOR		280.00
Special Nett Total S\$:				280.00
LABOUR :				

CONTINUE / ...

TO: MR MA
From: MDM LIM.

Pls check & fax to us.
Thank.
16/6/17

KUM CHEW MOTOR WORKSHOP

Blk 12 Sin Ming Industrial Estate Sector B

#01-71 Singapore 575656

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD #16-01

CITY HOUSE, SINGAPORE 068877.

motor_claims@first-insurance.com.sg

Attention : Motor Claim Department

Contact : 62222311/65073848(C) 65073852 Fax No. : 62244174/65073849(C)

Estimate : ES004132

Date : 01/06/2017

Vehicle Num. : SDD 8887 L

Make/Model : MIT. LANCER

Chassis/Eng# :

Accident Date : 25/05/2017

Claim No. :

Reference : KC/TP1477/1705-05

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PULL, KNOCK ON ACCIDENT PORTION & REPLACE THE ABOVE PARTS.	530	950.00
		TO SPRAY & PAINT ON ACCIDENT PORTION.	600	1,300.00
		TO ANTI-RUST REAR AFFECTED AREAS.	40	250.00
		TO CHECK & RE-WIRING ON ACCIDENT AREA.	30	150.00
		Labour Total S\$:		2,650.00

4/5 \$
1250/-
3w/1days

SingDollars : Five Thousand Seven Hundred Thirty-Four & Cents Forty Only

Total S\$: 5,734.40

KUM CHEW MOTOR WORKSHOP



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS3/FCI17010420/M1rbs2-1	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7904K	Veh. Inspected	SDD 8887L	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17005373MFSH	Excess (\$)	0.00	
Assign From	AUNG YIN MIN	Assign Date	30/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JMYSTCS3A5U003489	Colour	BLACK	
Odometer	142812	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55R15	BRIDGESTONE	7 mm	
L/H Front Tyre	195/55R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	195/55R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/55R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2017	Inspection Date	31/05/2017	
Survey held at	KUM CHEW MOTOR WORKSHOP BLOCK 12 SIN MING IND. EST. SECTOR B #01-71 SINGAPORE 575656			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 8887L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LID (N)	TO REPAIR SEE LABOUR	545.00	-
1	REAR LID LOCK (N)	SERVICEABLE	60.00	-
1	REAR LID RUBBER (N)	SERVICEABLE	164.00	-
1	REAR BUMPER (N)	DEFORMED	655.00	655.00
1	REAR BUMPER BRACKET - CENTRE (N)	BENT	171.00	171.00
6	REAR BUMPER CLIP @ \$2.00 (N)	NECESSARY	12.00	12.00
1	REAR BUMPER BRACKET (SIDE) (N)	BENT	40.00	40.00
18	REAR BUMPER RIVET @ \$2.00 (N)	NECESSARY	36.00	36.00
2	REAR LAMP @ \$397.00 (N)	SERVICEABLE	794.00	-
2	REAR LAMP CLIP @ \$3.00 (N)	NECESSARY	6.00	6.00
2	REAR LAMP PANEL @ \$58.00 (N)	TO REPAIR SEE LABOUR	116.00	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	406.00	-
1	REAR END PANEL GARNISH (N)	DISTORTED	93.00	93.00
6	REAR END PANEL GARNISH CLIPS @ \$3.00 (N)	NECESSARY	18.00	18.00
	LESS 10% DISCOUNT		-311.60	-103.10
			2,804.40	927.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	220.00
			280.00	220.00
	<u>LABOUR</u>			
	TO PULL, KNOCK ON ACCIDENT PORTION & REPLACE THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR LID, REAR LAMP PANEL AND REAR END PANEL.		950.00	500.00
	TO SPRAY & PAINT ON ACCIDENT PORTION.		1,300.00	600.00
	TO ANTI-RUST AFFECTED AREAS.		250.00	40.00
	TO CHECK & RE-WIRING ON ACCIDENT AREA.		150.00	30.00
			2,650.00	1,170.00
	GRAND TOTAL		5,734.40	2,317.90

Report Ref No. CS3/FCI17010420/M1rbs2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00
---	--	--	----------

Report Ref No. CS3/FCI17010420/M1rbs2-1

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.