

CWS Kenneth

ASSIGNMENT (Office)

From (Person): Eileen Lee of FCI Date/Time: 24/11/18 @ 3:11pm

Estimated Cost: Bill to:

OD: TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 8449X Insured: SHA 6278B

at Workshop m/s: LH Express Motor Tel: 64817221

of Bk 5038, # 01-405 AMK Ind. Prk. 2

Policy No: Claim No: D18600730MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 21/01/2018
(Client's Record)

CA / REV / REP / REV 24 HRS 'up' HOD 2 Subsequent:

Date/Time: 4:01pm @ 24/11/18 Person Contacted: Mr. Tay Vehicle: IN/OUT

Date/Time: Action/Inspection ✓

SKB 8449X - X

SHA 6278B - 023/ATG170 23331 / K11wb591 DUA: 07/12/17

25/1/18 Email preli revised to FCI

30/1 LISp @ 600m Carline (Red 8316.06, 587M)

ASS. REC. BY:

REF: FCZ/Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s 114 Express

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

25/1 File pass to Catherine

RECEIVED 30 JAN 2010

Veh No: SKB 8449X Yr Regn: 06, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A1 WagonMake: Chevrolet c.c. 1796Colour: Dark Blue A/C: Insured / Std / NI / NASp. Reading: 209753 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W020A14M75A2023327Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 2.1.18

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 24/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 30/1- typist

Report Format:

Lump Sum / I.B.I. (\$) 6000/-CWSDays Of Repair: 5Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos 851

Others

31/1/18

TOTAL

4x15=60170+605050+5023403



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001486/Kvb	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 25-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 6278B	Veh. Inspected	SKB 8449X
Policy No.		Coverage (\$)	0.00
Claim No.	D18000730MFSH	Excess (\$)	0.00
Assign From	CWS(EILEEN LEE)	Assign Date	24/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/01/2018	Inspection Date	24/01/2018
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000730MFSH
Our ref: CS/FC118001486/Kvb

Date : 25/1/2018

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKB 8449X


We thank for your instruction on 24/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/1/2018 at the premises of M/s LH EXPRESS MOTOR TRADING and have the following to report:-

Workshop Estimate Amount	: S\$14,316.06
Revised Estimate Amount	: S\$5,133.32
"Check" Items Amount	: S\$3,665.85
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: CS/PC118001486/Kvb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

30/1/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	23-01-2018	Our Ref No. D18000730MFSH
Accident Date	21-01-2018	Claim Type. Third Party
Insured Vehicle	SHA6278B	Third Party Vehicle. SKB8449X
Survey Location	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	
Contact Person.	MR YEOW	
Contact No.	64817221/ 90089959	Fax No. 64816131
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LH EXPRESS MOTOR TRADING	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234231)



PRI Documents



Close



PRI Header Details

Claim No	D18000730MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CH CORPO
Workshop Name	LH EXPRESS MOTOR TRADING (Contact Person : MR YEOW)	Survey Location & Contact Details	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL I Mobile: 90089959 , Phone: 64817221 , Fax: EmailId: MAIL@CHEONGHOH.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA6278B	TP Vehicle No	SKB84
PRI Recieved Date	23-01-2018 09:26:56 PM	Surveyor Appointed Date	24-01-2018 03:10:09 PM	Surveyor Accept Date	25-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-01-2018	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 25 January 2018 12:43 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000730MFSH/1, SKB 8449X
Attachments: SKB 8449X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKB 8449X
Date of survey: 24/1/2018
Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 24 January 2018 4:03 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000730MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 January 2018 3:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000730MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

LH Express Motor Trading.

Blk 5038 #01-405, Ang Mo Kio Ind. Park 2 Singapore 569541.
Email: lhmotortrading@gmail.com Fax: 64455393. Tel:64817221.

*Not Authorized
L1 Rep & Book
Resurvey After Paint*

Mohammed Nazly Bin Mohd Taha
Blk 912 Tampines St 91 #02-113
Singapore 520912.

Vehicle No : SKB8449X
Chassis No : WOLOAHM75A2023327
Make : OPEL-ZAFIRAH
Year :

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No financial modification(s) is allowed
• Supplementary (extra) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Bumper		Rur \$1,240.00 ✓
2	Rear Bumper Side Garnish LH/RH	\$85.00	Sn \$170.00 X
1 set	Rear Bumper Clips		m \$45.00 ✓
1	Rear Bumper Sponge		Sn \$163.00 X
1	Rear Reinforcement		Bz \$628.00 ✓
1	Rear End Panel		Bz \$1,180.50 ✓
1	Rear End Panel Garnish		myent \$235.00 ✓
2	Rear Bumper Side Retainer RH/LH	\$58.30	Sn \$116.60 X
1	Tail Lamp RH		Sn \$348.00 X
1	Tail Lamp LH		Sn \$348.00 X
1	Tail Gate Assy		Bz \$2,580.30 ✓
1	Tail Gate Inner Trimboard		Sn \$1,350.00 X
1	Tail Gate Lamp Chrome Garnish		Sn \$385.50 X
2	Tail Gate Number Plate Lamp RH/LH	\$90.00	Sn \$180.00 X
1	Tail Gate Lock		nd \$238.00 ✓
1	Tail Gate Wiper Motor		Sn \$650.00 X
2	Tail Gate Damper LH/RH	\$198.00	Sn \$396.00 X
1	Rear Windscreen Moulding		m \$128.50 ✓
1	Tail Gate weatherstrip		(19 Dillm \$238.00 50% ✓
1	Exhaust Silencer		n \$780.00 X
1	Tail Gate Emblem 'ZAFIRAH'		m \$105.00 ✓
1	Tail Gate Emblem 'LOGO'		m \$68.00 ✓
			\$11,573.40
		Less 10%	\$1,157.34
			\$10,416.06

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

\$1,500.00 *600*

Supply Paint Material and necessary items. To respray replaced and other affected panels

\$1,200.00 *660*

Reconnect wiring at the damage section and check for proper functions.

\$75.00 *20*

To carry out antirust treatment on affected panels.

\$180.00 *60*

To remove/ refit exhaust silencer box.

22 \$120.00 *X*

To remove/refit tailgate mechanisms, trimboard and transfer to new door.

\$180.00 *60*

To installed reverse sensor and calibrate setting

\$100.00 *50*

To remove/ refit tailgate windscreen and check water leakage.

\$150.00 *20*

Special Nett Item

Rear Windscreen Sealant

Me *405N*
\$55.00

Rear Number Plate

Sn \$40.00 *X*

Reverse Sensor

CMA *2005N*
\$300.00

Grand Total :

\$14,316.06



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001486/Kvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6278B	Veh. Inspected	SKB 8449X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000730MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	24/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	OPEL ZAFIRA (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	W0L0AHM75A2023327	Colour	METALLIC BLUE	
Odometer	209753	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	8 mm	
L/H Front Tyre	205/55 R16	PIRELLI	8 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/01/2018	Inspection Date	24/01/2018	
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 8449X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	1,240.00	1,240.00
2	REAR BUMPER SIDE GARNISH LH/RH @\$85.00	SERVICEABLE	170.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR BUMPER SPONGE	SERVICEABLE	163.00	-
1	REAR REINFORCEMENT	BENT	628.00	628.00
1	REAR END PANEL	BENT	1,180.50	1,180.50
1	REAR END PANEL GARNISH	MTG CRACKED	235.00	235.00
2	REAR BUMPER SIDE RETAINER RH/LH @\$58.30	SERVICEABLE	116.60	-
1	TAIL LAMP RH	SERVICEABLE	348.00	-
1	TAIL LAMP LH	SERVICEABLE	348.00	-
1	TAIL GATE ASSY	BENT	2,580.30	2,580.30
1	TAIL GATE INNER TRIMBOARD	SERVICEABLE	1,350.00	-
1	TAIL GATE LAMP CHROME GARNISH	SERVICEABLE	385.50	-
2	TAIL GATE NUMBER PLATE LAMP RH/LH @\$90.00	SERVICEABLE	180.00	-
1	TAIL GATE LOCK	DENTED	238.00	238.00
1	TAIL GATE WIPER MOTOR	SERVICEABLE	650.00	-
2	TAIL GATE DAMPER LH/RH @\$198.00	SERVICEABLE	396.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	128.50	128.50
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	780.00	-
1	TAIL GATE EMBLEM "ZAFIRAH"	NECESSARY	105.00	105.00
1	TAIL GATE EMBLEM "LOGO"	NECESSARY	68.00	68.00
	LESS 10% DISCOUNT		-1,133.54	-644.83
			10,201.86	5,803.47
1	TAIL GATE WEATHERSTRIP (50%)(SN)	DISTORTED / DENTED	238.00	119.00
	LESS 10% DISCOUNT		-23.80	-
			214.20	119.00
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	55.00	40.00

Report Ref No. CS/FCI18001486/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	SERVICEABLE	40.00	-
1	REVERSE SENSOR (SN)	CRACKED	300.00	200.00
			395.00	240.00
	LABOUR			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF EXHAUST SILENCER.		1,500.00	600.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		1,200.00	660.00
	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS.		75.00	20.00
	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS.		180.00	60.00
	TO REMOVE/REFIT EXHAUST SILENCER BOX.	NOT NECESSARY	120.00	-
	TO REMOVE/REFIT TAILGATE MECHANISMS,TRIMBOARD AND TRANSFER TO NEW DOOR.		180.00	60.00
	TO INSTALLED REVERSE SENSOR AND CALIBRATE SETTING.		100.00	50.00
	TO REMOVE/REFIT TAILGATE WINDSCREEN AND CHECK WATER LEAKAGE.		150.00	20.00
			3,505.00	1,470.00
	GRAND TOTAL		14,316.06	7,632.47
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00

Report Ref No. CS/FCI18001486/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.