

22/03/2012

ASS. REC. BY:

REF:

033 / CTI 8001504 / Sbs2

Special Instruction:

Range 2 days

Survivor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Sharon Han

of

CTL

Date/Time: 24/01/2018 4:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 2311C

Insured:

SJL 2809P

at Workshop m/s

Kent Seng

Tel:

6758 8367

of

Blk 1017 Tishun Ind Park A #01-240

Policy No:

DMPCSN1765941700

Claim No:

SYM 18D00404/02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up

H.O.D. Endorsement:

Date/Time:

25/01/2018 9:39am

Person Contacted:

Kent Seng

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLR 2311C - X
	SJL 2809P - X
	Dismantle Part: 26-01-2018

PRS

REF: CTL

Medimen

ASSIGNMENT

From: Date: 25/01/2018

Veh No: SLR 2311C Yr Regn: 2010 Feb 10

Estimated Cost:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLR 2311C

Make: BMW 318 2.0L A/T 1995

at Workshop mis:

Colour: Black A/C: Insured / Std / NI / NA

of Blk 1017 Yishun Ind Park A

So. Reading: 55175 T/Radio: Insured / Std / NI / NA

Insured:

#01-240

Eng No:

Policy No:

C/No: W13APF720SOA773512

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: M / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size F: 235/35 R19

R: 265/30 R19

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Good year

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 6 mm

R/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est. Repairs: days Res: Yes or No

D.O.A. 25/1/18 @ 11:00am

Lum Sum: % 3 Val: Yes or No

Survey held at: Kent Seng

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/1/18 No GIA / Estimate.

Date/Time: File Pass to?

☐

: Preli. Report

Days Of Repair:

Date/Time: File Return to?

☐

: Final Report

Resurvey No. of Trip:

Survey Fee

Transportation:

2

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Invs \$

☐

Weekend \$

(\$ - \$)

Photos

Others

Report Format:

PRS

Lump Sum / I.B./ \$

Total

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2018		24 Jan 2018 16:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PUNG WHEI LENG(FANG HUILING), ID: S7244903G		
Main Claimant:	CHEONG FU LIN NEILSON, ID: S9101478E		
Vehicle Reg. No.:	SLR2311C	Date of Loss:	22/01/2018 07:00 - :59
Claim Type:	TP / SNM18D00404C02	Policy/Cover Note No.:	DMPCSN1765941700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJL2809P	Policy No. (Claimant):	5094790007 CLASSIC
		Excess:	S\$0.00
Repairer:	Kent Seng Car Service () Blk 1017 Yishun Industrial Park A, #01-240, 768759 Yishun - Tel: 67588367		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/02/2018]		
Driver/Custodian (Insured):	PUNG WHEI LENG(FANG HUILING) (45 / Female), NRIC: S7244903G		
Adj Asg. Remarks:	NO EST, CASE W/O SJE		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

23/01/2018 @ 9:39am
Kent Seng Veh in

Range : \$ 3200 - \$ 3700

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	23 Jan 2018		24 Jan 2018 16:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PUNG WHEI LENG(FANG HUILING) , ID: S7244903G		
Main Claimant:	CHEONG FU LIN NEILSON , ID: S9101478E		
Vehicle Reg. No.:	SLR2311C	Date of Loss:	22/01/2018 07:00 - :59 [95 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00404C02	Policy/Cover Note No.:	DMPCSN1765941700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJL2809P	Policy No. (Claimant):	5094790007 CLASSIC
		Excess:	S\$0.00
Repairer:	Kent Seng Car Service () Blk 1017 Yishun Industrial Park A, #01-240, 768759 Yishun - Tel: 67588367		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 02/02/2018]		
Driver/Custodian (Insured):	PUNG WHEI LENG(FANG HUILING) (45 / Male), NRIC: S7244903G		
Adj. Asg. Remarks:	NO EST, CASE W/O SJE		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR2311C (SNM18D00404C02)**
[SJL2809P]
TP
CHEONG FU LIN NEILSON
Jan 22 2018 7:00AM
[PUNG WHEI LENG(FANG HUILING)]
Kent Seng Car Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	23/01/18 11:18	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	23/01/18 11:18	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	23/01/18 11:18	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	23/01/18 11:18	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	23/01/18 11:18	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	23/01/18 11:18	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	23/01/18 11:18	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/01/18 16:09	OI GIA REPORT		Load PDF	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	23/01/18 11:17	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	23/01/18 11:17	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/04/18 14:30	LKKPhotosIn6-1		Load PDF	
2	06/04/18 14:30	LKKPhotosIn6-2		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	23/01/18 11:18	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	23/01/18 11:18	Accident Photo		Load JPG	☒
2	23/01/18 11:18	Accident Photo		Load JPG	☒
3	23/01/18 11:18	Accident Photo		Load JPG	☒
4	23/01/18 11:18	Accident Photo		Load JPG	☒
5	23/01/18 11:18	Accident Photo		Load JPG	☒

Assessment Reports			1 per page ▾	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
6	23/01/18 11:18	Accident Photo	Load JPG	
Documentation			1 per page ▾	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	23/01/18 11:17	Sketch Plan	Load TIF	
2	23/01/18 11:17	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18001504/SBS2
Date: 12/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN1765941700
Claimant Vehicle No: SLR2311C Insured Vehicle No: SJL2809P
Date of Loss: 22/01/2018 Nature of Claim: TP Claim No: SNM18D00404C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR2311C
Make & Model: BMW 318I, 2.0 L (A) Engine No: A833I600N46B20BZ
Reg. Date: 10/02/2010 (Man. Year: 2009) Chassis No: WBAPF72080A793512
Colour: Black Odometer: 55175 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19 Rear Tyre Size: 265/30R19
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/01/2018
Date Inspected: 24/01/2018 Inspected At: Kent Seng Car Service
Blk 1017 Yishun Industrial Park A, #01-240
Singapore 768759
Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,200.00 - \$3,700.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts:	143	BMW 318I 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2311C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >