

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 3522**
Date Estimated : **24/01/2018**
Prepared By : **Wong Guo Xiang**

Page No. : **1 of 2**

- ESTIMATE REPAIR FOR -

PRESENTIN THOMAS
43 LORONG H TELOK KURAU

SINGAPORE 426042

- ACCOUNT - **2000**

CASH - Sale service
.

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD8339U	WF0EXXGBBEBL21655	12/01/2012	MON 2.OT 5DR	0

DESCRIPTION	VALUE
SUNDRIES	150.00
REPAIR /REPLACE REAR RHS FENDER,REAR BUMPER	2,400.00
RESPRAY REAR BUMPER,REAR RHS FENDER	1,800.00
WIRING CONNECTION & CHECK (NETT)	150.00
REMOVE & REPLACE REAR SUSPENSION SYSTEM (NETT)	1,500.00
REMOVE & REFIX REVERSE SENSOR (NETT)	150.00
WHEEL ALIGNMENT (NETT)	600.00
TUFF KOTE @ \$60 PER PANEL	120.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE (NETT)	600.00

Total Labour 1: **7,470.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
BS71A17906BB	BUMPER-REAR	1	1,562.00	10.00	1,405.80
XWAA					
7S71A17E850A	RHR BUMPER SIDE BRACKET	1	110.00	10.00	99.00
N					
6G915K652XAE	ARM ASY-RR SUSP	1	330.00	10.00	297.00
6G915A968FAJ	RHR KNUCKLE ARM	1	998.00	0.00	998.00
AG9C2B664FAA	RR WHEEL HUB	1	675.00	10.00	607.50

Total Parts : **3,407.30**

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 3522**
Date Estimated : **24/01/2018**
Prepared By : **Wong Guo Xiang**

Page No. : **2 of 2**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD8339U	WF0EXXGBBEBL21655	12/01/2012	MON 2.0T 5DR	0

Customer Service Officer

Contact

Labour 1	:	7,470.00
Parts	:	3,407.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	761.41
Grand Total	:	11,638.71

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.