

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL CS3/SMO18001526/Gbe2 Page No.:1 of 1

| | AFFLES PLACE # ERSINGAPORE 0 | #05-01/06 SINGAPORE LAND 048623 | Date: 28-03- | 2018 | |
|--|---|--|---------------|--------|-------------------------|
| | | | Code: SMO | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | GBD 6456J | Veh. Inspect | ed | SLP 2926P |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | CMTD1800380/NSW | Excess (\$) | | 0.00 |
| | Assign From | GRACE TEO | Assign Date | | 25/01/2018 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA CR-V | c.c | | 1498 |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | JHLRE48508C211607 | Colour | | WHITE |
| | Odometer | 120090 KM | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 225/60 R18 | YOKOHAMA | | 6 mm |
| | L/H Front Tyre | 225/60 R18 | YOKOHAMA | | 6 mm |
| | R/H Rear Tyre | 225/60 R18 | YOKOHAMA | | 6 mm |
| | L/H Rear Tyre | 225/60 R18 | YOKOHAMA | | 6 mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUS | HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | |
| | DAMAGES SEE DE | ES SEE DETAILS. | | | |
| 5. General Information | | | | | |
| | Accident Date | 20/01/2018 | Inspect Date | / Time | 29/01/2018 (11:30 AM) |
| | Survey held at | KARCOOL AIR-CONDITIONING AND ENGINEERING COMPANY | | | |
| | | 2 KAKI BUKIT AVENUE 2 #01-20 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | |
| 5a. | ia. Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 | | | | |

Report Ref No. CS3/SMO18001526/Gbe2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A **Automotive Assessor** BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

7 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.