

22/03/2012

ASS. REC. BY:

REF: CS/FCI8001527/Utbz

Special Instructions:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCI Date/Time: 24/01/2018 1453pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 6320P Insured: SHA 5278H

at Workshop m/l: VAX Auto Tel: 9689 0102

of 60 Kaki Bukit Ave 6

Policy No: Claim No: D18000668 MF8H

Sum Insured: Excess:

Make of Veh: D.O.A. 19012018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 25/01/2018 10:12am Person Contacted: Jounel Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 6320P - X
	SHA 5278H - CS/FCI 09024977 / Ubg1 DCA: 270769
26/1-	Report via email preli

REF: FCI

ASSIGNMENT

Front: Date: 25/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLT 6320P

at Workshop mis: Vix Auto

of: 60 Kaki Bukit Ave 6

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

morning

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 120k.

IDAC Accident Report: Consistent? : Yes or No

GIA / R Seen: 2 Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLT 6320P Vn Regn: 1215

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer of: CA /

Make: Honda Odyssey 2356

Colour: Red Insured / Std / NI / NA

Sp. Reading: 42428 T/Radio: Insured / Std / NI / NA

Eng. No:

C/No: JMMRC1890GC200739

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 215/55-R17

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 19/1/18

D.O.A: 25/1/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

219 72004

Rep 13800

7rim board 202-20

7-11ay 821-70-33170-76A
003

29/1/18 2/5 @ 7000 confirmed with Michael

RECEIVED 30 JAN 2018

Date/Time: File Pass to?

30/1 Typist

Date/Time: File Return to?

☐ Preli. Report☒ Final Report

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee:

- ☐ Site Insp \$
☐ Interview \$
☐ Tech Insp \$
☐ Weekend \$

Survey Fee:

Transportation:

3+Rg \$

Phone 058

Fax 058

Date 31/1/18

Total

Total

6x15: 90

170+90

50

100

100

100

100

100

100

100

100

100

100

Report Format:

Lump Sum / I.B.I: \$ 7000

TP



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001527/Ut6	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 5278H	Veh. Inspected	SLT 6320P
Policy No.		Coverage (\$)	0.00
Claim No.	D18000668MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	24/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/01/2018	Inspection Date	25/01/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	22-01-2018	Our Ref No. D18000668MFSH
Accident Date	19-01-2018	Claim Type. Third Party
Insured Vehicle	SHA5278H	Third Party Vehicle. SLT6320P
Survey Location	60 KAKI BUKIT AVE 6 ARK@KB	
Contact Person.	KELVIN POH	
Contact No.	64489268/ 96890102	Fax No. 64452368
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VFIX AUTO SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234146)



PRI Documents



Close



PRI Header Details

Claim No	D18000668MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VF
Workshop Name	VFIX AUTO SERVICE PTE LTD (Contact Person : KELVIN POH)	Survey Location & Contact Details	60 KAKI BUKIT AVE 6 ARK@KB Mobile: 96890102 , Phone: 64489268 , Fax: EmailId: VFIXAUTO@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA5278H	TP Vehicle No	SLT632
PRI Recieved Date	23-01-2018 04:29:45 PM	Surveyor Appointed Date	24-01-2018 04:52:42 PM	Surveyor Accept Date	25-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-01-2018	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9604D
Vehicle Details	
Vehicle No.:	SLT6320P
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	K24W72010232
Chassis No.:	JHMRC1890GC200739
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,188.00
Original Registration Date:	28 Dec 2015
First Registration Date:	28 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$31,464.00 15732
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2025
PARF Rebate Amount:	\$23,598.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$48,406.00
Total Rebate Amount:	\$72,004.00

The information contained herein is correct as at 25 Jan 2018

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Oct 2012 BMW 520i, PML Unit, 108000Km, Well Maintain



Only 14k Deprecation! Cheapest
In Market Yet Come With A 2
Digit Bidded Number!
Tely Auto Credit : StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

honda odyssey

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda odyssey		Any	Any	2015	Any	Any	Any	Available
	Honda	Odyssey 2.4A EXV-S	\$129,800	\$14,450 /yr	17-Dec-2015	2,356 cc	48,000 km	MPV	Available
1 Careful Owner With Low Mileage Done, Full Agent Maintain By Kah Motor, Agent Warranty, Prestige Condition With Spacious Interior And Flawless Leather, High Loan And High Trade In Available. Let Us A...									
Starise Automobile									
Posted: 14-Jan-2018 Tags: 2015 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda									
	Honda	Odyssey 2.4A Absolute	\$121,800	\$14,310 /yr	13-Jul-2015	2,356 cc	27,500 km	MPV	Available
Best Price! 8 Seaters JDM Absolute Model With 187bhp. Accident Free And Regularly Maintained. Owner Consigned, Please Call For Viewing Appointment.									
Posted: 11-Jan-2018 Tags: 2015 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda									
	Honda	Odyssey 2.4A EXV-S	\$126,800	\$15,720 /yr	05-Mar-2015	2,356 cc	-	MPV	Available
1 Owner Only! Very Low Mileage! On-going Agent Warranty! Highest Spec Model! Well Kept By Previous Owner In Excellent Condition, As Good As Brand New Ones. For You To See And Believe! Buy It From Us W...									
Dickson Automobile									
Posted: 24-Dec-2017 Tags: 2015 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used honda odyssey, honda odyssey Singapore, used honda odyssey Singapore, used honda odyssey, used vehicles Singapore or even buy used honda odyssey Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 26 January 2018 1:28 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000668MFSH/1
Attachments: PRELI ADVISED SLT 6320P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLT 6320P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 25 January 2018 10:14 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000668MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 January, 2018 4:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000668MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000668MFSH

Date: 26/1/2018

Our Ref: CS/FCI18001527/Utb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 6320P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/1/2018 at the premises of M/s Vfix, and have the following to report: -

Workshop Estimate Amount	: S\$ <u>16,818.80</u>
Revised Estimate Amount	: S\$ <u>9,373.16</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor



FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
Attention: Motor Claim Department

*Not Authorized
 Mark
 2/5 7000/2
 7 day.
 25/1/18
 to be photo after
 repair*

Vfix Auto Service Pte Ltd
 60 Kaki Bukit Ave 6
 Ark@KB Singapore 417892
 Email: vfixauto@gmail.com
 Tel: 64489268 Fax: 64452368

ESTIMATE

DATE : 23/01/2018
 ACC DATE : 19/01/2018
 REF NO. : VFIX - TP20180405
 POLICY NO :

RE : VEHICLE NO.SLT6320E HONDA ODYSSEY

DESCRIPTION	AMOUNT S\$
1 1 TAIL GATE <i>1049.80</i>	<i>Body</i> 1,403.00 ✓
2 1 TAIL GATE INNER TRIM BOARD	<i>Del trim</i> 363.60 ✓
3 1 TAIL GATE INNER PULL HANDLE	<i>11</i> 65.00 ✓
4 1 TAIL GATE RUBBER STOPPER	<i>11</i> 15.00 ✓
5 1 TAIL GATE LOGO <i>38.50</i>	<i>ner</i> 85.00 ✓
6 2 TAIL GATE REFLECTOR R+L <i>378.60 x 2 = 757.20</i>	522.30 <i>one</i> 1,044.60 ✓
7 1 TAIL GATE REFLECTOR CENTER <i>225.90</i>	<i>one</i> 436.00 ✓
8 2 TAIL GATE HINGE R+L	89.00 <i>11</i> 178.00 ✓
9 2 TAIL GATE DAMPER R+L	198.00 <i>11</i> 396.00 ✓
10 1 TAIL GATE LOCK <i>294.50</i>	<i>trim</i> 412.00 ✓
11 1 TAIL GATE LOCK CATCH	<i>11</i> 75.00 ✓
12 1 TAIL GATE OPENER SWITCH	<i>11</i> 186.00 ✓
13 1 AUTO LOCK SENSOR	<i>11</i> 298.00 ✓
14 1 TAIL GATE NUMBER PLATE CHROME	<i>one</i> 310.00 ✓
15 1 TAIL GATE WEATHERSTRIP	<i>trim</i> 210.40 ✓
16 2 TAIL LAMP <i>821.70 x 1643.40</i>	852.10 <i>one</i> 1,704.20 ✓
17 1 TAIL LAMP LOWER PANEL LH	<i>11</i> 285.60 ✓
18 1 REAR FENDER GARNISH RH	<i>11</i> 720.60 ✓
19 1 REAR BUMPER <i>557.20</i>	<i>11</i> 1,002.60 ✓
20 2 REAR BUMPER REFLECTOR R+L <i>32</i>	98.00 <i>0/500</i> 196.00 ✓
21 2 REAR BUMPER REFLECTOR COVER R+L	152.00 <i>11</i> 304.00 ✓
22 2 REAR BUMPER CORNER EXTENSION R+L	178.20 <i>11</i> 356.40 ✓
23 2 REAR BUMPER LOWER BRACKET <i>35 x 2 = 70</i>	70.40 <i>3rd</i> 140.80 ✓
24 2 REAR BUMPER SIDE RETAINER <i>38 x 2 = 76</i>	136.20 <i>3rd</i> 272.40 ✓
25 1 REAR END PANEL <i>685.20</i>	<i>Body</i> 1,307.90 ✓
26 1 REAR END PANEL TOP GARNISH	<i>trim</i> 367.80 ✓
27 1 REAR END PANEL TOP GARNISH COVER	<i>NS</i> 215.00 ✓
28 1 REAR FLOOR PANEL	<i>11</i> 1,088.60 ✓
29 1 REAR FLOOR PANEL GARNISH	<i>trim</i> 365.00 ✓
	13,804.50
	LESS 20% 2,760.90
	\$ 11,043.60

*7046.5
 5637.2*

DESCRIPTION

AMOUNT S\$

SPECIAL NETT ITEM					
1	1	REAR WINDSCREEN GLASS MOULDING	75	298.20	SN ✓
2	1	REAR WINDSCREEN GLASS SEALANT		120.00	SN 40
3	2	REVERSE SENSOR		500.00	SN 200
4	10	REAR BUMPER CLIP		50.00	SN ✓
5	1	TOOL CAR JACK		165.00	SN 2
6	1	REVERSE CAMERA		450.00	SN 380
7	6	REAR BUMPER CORNER EXTENSION CLIP		30.00	SN x
8	7	REAR FENDER GARNISH CLIP		42.00	SN x
9	1	KEYLESS REMOTE CONTROL		650.00	SN x
10	1	REAR FLOOR TRAY		220.00	SN 180
				\$ 2,525.20	

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary repair dented panel, replace new part refit align into position with all necessary components/attachments	880	1,400.00
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1000	1,200.00
3	To transfer tail gate components	60	150.00
4	To remove, refit rear windscreen glass and water test	120	200.00
5	To remove, refit rear compartment garnishes with all necessary components/attachments	80	200.00
6	To install reverse sensor and check function	50	100.00
			\$ 3,250.00
			3115

GRAND TOTAL : \$ 16,818.80

8742.2
7071

SINGAPORE DOLLARS : SIXTEEN THOUSAND EIGHT HUNDRED EIGHTEEN AND CENTS EIGHTY ONLY

Vfix Auto Service Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001527/Utn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5278H	Veh. Inspected	SLT 6320P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000668MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	24/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY (A)	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHMRC1890GC200739	Colour	RED	
Odometer	42428	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/01/2018	Inspection Date	25/01/2018	
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 6320P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	BADLY DENTED	1,403.00	1,049.80
1	TAIL GATE INNER TRIM BOARD	DEFORMED / TWISTED	363.60	363.60
1	TAIL GATE INNER PULL HANDLE	NOT NECESSARY	65.00	-
1	TAIL GATE RUBBER STOPPER	NOT NECESSARY	15.00	-
1	TAIL GATE LOGO	NECESSARY	85.00	38.50
2	TAIL GATE REFLECTOR R+L @\$522.30	CRACKED	1,044.60	757.20
1	TAIL GATE REFLECTOR CENTER	CRACKED	436.00	225.90
2	TAIL GATE HINGE R+L @\$89.00	NOT NECESSARY	178.00	-
2	TAIL GATE DAMPER R+L @\$198.00	NOT NECESSARY	396.00	-
1	TAIL GATE LOCK	TWISTED	412.00	294.50
1	TAIL GATE LOCK CATCH	NOT NECESSARY	75.00	-
1	TAIL GATE OPENER SWITCH	NOT NECESSARY	186.00	-
1	AUTO LOCK SENSOR	NOT NECESSARY	298.00	-
1	TAIL GATE NUMBER PLATE CHROME	CRACKED	310.00	310.00
1	TAIL GATE WEATHERSTRIP	TWISTED	210.40	210.40
2	TAILLAMP @\$852.10	CRACKED	1,704.20	1,643.40
1	TAILLAMP LOWER PANEL LH	TO REPAIR SEE LABOUR	285.60	-
1	REAR FENDER GARNISH RH	TO REPAIR SEE LABOUR	720.60	-
1	REAR BUMPER	DISTORTED	1,002.60	557.20
2	REAR BUMPER REFLECTOR R+L @\$98.00	O/S CRACKED	196.00	32.00
2	REAR BUMPER REFLECTOR COVER R+L @\$152.00	NOT NECESSARY	304.00	-
2	REAR BUMPER CORNER EXTENSION R+L @\$178.20	NOT NECESSARY	356.40	-
2	REAR BUMPER LOWER BRACKET @\$70.40	BENT	140.80	70.00
2	REAR BUMPER SIDE RETAINER @\$136.20	BENT	272.40	76.00
1	REAR END PANEL	BADLY DENTED	1,307.90	685.20
1	REAR END PANEL TOP GARNISH	TWISTED	367.80	367.80
1	REAR END PANEL TOP GARNISH COVER	NO SUCH PARTS	215.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,088.60	-

Report Ref No. CS/FCI18001527/Utn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL GARNISH	TORN	365.00	365.00
	LESS 20% DISCOUNT		-2,760.90	-1,409.30
			11,043.60	5,637.20
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN GLASS MOULDING (SN)	NECESSARY	298.20	75.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	120.00	40.00
2	REVERSE SENSOR @\$250.00 (SN)	SHORTED	500.00	200.00
10	REAR BUMPER CLIP @\$5.00 (SN)	NECESSARY	50.00	50.00
1	TOOL CAR JACK (SN)	NOT NECESSARY	165.00	-
1	REVERSE CAMERA (SN)	SHORTED	450.00	380.00
6	REAR BUMPER CORNER EXTENSION CLIP @\$5.00 (SN)	NOT NECESSARY	30.00	-
7	REAR FENDER GARNISH CLIP @\$6.00 (SN)	NOT NECESSARY	42.00	-
1	KEYLESS REMOTE CONTROL (SN)	NOT NECESSARY	650.00	-
1	REAR FLOOR TRAY (SN)	WARPED / DEFORMED	220.00	180.00
			2,525.20	925.00
	LABOUR			
	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR DENTED PANEL, REPLACE NEW PART REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS/ATTACHMENTS. INCLUSIVE OF THE REPAIR OF TAILLAMP LOWER PANEL LH, REAR FENDER GARNISH RH AND REAR FLOOR PANEL.		1,400.00	880.00
	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,200.00	1,000.00
	TO TRANSFER TAIL GATE COMPONENTS.		150.00	60.00
	TO REMOVE, REFIT REAR WINDSCREEN GLASS AND WATER TEST.		200.00	120.00
	TO REMOVE, REFIT REAR COMPARTMENT GARNISHES WITH ALL NECESSARY COMPONENTS/ATTACHMENTS.		200.00	80.00
	TO INSTALL REVERSE SENSOR AND CHECK FUNCTION.		100.00	50.00
			3,250.00	2,190.00
	GRAND TOTAL		16,818.80	8,752.20

Report Ref No. CS/FC118001527/Utbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00
---	--	--	----------

Report Ref No. CS/FCI18001527/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.