


From (Person): Meimien - Tau Fik of MSIG Date/Time: 25/01/2018
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SDE8008 C Insured: SKZ 5983M
 at Workshop m/s: Z-One Automotive Tel: 6250 2115 / 9755 2115
 of: 7 soon Lee Street, ispace # 01-27/47, 627 608 Sunny West
 Policy No: A28 68 0224 AVW Claim No: 531919
 Sum Insured: _____ Excess: _____
 Make of Veh (Client's Record): _____ D.O.A. 4/10/17
 CA / REV / REP / REV 24 HRS: 1wp H.O.D. Endorsement: _____
 Date/Time: 9/10/17 11:45am Person Contacted: Yvonne Vehicle: IN OUT
 Date/Time: _____ Action/Instructions: X Estimate PC NOT Finalize
SDE8008 C - NA/INC 41023137 / 01-D.O.A. 13/10/2017
SKZ 5983M - X
Disassemble Part: 10-10-2017

31-10-17 6:15pm Email to Katharine Wong from Meimien

1/5/18 6:00:00, 4 days

22/10/18 Submit LS \$6000 (Recd 3000, 3370), 4 days

RECEIVED 2 OCT 2018


 21/2/2018

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Fédération Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17019300/T1vb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 25-01-2018	
Code : MSG			
1. Policy Particulars - THIRD PARTY CLAIM			
Insured Veh.	SKZ 5983M	Veh. Inspected	SDE 8008C
Policy No.	A28680224AVW	Coverage (\$)	0.00
Claim No.	531919	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	25/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/10/2017	Inspection Date	25/01/2018
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Payment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2017		06 Oct 2017 16:34		20 Nov 2017 09:34 S\$0.00 (S\$192.60)		Pending for Payment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHERN CHEONG HOONG, ID: S6911292G, Tel: +6598465684, Email: CHERNCHEONGHOONG@GMAIL.COM		
Main Claimant:	Asia Technical Gas Co Pte Ltd, Co. Reg. No.: 197801958Z		
Vehicle Reg. No.:	SDE8008C	Date of Loss:	04/10/2017 08:00 - :59
Claim Type:	TP / 531919	Policy/Cover Note No.:	A28680224AVW (Comprehensive) Coverage: 28/01/2017 - 27/01/2018
Vehicle Reg. No. (Insured):	SKZ5983M	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Z-one Automotive Pte Ltd - Soon Lee () 7 Soon Lee Street, iSpace #01-27/47, 627608 Jurong West - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 07/10/2017]		
Driver/Custodian (Insured):	CHERN CHEONG HOONG (48 / Male), NRIC: S6911292G, Tel: +6598465684		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PAL'S

APPRAISER PTE LTD
No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 3802 Fax: 6747 1017
Registration No.: 201000268D

Report Reference : TP / 10-17022/AY / 2017

Date of Report : 26 Oct 2017

Asia Technical Gas Co Pte Ltd
c/o No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 4 Oct 2017

As per your instruction dated 10 Oct 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SDE 8008 C. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SDE 8008 C
Model : Mercedes Benz S300L
Year / Capacity : 2013/2997
Chassis No : WDD2211542A527354
Engine No : 27294632088977
Mileage : 110400
Colour : Black

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	255/45 R18	Michelin	6.00	mm	Sport
REAR	O/S	:	255/45 R18	Michelin	6.00	mm	Sport
FRONT	N/S	:	255/45 R18	Michelin	6.00	mm	Sport
REAR	N/S	:	255/45 R18	Michelin	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD
No. 1 Kaki Bukit Avenue 6 #01-53 Autollay @ Kaki Bukit Singapore 417883 Tel: 8181 5802 Fax: 6747 1017
Registration No.: 201000268(D)

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Z-One Automotive Pte Ltd
No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

5. Estimated normal period of repair : 4 working days to complete.
6. Enclosed number of photograph : 157 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SDE 8008 C
Report No: TP/ 10-17022/AY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
2	Rear taillamps LH - ok, RH - no X	Damage	\$ 1699.22	\$ 1849.61
1	Rear end panel	Repair	\$ 844.99	\$ 1699.22
1	Rear bumper	Damage	\$ 1748.39	\$ 1748.39
1	Rear bumper reinforcement	Damage	\$ 531.42	\$ 531.42
2	Rear bumper reinforcement stays	Damage	\$ 205.00	\$ 205.00
2	Rear bumper side retainers	Necessary	\$ 144.40	\$ 144.40
1	Rear bumper lower	Damage	\$ 586.00	\$ 586.00
1	Rear bumper tow hook cover	Damage	\$ 28.05	\$ 28.05
2	Rear bumper PDC sensors	Damage	\$ 929.32	\$ 929.32 464.66
1	Rear bumper centre guide	Damage	\$ 89.50	\$ 89.50
1	Rear undercover under cover	Damage	\$ 242.65	\$ 242.65
1	Rear o/s exhaust silencer	Damage	\$ 1880.00	\$ 1880.00 1000/repair SN 9101
1	Rear n/s exhaust silencer	Damage	\$ 896.00	\$ 896.00
2	Rear exhaust silencer chrome tail pipes	Damage LH	\$ 396.00	\$ 198 396.00 LH - cut, R+
2	Exhaust silencer insulators LH - ok, RH - X on	Damage	\$ 292.00	\$ 146 292.00
			\$ 10512.94	\$ 9667.95
				6729.68
				SN 100
				6279.68

Spare Parts Total \$ 10512.94 \$ 9667.95

Vehicle No: SDE 8008 C
Report No: TP/ 10-17022/AY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 10512.94	\$ 9667.95
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 30.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 100.00	\$ 60.00
3	To remove and refit rear bumper sensor.	\$ 120.00	\$ 40.00
4	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$ ✓ 100.00
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 500.00 ✓
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 500.00
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	1230 Not Required
Total		\$ 12832.94	\$ 11217.95

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9000.00

7459.68
4/5 \$ 6000

SDLS: NINE THOUSAND ONLY


Qualified Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2017		06 Oct 2017 16:34 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	CHERN CHEONG HOONG, ID: S6911292G, Tel: +6598465684, Email: CHERNCHEONGHOONG@GMAIL.COM		
Main Claimant:	Asia Technical Gas Co Pte Ltd, Co. Reg. No.: 197801958Z		
Vehicle Reg. No.:	SDE8008C	Date of Loss:	04/10/2017 08:00 - :59
Claim Type:	TP / 531919	Policy/Cover Note No.:	A28680224AVW (Comprehensive) Coverage: 28/01/2017 - 27/01/2018
Vehicle Reg. No. (Insured):	SKZ5983M	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Z-one Automotive Pte Ltd - Soon Lee () 7 Soon Lee Street, iSpace #01-27/47, 627608 Jurong West - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/02/2018]		
Driver/Custodian (Insured):	CHERN CHEONG HOONG (48 / Male), NRIC: S6911292G, Tel: +6598465684		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
MSIG_SG (21/02/2018): Report Send Back Alerts - SDE8008C (TP)			

ALL ASSOCIATED TASKS ☐										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SDE8008C (531919)**
[SKZ5983M]
TP
Asia Technical Gas Co Pte Ltd
Oct 4 2017 8:00AM
[CHERN CHEONG HOONG]
Z-one Automotive Pte Ltd - Soon Lee

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/10/17 14:33	Accident Statement From:OD - Reg. No: SKZ5983M, Claimant: CHERN CHEONG HOONG	 Load HTM	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/17 18:43	Odometer Reading	 Load JPG	☒
2	31/10/17 18:43	Chassis Number	 Load JPG	☒
3	31/10/17 18:43	General View	 Load JPG	☒
4	31/10/17 18:43	General View	 Load JPG	☒
5	31/10/17 18:43	General View	 Load JPG	☒
6	31/10/17 18:43	General View	 Load JPG	☒
7	31/10/17 18:43	General View	 Load JPG	☒
8	31/10/17 18:43	General View	 Load JPG	☒
9	31/10/17 18:43	General View	 Load JPG	☒
10	31/10/17 18:43	General View	 Load JPG	☒
11	31/10/17 18:43	General View	 Load JPG	☒
12	31/10/17 18:43	General View	 Load JPG	☒
13	31/10/17 18:43	General View	 Load JPG	☒
14	31/10/17 18:43	General View	 Load JPG	☒
15	31/10/17 18:43	General View	 Load JPG	☒
16	31/10/17 18:43	General View	 Load JPG	☒
17	31/10/17 18:43	General View	 Load JPG	☒
18	31/10/17 18:43	General View	 Load JPG	☒
19	31/10/17 18:43	General View	 Load JPG	☒
20	31/10/17 18:43	General View	 Load JPG	☒
21	31/10/17 18:43	General View	 Load JPG	☒
22	31/10/17 18:43	General View	 Load JPG	☒
23	31/10/17 18:43	General View	 Load JPG	☒
24	31/10/17 18:43	General View	 Load JPG	☒
25	31/10/17 18:43	General View	 Load JPG	☒
26	31/10/17 18:43	General View	 Load JPG	☒
27	31/10/17 18:44	Photographs of Damaged Parts	 Load JPG	☒
28	31/10/17 18:44	Photographs of Damaged Parts	 Load JPG	☒
29	31/10/17 18:44	Photographs of Damaged Parts	 Load JPG	☒
30	31/10/17 18:44	Photographs of Damaged Parts	 Load JPG	☒

31	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
32	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
33	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
34	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
35	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
36	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
37	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
38	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
39	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
40	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
41	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
42	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
43	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
44	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
45	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
46	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
47	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
48	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
49	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
50	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
51	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
52	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
53	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
54	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
55	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
56	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
57	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
58	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
59	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
60	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
61	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
62	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
63	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
64	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
65	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
66	31/10/17 18:44	Photographs of Damaged Parts		Load JPG	☒
67	23/01/18 09:18	Photo After Spray		Load JPG	☒
68	23/01/18 09:18	Photo After Spray		Load JPG	☒
69	23/01/18 09:18	Photo After Spray		Load JPG	☒
70	23/01/18 09:18	Photo After Spray		Load JPG	☒
71	23/01/18 09:18	Photo After Spray		Load JPG	☒
72	23/01/18 09:18	Photo After Spray		Load JPG	☒
73	23/01/18 09:18	Photo After Spray		Load JPG	☒
74	23/01/18 09:18	Photo After Spray		Load JPG	☒
75	23/01/18 09:18	Photo After Spray		Load JPG	☒
76	23/01/18 09:18	Photo After Spray		Load JPG	☒
Documentation				1 per page ▼	☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/10/17 14:33	TP GIA REPORT From:OD - Reg. No: SKZ5983M, Claimant: CHERN CHEONG HOONG		Load PDF	
2	06/10/17 14:38	TP request for PRI		Load PDF	
3	06/10/17 17:18	PRI DETAILS		Load PDF	
4	18/12/17 17:11	Survey Report		Load PDF	
5	18/12/17 17:11	Survey Photo 1		Load PDF	
6	18/12/17 17:11	Survey Photo 2		Load PDF	
7	18/12/17 17:11	Survey Photo 3		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/02/18 14:34	Invoice		Load PDF	
2	23/02/18 14:34	PHOTO1		Load PDF	
3	23/02/18 14:34	PHOTO2		Load PDF	
4	23/02/18 14:34	PHOTO3		Load PDF	
5	23/02/18 14:34	PHOTO4		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17019300/T1VBE2-1
Date: 23/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** A28680224AVW
Claimant Vehicle No : SDE8008C **Insured Vehicle No :** SKZ5983M
Date of Loss: 04/10/2017 **Nature of Claim:** TP **Claim No:** 531919

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDE8008C
Make & Model: MERCEDES-BENZ S280, 2.8 (A) **Engine No:** 27294632088977
Reg. Date: 30/09/2013 (Man. Year: 2013) **Chassis No:** WDD2211542A527354
Colour: Black **Odometer:** 110399 km
Engine Capacity: 2997 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 255/45 R18 **Rear Tyre Size:** 255/45 R18
Front Left Side: Michelin 6 mm **Rear Left Side:** Michelin 6 mm
Front Right Side: Michelin 6 mm **Rear Right Side:** Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,512.94	6,229.68	4,283.26	40.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,230.00	1,090.00	46.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,832.94	7,459.68	5,373.26	41.87
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	12,832.94	6,000.00	6,832.94	53.25
+ GST 7.00/7.00% (\$\$)	898.31	420.00	478.31	53.25
Nett Amount (\$\$)	13,731.25	6,420.00	7,311.25	53.25

INSPECTION

Date of Assignment: 06/10/2017
Date Inspected: 09/10/2017 **Inspected At:** Z-one Automotive Pte Ltd - Soon Lee
 7 Soon Lee Street, iSpace #01-27/47
 Singapore 627608
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2018)

Parts: 143 MERCEDES-BENZ S280 2.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDE8008C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILLAMPS	N/SCracked / O/S Not Necessary	1,699.22 F	*849.61 F
2	1	*REAR END PANEL	Repair	844.99 F	*- F
3	1	*REAR BUMPER	Damaged	1,748.39 F	*1,748.39 F
4	1	*REAR BUMPER REINFORCEMENT	Damaged	531.42 F	*531.42 F
5	2	*REAR BUMPER REINFORCEMENT STAYS	Damaged	205.00 F	*205.00 F
6	2	*REAR BUMPER SIDE RETAINERS	Necessary	144.40 F	*144.40 F
7	1	*REAR BUMPER LOWER	Damaged	586.00 F	*586.00 F
8	1	*REAR BUMPER TOW HOOK COVER	Damaged	28.05 F	*28.05 F
9	1	*REAR BUMPER PDC SENSORS (4 PCS)	Damaged-2 pcs only	929.32 F	*464.66 F
10	1	*REAR BUMPER CENTRE GUIDE	Damaged	89.50 F	*89.50 F
11	1	*REAR UNDERCOVER UNDER COVER	Damaged	242.65 F	*242.65 F
12	1	*REAR O/S EXHAUST SILENCER (LOCAL REPAIR)	Damaged	1,880.00 FS	*100.00 FS
13	1	*REAR N/S EXHAUST SILENCER	Damaged	896.00 F	*896.00 F
14	1	*REAR EXHAUST SILENCER CHROME TAIL PIPES	N/S Cut / O/S Not Necessary	396.00 F	*198.00 F
15	1	*EXHAUST SILENCER INSULATORS	N/S Deformed /O/SNot Necessary	292.00 F	*146.00 F
				Total Parts (S\$)	10,512.94 6,229.68

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	100.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	120.00	40.00
4	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS	New	150.00	100.00
5	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	900.00	500.00
6	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	900.00	500.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	100.00	0.00
Gross Labour Cost (\$\$)			2,320.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >