



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2014 NISSAN NV350 PANEL VAN 2.5 5MT (GBD5776S)

Date of Loss

18 November 2017

Time of Loss

10.25

Loss Description

GBD5776S (INSD) HIT SLG185X (TP) INTO REAR

Comment

Workshop Details

Total Rebate Amount

35911

Nett Loss Amount

\$22,089.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

03/04/2018



Days of work completion *

68



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

GBD5776S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

19/12/2014



Mileage

176051

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2014

ASSESSMENT INFO...

2014

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

ER SHYH SHYAN

CATEGORY Make

POLICY INFORMAT... NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... NV350 PANEL VAN 2.5 5MT

ASSESSMENT INFO... NV350 PANEL VAN 2.5 5MT 5DR EURC

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JN1MC2E26Z0002796

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 6 September 1967

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 50

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JN1MC2E26Z0002796

CATEGORY Engine No

POLICY INFORMAT... YD25353693A

ASSESSMENT INFO... YD25353693A

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2488

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 58000

FNOL INFORMATI... 30

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 1988

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... APT BLK 55 SIMS DRIVE # 10-1065,
SINGAPORE, 380055, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1791457Z

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

26/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

700

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195R15

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195R15

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Rear left side

YOKOHAMA6mm

Rear right side

YOKOHAMA6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------	-------

AddApproveDeny

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1		A/C HEATER ASSY			Cracked	1845		30		1291.5	Reviewing

Labour

AddApproveDeny

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP	20	0	0	Reviewing	
		2		TO REMOVE AND REINSTALL FRONT WINDSCREEN FOR NECESSARY HEADLAMP	100	0	0	Reviewing	
		3		TO REMOVE, REPLACE AND REINSTALL DASHBOARD	200	0	0	Reviewing	
		4		TO REMOVE, REPLACE AND REINSTALL A/C BLOWER AND A/C EVAPORATOR (INCLUDE VACUUM & RECHARGE A/C GAS)	100	0	0	Reviewing	
		5		TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	800	0	0	Reviewing	
		6		TO SPRAY PAINTING ON AFFECTED AREA	600	0	0	Reviewing	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

FRT PANEL (DISC 10%)

Reviewing

987.21

BADLY DENTED



2

FRT CORNER PANEL R/L - 2 PCS (DISC 10%)

Deny

0

REPAIR



3

HEADLAMP R/L - 2PCS (DISC 10%)

Reviewing

329.76

N/S CRACKED



4

FRT GRILLE ASSY (DISC 10%)

Reviewing

409.5

CRACKED



5

FRT GRILLE EMBLEM (LOGO) (DISC 10%)

Reviewing

65.7

NECESSARY



6

FRT BUMPER (DISC 10%)

Reviewing

463.23

DENTED / DEFORMED



7

FRT BUMPER TOW COVER (DISC 10%)

Deny

0

NOT NECESSARY



	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		8	FRT BUMPER FOG LAMP R/L - 2PCS (DISC 10%)	Deny	0	NOT NECESSARY	
		9	FRT BUMPER FOG LAMP GRILLE R/L - 2 PCS (DISC 10%)	Deny	0	NOT NECESSARY	
		10	FRT BUMPER BRACKET R/L - 2 PCS (DISC 10%)	Deny	0	NOT NECESSARY	
		11	FRT BUMPER REINFORCEMENT (DISC 10%)	Reviewing	567	DENTED	
		12	A/C BLOWER ASSY (DISC 10%)	Reviewing	612.36	CRACKED	
		13	A/C SUCTION PIPE	Deny	0	NOT NECESSARY	
		14	A/C DISCHARGE PIPE	Deny	0	NOT NECESSARY	
		15	A/C LIQUID PIPE	Deny	0	NOT NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		16	FRT WINDSCREEN SEALANT	Reviewing	40	NECESSARY	
		17	FRT PANEL SEALANT	Deny	0	NOT NECESSARY	
		18	FRT GRILLE CLIP - 6 PCS	Deny	0	NOT NECESSARY	
		19	FRT BUMPER CLIP - 8 PCS	Reviewing	25.6	NECESSARY	
		20	FRT BUMPER RETAINER R/L - 2PCS	Deny	0	NOT NECESSARY	
		21	FRT NO.PLATE	Reviewing	15	BENT	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$5,926.86

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,820.00	\$1,820.00
Spare Parts	\$1,291.50	\$1,291.50
Miscellaneous	\$3,515.36	\$3,515.36
Excess	-\$700.00	-\$700.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny



EDIT



SR NO

1

NAME

FINAL LUMP SUM

ACTION

Reviewing

AMOUNT

5300

COMMENT

REMOVE



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$4,600.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$5,300.00	\$5,300.00
Excess	-\$700.00	-\$700.00

Submit for Review