

No report.

?



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liubro@ymail.com

Invoice/Ref No: GBG4810S180118

Estimate

Customer		Date: 25-01-18	
Name: AIG Asia Pacific Insurance Pte Ltd		Vehicle No: GBG4810S	
Address: Motor Claims Department		Model/Make: Fiat Doblo Cargo	
78 Shenton Way #07-16		Maxi L6 MTJ AMT Glaze	
AIG Building Singapore 079120			

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Fender <i>oil</i>	\$ 2,350.00	X
2	"Corporate" Advertisement Sticker <i>oil</i>	\$ 400.00	SN 3005
3	Tail Lamp <i>oil</i> <i>sun</i>	\$ 389.00	X
	To check all wiring & electrical component for proper function	\$ 30.00	20
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 60.00	X
	Remove and refix rear reverse sensor	\$ 50.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 900.00	600
	To putty & spray painting & including touch up paint on accident affected areas	\$ 600.00	380

Total Parts & Labour of estimate for damaged vehicle \$ 4,779.00

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not allowed
due
7/7 1650.10
4 day.
26/1/18

P-389
10%
389.1
1650.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: