

REF: CS/MSG18001596/KlrD3n2

ASSIGNMENT (Office)

Menimen Kalvin

ASSIGNMENT (Office)

Front/Back: Jasmine Lok

MSG

Date/Time: 26/01/2018 @ 10:54am

Estimated Cost: _____

Blk: _____

OD: WS / TP RES / OD RES / EVA / INV / MV / CE

To Inspect Vehicle No: SHA 7717U

Insured: SIF 7454D

at Workshop no: Comfort Delgro

Tel: 6214 8300

at: 59 Loyang Drive

Policy No: A29010230 QMX

Claim No: 547462

Sum Insured: _____

Excess: _____

Make of Vehl: _____
(Client's Record)

D.O.A: 21/01/2018

CA / REV / REP: / REV 24 HRS

MOD: Estimate

Date/Time: 11:00am @ 26/1/18

Person Contacted: jumini

VEH: OUT

Date/Time: _____ Action/Instruction: Estimate

SHA 7717U - CS/MI17619029/Klrbe2

D-O-A: 31/0/17

SIF 7454D-X

21/1/18 sent preli through menimen

Kalvin

ASSIGNMENT

SHA 7774 21 May 2018

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVAL / INV / MV

Truck / Trailer: 0 Prime Mover

To inspect vehicle No:

Make: Hyundai I40 No: 168

at Workshop No:

Colour: Blue Insured / Std: NI / NA

of:

Sp Reading: 577470 Insured / Std: NI / NA

Insured:

Eng No:

Policy No:

CNo: KMHLD414MF4069150

Claims No:

Gen. Condi: Good / 6 / Poor / Burnt

Sum Insured

Excess:

Steering: 6 Inoperative / Jammed / Leaked - Burnt or

(Client's Record)

Brake: 6 Inoperative / Jammed / Leaked - Burnt or

Make of Veh:

Mod: 6 Nil / S.Rim / SD A/Rim or

Policy Condition:



Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Wells

Ball or Market Value:

Front: 7 mm, Rear: 7 mm

CAC Accident Report: Consistent? Yes or No

R.Bal: 7 mm, L.Bal: 7 mm

GIA / PR Seen: Consistent? Yes or No

D.O.A: 24/1/8, D.O.A: 26/1/8

Est. Repairs: days: Fee: Yes or No

Survey held at: COKE (72)

Lump Sum: %: 3 val: Yes or No

CA / REV / REP. / 24 HRS

Des. of Damages: Rear / Frt / Rear / OS / NS / UIC / Rooftop or

Date:

Person Contacted:

Vehicle IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time: 20/1/18 Action/Instructor: Condensed PIP \$1406.08 / 2 days.

MSB PIP

Red: \$1584.26, 53%

RECEIVED 31 JAN 2018

Task/Time File Path's:

Prelim. Report
 Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

typist

Date/Time File Return:

Add Fee: Site Insp \$
 Material \$
 Tech Insp \$
 Wash P. \$

200
10

Report Format:

TP
1406.08

Lump Sum / LB No:

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2018		26 Jan 2018 10:54 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GOH CHENG XI CALVIN, ID: S8504466D, Tel: +6581233169		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA7717U	Date of Loss:	24/01/2018 15:00 - :59
Claim Type:	TP / 547462	Policy/Cover Note No.:	A29010230QMX (Comprehensive) Coverage: 07/09/2017 - 06/09/2018
Vehicle Reg. No. (Insured):	SLF7454D	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/01/2018]		
Driver/Custodian (Insured):	HUANG HUEI MEI (), NRIC: S2731457, Tel: +6581233169		
Adj Asg. Remarks:	Car is in. Pls liaise with workshop to survey the vehicle.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001596/K1ru3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 7454D	Veh. Inspected	SHA 7717U
Policy No.	A29010230QMX	Coverage (\$)	0.00
Claim No.	547462	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	26/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/01/2018	Inspection Date	26/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 29 Jan 2018

Preliminary Advice

Insured Vehicle No	: SLF7454D		
TP Vehicle No	: SHA7717U	Accident Date	: 24/01/2018
Make	: HYUNDAI I40	Assignment Date	: 26/01/2018
Date of Inspection	: 26/01/2018	Est. Duration of Repair	: 2.00
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,990.34
Revised Amount	:S\$	1,373.28
Check Items (Estimated)	:S\$	884.60
Total	:S\$	2,257.88
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2018 10:55
Date Of Accident	24/01/2018 15:40
Exact Location Of Accident	CLEMENTI RD > UPP B TIMAH RD NEAR T-JUNCT MAJU DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7717U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	YEO KIM LENG
NRIC No	S6938290H
Date Of Birth	30/10/1969
Occupation	OUTDOOR
Date Of Driving Pass	18/09/1987
Driving Experience	30 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	YEOKIMLENG@OUTLOOK.COM

Address	BLK 215 MARSILING LANE #22-808
Postcode	730215
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF7454D
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HUANG HUEI MEI
NRIC/Passport Number	S2731457J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO. 305110521

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 L (R) (O) (P)	REGN NO: SHA7717U	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: I-40	DATE/TIME IN 24.01.2018 16:35
	YR OF MANU: 21.05.2015	TARGET DATE
	CHASSIS CODE: KMHLB41UMFU069150	COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 24.01.2018
 NATURE: 3P 24.01.2018

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA7717U
 CHIANG @

Vehicle No.: SHA7717U

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7717U

DATE 25/1/2018 10:45

M810

MAKE :

Chiang

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid 'H' Emblem <i>X^{an}</i>			\$ 27.20
	Boot Lid CRDI Plate <i>X^{an}</i>			\$ 41.00
	Rear Bumper <i>X^{an}</i>			\$ 603.60
	Rear Bumper Reinforcement <i>X^{an}</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X^{an}</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X^{an}</i>		\$ 49.00	\$ 98.00
	Rear Bumper Clips <i>X^{an}</i>			\$ 22.00
	Rear Bumper Sponge <i>X^{an}</i>			\$ 143.40
	Rear Bumper Under Cover <i>X^{an}</i>			\$ 225.00
	Boot Lid Emblem - 240 <i>X^{an}</i> \$41			
	SUB TOTAL			\$ 2,024.55
	LESS 20%			\$ 404.91
	DISCOUNTED TOTAL			\$ 1,619.64
	Boot Lid Comfort Logo & Tel No. Sticker <i>X^{an}</i>			\$ 30.00 Nett
	Rear No. Plate <i>X^{an}</i>			\$ 25.00 Nett
	Rear Bumper Reverse Sensor <i>X^{an}</i>			\$ 135.70 Nett
				\$ 190.70
	Labour Charge			
	Panel Beating-Repair Bootlid			\$ 560.00 <i>300</i>
	Spray Painting Charge			\$ 400.00 <i>260</i>
	Wiring Charge			\$ 50.00 <i>X^{an}</i>
	Tuff Kote			\$ 50.00 <i>X^{an}</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X^{an}</i>
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 2,990.34
				<i>3023.14</i>

Kalvin (Kee)
M 26/1/18 15 20hr
2 hrs
PIP
Before print pls

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305110521
 REGN NO : SHA7717U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 21.05.2015
 DATE/TIME IN : 24.01.2018 16:35
 ACCIDENT DATE : 24.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004	04-01-0103-0786-G	I40VC EMBLEM-CRDI	1	41.00	20.00	32.80
0005	04-01-0103-0787-G	I40VC EMBLEM-I40	1	41.00	20.00	32.80
						SUB-TOTAL : 746.08

JOB NATURE

0000 L	PANEL BEATING	300.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	360.00
		SUB-TOTAL : 660.00
		TOTAL : 1,406.08

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305110521
Date : 25/01/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : KALVIN
Vehicle Reg No. : SHA7717U 24/1 /2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG SLF7454D
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$746.08</u>
(b) Labour Charges	<u>\$660.00</u>
Total for Part-By-Part Repair Cost	<u>\$1,406.08</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
Final Lumpsum Repair cost	_____

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : _____
Name : Kalvin
Date : 30/1/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001596/K1RD3N2
Date: 02/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29010230QMX
Claimant Vehicle No :	SHA7717U	Insured Vehicle No :	SLF7454D
Date of Loss:	24/01/2018	Nature of Claim:	TP
		Claim No:	547462

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7717U	Engine No:	D4FDEU449410
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMFU069150
Reg. Date:	21/05/2015 (Man. Year: 2015)	Odometer:	573470 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,843.14	746.08	1,097.06	59.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	660.00	520.00	44.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,023.14	1,406.08	1,617.06	53.49
+ GST 7.00/7.00% (S\$)	211.62	98.43	113.19	53.49
Nett Amount (S\$)	3,234.76	1,504.51	1,730.25	53.49

INSPECTION

Date of Assignment:	26/01/2018	
Date Inspected:	26/01/2018	Inspected At:
		ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2018)
Parts: 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7717U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID H EMBLEM	Not Necessary	27.20 FL	*- FL
2	1	*BOOT LID CRDI PLATE	Necessary	41.00 FL	*41.00 FL
3	1	*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
4	1	*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
5	2	*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Serviceable	360.00 FL	*- FL
6	2	*REAR BUMPER SIDE BRACKET	Serviceable	98.00 FL	*- FL
7	10	*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1	*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
9	1	*REAR BUMPER UNDER COVER	Cut	225.00 FL	*225.00 FL
10	1	*BOOT LID EMBLEM I40	Necessary	41.00 FL	*41.00 FL
11	1	*BOOT LID COMFORT LOGO & TEL NO STICKER	Not Necessary	30.00 FS	*- FS
12	1	*REAR NO PLATE	Repair	25.00 FS	*- FS
13	1	*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
				Sub Total (S\$)	2,256.25 932.60
				- List Item Discount on L Items 20.00/20.00% (S\$)	413.11 186.52
				Total Parts (S\$)	1,843.14 746.08

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING-REPAIR BOOTLID	New	560.00	300.00
2	SPRAY PAINTING CHARGE	New	400.00	360.00
3	WIRING CHARGE	New	50.00	-
4	TUFF KOTE	New	50.00	-
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	-
Gross Labour Cost (S\$)			1,180.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >