

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ STTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐	39	1			FRONT BUMPER REINFORCEMENT HOLDER BRACKET RH			Necessary	10				10
Labour													
☐	Approve Deny	SR NO	REPAIR/REPLACE (LABOUR)		PART NAME		LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT	
☐	EDIT	1			TO CHECK WIRING AND REFOCUS HEADLAMP.		20	0	0	Reviewing			
☐		2			TO REMOVE AND REPLACE A/C CONDENSER, PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS.		100	0	0	Reviewing			
☐		3			TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL & HEADLAMP PANEL. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		500	0	0	Reviewing			
☐		4			TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, FRONT SUPPORT PANEL, BUMPER REINFORCEMENT AND AFFECTED AREAS.		600	0	0	Reviewing			

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		10	1			FRONT BUMPER CENTER LOWER GRILLE (NPA)			Serviceable	0				0
☐		11	1			FOGLAMP COVER RH			Serviceable	0				0
☐		12	1			TOWING COVER			Necessary	24				24
☐		13	1			HEADLAMP LH			Serviceable	0				0
☐		14	1			HEADLAMP RH			Cracked	1100				1100
☐		15	1			HEADLAMP LOWER BRACKET RH			Serviceable	0				0
☐		16	1			RADIATOR GRILLE			Cracked	220				220
☐		17	1			RADIATOR GRILLE BASE			Cracked	60				60
☐		18	1			RADIATOR SUPPORT PANEL			Cracked	360				360
☐		19	1			RADIATOR			Cracked	380				380
☐		20	2			RADIATOR TOP BUSH			Serviceable	0				0
☐		21	2			RADIATOR TOP CLIP			Necessary	2				4
☐		22	1			RADIATOR FAN COWLING			Cracked	230				230
☐		23	1			RADIATOR FAN MOTOR			Cracked	360				360
☐		24	1			AIR CON CONDENSER			Bent	400				400

Detailed Assessment

Inspection
Date *

mm/dd/yyyy

Condition of Vehicle at time of survey

General
condition

Excellent

Tyre Condition

Total Loss

Towing Charges

Voluntary
Excess

Compulsory
Excess

Young/Inexperie
nced/Unnamed
Driver Excess

Other Excess

Handbrake
(Serviceable)

Engine
Modification

Pre-accident
condition

Steering
(Serviceable)

Footbrake
(Serviceable)

Excellent

Age of Tyres

Front Tyre Size

Front left side

Front right side

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		mm/dd/yyyy
Address	134 KING'S ROAD, 268168, Singapore	
Address type	Personal Correspondence	Business
Gender	Female	Female
Marital status	Unknown	Single
Identification #	S9713278Z	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Model	A6 2.0	
Type		Listed on ▼
Type of Paint		
Chassis No	WAUZZZ4F8AN010776	
Engine No	BPJ159376	
Engine Capacity		
Sum Insured	0	
Market Value	0	
Driver Details		
CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION

Accelerated survey
and authorize

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

- Messages
- Assessment
- Invoices
- Metrics
- History
- Notes
- Documents
- Add

Additional Instructions

EXCESS \$400 + \$2500(UNNAMED YOUNG) =
\$2900

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	1/27/18 9:23 AM	\$5,005.00	\$5,005.00	In Review	Share	Clone
User Portal	1/26/18 5:37 PM	\$10,840.00	\$10,840.00	In Review	Share	Clone
TEO Kitty	1/26/18 1:45 PM			Open	Share	Clone

Accelerated survey
and authorize

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Additional Instructions

EXCESS \$400 + \$2500(UNNAMED YOUNG) =
\$2900

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
PARTS INVOICE.pdf	Invoice	Spare Part / Accessories Supplier	LKK AUTO CONSULTANTS PTE LTD (OD)	April 16, 2018
Full page photo of SDR 280R 2.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 5, 2018
Full page photo SDR280R.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2018