

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: SG Sagawa Ameroid Pte Ltd
c/o 65 Chestnut Avenue
#18-15
Singapore 679524

Date : 14/03/2018

Reference No : CAS/18-03/034

General Information

Registration No. : YP 3479C
Accident Date : 07/12/2017

Particulars of Damaged Vehicle

Colour	: Blue	Make & Model	: Mitsubishi Fuso FM65FM2RDEB
Engine Capacity	: 7545 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 92757	Engine No.	: 6M60214667
Chassis No.	: FM65FMA30072	Steering	: In Order
Registration Date	: 22/07/2016	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	11R22.5	BRIDGESTONE	40%
L/H Front Tyre	11R22.5	BRIDGESTONE	40%
R/H Rear Tyre	11R22.5 (D)	BRIDGESTONE	40% / 40%
L/H Rear Tyre	11R22.5 (D)	BRIDGESTONE	40% / 40%

Inspection

Repairer : LYS Engineering
65 Chestnut Avenue, #18-15, Singapore 679524

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$8,095.00
Revised Amount : \$5,950.00
Less Excess : -
Nett Total : \$5,950.00

Remarks

- (A) Survey was done on 07/03/2018
- (B) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (C) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1pc	Rear box body panel RH	Dented/Warped	2,800.00	2,800.00
2	1pc	Rear box body panel trim bottom RH	Broken	220.00	220.00
3	1set	Rear box body panel rivet RH	Necessary	65.00	65.00
4	1pc	Rear box pillar RH	Dented/Twisted	1,600.00	1,600.00
5	1pc	Rear box pillar trim RH	Broken	280.00	280.00
6	1pc	Rear box bottom wooden beam	Broken	650.00	650.00
7	1pc	Taillamp assy RH	Serviceable	280.00	-
			Sub total	5,895.00	5,615.00
		<u>LABOUR & MISC. CHARGES</u>			
1		To spray painting rear affected area		1,000.00	800.00
2		Labour to repair & replace rear damaged parts		1,200.00	1,000.00
			Grand total	8,095.00	7,415.00
Recommended cost of lump sum repair (To its pre-accident condition)					5,950.00


Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$5,950.00** on a contractual basis. Under normal circumstances, the repair period would be about **4 (Four)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA