32/03/2902	
ASS. REC. BY: REF: CS EGII 8001725/A-	322 Special Instruction:
Surveyer: Adman ASSIGNMENT (Office)	
From (Person): Value of EGI	Dete/Time: 29/1/18 @ 3.20pm
Estimated Cost: Bill to:	
OD HP WS/TP RES/OD RES/EVA/INV/MV/CS	
To Inspect Vehicle No: PC 6460K	_ Insured: _ SGUG851C
at Workshop m/s New Hock Teck	Tel: 6747 9241
of Ikaki BK Ave 6 # 01-13 Autobay	0/4/14-1
Policy No: Claim No:	SG4.6851C/RH/P1
Sum Insured: Excess:	
Make of Veh: (Client's Record)	D.O.A. 27/01/2018
CA / REV / REP. / REV 24 HRS WP?	H.G.D. Endorsement:
Date/Time: 3:2Spm 32 118 Person Contacted: SUKyi-	Vehicle IN OUT
Date/Time Action/Instruction () Estimate	
PC 6460K X	
SGU (2510-x	
30/1- Pevert via email pending as	timate.
City (Colored)	
Jump Sum \$17,300- (Red: 2	6152.55; 60%) 14days.

REF:

Nivitha (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Monday, 29 January 2018 3:20 PM

To:

'admin-d@lkkauto.com'

Subject: Attachments: OI : SGU6851C / TP : PC6460K/LKK / DOA : 27/01/2018 PC6460K - PRS FORM.pdf; PC6460K - PRS NOTICE.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR WORKSHOP**.

ADDRESS

: 1 KAKI BUKIT AVE 6

#01-43 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

PERSON TO CONTACT

: SUKYI / REENA @ 6747 9241

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Thank you

Yee Pei Li

Claims Assistant (Motor) ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

Tel.: 65 6829 9199 DID: 65 6829 9194

Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

NEW HOCK TECK MOTOR PTE LTD

1 Kaki Bukit Ave 6

Our Ref Your Ref

: PC6460K

Date

: 29/1/2018

: SGU6851C

Blk C @ Autobay, #01-43

Singapore 417883

Tel: (65) 6747 9241 Fax: (65) 6741 7276

Ergo Insurance Pte Ltd

BY FAX

6829 9247

Attention:

Motor Claims Department

Dear Sirs.

DATE OF ACCIDENT: 27 January 2018 @ 22:30 hours

NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We act for MARITEAM TRANSPORT SERVICES PTE LTD who has appointed the undermentioned workshop to repair motor vehicle no. PC6460K

Please be informed that the said vehicle can be inspected at :

NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #01-43 BLK C @ AUTOBAY

SINGAPORE 417883

Contact Person: Office @ 6747 9241 (Reena / Sukyi)

the motor Union Dept
Pla send us your surreyor Let, Thanks.

Duyi 27/1/12

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The said workshop will commence repairs thereafter without further reference to you.

Yours Faithfully

For Surveyor.

Please initial here after compleion of Pre-repair inspection. Thank you

Surveyor Name

& signature

Date&Time

New Hock Teck Motor Pte Ltd

29-01-18;14:48 ; > 29-01-18:14:02 :From:ERGO | Insurance Pte. Ltd. To:967417276

ERGO

Dale;	29.01.2018			Sent via Fax	
Our Reference:	SGU 6851C/RH/p	ol	•		6741 7276
Your Reference:	PC 6460K		•	or	
			•	Email	
То:	NEW HOCK TE	CK MOTOR WO	RKSHOP		-
<u>Pre-Repair Su</u>	rvey (PRS) Acknov	<u>vledgement</u>			
Vehicle For Inspe	ection: PC 6	460K	_		
Insured's Vehicle	s sgu	6851C	_		
Date Of Acciden	: <u>27.0</u> :	1.2018			
We acknowledge	receipt of your requ	est for PRS on:	29.01.2018	_	
in compliance w	lth "State Courts Pra	ctice Directions Ame	indment No.1 of		lect an assessor from
the list below ar	d indicate your selec	tion in the box mark	red *.		* LKK
AI5	Automobile Inspection	Services Pte Ltd	L85	L.B.S Auto Cor	nsultants Pte Lld
FTA	FormTeam Consultane		ŁKK	LKK Auto Cons	sultants Pte Ltd
JPK	Infiniti Appraisal Servi JP Knights Pte Ltd	ce	PŚ	Priority Servic	es
	Anglis Pie Liu		VAC	Vicom Lld	
V Your reque	st for inspection does r st for inspection does r viedge your interest for t's driver has not report OFFICER-IN-CHARGI	ot have your client's G direct settlement, we led the accident to us t	ifA report, kindly fi will assess & reve	orward a copy.	
Prepared by:	& .()		Pei Li	6829 9	claims@ergo.com.sg
Signature:	40				FAX: 6829 9247
Assessor use only: Assignment Date: Assignment Time: Remarks:		<u> </u>		d workshop on	
			Workshop Acknow Note: Our Inspect	wledgement & Ion is on a with	Stamp. out admission to liability basis.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ER€	GO INSURANCE F	PTE LTD	Ref : CS/EGI18001	725/Atd3
#04	EMASEK BOULEV -01 SUNTEC TOV GAPORE 038985		Date : 29-01-2018	
1.			Code: EGI	
٠.	Insured Veh.	SGU 6851C	articulars :- THIRD PARTY CLA	<u> Thair an an Andrew Weiters</u>
	Policy No.		Veh. Inspected	PC 6460K
	Claim No.	SGU 6851C/RH/pl	Coverage (\$)	0.00
		YEE PEI LI	Excess (\$)	0.00
<u> </u>	Assign From		Assign Date	29/01/2018
2.		Veh	icle Particulars & Condition	<u> 4.5 12 1</u>
	Make & Model	14155511	с.с	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	<u>-</u>	Steering	
	Brakes	_	Modification	
	General			
3.	<u> </u>		Conditions of Tyres	
	<u> </u>	Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre	<u> </u>		mm
	L/H Rear Tyre			mm
2.1			Description of Damages :::-	
5.			General Information	
• • • • • • • • • • • • • • • • • • • •	Accident Date	27/01/2018	Inspection Date	29/01/2018
	Survey held at	NEW HOCK TECK M		<u> </u>
		1 KAKI BUKIT AVENU SINGAPORE 417883	IE 6 #01-43 AUTOBAY @ KAKI BUK	KIT
	All his section of the section of th		Remarks	

MSME18013864 / SME Motor Pte Ltd - Keki Bukit ENTRY DATE & TIME: 29/01/2018 12:42 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

29/01/2018 12:42 Date Of Report Date Of Accident 27/01/2018 22:30

BLK 419 PASIR RIS DR 6 CARPARK **Exact Location Of Accident**

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number PC6460K

Insured/Policyholder

MARITEAM TRANSPORT SERVICES PTE LTD Name Of Registered Owner

200402055D Co Reg No **NOEMAIL Email Address**

Mobile Phone No.

Alternative Phone No OFFICE-NOPHONE

Vehicle Particulars

Manufacturer **TOYOTA** Model HIACE

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

Policy Number B29055959MKC

Cover Note Number

Driver

Name of Driver NG SOCK GUAN EDMOND

NRIC No S7436465I Date Of Birth 28/10/1974 **INDOOR** Occupation Date Of Driving Pass 17/02/1995

22 YEARS AND 11 MONTHS Driving Experience

Gender MALE

(LOCAL) +65-83331028 Mobile Number

Fax Number

Contact Number

EMail Address NOEMAIL

Page 1 of 16

Address BLK 419 PASIR RIS DRIVE 6 #07-273

Postcode 5104

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

/enicle

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS PARKED STATIONARY IN CARPARK OF BLK 419 PASIR RIS DRIVE 6 CARPARK. SUDDENLY, I RECEIVED A CALL FROM MY NEIGHBOUR SAYING THAT VEHICLE B HAD HIT ONTO MY CAR AND CAUSED DAMAGE. THE IMPACT WAS SO HUGE THAT MY VEHICLE WAS SWERVED TOWARDS THE RIGHT TO THE NEXT LOT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGU6851C

Vehicle Make/Model/Colour

Details Of Properties VEHICLE B
Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 16

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate opticy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers liawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (h) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their (awyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud datection, investigation and management in present and all future claims.
- (ii) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Cate & Time:

Driver's Signature (IF driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

MARKAT Steel beingebert, von

NOW HOCK TEEK

Sketch Plan #2 Pg. 1

KETCH PLAN			
			0
			A PC6460K
			B 2011 88616
;	(2/6)		Mar ille Corne
4	6 ()		BIK YIM FASIR RIS PRIVE E
	A		Corpart
.:			(b Treeter
ESCRIBE CIRCUMSTANCES OF THE A	CCIDENT		A STATE OF THE PARTY OF THE PAR
MU VELACIZ ISOO	earred Clatter	iaru in	(arpark
my vertice was	ur pis prive	l larpo	nk'
SIACIDIAL I VOCA	avoid a contra	Cial mou	10 0 10 10 10 10 1K
suddenly i vece sayina ilvat v	enkly "B" ha	d nit al	ato my
iar and (aw	red dannage.		,
TIAD GARRYH IN	an in huno the	OF MAIN	rétricté
May (Mayive	d Manawardi	toward	refricte 2 Me INEXT Int
and the state of t		Angle of the color	
			<u>an and property of the property of the state of the stat</u>
The state of the s			
DECLARATION //We declare the foregoing particulars are true	ue in every respect.		
n X	0./		
	<u> </u>		
Policyholder's Signature Marie	Oriver's Signature (If driver is not the policy Date & Time;	holder)	Reporting Centre Personnel's Signatur Name: NRIC/FIN No.:
	Oate & Line:		eys ar room

R rebytok
K rebytok

RIK YM NOGE Richard Color

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ONLY VELLICLE (LICE CONTROL CONTROL CONTROL CONTROL CONTROL CONTROL
Suddenly receive to ion filter not neighbour. Sugma wat remote 6 kool on with any our and award damage.
The lumpered were to hope there my vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)
Date & Time:

NRIC/FIN No.:

Reporting Centre Personnel's Signature Name:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2055D

Vehicle Details

Vehicle No.: PC6460K

Vehicle to be Exported: Yes

Intended De-registration Date: 29 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE COMMUTER GL 3.0 AUTO

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 1KD2744828

Chassis No.: KDH2230033811

Maximum Power Output: -

Open Market Value: \$42,618.00

Original Registration Date: 30 Nov 2017

First Registration Date: 30 Nov 2017

Transfer Count: 0

Actual ARF Paid: \$2,131.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Nov 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$57,701.00

COE Rebate Amount: \$46,160.00

Total Rebate Amount: \$46,160.00

The information contained herein is correct as at 29 Jan 2018

ОК

SGCARMART.COM

Login Sign up

Forum

Articles

Used Cars Sell My Car Directory **Products Tools & Tips New Cars** · Little voices inside your head and random urges Harrier 2017 SIBOR rates and home loan repricing New 5 Year Coe Renewai Toyota Wish 1.8A Post an Advertisement ★ Lake View view our cars * Credit Pte Ltd Sell it yourself! Advertise it at just \$250 G Downloayment Moritally > Low prices guaranteed From \$688 Onwards, Lowest \$58 until it's SOLD! > Specialist in Japanese cars 3.65m P.Au div Cars Financing > Easy loan approval GV Credit Pte Ltd 1819 32 Post an Ad Advertiser Login Ways of Selling > All terms are negotiable ▼ ▼ 20 results/page ▼ Browse by Category Sort by Date Posted 9 vehicles Adul kirk Seurch - 🖼 Hiace Commuter Make Model Depreciation Reg Date Eng Cap Mileage Veh Type Search Selection **Hiace Commuter** 2017 Any Any Available Any **Toyota Hiace Commuter** \$103,800 \$11,240 /yr 24-Apr-2017 2,982 cc Available Bus Fuel Type: Diesel Ready Stock Available! Gl. Model! Keyless Entry! 14 Seaters! Price Slash To Lowest And Affordable! Call Now To View The Actual Unit! PREMIUM AD ABWIN Bus Pte Ltd Posted: 24-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota **Toyota Hiace Commuter** \$104,800 \$11,150 /yr 22-Jun-2017 2,982 cc Available Fuel Type: Diesel 14 Seater! Ready Stock For Registration, Prices Included COE High Loan And High Trade In. Can Register Excursion Private Hire Or Private Bus. Call Our Sales Executive And Grab It Before It's Gone! Sto... KSL Automotive Pte Ltd Posted: 29-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota **Toyota Hiace Commuter** \$105,800 \$11,080 /yr 17-Aug-2017 2.982 cc Bus Available Fuel Type: Diesel Please Call To Arrange For Viewing, Thanks. Posted: 28-Dec-2017 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota **Toyota Hiace Commuter** \$99,800 \$10,380 /yr 08-Sep-2017 2.982 cc Bus Available Fuel Type: Diesel Cheapest In The Market 14 Seater! Ready Stock For Registration, Prices Included COE High Loan And High Trade In. Can Register Excursion Private Hire Or Private Bus. Call Our Sales Executive And Grab I ... PREMIUM CO Net Link Partners Pte Ltd Posted: 24-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota Car Buying Car Selling Car Aftermarket Buying a pre-owned car, but Unsure of its Condition? Car Ownership Gat, STA Car Evaluation On The Move Lifestyle **Toyota Hiace Commuter** \$108,800 \$11,290 /vr 18-Sep-2017 2.982 cc Available Fuel Type: Diesel Almost Brand New Euro 6 Japan Made Vehicle Comes With New Facelift! Extended 5 Years Warranty At Own Workshop! Free Servicing And 1 Year Road Tax! High Trade In And High Loan Are Accepted! Kindly Call... PREMIUM AD ABWIN Bus Pte Ltd Posted: 25-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota **Toyota Hiace Commuter** \$99,800 \$10,170 /yr 22-Nov-2017 2,982 cc Bus Available Fuel Type: Diesel Durable And Low Maintenance! Engine, Gear Box And Aircon All In Tip Top Condition! Price Negotiable! High Loan And High Trade In Available! Call Us FREMIUM AD Now For No Obligation Quote And Test Drive! 14 Seate... Net Link Partners Pte Ltd Posted: 02-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

\$10,160 /yr

14 Seater Euro 6 Mini Bus For Sales! Ready Stock Immediate Registration, 3Yrs Or 100000km Warranty Whichever Come First, Include 6 Mths Road

23-Nov-2017

2,982 cc

\$99,800

Toyota Hiace Commuter

Fuel Type: Diesel

Available


Bus



Tax, And Lots Of Accessories, High Loan And High Trade In. ...

KSL Automotive Pte Ltd

Posted: 25-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota





Toyota Hiace Commuter

\$106,800

\$10,860 /yr

29-Nov-2017

2,982 cc

Bus

Available

PREMIUM #EI

Fuel Type: Diesel

Warranty 5 Year, 140,000km, High Loan And Call For Viewing.

ABWIN Bus Pte Ltd

Posted: 24-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace Commuter

\$90,800

\$9,210 /yr

06-Dec-2017

2,982 cc

Bus

Available

FREMIUM AD

DUS AVA

Fuel Type: Diesel
Original Rear Aircon From Japan, 12 Seater Minl Bus, Can Be Registered Under Excursion, Private Bus Or School Bus. Call To Arrange A Viewing Now!

ABWIN Bus Pte Ltd

Posted: 22-Jan-2018 Tags: 2017 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Starts

For old advertisements, view Expired ads

20 ▼ results/page

sgCarMart is the number one car classifieds for parallel import cars. Toyota, Honda, Nissan, Mitsubishi & BMW, There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Hiace Commuter, Hiace Commuter Singapore, used Hiace Commuter Singapore, used Hiace Commuter, used vehicles Singapore or even buy used Hiace Commuter Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used CarSell Car
- Motoring Directory
- Products GuideArticle
- Forum
- Tool & Tip
- © 2004-2018 sgCarMart. All rights reserved.

- About Us
- Careers
- Contact Us
- Sitemap
- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

29/01/2018



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Email: admin@nhtmotor.com Website: www.nhtmotor.com Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

MARITEAM TRANSPORT SERVICES PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPEMP

perise

Accident date: 27/01/2018

Estimated repair cost for vehicle no: PC6460K TOYOTA HIACE COMMUTER GL 3.0 A 1:

CHASSIS: KDH2230033811

S/n	Qty	Items	U/price	Amount
1	1	Front Grille could		\$581.10 /
2	8	Front Grille Clip ww	\$6.50	\$ 52.00 20
3	1	Front Grille Top Cover 7 AH		\$371.30 ×
4	1	Front Grille Lower Cover	<u></u>	\$287.30 × .
5	1	Front Bumper Distorted		\$581.90
6	8	Front Bumper Clip New	\$6.50	\$ 52.00 30 ·
7	1	Front Bumper Number Plate Hot Nec		\$50.00×
8	1	Front Bumper Centre Garnish Deloined		\$281.25
9	1	Front Bumper Top Beam Sext		\$381.25
10	1	Front Bumper Reinforcement Sext		\$374.45
11	2	Front Bumper Reinforcement Side Bracket ***	\$182.10	\$364.20
12	1	Front L/H Bumper Side Retainer Oomaged Front L/H Bumper Fog Lamp Cover Missing		\$177.10
13	1	Front L/H Bumper Fog Lamp Cover Missing		\$132.25
14	1	Front L/H Horn Nt M	- 4	\$182.10×
15	2	Front Head Lamp Cruled	\$1,712.45	(\$3,424.90)
16	2	Front Head Lamp Lower Bracket He New	\$171.10	\$342.20
17	1	Front Support Panel HM		\$561.60
18	2	Front L/H & R/H Support Panel Top Cover ***	\$374.45	\$748.90 ×
19	1	Front Radiator Tank Front Radiator Tank		\$377.70 ×
20	1	Front Wiper Tank		\$182.10 *
21	1	Front L/H Side Panel Bullud		\$172.45
22	1	Front L/H Door Pillar Outer Distorted		\$631.35
23	1	Front L/H Door Pillar Inner Pepis		\$621.10
24	1	Front L/H Door Distorted.		\$1,712.10
25	2	Front L/H Door Hinge 🖼	\$132.25	\$264.50
26	1	Front L/H Door Inner Rubber		\$181.90
27	1	Front L/H Door Inner Lower Rubber		\$177.10
28	1	Front L/H Door Inner Lock Pany d		\$289.10

1 Front L/H Door Wiring Parket 1 Front L/H Door Checker Lock MAN 2 1 Front L/H Door Glass Gear Motor Assy Paryd 3 1 Front L/H Door Body Logo (Special Nett) Hu 3 1 Front L/H Arch Panel Pildar Rubber at 3 1 Front L/H Arch Panel Rubber at 3 1 Front L/H Arch Panel Rubber at 3 1 Front L/H Arch Panel Garnish by L 3 1 Front L/H Step Panel Beat 3 1 Front L/H Step Panel Cover at 4 1 Front Wiring Bracket Pland 4 1 Front Wiring Bracket Pland 4 1 Front Abs Pump and Side Cover Ast May 4 1 Front Abs Pump and Side Cover Ast May 4 1 Front Abs Pump Dember Special 4 1 Front Abs Pump Dember Special 5 1 Front Abs Pump Dember Special 5 1 Front Abs Pump Pipe Member Special 5 1 Front Carpet Special 5 1 Front Carpet Special 5 1 Front Wiringscreen Moulding May 5 1 Front L/H Rim Member 5 1 Front L/H Lower Arm Beat 5 1 Front L/H Lower Arm Beat 5 1 Front L/H Knuckle Arm Beating May 5 1 Front L/H Stabilliser Bar Refer 6 1 Front L/H Stabilliser Bar Refer 6 1 Front L/H Stool Bar Beat 6 1 Front L/H Stool Bar Beat 6 1 Front L/H Stool Bar Beat 6 1 Front L/H Anti Roll Bar Beat					•
1 Front L/H Door Checker Lock AT ~ 1 Front L/H Door Glass Gear Motor Assy Pany d 1 Front L/H Door Body Logo (Special Nett) Au 3 1 Front L/H Arch Panel Piber Cld 3 1 Front L/H Arch Panel Piber Cld 3 1 Front L/H Arch Panel Rubber Cld 3 1 Front L/H Arch Panel Rubber Cld 3 1 Front L/H Arch Panel Garnish Arch 3 1 Front L/H Step Panel Cover Cld 3 1 Front L/H Step Panel Cover Cld 4 1 Front Body Wiring March 4 1 Front Wiring Bracket Arch 4 1 Front Wiring Bracket Arch 4 1 Front Wiring Bracket Arch 4 1 Front Abs Pump Could 4 1 Front Abs Pump Could 4 1 Front Abs Pump Could 4 1 Front Abs Pump Domember 4 1 Front Abs Pump Inp Member 4 2 1 Front Abs Pump Pipe Member 4 3 1 Front L/H Carpet Hold 5 2 5 1 Front Crossmember Not Note 5 1 Front Floor Panel Poly 5 1 Front Wiringscreen Moulding Note 5 1 Front L/H Rim Arch 5 1 Front L/H Lower Arm Back 5 1 Front L/H Stabilliser Bar Refer 5 1 Front L/H Stabilliser Bar Refer 5 1 Front L/H Stabilliser Bar Refer 5 1 Front L/H Stock Absorber 5 20 1 Front L/H Stock Absorber 5 1 Front L/H Stock Absorber 5 1 Front L/H Stock Absorber 5 20 1 Front L/H Stock Absorber 5 1 Front L/H Stock Absorber 5 20 1 Front L/H Stock Absorber 5 3 1 Front L/H Anti Roll Bar Back 6 2 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar Back 6 3 1 Front L/H Anti Roll Bar	\$561.60			1	29
1 Front L/H Door Glass Gear Motor Assy Tary d 1 Front L/H Door Body Logo (Special Nett) Hu 1 Front L/H Arch Panel Districted 3 1 Front L/H Arch Panel Rubber Lt 3 1 Front L/H Arch Panel Rubber Lt 3 1 Front L/H Arch Panel Garnish & L 3 1 Front L/H Arch Panel Garnish & L 3 1 Front L/H Step Panel But 3 1 Front L/H Step Panel Cover Lt 4 1 Front Body Wiring Hr St 4 1 Front Body Wiring Hr St 4 1 Front Dashboard Crauled 4 1 Front Dashboard Crauled 4 1 Front Abs Pump Couled 4 1 Front Abs Pump Couled 4 1 Front Abs Pump Top Member Luck 4 1 Front Abs Pump Top Member Luck 4 1 Front Abs Pump Pipe Member Luck 4 1 Front Carpet Hole 5 1 Front Carpet Hole 5 1 Front Windscreen Moulding Have 5 1 Front L/H Rim Hell 5 1 Front L/H Rim Hell 5 1 Front L/H Rim Hell 5 1 Front L/H Hub Cap Lt 5 1 Front L/H Knuckle Arm But 5 1 Front L/H Knuckle Arm But 5 1 Front L/H Stabilliser Bar Refer 6 1 Front L/H Stabilliser Bar Refer 6 1 Front L/H Stabilliser Bar Refer 6 1 Front L/H Stabilliser Bar But 6 1 Front L/H Anti Roll Bar Bush 6 1 Front L/H Anti Roll Bar Bush 6 2 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 6 3 1 Front L/H Anti Roll Bar Bush 7 208165 Subtotal:- \$34	\$850.10 X 30	lec	Front L/H Door Wiring	1	30
1 Front L/H Arch Panel Pishor Add 1 Front L/H Arch Panel Pishor Add 35 1 Front L/H Arch Panel Rubber Add 36 1 Front L/H Arch Panel Rubber Add 37 1 Front L/H Arch Panel Pillar Rubber Add 38 1 Front L/H Step Panel Bank 39 1 Front L/H Step Panel Bank 39 1 Front L/H Step Panel Cover Add 40 1 Front Body Wiring Mark 40 1 Front Body Wiring Mark 41 1 Front Wiring Bracket Palamad 42 1 Front Dashboard Could Add 43 1 Front L/H Dashboard Side Cover Mot Mark 44 1 Front Abs Pump Could State 45 1 Front Abs Pump Lower Member Add 46 1 Front Abs Pump Lower Member Add 47 1 Front Abs Pump Dower Member Add 48 1 Front Engine Lower Cover Mot Mark 49 1 Front Carpet Holl 49 1 Front Carpet Holl 50 1 Front Floor Panel Park 51 1 Front Windscreen Moulding Mark 52 1 Front Windscreen Moulding Mark 53 1 Front L/H Rim Mark Mark 54 1 Front L/H Hub Cap Lad 55 1 Front L/H Hub Cap Lad 55 1 Front L/H Hub Cap Lad 56 1 Front L/H Knuckle Arm Bank 57 1 Front L/H Knuckle Arm Bank 58 1 Front L/H Knuckle Arm Bank 59 1 Front L/H Stabilliser Bar Palamad 59 1 Front L/H Stabilliser Bar Palamad 50 1 Front L/H Shock Absorber 50 1 Front L/H Shock Absorber 51 Front L/H Shock Absorber 52 1 Front L/H Shock Absorber 53 1 Front L/H Shock Absorber 54 1 Front L/H Shock Absorber 55 1 Front L/H Shock Absorber 56 1 Front L/H Shock Absorber 57 1 Front L/H Shock Absorber 58 1 Front L/H Shock Absorber 59 1 Front L/H Shock Absorber 50 1 Front L/H Anti Roll Bar Bush 50 2 834	\$172.25 ×	xH ~	Front L/H Door Checker Lock	1	31
1 Front L/H Arch Panel Districted 1 Front L/H Arch Panel Rubber Lt 1 Front L/H Arch Panel Rubber Lt 1 Front L/H Arch Panel Garnish Let 1 Front L/H Step Panel Bot Lt 1 Front Body Wiring Mark 1 Front Wiring Bracket Lloud 1 Front Dashboard Cralled 1 Front Abs Pump Could 1 Front Abs Pump Top Member Lt 1 Front Abs Pump Top Member Lt 1 Front Abs Pump Inpe Member Lt 1 Front Abs Pump Pipe Member Lt 1 Front Abs Pump Pipe Member Lt 1 Front Carpet Lower Cover tota 1 Front Carpet Lower Cover tota 1 Front L/H Rim Member Lt 1 Front L/H Rim Rem Rearing Member Lt 1 Front L/H Rim Rem Rearing Member Lt 1 Front L/H Rim Rim Rem Rearing Member Lt 1 Front L/H Rim Rim Rem Rearing Member Lt 1 Front L/H Rim Rim Rem Rearing Member Lt 1 Front L/H Stabilliser Bar Refer 1 Front L/H Roll Bar Bush Lt 1 Front L/H Anti Roll Bar Bush Lt 1 Front L/H Lt 1 Front L/H Anti Roll Bar Bush Lt 1 Front L/H Anti Roll Bar Bush Lt 1 Front L/H Anti Roll Bar Bush Lt 1 Front L/H	\$381.10	itor Assy Danzd	Front L/H Door Glass Gear Mo	1	32
1 Front L/H Arch Panel Rubber At 1 Front Boy Pump Pipe Member 1 Front Carpet Holl Front L/H Rim Holling Front Signature Signatur	\$300.00			1	33
1 Front L/H Arch Panel Pillar Rubber Let 37 1 Front L/H Arch Panel Garnish & L d 38 1 Fornt L/H Step Panel Bod 39 1 Front L/H Step Panel Cover Cot 40 1 Front Body Wiring Mr S1 41 1 Front Wiring Bracket Plond 42 1 Front Dashboard Cracked 43 1 Front L/H Dashboard Side Cover Mot March 44 1 Front Abs Pump Coulcd 45 1 Front Abs Pump Top Member 2 Bod 46 1 Front Abs Pump Lower Member 47 1 Front Abs Pump Lower Member 48 1 Front Engine Lower Cover total 49 1 Front Carpet + p(N) 50 1 Front Floor Panel Panel Panel 51 1 Front Crossmember March 52 1 Front Windscreen Moulding March 53 1 Front L/H Rim Me March 54 1 Front L/H Hub Cap Let 55 1 Front L/H Hub Cap Let 56 1 Front L/H Knuckle Arm Bod 57 1 Front L/H Knuckle Arm Bod 58 1 Front L/H Stabilliser Bar Refer 59 1 Front L/H Stabilliser Bar Refer 60 1 Front L/H Stabilliser Bar Refer 61 1 Front Steering Rack Bod 62 1 Front L/H Anti Roll Bar Bod 64 1 Font L/H Anti Roll Bar Bush 65 1 Front L/H Anti Roll Bar Bush 66 1 Front L/H Anti Roll Bar Bush 67 1 Front L/H Anti Roll Bar Bush 68 1 Front L/H Anti Roll Bar Bush 69 1 Front L/H Anti Roll Bar Bush 60 1 Front L/H Anti Roll Bar Bush 61 1 Front L/H Anti Roll Bar Bush 62 20818-65 Subtotal:- 63 1 Front L/H Anti Roll Bar Bush 64 1 Font L/H Anti Roll Bar Bush 65 20818-65 Subtotal:-	\$374.45	octed	Front L/H Arch Panel Disk	1	34
1 Front L/H Step Panel Bent 39 1 Front L/H Step Panel Bent 39 1 Front L/H Step Panel Cover Lt 40 1 Front Body Wiring Hr Step Panel Cover Lt 41 1 Front Wiring Bracket Planel 42 1 Front Dashboard Coulct 43 1 Front L/H Dashboard Side Cover Hat Nov 44 1 Front Abs Pump Coulct 45 1 Front Abs Pump Top Member 46 1 Front Abs Pump Lower Member 47 1 Front Abs Pump Pipe Member 48 1 Front Engine Lower Cover tota 49 1 Front Carpet + planel 49 1 Front Crossmember Not Nov 49 1 Front Crossmember Not Nov 50 1 Front Floor Panel 51 1 Front Crossmember Not Nov 52 1 Front Windscreen Moulding Nov 53 1 Front L/H Rim He Nov 54 1 Front L/H Hub Cap Lot 55 1 Front L/H Hub Cap Lot 56 1 Front L/H Lower Arm Bent 57 1 Front L/H Knuckle Arm Dect 58 1 Front L/H Knuckle Arm Dect 59 1 Front L/H Stabilliser Bar Refer 60 1 Front L/H Stabilliser Bar Refer 60 1 Front L/H Shock Absorber 61 1 Front Steering Rack Bent 62 1 Front Anti Roll Bar Bent 63 1 Front L/H Anti Roll Bar Bent 64 1 Front L/H Anti Roll Bar Bush 65 20818-65 Subtotal:- \$34	\$289.90	从	Front L/H Arch Panel Rubber	1	35
1 Front L/H Step Panel Both 1 Front L/H Step Panel Cover Lt 1 Front Body Wiring Mr \$1 1 Front Wiring Bracket It of the Step Panel Cover Lt 1 Front Wiring Bracket It of the Step Panel Cover Lt 1 Front Dashboard Coulch 1 Front Dashboard Side Cover Not No. 1 Front Abs Pump Coulch 1 Front Abs Pump Top Member It of the Step Pump Lower Member It of the Step Pump Pipe Pipe Pipe Pipe Pipe Pipe Pipe Pip	\$174.45	bber ut	Front L/H Arch Panel Pillar Ru	1	36
1 Front L/H Step Panel Cover Lt 40 1 Front Body Wiring Mr \$1 41 1 Front Wiring Bracket Pland 42 1 Front Dashboard Coulcd 43 1 Front L/H Dashboard Side Cover Not Nov 44 1 Front Abs Pump Coulcd 45 1 Front Abs Pump Coulcd 46 1 Front Abs Pump Lower Member Plant 47 1 Front Abs Pump Pipe Member Plant 48 1 Front Engine Lower Cover Tolin 49 1 Front Carpet Holin 50 1 Front Floor Panel Plant 51 1 Front Crossmember Nov Nov 52 1 Front Windscreen Moulding Nov 53 1 Front L/H Rim Ne Nov 54 1 Front L/H Hub Cap Let 55 1 Front L/H Hub Cap Let 56 1 Front L/H Hupper Arm Pant 57 1 Front L/H Knuckle Arm Pant 59 1 Front L/H Knuckle Arm Bearing Am 59 1 Front L/H Shock Absorber Pant 60 1 Front Steering Rack Beat 61 1 Front Steering Rack Beat 62 1 Front Anti Roll Bar Beat 63 1 Front L/H Anti Roll Bar Bush 64 1 Front L/H Anti Roll Bar Bush 65 20818-65 Subtotal:- \$34	\$372.25	De L d	Front L/H Arch Panel Garnish	1	37
40 1 Front Body Wiring Hr 41 1 Front Wiring Bracket Pland 42 1 Front Dashboard Coulcd 43 1 Front L/H Dashboard Side Cover Hat Nov 44 1 Front Abs Pump Coulcd 45 1 Front Abs Pump Top Member 2 Book 46 1 Front Abs Pump Lower Member 3 47 1 Front Abs Pump Pipe Member 3 48 1 Front Engine Lower Cover Hote 49 1 Front Carpet Home 50 1 Front Floor Panel Pand 51 1 Front Crossmember Not Noc 51 51 1 Front Windscreen Moulding Noc 51 52 1 Front Windscreen Moulding Noc 51 53 1 Front L/H Rim Hemm 54 1 Front L/H Hub Cap Let 55 1 Front L/H Hub Cap Let 56 1 Front L/H Upper Arm Book 57 1 Front L/H Knuckle Arm Bearing Noc 51 58 1 Front L/H Stabilliser Bar Peter 60 1 Front L/H Stabilliser Bar Peter 61 1 Front Steering Rack Book 52 62 1 Front Anti Roll Bar Book 63 1 Front L/H Anti Roll Bar Bush 203 64 1 Front L/H Anti Roll Bar Bush 203 64 1 Front L/H Anti Roll Bar Bush 203 65 Subtotal:- \$34	\$381.90		Fornt L/H Step Panel Bed	1	38
41 1 Front Wiring Bracket Pland 42 1 Front Dashboard Couled 43 1 Front L/H Dashboard Side Cover Not Not 44 1 Front Abs Pump Couled 45 1 Front Abs Pump Top Member 2 Best 46 1 Front Abs Pump Dower Member 3 47 1 Front Abs Pump Pipe Member 48 48 1 Front Engine Lower Cover total 49 1 Front Carpet total 50 1 Front Floor Panel 4900 51 1 Front Crossmember Not Nac 51 52 1 Front Windscreen Moulding Noc 51 53 1 Front L/H Rim Helder 55 54 1 Front L/H Lower Arm Best 55 55 1 Front L/H Upper Arm Sout 55 56 1 Front L/H Upper Arm Sout 55 57 1 Front L/H Knuckle Arm Bearing Nac 55 58 1 Front L/H Shock Absorber 80 59 1 Front L/H Shock Absorber 80 60 1 Front L/H Shock Absorber 80 61 1 Front Steering Rack 80 62 1 Front Anti Roll Bar 80 63 1 Front L/H Anti Roll Bar Bush 20 64 1 Font L/H Anti Roll Bar Bush 20 65 Subtotal:- \$34	\$172.10	<i>x</i>	Front L/H Step Panel Cover C	1	39
1 Front Dashboard Craded 43 1 Front L/H Dashboard Side Cover Not Nor 44 1 Front Abs Pump Craded 45 1 Front Abs Pump Craded 46 1 Front Abs Pump Lower Member 2 Book 46 1 Front Abs Pump Lower Member 4 47 1 Front Abs Pump Pipe Member 4 48 1 Front Engine Lower Cover 10 In 49 1 Front Carpet 10 In 50 1 Front Floor Panel 10 In 50 1 Front Windscreen Moulding 10 In 51 1 Front Windscreen Moulding 10 In 52 1 Front Windscreen Moulding 10 In 53 1 Front L/H Rim 10 In 54 1 Front L/H Hub Cap 10 In 55 1 Front L/H Upper Arm 10 In 56 1 Front L/H Knuckle Arm 10 In 57 1 Front L/H Knuckle Arm Bearing 10 In 58 1 Front L/H Knuckle Arm Bearing 10 In 59 1 Front L/H Stabilliser Bar 10 In 50 1 Front L/H Shock Absorber 10 In 60 1 Front Steering Rack 10 In 61 1 Front Steering Rack 10 In 62 1 Front Anti Roll Bar 10 In 63 1 Front L/H Anti Roll Bar Bush 10 In 64 1 Front L/H Anti Roll Bar Bush 10 In 65 Subtotal:- \$34	\$1,250.30 ×		Front Body Wiring $H \sim$	1	40
1 Front L/H Dashboard Side Cover Not No. 1 Front Abs Pump Could 1 Front Abs Pump Top Member 2 Bent 1 Front Abs Pump Lower Member 3 1 Front Abs Pump Pipe Member 3 1 Front Engine Lower Cover 10/n 1 Front Engine Lower Cover 10/n 1 Front Carpet 19/n 1 Front Crossmember Not No. 1 Front Windscreen Moulding No. 1 Front L/H Rim No. 1 Front L/H Hub Cap Let 1 Front L/H Lower Arm Sect 1 Front L/H Upper Arm Sect 1 Front L/H Knuckle Arm Bearing No. 1 Front L/H Stabilliser Bar Refer 1 Front L/H Shock Absorber Sect 1 Front L/H Shock Absorber Sect 1 Front L/H Shock Absorber Sect 1 Front L/H Anti Roll Bar Best 1 Front L/H Anti Roll Bar Bush 20 1 Front L/H Anti	\$174.45	_d	Front Wiring Bracket 🏻 🌣 🗠 〜	1	41
44 1 Front Abs Pump Could 45 1 Front Abs Pump Top Member 2 Block 46 1 Front Abs Pump Lower Member 3 47 1 Front Abs Pump Pipe Member 3 48 1 Front Engine Lower Cover 1011 49 1 Front Carpet 1011 50 1 Front Floor Panel 1011 51 1 Front Crossmember 111 52 1 Front Windscreen Moulding 112 53 1 Front L/H Rim 111 54 1 Front L/H Hub Cap 111 55 1 Front L/H Lower Arm 111 56 1 Front L/H Upper Arm 111 57 1 Front L/H Knuckle Arm 111 58 1 Front L/H Knuckle Arm 111 59 1 Front L/H Stabilliser Bar 111 60 1 Front L/H Stabilliser Bar 111 61 1 Front Steering Rack 111 62 1 Front Anti Roll Bar 111 63 1 Front L/H Anti Roll Bar 111 64 1 Front L/H Anti Roll Bar 111 65 Subtotal:- \$34	\$972.40		Front Dashboard Couled	1	42
1 Front Abs Pump Top Member 2 But 1 Front Abs Pump Lower Member 3 1 Front Abs Pump Pipe Member 4 1 Front Engine Lower Cover 101 1 Front Carpet 101 1 Front Floor Panel 101 1 Front Crossmember 111 1 Front Windscreen Moulding 112 1 Front L/H Rim 112 1 Front L/H Hub Cap 112 1 Front L/H Upper Arm 112 1 Front L/H Knuckle Arm 113 1 Front L/H Knuckle Arm 113 1 Front L/H Stabilliser Bar 114 1 Front L/H Stabilliser Bar 114 1 Front L/H Shock Absorber 114 1 Front Steering Rack 102 1 Front L/H Anti Roll Bar 103 1 Front L/H	\$272.25×	er Not New	Front L/H Dashboard Side Cov	1	43
46 1 Front Abs Pump Lower Member 47 1 Front Abs Pump Pipe Member 48 1 Front Engine Lower Cover to 1/4 1 Front Carpet 40 (No. 1) Front Carpet 40 (No. 1) Front Floor Panel 1 Front Crossmember Not No. 1 Front Windscreen Moulding No. 1 Front L/H Rim 1 No. 1 Front L/H Hub Cap (No. 1) Front L/H Lower Arm 1 Front L/H Upper Arm 1 Front L/H Upper Arm 1 Front L/H Knuckle Arm 1 Front L/H Knuckle Arm 1 Front L/H Stabilliser Bar 1 Stabilliser Bar 1 Front L/H Stabilliser Bar 1 Stabilliser Bar 1 Front L/H Stabilliser Bar 1 Stabilli	\$2,821.10		Front Abs Pump Coulic	1	44
46 1 Front Abs Pump Lower Member 47 1 Front Abs Pump Pipe Member 48 1 Front Engine Lower Cover 4010 48 1 Front Engine Lower Cover 4010 49 1 Front Carpet 4010 50 1 Front Floor Panel 4910 51 1 Front Crossmember 1910 52 1 Front Windscreen Moulding 1910 53 1 Front L/H Rim 1910 54 1 Front L/H Hub Cap 1910 55 1 Front L/H Lower Arm 1910 56 1 Front L/H Upper Arm 1910 57 1 Front L/H Knuckle Arm 1910 58 1 Front L/H Knuckle Arm Bearing 1910 59 1 Front L/H Stabilliser Bar 1910 60 1 Front L/H Shock Absorber 1910 61 1 Front Steering Rack 1910 62 1 Front Anti Roll Bar 1910 63 1 Front L/H Anti Roll Bar 1910 64 1 Front L/H Anti Roll Bar 1910 65 Subtotal:- \$34	\$172.10	2 Rest	Front Abs Pump Top Member	1	45
1 Front Engine Lower Cover to M 49 1 Front Carpet + MM 50 1 Front Floor Panel PASS Subtotal:- 51 1 Front Crossmember MSR MC \$1 52 1 Front Windscreen Moulding MC \$1 53 1 Front L/H Rim MR MM 54 1 Front L/H Hub Cap M 55 1 Front L/H Lower Arm BM 56 1 Front L/H Upper Arm MM 57 1 Front L/H Knuckle Arm M 58 1 Front L/H Knuckle Arm Bearing MM 59 1 Front L/H Stabilliser Bar MR MM 60 1 Front L/H Shock Absorber MM 61 1 Front Steering Rack MM 62 1 Front L/H Anti Roll Bar MM 63 1 Front L/H Anti Roll Bar Bush MM 64 1 Front L/H Anti Roll Bar Bush MM 65 Subtotal:- \$34	\$182.25		Front Abs Pump Lower Memb	1	46
1 Front Carpet + 10 1 51 1 Front Floor Panel 12 151 1 Front Crossmember 12 152 1 Front Windscreen Moulding 16 153 1 Front L/H Rim 15 16 16 16 16 16 16 16 16 16 16 16 16 16	\$191.60 <i>X</i>	· levis	Front Abs Pump Pipe Member	1	47
50 1 Front Floor Panel Pris \$1 51 1 Front Crossmember Not Nec \$1 52 1 Front Windscreen Moulding Nec \$1 53 1 Front L/H Rim Ne Nec \$1 54 1 Front L/H Hub Cap Let \$1 55 1 Front L/H Lower Arm Beat \$1 56 1 Front L/H Upper Arm Pert \$1 57 1 Front L/H Knuckle Arm Dec \$1 58 1 Front L/H Knuckle Arm Bearing Nec \$1 59 1 Front L/H Stabilliser Bar Peter \$1 60 1 Front L/H Stabilliser Bar Peter \$1 60 1 Front Steering Rack Best \$2 62 1 Front Anti Roll Bar Best \$2 63 1 Front L/H Anti Roll Bar Bush Pol \$2 64 1 Front L/H Anti Roll Bar Bush Pol \$3 65 Subtotal:- \$34	\$374.45	in	Front Engine Lower Cover to	1	48
51 1 Front Crossmember Not Nec \$1 52 1 Front Windscreen Moulding Nec \$1 53 1 Front L/H Rim Net Me \$1 54 1 Front L/H Hub Cap Int \$1 55 1 Front L/H Lower Arm But \$1 56 1 Front L/H Upper Arm Sut \$1 57 1 Front L/H Knuckle Arm Bearing Nec \$1 58 1 Front L/H Knuckle Arm Bearing Nec \$1 59 1 Front L/H Stabilliser Bar Peter \$1 60 1 Front L/H Shock Absorber Sut \$2 61 1 Front Steering Rack Sut \$2 62 1 Front Anti Roll Bar Bush \$2 63 1 Front L/H Anti Roll Bar Bush \$2 64 1 Funt L/H Anti Roll Bar Bush \$2 65 Subtotal:- \$34	\$ 650.00 > 400		Front Carpet +0(N	1	49
1 Front Windscreen Moulding No. 1 Front L/H Rim Hem 54 1 Front L/H Hub Cap Ut 55 1 Front L/H Lower Arm But 56 1 Front L/H Upper Arm Sut 57 1 Front L/H Knuckle Arm Mod 58 1 Front L/H Knuckle Arm Bearing No. 59 1 Front L/H Stabilliser Bar Refer 60 1 Front L/H Shock Absorber Sut 61 1 Front Steering Rack But 62 1 Front Anti Roll Bar But 63 1 Front L/H Anti Roll Bar Bush 64 1 Funt L/H Anti Roll Bar Bush 59 2081865 Subtotal:- \$34	\$1,474.40 × .		Front Floor Panel Pris	1	50
1 Front L/H Rim He Me 1 Front L/H Hub Cap Let 1 Front L/H Lower Arm Bet 1 Front L/H Upper Arm Set 1 Front L/H Knuckle Arm Bearing Me 1 Front L/H Knuckle Arm Bearing Me 1 Front L/H Stabilliser Bar Refer 1 Front L/H Shock Absorber Set 1 Front Steering Rack Bet 1 Front Steering Rack Bet 1 Front Anti Roll Bar Bet 1 Front L/H Anti Roll Bar Bush Set 1 Front L/H Anti Roll Bar Bush Set 1 Front L/H Anti Roll Bar Bush Set 1 Subtotal:- \$34	\$1,218.85		Front Crossmember ಸುನೇ Mcc	1	51
1 Front L/H Hub Cap Ut 55 1 Front L/H Lower Arm But 56 1 Front L/H Upper Arm 57 1 Front L/H Knuckle Arm 58 1 Front L/H Knuckle Arm Bearing Am 59 1 Front L/H Stabilliser Bar 60 1 Front L/H Shock Absorber 61 1 Front Steering Rack 62 1 Front Anti Roll Bar 63 1 Front L/H Anti Roll Bar Bush 64 1 Funt L/H Anti Roll Bar Bush 65 Subtotal:- \$34	\$272.45	Her		1	52
55 1 Front L/H Lower Arm But 56 1 Front L/H Upper Arm But 57 1 Front L/H Knuckle Arm 58 1 Front L/H Knuckle Arm Bearing Am 59 1 Front L/H Stabilliser Bar 60 1 Front L/H Shock Absorber 61 1 Front Steering Rack 62 1 Front Anti Roll Bar 63 1 Front L/H Anti Roll Bar Bush 64 1 Font L/H Anti Roll Bar Bush 65 Subtotal:- 58 Subtotal:- 59 Subtotal:-	\$680.00		Front L/H Rim He Mh	1	53
56 1 Front L/H Upper Arm Set 57 1 Front L/H Knuckle Arm Jan C 58 1 Front L/H Knuckle Arm Bearing Am 59 1 Front L/H Stabilliser Bar Rhem 60 1 Front L/H Shock Absorber 61 1 Front Steering Rack Bet 62 1 Front Anti Roll Bar Bet 63 1 Front L/H Anti Roll Bar Bush 25 64 1 Font L/H Tyre Lit 208/8/65 Subtotal:- \$34	\$18 0.00 60/5		Front L/H Hub Cap 4	1	54
57 1 Front L/H Knuckle Arm 2 2 3 5 5 5 5 Subtotal:- \$34	\$382.25		Front L/H Lower Arm Beck	1	55
1 Front L/H Knuckle Arm Bearing Am 58 1 Front L/H Knuckle Arm Bearing Am 59 1 Front L/H Stabilliser Bar Rhem 60 1 Front L/H Shock Absorber Am 61 1 Front Steering Rack Best 62 1 Front Anti Roll Bar 63 1 Front L/H Anti Roll Bar Bush Am 64 1 Front L/H Anti Roll Bar Bush Am 20818.65 Subtotal:- \$34	\$972.10		Front L/H Upper Arm	1	56
1 Front L/H Stabilliser Bar Rhem 1 Front L/H Shock Absorber Rhem 1 Front Steering Rack Best 1 Front Anti Roll Bar Best 1 Front L/H Anti Roll Bar Bush Roll 1 Font L/H Tyre At 20818-65 Subtotal:- \$34	\$561.60	39	Front L/H Knuckle Arm	1	57
60 1 Front L/H Shock Absorber 194 52 61 1 Front Steering Rack 3est 52 62 1 Front Anti Roll Bar 3est 55 63 1 Front L/H Anti Roll Bar Bush 200 2 64 1 Font L/H Tyre 1st 20818.65 Subtotal:- \$34	\$374.40	g an	Front L/H Knuckle Arm Bearin	1	58
61 1 Front Steering Rack Best \$2 62 1 Front Anti Roll Bar Best \$2 63 1 Front L/H Anti Roll Bar Bush 202 64 1 Front L/H Tyre Lit 208/8/65 Subtotal:- \$34	\$378.85 <i>×</i>	hen	Front L/H Stabilliser Bar	1	59
62 1 Front Anti Roll Bar Best 5 63 1 Front L/H Anti Roll Bar Bush 202 64 1 Front L/H Tyre Let 20818.65 Subtotal:- \$34	\$174.70	ent	Front L/H Shock Absorber	1	60
63 1 Front L/H Anti Roll Bar Bush 202 64 1 Front HH Tyre at 20818.65 Subtotal:- \$34	\$2,821.10		Front Steering Rack Best	1	61
64 1 Font HH Tyre let 20818.65 Subtotal: 534	\$381.90	*	Front Anti Roll Bar Ben	1	62
208/8.6≤ Subtotal:- \$34	\$43.75	2 52	Front L/H Anti Roll Bar Bush	1	63
3ubtotal :	_280 180/SN	_	Font HH Tyre at	1	64
13613.98 SN 790	\$34,562.55	_	· · · · · · · · · · · · · · · · · · ·		•
		13613.98 SN 790			

Labour charges

To remove & refit cushion &	& carpet		\$350.00 200
To remove & refit roof linni	ng		\$450.00 <i>×</i>
To remove & refit front win	dscreen		\$150.00 120 \$50.00
Gum			\$50.00
To remove & refit front L/H rubber & trim board	door, gear, motor, lock, glass,		\$180.00 &
To remove & refit front das	hboard		\$380.00 222 \$450.00 X
To remove & refit air-con b & top up gas	lower, air duct blower		\$450.00 X
To remove & refit crossmer	mber, steering rack & ABS pump		\$450.00 250
To remove & refit front boo	ly wiring & door wiring		\$450.00 250 \$750.00 280 \$380.00 200 \$150.00 82 \$100.00 30
To remove & refit front L/H	undercarriage		\$380.00200
To check wheel alignment			\$150.0080
To check wiring			\$100.00 ^{3)}
Towing fee	LKK Auto Consultants hence notify the Repairer of the following:	5230	\$190.00 6 0 \$150.00 6 0
Tuff kote	To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	2250	\$150.00 617
Panel beating	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		\$2,800.00 2000 \$2,000.00 1600
Spray painting	Acknowledged by Repairer Signature:		\$2,000.00 1600
į.	Date:	Subtotal :-	\$8,890.00
		Total:-	\$43,452.55
	17.3K.		21633.98 17.3 K.: 120ays 113732 xs
		•	12 Days . 113732 55



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des	Experts En Automob	lloe - San Angel
	O INSURANCE P		Ref:		
#04-	MASEK BOULEV 01 SUNTEC TOW 3APORE 038985		Date :	16-05-2018	
			Code :	EGI	
1.		Policy Particulars	:- THIR	PARTY CLAIM	
	Insured Veh.	SGU 6851C	Veh. Ir	spected	PC 6460K
	Policy No.		Cover	age (\$)	0.00
	Claim No.	SGU6851C/RH/pl	Exces	s (\$)	0.00
	Assign From	YEE PEI LI	Assig	n Date	29/01/2018
2.		Vehicle Parti	culars 8	Condition	TO A SALES AND THE SALES
	Make & Model	TOYOTA HIACE	c.c		2982
	Engine No.	HIDDEN	Year o	f Reg.	2017
	Chassis No.	KDH2230033811	Colou	7	WHITE
	Odometer	11319	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	NIL
	General	GOOD			
3.		Condit	ions of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/80 R15	BRIDG	ESTONE	6 mm
	L/H Front Tyre	195/80 R15	BRIDG	ESTONE	6 mm
	R/H Rear Tyre	195/80 R15	BRIDG	ESTONE	6 mm
	L/H Rear Tyre	195/80 R15	BRIDG	ESTONE	6 mm
4.		Descript	on of Da	ım ages	The transfer of the second
	THE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT N/S	AND UNDERCARR	RIAGE PORTION.
	DAMAGES SEE D	ETAILS.			
5.	A Maria Caranga A and a second	Genera	l inform	atlon 🐉 🔭 🐒	
	Accident Date	27/01/2018	Inspec	tion Date	29/01/2018
	Survey held at	NEW HOCK TECK MOTOR PT	ELTD		
		1 KAKI BUKIT AVENUE 6 #01-4 SINGAPORE 417883	3 AUTO	BAY @ KAKI BUKIT	
5a.	and selection assessment of the selection of the selectio	R	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	Æ HAVE	NOT AUTHORISED	
5b.		Estimate	Days of	Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		14 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6460K

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT GRILLE	CRACKED	581.10	581.10
8	FRONT GRILLE CLIP @\$6.50	NECESSARY	52.00	20.00
1	FRONT GRILLE TOP COVER	NOT NECESSARY	371.30	-
1	FRONT GRILLE LOWER COVER	NOT NECESSARY	287.30	
1	FRONT BUMPER	DISTORTED	581.90	581.90
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	
1	FRONT BUMPER CENTRE GARNISH	DEFORMED	281.25	281.25
1	FRONT BUMPER TOP BEAM	BENT	381.25	381.25
1	FRONT BUMPER REINFORCEMENT	BENT	374.45	374.45
2	FRONT BUMPER REINFORCEMENT SIDE BRACKET @\$182.10	NOT NECESSARY	364.20	
1	FRONT L/H BUMPER SIDE RETAINER	DAMAGED	177.10	177.10
1	FRONT L/H BUMPER FOG LAMP COVER	MISSING	132.25	132.25
1	FRONT L/H HORN	NOT NECESSARY	182.10	
2	FRONT HEAD LAMP @\$1712.45	CRACKED	3,424.90	1,376.20
2	FRONT HEAD LAMP LOWER BRACKET @\$171.10	NOT NECESSARY	342.20	
1	FRONT SUPPORT PANEL	NOT NECESSARY	561.60	
2	FRONT L/H & R/H SUPPORT PANEL TOP GARNISH @\$374.45	NOT NECESSARY	748.90	
1	FRONT RADIATOR TANK	NOT NECESSARY	377.70	
1	FRONT WIPER TANK	NOT NECESSARY	182.10	
1	FRONT L/H SIDE PANEL	BUCKLED	172.45	172.45
1	FRONT L/H DOOR PILLAR OUTER	DISTORTED	631.35	631.35
1	FRONT L/H DOOR PILLAR INNER	TO REPAIR SEE LABOUR	621.10	
1	FRONT L/H DOOR	DISTORTED	1,712.10	1,712.10
2	FRONT L/H DOOR HINGE @\$132.25	BENT	264.50	264.50
1	FRONT L/H DOOR INNER RUBBER	CUT	181.90	181.90
1	FRONT L'H DOOR INNER LOWER RUBBER	CUT	177.10	177.10
1	FRONT L/H DOOR INNER LOCK	DAMAGED	289.10	289.10
1	FRONT L/H DOOR INNER TRIM BOARD	CRACKED	561.60	561.60

Report Ref No. CS/EGI18001725/Atd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (5))	Our Adjusted (\$)
1	FRONT L/H DOOR WIRING	CRACKED	850.10	385.00
1	FRONT L/H DOOR CHECKER LOCK	NOT NECESSARY	172.25	-
1	FRONT L/H DOOR GLASS GEAR MOTOR ASSY	DAMAGED	381.10	381.10
1	FRONT L/H ARCH PANEL	DISTORTED	374.45	374.45
1	FRONT L/H ARCH PANEL RUBBER	сит	289.90	289.90
1	FRONT L/H ARCH PANEL PILLAR RUBBER	сит	174.45	174.45
1	FRONT L/H ARCH PANEL GARNISH	DEFORMED	372.25	372.25
1	FRONT L/H STEP PANEL	BENT	381.90	381.90
1	FRONT L/H STEP PANEL COVER	сит	172.10	172.10
1	FRONT BODY WIRING	NOT NECESSARY	1,250.30	-
1	FRONT WIRING BRACKET	DEFORMED	174.45	174.45
1	FRONT DASHBOARD	CRACKED	972.40	972.40
1	FRONT L/H DASHBOARD SIDE COVER	NOT NECESSARY	272.25	-
1	FRONT ABS PUMP	CRACKED	2,821.10	2,821.10
1	FRONT ABS PUMP TOP MEMBER	BENT	172.10	172.10
1	FRONT ABS PUMP LOWER MEMBER	BENT	182.25	182.25
1	FRONT ABS PUMP PIPE MEMBER	TO REPAIR SEE LABOUR	191.60	-
1	FRONT ENGINE LOWER COVER	TORN	374.45	374.45
1	FRONT FLOOR PANEL	TO REPAIR SEE LABOUR	1,474.40	-
1	FRONT CROSSMEMBER	NOT NECESSARY	1,218.85	-
1	FRONT WINDSCREEN MOULDING	NECESSARY	272.45	272.45
1	FRONT L/H RIM	NOT NECESSARY	680.00	-
1	FRONT L/H LOWER ARM	BENT	382.25	382.25
1	FRONT L/H UPPER ARM	BENT	972.10	653.00
1	FRONT L/H KNUCKLE ARM	DAMAGED	561.60	561.60
1	FRONT L/H KNUCKLE ARM BEARING	NECESSARY	374.40	374.40
1	FRONT L/H STABILISER BAR	NOT NECESSARY	378.85	-
1	FRONT L/H SHOCK ABSORBER	BENT	174.70	174.70
1	FRONT STEERING RACK	BENT	2,821.10	2,821.10
1	FRONT ANTI ROLL BAR	BENT	381.90	381.90
1	FRONT L/H ANTI ROLL BAR BUSH	DAMAGED	43.75	43.75

Report Ref No. CS/EGI18001725/Atd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (5)
	LESS 25% DISCOUNT		-	-5,204.66
			33,432.55	15,613.99
	SPECIAL NETT ITEMS			
1	FRONT L/H DOOR BODY LOGO (SN)	NECESSARY	300.00	150.00
1	FRONT CARPET (SN)	TORN	650.00	400.00
1	FRONT L/H HUB CAP (SN)	сит	180.00	60.00
1	FRONT L/H TYRE (SN)	сит	280.00	180.00
			1,410.00	790.00
	LABOUR			
	TO REMOVE & REFIT CUSHION & CARPET.		350.00	200.00
	TO REMOVE & REFIT ROOF LINNING.	NOT NECESSARY	450.00	-
	TO REMOVE & REFIT FRONT WINDSCREEN.		150.00	120.00
	GUM.		50.00	50.00
	TO RMEOVE & REFIT FRONT L/H DOOR, GEAR, MOTOR, LOCK, GLASS, RUBBER & TRIM BOARD.		180.00	80.00
	TO REMOVE & REFIT FRONT DASHBOARD.		380.00	220.00
	TO REMOVE & REFIT AIR-CON BLOWER, AIR DUCT BLOWER & TOP UP GAS.	NOT NECESSARY	450.00	-
	TO REMOVE & REFIT CROSSMEMBER, STEERING RACK & ABS PUMP.		450.00	250.00
	TO REMOVE & REFIT FRONT BODY WIRING & DOOR WIRING.		750.00	280.00
	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE.		380.00	200.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.		100.00	60.00
	TUFF KOTE.		150.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT L/H DOOR PILLAR INNER, FRONT ABS PUMP PIPE MEMBER AND FRONT FLOOR PANEL.		2,800.00	2,000.00
	SPRAY PAINTING.		2,000.00	1,600.00
			8,890.00	5,230.00
	GRAND TOTAL		43,732.55	21,633.99

Report Ref No. CS/EGI18001725/Atd3e2



Page No.:4 of 4

			A STATE OF THE STA
C 18 7 18 7 27 26 45 45 45 4 5 7 7 7 18 7 17 17 17 17 17 17 17 17 17 17 17 17 1	The territory of the second se	 In all the respective probabilities of the state of the	、 6、以及心心感,心,实验现不会 14000 以下,不知知识是心理实理的感染了特征,但在15000 EEC 4000 的复数
	· · · · · · · · · · · · · · · · · · ·	」、「中」 ■毎年 海中の海に投げた 記さる 「大 テニカーのころ」とは大き歩 デモリア	大学····································
**************************************	DEBINE SING REPAIRS	- Tak # 7 . ファイ・カイナル アイス アイス アイス (1984年) 2000 (1987年) 2000 (1987年)	17,300.00
NECOMINE TO LO COUR	OF LUMP SUM REPAIRS		· 人名英格兰人姓氏格兰 化二苯基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基
		(*) *** *** *** *** *** *** *** *** ***	"大学"在1862年,在1988年中国的国际的国际的国际的国际的国际的工作的企业的,在2012年的第二次。
les colesia		THE RESERVE OF THE PARTY OF THE	
TO ITS PRE-ACCIDENT		· · · · · · · · · · · · · · · · · · ·	1、一般を使用が経緯をは他の場合を構造しているという。 かんしょうかい 人にはなっている。
		이 강도가 불어 가능하면 보면도 가득하다	1. 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
As a Transfer of the real file and the real file.	The state of the s		

Report Ref No. CS/EGI18001725/Atd3e2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No hability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.