

tanjin

AXA

Date 02/02/2018

SLM5013H

2017 March

Estimated Loss

① WS THREE CO RESERVE (V.V.)

To inspect vehicle SLM 5013H

at location Motor Image

at 25 Leng Kee Rd

Insured

Policy No

Claims No

Sum Insured

Excess

Client's Record


12pm - 3.30pm

Make of car

Dennis

Policy Condition

Remarks: The veh had commenced its repair at the time of inspection.



Bar or Market Value

DAC Accident Report Consistent? Yes or No

BA - PP - Consistent? Yes or No

Est. Repairs days Res: Yes or No

Lat. Sur: Yes or No

CA REV / REP. 24 HRS /wp

Date Person Contacted

Vehicle IN / OUT Dennis

① The Motor Vehicle Bus Van Long Tan Prime Tower

Truck Trailer

Make Subaru Forester 2.0

1995.

Color Grey

St. Reading 15743.

Engine

Chassis

JF1SJSKCSH G7086132

Gen. Cond. Good Fair Poor Burnt

Steering In order Jammed Leaked Burnt or

Brake In order Jammed Leaked Burnt or

Mod. Nil. S.R. STD A.R.

Tyre Size

225/60K17

R.

BSI DUN EXNOVA GY PS LIZA MC OPTSU RIR SLV

TOYO YOKO or

Front

Rear

R.Ba.

R.Ba.

L.Ba.

L.Ba.

D.O.A.

D.O.

Surveyed at

Motor Image Leng Kee

Des. of Damages Fr. Rear OS NS UC Rooktop or

The U.C. Chassis frame Body Structure affected due to collision

Date Time Action Instruction

Ins Time Re-Parment ☐ Prelim. Report

☐ Final Report

Ins Time Re-Parment

Days Of Repair

Resurvey No. of Trc

Survey Fee

Truck Fee

Add Fee

Shuttle

Truck

Truck

Truck

Record By: Tanjin

Date: 02/02/2018

AXA MOTOR INSURANCE CO. LTD.

AXA MOTOR INSURANCE CO. LTD.