



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4679E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR RR/ RH (DISC 25%)(CONSISTENT)	DENTED	954.50	715.87
1	PIXEL STICKER (SN)(CONSISTENT)	NECESSARY	60.00	60.00
1	STICKER DECAL SMRT (SN)(CONSISTENT)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)(CONSISTENT)	NECESSARY	21.60	21.60
1	SOLAR FILM (SN)(CONSISTENT)	NECESSARY	125.00	125.00
1	QUARTER GLASS RR/RH (CONSISTENT)	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	FENDER RR/RH (CONSISTENT)	TO REPAIR SEE LABOUR	766.80	-
1	MOULDING BODY, RH (CONSISTENT)	TO REPAIR SEE LABOUR	673.60	-
			3,492.80	930.27
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK .INCLUSIVE OF THE REPAIR OF FENDER RR/RH AND MOULDING BODY, RH. SPRAY PAINT.		676.00	300.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		936.00	500.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		100.00	30.00
	TO TRANSFER DOOR MECHANISM .	NOT NECESSARY	80.00	-
	TO REPLACE SUNDRY PARTS.		120.00	60.00
	TO WASH AND VACUUM .		100.00	20.00
	TO REMOVE & REFIT REAR QUARTER GLASS RH .	NOT NECESSARY	60.00	-
		NOT NECESSARY	120.00	-
			2,192.00	910.00
GRAND TOTAL			5,684.80	1,840.27
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC4/ASM18001735/Spa3q2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.