

22/03/2002

ASS. REC. BY:

REF: CS/FCI18001781/Avd3n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

30/1/18 @ 9:52am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 9338H

Insured:

SH8996G

at Workshop m/s

MG solution

Tel:

G744 4165

of

23 Kaki Bkt Ave 4 #02-03

Policy No:

Claim No:

D18000891MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

10:46am @ 30/1/18

Person Contacted:

Ms. Heng

Vehicle: ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 9338H-X

SH8996G-CS/FCI16023101/Kg bn2

D.O.A.: 22/11/2016

31/1/18

Email FCI pending workshop est

16/3/18

Adrian confirmed LS \$4400 (Red 5024.57, 5390)

19/3/18

Email preli revised to FCI

REF:

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH9338H Yr Regn: 2016 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astra C.C. 999Colour: White A/C: Insured / Std / NI / NASp. Reading: 8144 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOLBE6EA7HG004269Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17
R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 30/01/18Survey held at MG solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap

RECEIVED 19 MAR 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 19/3 - typistReport Format : CWSLump Sum / I.B.I.: (\$) 4400 pDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

170

50

50

25

295

Survey Department Check List (Case Handler)

Reference No.: CS/FCI/800/1781/Av03
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded.	✓			
---	---------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 19/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001781/Avd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8996G	Veh. Inspected	SLH 9338H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18000891MFSH	Excess (\$)	0.00	
Assign From	CWS (KAREN TAN)	Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/01/2018	Inspection Date	30/01/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	29-01-2018	Our Ref No. D18000891MFSH
Accident Date	27-01-2018	Claim Type. Third Party
Insured Vehicle	SH8996G	Third Party Vehicle. SLH9338H
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	HENG YOKE HONG	
Contact No.	67444165/ 0	Fax No. 67444604
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234451)



PRI Documents



Close



PRI Header Details

Claim No	D18000891MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & MG SOLU
Workshop Name	MG SOLUTION PTE LTD (Contact Person : HENG YOKE HONG)	Survey Location & Contact Details	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03 Mobile: 0 , Phone: 674444165 , Fax: 67444604 EmailId: MG3SOLUTION@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8996G	TP Vehicle No	SLH9338H
PRI Recieved Date	29-01-2018 10:49:46 PM	Surveyor Appointed Date	30-01-2018 09:51:23 AM	Surveyor Accept Date	30-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 19 March 2018 11:45 AM
To: 'Claim Workflow System'
Cc: 'KARENTAN@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18000891MFSH/1, SLH 9338H
Attachments: SLH 9338H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLH 9338H
Date of survey: 30/1/2018
Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 31 January 2018 3:40 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000891MFSH/1, SLH 9338H

Dear Sir/Madam

Please be informed that we have inspected the vehicle SLH 9338H on 30/1/2018

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 30 January 2018 10:48 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000891MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 30 January 2018 9:52 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18000891MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000891MFSH
Our ref: CS/FCI18001781/Avd3

Date : 19/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 9338H


We thank you for your instruction on 30/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/1/2018 at the premises of M/s MG SOLUTION PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$9,424.57
Revised Estimate Amount	: S\$5,578.56
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 31 January 2018 3:40 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000891MFSH/1, SLH 9338H

Dear Sir/Madam

Please be informed that we have inspected the vehicle SLH 9338H on 30/1/2018

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 30 January 2018 10:48 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000891MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 January 2018 9:52 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000891MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO : FIRST CAPITAL INSURANCE DATE : 29/01/2018

ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM

ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SLH9338H

MODEL : OPEL ASTRA 1.4

Veron

CHASSIS NO

WOLBE6EA7H6004269

ACCIDENT DETAILS

DATE : 27-Jan-18

TIME : 14:40HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 1,320.00	\$ 1,320.00
2	REAR BUMPER SIDE RETAINER RH <i>in</i>	1	\$ 62.40	\$ 62.40
3	REAR BUMPER REFLECTOR RH <i>crushed</i>	1	\$ 89.00	\$ 89.00
4	REAR BUMPER TOWING COVER <i>crushed</i>	1	\$ 77.00	\$ 77.00
5	REAR BUMPER REINFORCEMENT <i>dent</i>	1	\$ 450.00	\$ 450.00
6	REAR BUMPER LOWER LID <i>crushed</i>	1	\$ 520.00	\$ 520.00
7	TAILLAMP RH <i>crushed</i>	1	\$ 630.00	\$ 630.00
8	TAILLAMP PANEL RH <i>crushed</i>	1	\$ 358.90	\$ 358.90
9	FENDER RH <i>in</i>	1	\$ 1,800.00	\$ 1,800.00
10	FENDER INNER COWLING RH <i>crushed</i>	1	\$ 290.00	\$ 290.00
11	REAR END PANEL <i>crushed</i>	1	\$ 870.00	\$ 870.00
12	REVERSE SENSOR <i>crushed 1 piece</i>	4	\$ 290.00	\$ 1,160.00

4598.40
4138.56

TOTAL PRICE \$ 7,627.30
LESS 10% \$ 762.73
SUB TOTAL PRICE \$ 6,864.57

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>in</i>	1	\$ 20.00	\$ 20.00
2	REAR FENDER INNER COWLING CLIPS(SET) <i>in</i>	1	\$ 20.00	\$ 20.00

3	REAR END PANEL INSULATION SEAL	<i>Mer</i>	1	\$	150.00	\$	150.00	<i>260</i>
---	--------------------------------	------------	---	----	--------	----	--------	------------

100

TOTAL \$ 190.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$	1,000.00	<i>600</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$	1,000.00	<i>700</i>	
3	TUFF COAT	\$	40.00	<i>X</i>	
4	WIRING CHECK	\$	30.00	<i>✓</i>	
5	UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$	120.00	<i>50</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	100.00	<i>60</i>	
7	CONDUCT WATER LEAKAGE TEST	\$	80.00	<i>X</i>	

1340

TOTAL \$2,370.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,054.57
TOTAL LABOUR COST : \$ 2,370.00
TOTAL REPAIR COST : \$ 9,424.57

Adrian Lj
Hs 30/01/18
OS Rys
total: 5578.56
H/S: H4K

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

signed by Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001781/Avd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8996G	Veh. Inspected	SLH 9338H	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000891MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	OPEL ASTRA	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	W0LB6EA7HG004269	Colour	WHITE	
Odometer	8144	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/01/2018	Inspection Date	30/01/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 9338H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	1,320.00	1,320.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	62.40	62.40
1	REAR BUMPER REFLECTOR RH	CRACKED	89.00	89.00
1	REAR BUMPER TOWING COVER	DEFORMED	77.00	77.00
1	REAR BUMPER REINFORCEMENT	BENT	450.00	450.00
1	REAR BUMPER LOWER LID	DEFORMED	520.00	520.00
1	TAILLAMP RH	CRACKED	630.00	630.00
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	358.90	-
1	FENDER RH	NOT NECESSARY	1,800.00	-
1	FENDER INNER COWLING RH	DEFORMED	290.00	290.00
1	REAR END PANEL	DENTED	870.00	870.00
4	REVERSE SENSOR @\$290.00	DAMAGED (1 PC ONLY)	1,160.00	290.00
	LESS 10% DISCOUNT		-762.73	-459.84
			6,864.57	4,138.56
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
			190.00	100.00
LABOUR				
	PANEL BEATING, REMOVAL AND REPLACING PARTS INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH.		1,000.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	600.00
	TUFF COAT.	NOT NECESSARY	40.00	-
	WIRING CHECK.		30.00	30.00
	UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR.		120.00	50.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	60.00

Report Ref No. CS/FCI18001781/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
			2,370.00	1,340.00
	GRAND TOTAL		9,424.57	5,578.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CS/FCI18001781/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.