



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 4918P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SET BALL	NECESSARY	10.00	10.00
1	SET BALL	NECESSARY	12.20	12.20
1	BOTTOM DUST GUARD	CRACKED	19.00	19.00
1	BRACKET FOR TANKS	BENT	15.00	15.00
1	COVER COMPARTMENT TANK	BROKEN	27.30	27.30
1	COVER SIDE LH	CRACKED	76.00	76.00
1	FOOTBOARD LH	CRACKED	105.00	105.00
1	FOOTBOARD MAT LH	CUT	20.00	20.00
1	FOOTBOARD RH	CRACKED	72.00	72.00
1	FORK FRONT ASSY COMPLETE	BENT / JAMMED	603.00	603.00
2	HOOK SNAP @\$38.00	TWISTED	76.00	76.00
1	LEG SHIELD	CRACKED	75.00	75.00
1	LOWER SUPPORT LH	BENT	30.00	30.00
1	LOWER SUPPORT RH	BENT	30.00	30.00
1	MAT FOOTBOARD RH	NOT NECESSARY	84.00	-
1	METALIC FRONT MUDGUARD	CRACKED	43.70	43.70
1	MOTOR FULL GEAR	JAMMED	403.00	403.00
1	MOTOR WIPER	DAMAGED	230.00	230.00
1	PUMP ELECTRIC	SHORTED	57.00	57.00
1	RACE STRG TOP COND	NECESSARY	19.00	19.00
1	ROOF WINDSHIELD	BROKEN	253.85	253.85
1	SEAL OIL (35X62X3.8)	NECESSARY	5.00	5.00
1	SHIELD ASSY FRONT METALLIC (BLUE)	BROKEN	377.00	377.00
1	SIDE COVER RH (GRAPHITE)	CRACKED	75.50	75.50
1	SPRITZ ARTICULATE HEAD	NECESSARY	16.00	16.00
1	STICKER (AJAENTERPRISE) FULL SET	NOT INSURED	120.00	-
1	TANK LIQUID COOLANT	NECESSARY	73.00	73.00
1	TOP CAP (1)	NECESSARY	19.00	19.00
1	TOP CAP (2)	NECESSARY	19.00	19.00
1	WINDSHIELD WIPER TANK	DEFORMED	46.00	46.00

Report Ref No. CS/EQI18001801/Uvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)	
1	WIPER	DAMAGED	19.00	19.00	
			3,030.55	2,826.55	
	<b>LABOUR</b>				
	ALIGNMENT BODY.			330.00	280.00
	COMPLETE SPRAY PAINT.			1,340.00	440.00
	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.			420.00	350.00
	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED - BIKE TOWED IN TO WORKSHOP.			70.00	35.00
			2,160.00	1,105.00	
	<b>GRAND TOTAL</b>		<b>5,190.55</b>	<b>3,931.55</b>	
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,931.55</b>	
	<b>LESS EXCESS</b>			<b>-300.00</b>	
	<b>NETT LIABILITY</b>			<b>3,631.55</b>	

Report Ref No. CS/EQI18001801/Uvd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.