## COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE\***

VEHICLE NO: SHA 1972M

DATE 29/1/2018 11:31

Alg. LAK

MAKE

ODEL Qty	: HYUNDAI SONATA Parts Description/ Labour		Unit Price		Amount	
2.5	Boot Lid	Type			\$	1,349.50
	Boot Lid Rubber ×				\$	110.90
	Boot Lid Lock Upper				\$	132.10
	Boot Lid Lock Lower × ry				\$	30.30
	Boot Lid Sonata Plate				\$	43.60
	Boot Lid Hyundai Plate				\$	24.20
	Boot Lid 'H' Emblem				\$	26.10
	Boot Lid CRDI Plate				\$	22.70
	Boot Lid Lamp (LH/RH) ★		\$	230.20	\$	460.40
	Rear Bumper				\$	578.40
	Rear Bumper Reinforcement				\$	483.30
	Rear Bumper Clip				\$	22.00
	Rear Bumper Sponge				\$	137.40
	Rear Bumper Under Cover				\$	185.80
			\$	38.00	\$	76.00
	Rear Bumper Protector (LH/RH) × Y4		\$	344.00	\$	688.00
	Tail Lamp Quarter Panel (LH/RH)				\$	93.80
	Rear Panel				\$	391.80
	Rear Panel Garnish				\$	95.80
	Spare Tyre Holder 😾				\$	27.60
	Spare Tyre Panel × ~~~				\$	863.00
	Spare Tyre Panel Cushion ×				\$	200.30
	SUB TOTA				\$	6,043.00
	LESS 20				\$	1,208.60
	DISCOUNTED TOTA	T			\$	4,834.40
	Boot Lid Comfort Logo & Tel No. Sticker				\$	30.00
	Boot Lid Advertisement Logo LKK	Auto Consulta	nts hence	notify	\$	100.00
	Rear Rumper Reverse Sensor	Repairer of the	following:		8	135.70
	Rear Bumper Advertisement Logo • To	resurvey before/at display damaged p	art(s) during	resurvey	\$	50.00
	Rear Fender Advertisement Logo (LH/RH)	ts prices are subject party survey is colleged modification	et (\$ confirm)	ation 100.00 Prejudice* basis	\$	200.00
	• Sup	plementary item(s	must be res	urveyed and urance Company	\$	515.70
	- Advan	wledged by Repa		,		600
	Panel Beating	ture:			\$	1,200.00
	Spray Painting Charge	Sohn			\$	800.00
	Wiring Charge 30-18				\$	50.00
	Tuff Kote //s				\$	50.00
	Remove/Refix Reverse Sensor  After 1	lepar pr	1/2		\$	120.00
	TOTAL LABOU	R			\$	2,220.00
	ESTIMATE TOTA	AL.			\$	7,570.10
	This is an initial estimate based on a visual inspection of		1:1 701	6 1 .	=	

## COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Bratidal Post Shoesow 519701

Marrine +65 6383 6380 Fecamile -65 6380 (1)

Service Centres

9 Bruddet Road Sindapor v (1910) Pundan Road Singapore 609280 Singer Kanut Vew Signapore 72870

59 Upsing Drive Singapore 5086 780 Sen Ming Drive Singapore 51 020 Uci Road 3 Singapore 1086





## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition					
0.11	Received: 1524	3. Vehicle Type:		A. Time of Tandari	
2. New SPA Name of Customer : YY	Private Taxi (CTPL/CCPL) Fleet STK (Boon Lay)		4. Type of Towing: Normal Tow King Dolly Flat Bed Crane-up		
Vehicle No. : SHA  Make/Model/Colour: SON  Email :	5. Nature of Service;  Jumpstart  Recovery  Change Tyre / Batte	ery	6. Parts Replaced/Remarks:		
0 0	est St 65	8		v - In Workshop:	
9. Preferred Workshop:  Braddell Loyang Sin Ming Sungei K Senoko Komoco Others:	adut (UBI / Leng Kee)	Pandan Ubi Cycle & Carriage (PD)	Overhe	eating Steering Faulty Faulty Alternator Faulty g Problem Loss Power ent Engine Stalled	
10. Odometer Reading :	77613 F 1/4 1/2 3/4 E	11. Radio / CD Pla OK Faulty Not test		FECHI	
12. Tow Truck / Recovery Van : Name of Driver : Vehicle No. : Time Dispatch : Time of Arrival : Time Completed :	VRS QA GAC MUDUGAN YIC 985D 1524 1600	TZ YISHUN TOWING	OTHERS	#: Cracked X: Dedd /: Scatched O: Missing Signature of Customer	
Cash Invoice Details (if applicat				Signature of Gustomer	
13. Cash Invoice No. :					
Customer Acknowledgement					
a. I have been advised to remove all valual cash cards, spectacles, pen, etc. b. I understand that any items left behind c. Surcharge: Towing fee will be levied if the surcharge and the surcha	are at my own risk and SPARK	Car CaroTM will not be held lieble	for such loss in SPARK Ca		
Name of Attending Staff/Guard	Date & Time of A	Arrival .	Signature of	f Attending Staff/Guard	