



## Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

### General Details

**Involving**

69 2008 TOYOTA HIACE MANUAL TOYXXX (GBB1479L)

**Date of Loss**

13 January 2018

**Time of Loss**

10.00

**Loss Description**

GBB1479L (INSD) C/W SLM1133H (TP)

**Comment**

### Workshop Details

**Total Rebate Amount**

632

**Nett Loss Amount**

\$12,368.00

**Assigned Workshop**

LKK AUTO CONSULTANTS PTE LTD (OD)

**Target Date of Completion \***

17/09/2018

**Days of work completion \***

230



<< **Assessment Details**

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#

Registration State

Mileage

Purchase Date

Registration Date \*

Age of Vehicle

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2008	<input type="text" value="2008"/>
Make	TOYOTA HIACE MANUAL	<input type="text" value="TOYOTA"/>
Model	TOYXXX	<input type="text" value="HIACE MANUAL"/>
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	JTFHT02P800029905	<input type="text" value="JTFHT02P800029905"/>
Engine No	1KD1853340	<input type="text" value="1KD1853340"/>
Engine Capacity		<input type="text" value="2982"/>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	SAZLINDA BTE HASHIM	<input type="text"/>
Date of Birth	27 May 1974	<input type="text" value="dd/mm/yyyy"/>
Age	44	
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	0	
Driver License #		<input type="text"/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="13000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	BLK 110 JURONG EAST, 600110, Singapore	<input type="text" value=""/>
Address type	Personal Correspondence	<input type="text" value=""/>
Gender	Female	<input type="text" value=""/>
Marital status	Unknown	<input type="text" value=""/>
Identification #	S7416536B	<input type="text" value=""/>



<< **Assessment Details**

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *	<input type="text" value="31/01/2018"/>	
Total Loss	<input type="radio"/> Yes <input type="radio"/> No	
Towing Charges	<input type="text" value="0"/>	
Voluntary Excess	<input type="text" value="0"/>	
Compulsory Excess	<input type="text" value="600"/>	
Young/Inexperienced/Unarmed Driver Excess	<input type="text" value="0"/>	
Other Excess	<input type="text"/>	

Condition of Vehicle at time of survey

General condition	<input type="text" value="Good"/>
Steering (Serviceable)	<input type="radio"/> Yes <input type="radio"/> No
Footbrake (Serviceable)	<input type="radio"/> Yes <input type="radio"/> No
Handbrake (Serviceable)	<input type="radio"/> Yes <input type="radio"/> No
Engine Modification	<input type="radio"/> Yes <input type="radio"/> No
Pre-accident condition	<input type="text" value="Good"/>

Tyre Condition

Age of Tyres	<input type="text"/>
Front Tyre Size	<input type="text" value="195/80R15"/>
Front left side	<input type="text" value="BRIDGESTONE8mm"/>
Front right side	<input type="text" value="BRIDGESTONE8mm"/>
Spare wheel	<input type="text"/>
Rear Tyre Size	<input type="text" value="195/80R15"/>
Rear left side	<input type="text" value="BRIDGESTONE8mm"/>
Rear right side	<input type="text" value="BRIDGESTONE8mm"/>

## << Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

# Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary   **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT BUMPER			Deformed	220				220	Reviewing	
		2	1			FRONT BUMPER BRACKET LH			Damaged	80				80	Reviewing	
		3	1			FRONT BUMPER BRACKET RH			Damaged	80				80	Reviewing	
		4	1			FRONT BUMPER TOW HOCK COVER LH			Damaged	10				10	Reviewing	
		5	1			FRONT BUMPER TOW HOCK COVER RH			Damaged	10				10	Reviewing	
		6	1			FRONT BUMPER FOG LAMP LH			Serviceable	0	0	0	0	0	Deny	
		7	1			FRONT BUMPER FOG LAMP RH			Serviceable	0	0	0	0	0	Deny	
		8	1			FRONT BONNET HINGE LH			Repair	0	0	0	0	0	Deny	
		9	1			FRONT BONNET HINGE RH			Repair	0	0	0	0	0	Deny	
		10	1			FRONT BONNET			Repair	0	0	0	0	0	Deny	
		11	1			FRONT DOOR LH			Dented	650				650	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		12	1			FRONT DOOR RH			Repair	0	0	0	0	0	Deny	
		13	1			FRONT DOOR PILLAR LH			Dented	330				330	Reviewing	
		14	1			FRONT DOOR PILLAR 2ND LAYER			Repair	0	0	0	0	0	Deny	
		15	1			FRONT DOOR HINGE UPPER LH			Repair	0	0	0	0	0	Deny	
		16	1			FRONT DOOR HINGE LOWER LH			Repair	0	0	0	0	0	Deny	
		17	1			FRONT DOOR CHECK LH			Serviceable	0	0	0	0	0	Deny	
		18	1			FRONT DOOR PILLAR RH			Repair	0	0	0	0	0	Deny	
		19	1			FRONT DOOR HINGE UPPER RH			Repair	0	0	0	0	0	Deny	
		20	1			FRONT DOOR HINGE UPPER LH			Repair	0	0	0	0	0	Deny	
		21	1			FRONT DOOR STEP COVER LH			Damaged	95				95	Reviewing	
		22	1			FRONT DOOR STEP COVER RH			Damaged	95				95	Reviewing	
		23	1			FRONT DOOR STEP PANEL RH			Bent	125				125	Reviewing	
		24	1			LH SIDE DOOR			Dented	750				750	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		25	1			RH SIDE DOOR			Dented	750				750	Reviewing	
		26	1			AIR COND SUCTION HOSE			Bent	210				210	Reviewing	
		27	1			AIR COND DISCHARGE HOSE			Bent	195				195	Reviewing	
		28	1			AIR FILTER BOX ASSY			Damaged	340				340	Reviewing	
		29	1			REAR BUMPER			Deformed	230				230	Reviewing	
		30	1			REAR BUMPER BRACKET LH			Necessary	45				45	Reviewing	
		31	1			REAR BUMPER BRACKET RH			Necessary	45				45	Reviewing	
		32	1			REVERSE SENSOR			Shorted	180				180	Reviewing	
		33	1			REAR FENDER RH			Repair	0	0	0	0	0	Deny	
		34	1			FRONT EXHAUST PIPE			Bent	2600				2600	Reviewing	
		35	1			REAR EXHAUST PIPE			Repair	0	0	0	0	0	Deny	
		36	1			FRONT NUMBER PLATE			Damaged	30				30	Reviewing	
		37	2			DOOR COMPANY STICKER			Necessary	15				30	Reviewing	
		38	1			RH SIDE DOOR FLOOR PANEL			Bent	330				330	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	39	1			RH SIDE DOOR FLOOR PANEL 2ND LAYER			Bent	250				250	Reviewing	
	40	1			RH SIDE DOOR INNER BOARD			Serviceable	0	0	0	0	0	Deny	
	41	1			FRONT SUPPORT PANEL			Repair	0	0	0	0	0	Deny	
	42	1			RADIATOR LOWER SUPPORT PANEL			Bent	220				220	Reviewing	
	43	1			AIR COND CONDENSER			Bent	580				580	Reviewing	
	44	1			RADIATOR ASSY			Bent	590				590	Reviewing	
	45	1			RADIATOR HOSE UPPER			Serviceable	0	0	0	0	0	Deny	
	46	1			RADIATOR HOSE LOWER			Damaged	30				30	Reviewing	
	47	1			RADIATOR FAN COVER			Damaged	125				125	Reviewing	
	48	1			RADIATOR FAN MOTOR			Serviceable	0	0	0	0	0	Deny	
	49	1			AIRCOND FAN MOTOR			Serviceable	0	0	0	0	0	Deny	
	50	1			RADIATOR FAN BLADE			Serviceable	0	0	0	0	0	Deny	
	51	1			AIR COND FAN BLADE			Serviceable	0	0	0	0	0	Deny	
	52	1			COOLANT			Necessary	30				30	Reviewing	

Labour

Add Approve Deny Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	1		PANEL BEATING & BODY WORK	2200	0	0	Reviewing		
 	2		SPRAY PAINT	1600	0	0	Reviewing		
 	3		TOWING FEE	120	0	0	Reviewing		

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	1	DAYS OF REPAIR : 12 DAYS	Reviewing			

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$12,575.00

Claim Amount \$12,575.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$3,920.00	\$3,920.00
Excess	-\$600.00	-\$600.00
Spare Parts	\$9,255.00	\$9,255.00

Submit for Review

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	10000	

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$9,400.00

Claim Amount \$9,400.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$10,000.00	\$10,000.00
Excess	-\$600.00	-\$600.00

Submit for Review