

ASS. REC. BY:

REF: CS / msc(1800)1825 / Arb02

Special instruction:

Surveyor:

ASSIGNMENT (Office)

Mejimen

From (Person): Monica Chung

of msh

Date/Time: 30/12/18 3:41pm

Estimated Cost:

Bill to:

OD / FP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: (7BD) 867X

Insured: SLS 4598Z

at Workshop m/s Ho Beng

Tel:

of Bk 3020A Ubi Rd 1 #01-33

Policy No: A804446908MY

Claim No: 547746

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 25/12/18

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 30/12/18 3:59pm

Person Contacted: Chris

Vehicle: D/L0BT

Date/Time	Action/Instruction (✓) Estimate
	(7BD) 867X - NA / ZNC17021700/24
	SLS 4598Z - X
31/1/18	Sent pending est from repairer thru email
	Sent preli thru mejimen

DA: 131117



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001825/Arb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 30-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLS 4598Z	Veh. Inspected	GBD 867X
Policy No.	A80444690QMY	Coverage (\$)	0.00
Claim No.	547746	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/01/2018	Inspection Date	30/01/2018
Survey held at	HO BENG TRADING BLK 3020A, UBI ROAD 1 #01-33 SINGAPORE 408714		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jan 2018		30 Jan 2018 15:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	WANG ZHENYU, ID: S76676251, Tel: +6590489185, Email: JAMESRILI.WANG@GMAIL.COM	
Main Claimant:	DCSRIVER ENGINEERING & TRADING, Co. Reg. No.: 53137304E	
Vehicle Reg. No.:	GBD867X	Date of Loss: 25/01/2018 20:00 - :59
Claim Type:	TP / 547746	Policy/Cover Note No.: A80444690QMY (Comprehensive) Coverage: 06/10/2017 - 05/10/2018
Vehicle Reg. No. (Insured):	SLS4598Z	Policy No. (Claimant):
		Excess: S\$500.00
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2018]	
Driver/Custodian (Insured):	WANG ZHENYU (41 / Male), NRIC: S76676251, Tel: +6590489185	
Adj Asg. Remarks:	assign to Adrian	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Print Sent Message

This mail is associated with :

*GBD867X (547746)
[SLS4598Z]

TP
DCSRIVER ENGINEERING & TRADING
Jan 25 2018 8:00PM
[WANG ZHENYU]
Ho Beng Trading

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 31/01/2018 12:36 PM.
To monica_chung@sg.msig-asia.com; MSIG_SG
CC sur@lkkauto.com
Subject GBD867X (547746)

Dear Monica,

Please be informed that we have inspected the vehicle **GBD 867X** on 29/01/2018
We are pending estimate from repairer.

Thank you.

Regards,
Janice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 02 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLS4598Z	Accident Date	: 25/01/2018
TP Vehicle No	: GBD867X	Assignment Date	: 30/01/2018
Make	: TOYOTA HIACE	Est. Duration of Repair	: 3.00
Date of Inspection	: 29/01/2018		
Inspection At	: HO BENG TRADING (HQ) BLK 3020A #01-33, UBI ROAD 1 SINGAPORE 408714		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,366.93
Revised Amount	:S\$	2,023.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,023.44
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 7304E

Vehicle Details

Vehicle No.: GBD867X

Vehicle to be Exported: Yes

Intended De-registration Date: 29 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR MANUAL

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 1KD2410796

Chassis No.: JTFHT02PX00142500

Maximum Power Output: -

Open Market Value: \$27,502.00

Original Registration Date: 12 Jun 2014

First Registration Date: 12 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$1,376.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Jun 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$40,889.00

COE Rebate Amount: \$26,043.00

Total Rebate Amount: \$26,043.00

The information contained herein is correct as at 29 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2018 14:08
Date Of Accident	25/01/2018 19:25
Exact Location Of Accident	TPE TWDS SLE NEAR PUNGGOL EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD867X
Insured/Policyholder	
Name Of Registered Owner	DCSRIVER ENGINEERING & TRADING
Co Reg No	53137304E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92280272

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	AFTER WORK OTW BACK HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072148643-02
Cover Note Number	-

Driver

Name of Driver	KOH HAK SIO
NRIC No	S7011899H
Date Of Birth	08/04/1970
Occupation	OUTDOOR
Date Of Driving Pass	29/01/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92280272
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 128 RIVERVALE ST #07-820
Postcode	540128
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	AFTER RAINED
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG TPE TWDS SLE NEAR PUNGGOL EXIT ON THE SECOND LANE FROM THE RIGHT, ALL OF A SUDDEN, VEH B (BEARING NO SLS4598Z) FROM LEFT LANE LOST CONTROL SWERVED INTO MY LANE. AS THE RESULT, HEAD ON HIT ONTO MY VEH FRONT PORTION. AFTER THE IMPACT, A LORRY COME FROM THE LEFT LANE ALSO HIT ONTO THE VEH B RIGHT HAND SIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SLS4598Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WANG ZHENYU
NRIC/Passport Number	S7667625I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XE3468D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Please Refer to Statement

DECLARATION

DCSRIVER ENGINEERING & TRADING
128 Rivervale Street # 07-820
Singapore 540128
HP: 9228 0272

I/we declare the particulars are true in every respect

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
 Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
 Email : chris_chanbebe@hotmail.com

DCSRIVER ENGINEERING & TRADING
 BLOCK 3020A UBI ROAD 1
 # 01-33
 Singapore 408714

29th JANUARY 2018

TPMS14.
 Janice

JTFHT02PX00142500

Accident date: 25th January 2018
 Estimated repair cost for vehicle no: GBD867X TOYOTA HIACE '14

S/n	Qty	Items	U/price	Amount
1	2	Front head lamp LH correct	\$360.40	\$720.80 36040
2	2	head lamp bracket	\$92.50	\$185.00 x
3	1	front panel		\$1,169.90 x
4	1	Front bumper Del		\$634.58 ✓
5	2	Front bumper side bracket	\$38.20	\$76.40 ✓
6	8	Front bumper clips	\$12.90	\$103.20 30
7	1	front bumper center moulding		\$188.20 x
8	1	front bumper number plate		\$50.00 30(500)
9	2	front bumper bracket	\$185.00	\$370.00 +
10	1	Front bumper reinforcement		\$420.20 ✓
11	2	Front bumper fog lamp	\$155.20	\$310.40 x
12	1	Front grille		\$454.25 ✓
13	1	front grille logo		\$42.10 ✓
14	1	Front air cond condenser		\$1,371.80 +
15	1	front water tank		\$0.00 +
16	1	Front support panel		\$420.00 +
17	1	front support garnish		\$120.10 x

Subtotal :- \$6,636.93

2017 93

S.N. 30

151344

<u>Labour charges</u>		
To Remove & refix air-con condenser & top up gas		\$380.00 X
To Check Wiring System		\$80.00 30
Tuff kote		\$120.00 X
WHEEL alignment (computer)		\$150.00 X
Panel beating	480	\$1,000.00 200
Spray painting		\$1,000.00 250
		Subtotal :- <u>\$2,730.00</u>
		Total:- <u>\$9,366.93</u>

total: 2023.44
 4/2: 1.6K
 030yr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001825/ARBN2
Date: 06/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80444690QMY
Claimant Vehicle No :	GBD867X	Insured Vehicle No :	SLS4598Z
Date of Loss:	25/01/2018	Nature of Claim:	TP
			Claim No: 547746

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD867X	Engine No:	1KD2410796
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02PX00142500
Reg. Date:	12/06/2014 (Man. Year: 2014)	Odometer:	116036 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80R16	Rear Tyre Size:	195/80R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,636.93	1,543.45	5,093.48	76.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	480.00	2,250.00	82.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,366.93	2,023.45	7,343.48	78.40
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	9,366.93	1,600.00	7,766.93	82.92

INSPECTION

Date of Assignment:	30/01/2018		
Date Inspected:	29/01/2018	Inspected At:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1 Singapore 408714

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 06 Mar 2018)
Parts:	N/A TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD867X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP	N/s Cracked	720.80 F	*360.40 FL
2	2		*HEAD LAMP BRACKET	Not Necessary	185.00 F	*- FL
3	1		*FRONT PANEL	Not Necessary	1,169.90 F	*- FL
4	1		*FRONT BUMPER	Deformed	634.58 F	*634.58 FL
5	2		*FRONT BUMPER SIDE BRACKET	Necessary	76.40 F	*76.40 FL
6	8		*FRONT BUMPER CLIPS	Necessary	103.20 F	*30.00 FL
7	1		*FRONT BUMPER CENTER MOULDING	Not Necessary	188.20 F	*- FL
8	2		*FRONT BUMPER BRACKET	Not Necessary	370.00 F	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	420.20 F	*420.20 FL
10	2		*FRONT BUMPER FOG LAMP	Not Necessary	310.40 F	*- FL
11	1		*FRONT GRILLE	Cracked	454.25 F	*454.25 FL
12	1		*FRONT GRILLE LOGO	Necessary	42.10 F	*42.10 FL
13	1		*FRONT AIR COND CONDENSER	Not Necessary	1,371.80 F	*- FL
14	1		*FRONT WATER TANK (NPA)	Not Necessary	0.00 F	*- FL
15	1		*FRONT SUPPORT PANEL	Not Necessary	420.00 F	*- FL
16	1		*FRONT SUPPORT GARNISH	Not Necessary	120.10 F	*- FL
17	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,636.93	2,047.93
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	504.48
Total Parts (\$\$)	6,636.93	1,543.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX AIR-CON CONDENSER & TOP UP GAS	New	380.00	-
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TUFF KOTE	New	120.00	-
4	WHEEL ALIGNMENT (COMPUTER)	New	150.00	-
5	PANEL BEATING	New	1,000.00	200.00
6	SPRAY PAINTING	New	1,000.00	250.00
Gross Labour Cost (\$\$)			2,730.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >