

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI18001840/Sd3et

Special Instruction:

Survivor:

Sebastian

Menmen

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

30/1/18 @ 3:07pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFW 3007U

Insured:

GBE 8844D

at Workshop m/s

Sheng Koon Motor

Tel:

G382 1939

of

393 Woodlands Rd, Blk D4 Yew Tee Ind. Est.

Policy No:

DMCVSN3098711700

Claim No:

SNM18D00520C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/01/2018

31/01/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

3:49pm @ 30/1/18

Person Contacted:

Eric

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SFW 3007U - NA / INC 11021908 / W1W1

D.O.A: 06/10/2011

GBE 8844D - X

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFW 30074 Yr Regn: 2005 / Jun 30Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios 1.5E (A) C.C. 1497Colour: Black A/C: Insured / Std / NI / NASp. Reading: No Display T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MK053HY4204139547Gen. Cond: Good / Poor / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: MV / S/Rim / STD A/Rim orTyre Size: F: 185/65R14R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 23/1/18

Survey held at

Sheng Koon

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 30/1/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$8,500 - \$9,800

8 days

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 8Resurvey No. of Trip: 1

Survey Fee:

150

Transportation:

) \$ + PS. \$

) Photos

) Others

TOTAL

150

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: PR2

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		30 Jan 2018 15:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ZENG KENG BOO , ID: S1628769E		
Vehicle Reg. No.:	SFW3007U	Date of Loss:	23/01/2018 00:00 - :59
Claim Type:	TP / SNM18D00520C02	Policy/Cover Note No.:	DMCVSN3098711700
Vehicle Reg. No. (Insured):	GBE8844D	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Sheng Khoon Motor Service (HQ) 393 WOODLANDS ROAD BLK D4 YEW TEE IND EST, 677972 Woodlands - Tel: 63821939		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/02/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



AMY LIM LAW PRACTICE

High Street Centre
1 North Bridge Road
#08-08
Singapore 179094
T: 9625 8742 / 9639 3110
F: 6491 5638
UEN: 53361230J
We do not accept service by fax

Our Ref: 2018.1060.PD.SKM
Your Ref: GBE8844D

26 JAN 2018

China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Department

BY FAX: (6224 7478) ONLY

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION

CLAIMANT: ZENG KENG BOO
TRAFFIC ACCIDENT ON 23 JANUARY 2018 AT 08:00 HRS ALONG PIE
TOWARDS TUAS INVOLVING VEHICLES NO. SFW3007U & GBE8844D

We are instructed by Zeng Keng Boo to notify you of a road accident on 23 January 2018 at about 08:00 along PIE towards Tuas involving our client's vehicle registration number SFW3007U and vehicle registration number GBE8844D driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: **Sheng Khoon Motor Service**
Address: 393 Woodlands Road
Yew Tee Industrial Estate
Singapore 677972
Contact: Eric @ 6392 1939

Please liaise with the above workshop directly.

Yours faithfully


Esther Moey
Email: claims@esthermoey.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8769E
Vehicle Details	
Vehicle No.:	SFW3007U
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Black
Manufacturing Year:	2005
Engine No.:	1NZX290733
Chassis No.:	MR053HY4204139547
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,305.00
Original Registration Date:	30 Jun 2005
First Registration Date:	30 Jun 2005
Transfer Count:	1
Actual ARF Paid:	\$13,536.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$33,054.00
COE Rebate Amount:	\$13,533.00
Total Rebate Amount:	\$13,533.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Jun 2018

OK






































...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2018		30 Jan 2018 15:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: ZENG KENG BOO , ID: S1628769E									
Vehicle Reg. No.:	SFW3007U	Date of Loss:	23/01/2018 00:00 - :59 [150 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D00520C02	Policy/Cover Note No.:	DMCVSN3098711700						
Vehicle Reg. No. (Insured):	GBE8844D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Sheng Khoon Motor Service (HQ) 393 WOODLANDS ROAD BLK D4 YEW TEE IND EST, 677972 Woodlands - Tel: 63821939								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 08/02/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFW3007U (SNM18D00520C02)
 [GBE8844D]
 TP
 ZENG KENG BOO
 Jan 23 2018 12:00AM
 [-]
 Sheng Khoon Motor Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
34	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
43	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
44	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
45	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
46	31/05/18 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
47	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	31/05/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/18 15:06	PRS	 Load PDF	
2	19/02/18 15:41	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18001840/SD3E2

Date: 14/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3098711700

Claimant Vehicle
No : SFW3007UInsured Vehicle
No : GBE8844D

Date of Loss: 23/01/2018

Nature of Claim: TP

Claim
No: SNM18D00520C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFW3007U

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX290733

Reg. Date: 30/06/2005 (Man. Year: 2005)

Chassis No: MR053HY4204139547

Colour: Black

Odometer: 0 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2018

Date Inspected: 30/01/2018 Inspected At:

Sheng Khoon Motor Service (HQ)
393 WOODLANDS ROAD BLK D4 YEW
TEE IND EST
Singapore 677972

Estimated Period of Repair: 8.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500.00 - \$9,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2018)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFW3007U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >