

Claim Reference:

Assessment Number: SH000200

Version: S&HMOTOR/1

Date Calculated: 30/01/2018 09:47

Full Report - 1

Registration: SDX71

Printed: 30/01/2018 17:14

Sub Total	96.8HRS	\$4,452.80
Paint Labour	20.9HRS	\$961.40
Total Labour	117.7HRS	\$5,414.20

PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR. Price = \$46.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC			
	- PREPARE OFF VEHICLE			
1481	LEFT FRONT DOOR NEW PART PAINTING		13.0	
1781	L/R DOOR NEW PART PAINTING		13.0	
2279	L/OUTER B-PILLAR NEW PART PAINTING		14.0	
3481	L/R WING NEW PART PAINTING		26.0	
1563	L/F DOOR OUT HANDLE NEW PART PAINT K1R		3.0	
1739	L/DOOR MIRROR HSG NEW PART PAINT K1R		3.0	
1863	L/R DOOR OUT HANDLE NEW PART PAINT K1R		3.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R		12.0	
2101	L/SILL PANEL REPAIR PAINTING <50%		9.0	
2227	L/OUTER A-PILLAR REPAIR PAINTING <50%		12.0	
2351	ROOF REPAIR PAINTING <50%		23.0	
2353	L/ROOF COVER PANEL REPAIR PAINTING <50%		8.0	
741	L/F WING SURFACE PAINT		5.0	
2207	L/SILL PANNELLING SURFACE PAINT PLAST.		6.0	
2711	LWR REAR CENTRE PARTS SURFACE PAINT		6.0	
2931	BOOTLID/TAI LGATE SURFACE PAINT		9.0	
3482	R/R WING SURFACE PAINT		7.0	
4101	L/INNER C-PILLAR SURFACE PAINT		5.0	

LABOUR COST - PAINT

TIME(PAINT)	179.0
Preparation Main Work Plastic	5.0
Preparation Main Work Metal	25.0
Preparation Work Multi Layer Paint	0.0
Total Work Units (10WU/HR)	209.0
Total Paintwork Labour	20.9HRS

MATERIAL COST - PAINT

New Part Painting	\$961.40
New Part Painting - Plastic K1R	\$119.30
Material-Constant Main Work Metal	\$64.90
Surface-/Blend Paint	\$28.50
Surface Paint Plastic	\$68.20
Repair Painting	\$18.40
Material-Const Main Work Plastic	\$77.10
Total Excluding Pearlescent Uplift	\$9.00
Pearlescent Uplift @ 0.0%	\$384.40
Total Paint Material Cost	\$384.40

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/201	Set.	Price (\$)
1479	①	L/F DOOR MODULE (Crew)	212 720 1579		0%	✓	420.00
1481	1	LEFT FRONT DOOR	204 720 0105	SA	0%	✓	1,050.00
1487	1	L/F UPPER DOOR HINGE	204 720 1537	SA	0%	✓	110.00
1495	1	L/F LOWER DOOR HINGE	204 720 1737	SA	0%	✓	110.00
1509	1	L/F DOOR SEAL	204 727 1187	SA	0%	✓	170.00

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000200

Version: S&HMOTOR/1

Date Calculated: 30/01/2018 09:47

Full Report - U

Registration: SDX72

Printed: 30/01/2018 17:4

1519	1	L/F DOOR WINDOW	204 725 0700	0%	✓	230.00*
1563	1	L/F DOOR OUT HANDLE	204 760 0170 9999	0%	✓	293.00*
1567	1	L/F OUT HANDLE PLATE	204 760 2534	0%	✓	128.00*
1577	1	L/F DOOR LOCK	204 720 1735	0%	✓	190.00*
1581	1	L/F DOOR STRIKER	204 720 0104	0%	✓	95.00*
1597	1	L/F WINDOW CHANNEL	204 725 1525	0%	✓	195.00*
1655	1	L/F DOOR TRIM REAR	204 690 2587	0%	✓	95.00*
1661	1	L/F OUT WINDOW SEAL	204 725 1565	0%	✓	95.00*
1671	1	L/F UPPER DOOR TRIM	204 725 0171 9051	0%	✓	235.00*
1681	1	L/F DOOR MOULDING	204 720 0180	0%	✓	70.00*
1729	1	L/F MOUNTING KIT	USE SINGLE PARTS	0%	✓	30.00*
1745	1	L/MIRROR BASE	204 810 3976	0%	✓	1,350.00*
1777	1	L/F DOOR FRAME SEAL	204 697 0951	0%	✓	115.00*
			9B00			
1781	1	L/R DOOR	204 730 2100	0%	✓	1,180.00*
1791	1	L/R UPPER DOOR HINGE	204 730 1037	0%	✓	118.00*
1793	①	L/R DOOR MODULE (Clean)	212 730 1779	0%	✓	420.00*
1795	1	L/R LWR DOOR HINGE	204 730 1237	0%	✓	110.00*
1809	1	L/R DOOR SEAL	204 727 1187	0%	✓	170.00*
1819	1	L/R DOOR WINDOW	204 735 0300	0%	✓	230.00*
1847	1	L/R QUARTER GLASS	204 730 3500	0%	✓	37.45L
1849	1	RR D/WDW BONDING KIT	000 670 0100	0%	✓	51.75L
1863	1	L/R DOOR OUT HANDLE	204 760 0170 9999	0%	✓	230.00*
1877	1	L/R DOOR LOCK	204 730 3935	0%	✓	190.00*
1897	1	L/R WINDOW CHANNEL	204 735 2125	0%	✓	195.00*
1961	1	L/R DOOR WINDOW SEAL	204 735 1565	0%	✓	95.00*
1971	1	L/R WDW FRAME TRIM	204 735 0171 9051	0%	✓	235.00*
1981	1	L/R DOOR MOULDING	204 730 0180	0%	✓	70.00*
2029	1	L/R MOUNTING KIT	USE SINGLE PARTS	0%	✓	30.00*
2063	1	L/R DOOR FRAME SEAL	204 697 0151	0%	✓	115.00*
			9B00			
2279	1	L/OUTER B-PILLAR	204 637 1924	0%	✓	780.00*
2583	1	REAR BUMPER COVER	204 885 1025 9999	0%	✓	950.00*
2615	1	CTR REAR BUMPER MLDG	204 885 0421	0%	✓	95.00*
2617	1	L/R BUMPER MOULDING	204 885 0921	0%	✓	80.00*
2618	1	R/R BUMPER MOULDING	204 885 1021	0%	✓	80.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	0%	✓	35.00*
3281	1	L/R LAMP ASSY	204 906 8502	0%	✓	350.00*
3481	1	L/R WING	204 630 0921	0%	✓	1,150.00*
3677	1	L/R WHL-HOUSE COVER	204 690 2330	0%	✓	110.00*
1000	1	DOOR FRAME STICKER	LH front door	0%	✓	120.00*
1000	1	DOOR FRAME STICKER	LH front door	0%	✓	120.00*
1000	1	HANDLE INNER BRACKET	LH front door	0%	✓	95.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

Sundry Parts

Total Parts

(5 %)

(Fixed)

\$62,224.20

\$611.21

\$100.00

\$12,935.41

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description

SPECIALIST

Betterment

0%

Price

AUDATEX FEES

INNER RUBBER SEAL REAR WINDSCREEN

✓

✓

\$42.00

\$38.00

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000200

Version: S&HMOTOR/1

Date Calculated: 02/03/2018 04:51

Full Report - V1

Registration: SDK72L

Printed: 02/03/2018 12:58

Sub Total	96.8HRS	\$4,452.80
Paint Labour	20.9HRS	\$961.40
Total Labour	117.7HRS	\$5,414.20

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1481	LEFT FRONT DOOR NEW PART PAINTING	15.0	
1781	L/R DOOR NEW PART PAINTING	13.0	
2279	L/OUTER B-PILLAR NEW PART PAINTING	14.0	
3481	L/R WING NEW PART PAINTING	26.0	
1563	L/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0	
1739	L/DOOR MIRROR HSG NEW PART PAINT K1R	3.0	
1863	L/R DOOR OUT HANDLE NEW PART PAINT K1R	3.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	12.0	
2101	L/SILL PANEL REPAIR PAINTING <50%	9.0	
2227	L/OUTER A-PILLAR REPAIR PAINTING <50%	12.0	
2351	ROOF REPAIR PAINTING <50%	23.0	
2353	L/ROOF COVER PANEL REPAIR PAINTING <50%	8.0	
741	L/F WING SURFACE PAINT	5.0	
2207	L/SILL PANELLING SURFACE PAINT PLAST.	6.0	
2711	LWR REAR CENTRE PARTS SURFACE PAINT	6.0	
2931	BOOTLID/TAILGATE SURFACE PAINT	9.0	
3482	R/R WING SURFACE PAINT	7.0	
4101	L/INNER C-PILLAR SURFACE PAINT	5.0	
LABOUR COST - PAINT			
TIME(PAINT)		179.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		209.0	
Total Paintwork Labour		20.9HRS	\$961.40
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$119.99
New Part Painting - Plastic K1R			\$64.94
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$68.23
Surface Paint Plastic			\$16.47
Repair Painting			\$77.19
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$384.42
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$384.42

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
1479	1	L/F DOOR MODULE	212 720 1579		420.00*
1481	1	LEFT FRONT DOOR	204 720 0105		1,050.00*
1487	1	L/F UPPER DOOR HINGE	204 720 1537		110.00*
1495	1	L/F LOWER DOOR HINGE	204 720 1737		110.00*
1509	1	L/F DOOR SEAL	204 727 1187		170.00*

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000200

Version: S&HMOTOR/1

Date Calculated: 02/03/2018 04:51

Full Report - V1

Registration: SDK72L

Printed: 02/03/2018 12:58

1519	1	L/F DOOR WINDOW	204 725 0700	0%	230.00*
1551	1	L/F WINDOW MOTOR	212 906 6802	0%	285.00*
1563	1	L/F DOOR OUT HANDLE	204 760 0170 9999	0%	295.00*
1567	1	L/F OUT HANDLE PLATE	204 760 2534	0%	125.00*
1577	1	L/F DOOR LOCK	204 720 1735	0%	190.00*
1581	1	L/F DOOR STRIKER	204 720 0104	0%	95.00*
1597	1	L/F WINDOW CHANNEL	204 725 1525	0%	195.00*
1655	1	L/F DOOR TRIM REAR	204 690 2587	0%	95.00*
1661	1	L/F OUT WINDOW SEAL	204 725 1565	0%	95.00*
1671	1	L/F UPPER DOOR TRIM	204 725 0171 9051	0%	265.00*
1681	1	L/F DOOR MOULDING	204 720 0180	0%	70.00*
1729	1	L/F MOUNTING KIT	USE SINGLE PARTS	0%	30.00*
1745	1	L/MIRROR BASE	204 810 3976	0%	1,050.00*
1777	1	L/F DOOR FRAME SEAL	204 697 0951	0%	115.00*
			9B00		
1781	1	L/R DOOR	204 730 2100	0%	1,180.00*
1791	1	L/R UPPER DOOR HINGE	204 730 1037	0%	110.00*
1793	1	L/R DOOR MODULE	212 730 1779	0%	420.00*
1795	1	L/R LWR DOOR HINGE	204 730 1237	0%	110.00*
1809	1	L/R DOOR SEAL	204 727 1187	0%	170.00*
1819	1	L/R DOOR WINDOW	204 735 0300	0%	230.00*
1847	1	L/R QUARTER GLASS	204 730 3500	0%	38.69U
1849	1	RR D/WDW BONDING KIT	000 670 0100	0%	51.75U
1851	1	L/R WINDOW MOTOR	204 820 0542	0%	285.00*
1863	1	L/R DOOR OUT HANDLE	204 760 0170 9999	0%	280.00*
1877	1	L/R DOOR LOCK	204 730 3935	0%	190.00*
1897	1	L/R WINDOW CHANNEL	204 735 2125	0%	195.00*
1961	1	L/R DOOR WINDOW SEAL	204 735 1565	0%	95.00*
1971	1	L/R WDW FRAME TRIM	204 735 0171 9051	0%	265.00*
1981	1	L/R DOOR MOULDING	204 730 0180	0%	70.00*
2029	1	L/R MOUNTING KIT	USE SINGLE PARTS	0%	30.00*
2063	1	L/R DOOR FRAME SEAL	204 697 0151	0%	115.00*
			9B00		
2279	1	L/OUTER B-PILLAR	204 637 1924	0%	780.00*
2583	1	REAR BUMPER COVER	204 885 1025 9999	0%	950.00*
2615	1	CTR REAR BUMPER MLDG	204 885 0421	0%	95.00*
2617	1	L/R BUMPER MOULDING	204 885 0921	0%	80.00*
2618	1	R/R BUMPER MOULDING	204 885 1021	0%	80.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	0%	35.00*
3281	1	L/R LAMP ASSY	204 906 8502	0%	350.00*
3481	1	L/R WING	204 630 0921	0%	1,150.00*
3677	1	L/R WHL-HOUSE COVER	204 690 2330	0%	110.00*
1000	1	DOOR FRAME STICKER	LH front door	0%	120.00*
1000	1	DOOR FRAME STICKER	LH front door	0%	120.00*
1000	1	HANDLE INNER BRACKET	LH front door	0%	95.00*
1000	1	LH PILLAR SOCKET	LH centre pilla	0%	165.00*
1000	1	DOOR PILLA HINGE TOP	LH rear door	0%	125.00*
1000	1	DOOR PILLA HINGE LWR	LH rear door	0%	125.00*
1000	1	WINDOW METAL CHANNEL	LH rear door	0%	115.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

Sundry Parts

Total Parts

(5 %)

(Fixed)

\$13,325.44

\$666.27

\$100.00

\$14,091.71

S & H Motor Pte Ltd**Claim Reference:****Assessment Number: SH000200****Version: S&HMOTOR/1****Date Calculated: 02/03/2018 04:51****Full Report - V1****Registration: SDK72L****Printed: 02/03/2018 12:58****NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER****Extras**

Description	Betterment	Price
AUDATEX FEES SPECIALIST	0%	\$42.00
INNER RUBBER SEAL REAR WINDSCREEN		\$38.00
SEALANT REAR WINDSCREEN	0%	\$80.00
ECU DIAGNOSTIC SPECIALIST		\$180.00
WHEEL ALIGNMENT SPECIALIST	0%	\$65.00
QUA GLASS INNER LH REAR DOOR SEAL		\$18.00
QUA GLASS SEALANT LH REAR DOOR	0%	\$30.00
SOUNDPROOF LH FRONT DOOR STICKER		\$80.00 <i>NECV</i>
SOUNDPROOF LH REAR DOOR STICKER	0%	\$80.00 <i>NECV</i>
Total Extras		\$613.00

Final Calculation

Total Parts		\$14,091.71
Labour		
Total Panel/Mechanical	\$4,452.80	
Total Paintwork	\$961.40	
Total Labour		\$5,414.20
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$613.00	
Total of Additional Costs		\$613.00
Total Paint/Material Costs		\$384.42
Grand Total Excludes GST		\$20,503.33
GST @ 7 %		\$1,435.23
Grand Total Includes GST		\$21,938.56

Assessment Notes



INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
 Policy No: DMPCSN3021361700
 Vehicle Reg. No.: **SDK72L**
 Driver Age/Info: 65 / MALE
 TP Injury Involved? NO
 Insured/Claimant: LEE TOON SEN
 Driver: LEE TOON SEN

Ref. No:
 Date of Loss: 28/01/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES
 Contact No: +6596816776

Make/Model: MERCEDES-BENZ C180, 1.6 (A)
 Vehicle Colour: METALLIC BLACK
 Engine No: 27191031343220
 Odometer: 0 KM

Vehicle Reg. Date: 15/04/2011
 Chassis No: WDD2040452A522836

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) 14

Description of Accident/Loss: REFER ATTACHED REPORT.
 Present Location: S & H MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	12,835.41
Miscellaneous Items	553.00
Labour	5,798.62
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,187.03
+ GST 7.00% (S\$)	1,343.09
Nett Amount (S\$)	20,530.12

This claim is handled by: LUM WEE KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

20502.03

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2018)

Parts: 143 MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SDK72L/30/01/2018 18:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*CTR REAR BUMPER MLDG	0.00	0.00	nec *95.00 F ✓
2	1	NA	*DOOR FRAME STICKER	0.00	0.00	nec *120.00 F ✓
3	1	NA	*DOOR FRAME STICKER	0.00	0.00	nec *120.00 F ✓
4	1	NA	*HANDLE INNER BRACKET	0.00	0.00	BF *95.00 F ✓
5	1	NA	*L/F DOOR FRAME SEAL	0.00	0.00	nec *115.00 F ✓
6	1	NA	*L/F DOOR LOCK	0.00	0.00	BF *190.00 F ✓
7	1	NA	*L/F DOOR MODULE	0.00	0.00	CRA *420.00 F ✓
8	1	NA	*L/F DOOR MOULDING	0.00	0.00	*70.00 F Xnn
9	1	NA	*L/F DOOR OUT HANDLE	0.00	0.00	DIS *295.00 F ✓
10	1	NA	*L/F DOOR SEAL	0.00	0.00	DIS *170.00 F ✓
11	1	NA	*L/F DOOR STRIKER	0.00	0.00	BF *95.00 F ✓
12	1	NA	*L/F DOOR TRIM REAR	0.00	0.00	nec *95.00 F ✓
13	1	NA	*L/F DOOR WINDOW	0.00	0.00	BF *230.00 F ✓
14	1	NA	*L/F LOWER DOOR HINGE	0.00	0.00	BF *110.00 F ✓
15	1	NA	*L/F MOUNTING KIT	0.00	0.00	nec *30.00 F ✓
16	1	NA	*L/F OUT HANDLE PLATE	0.00	0.00	DIS *125.00 F ✓
17	1	NA	*L/F OUT WINDOW SEAL	0.00	0.00	nec *95.00 F ✓
18	1	NA	*L/F UPPER DOOR HINGE	0.00	0.00	BA *110.00 F ✓
19	1	NA	*L/F UPPER DOOR TRIM	0.00	0.00	*265.00 F Xnn
20	1	NA	*L/F WINDOW CHANNEL	0.00	0.00	nec *195.00 F ✓
21	1	NA	*L/MIRROR BASE	0.00	0.00	CUT *1,050.00 F ✓
22	1	NA	*L/OUTER B-PILLAR	0.00	0.00	BA *780.00 F ✓
23	1	NA	*L/R BUMPER MOULDING	0.00	0.00	nec *80.00 F ✓
24	1	NA	*L/R DOOR	0.00	0.00	CT *1,180.00 F ✓
25	1	NA	*L/R DOOR FRAME SEAL	0.00	0.00	nec *115.00 F ✓
26	1	NA	*L/R DOOR LOCK	0.00	0.00	BF *190.00 F ✓
27	1	NA	*L/R DOOR MODULE	0.00	0.00	CRA *420.00 F ✓
28	1	NA	*L/R DOOR MOULDING	0.00	0.00	nec *70.00 F ✓
29	1	NA	*L/R DOOR OUT HANDLE	0.00	0.00	DIS *280.00 F ✓
30	1	NA	*L/R DOOR SEAL	0.00	0.00	nec *170.00 F ✓
31	1	NA	*L/R DOOR WINDOW	0.00	0.00	CUT *230.00 F ✓
32	1	NA	*L/R DOOR WINDOW SEAL	0.00	0.00	nec *95.00 F ✓
33	1	NA	*L/R LAMP ASSY	0.00	0.00	CUT *350.00 F ✓
34	1	NA	*L/R LWR DOOR HINGE	0.00	0.00	BF *110.00 F ✓
35	1	NA	*L/R MOUNTING KIT	0.00	0.00	nec *30.00 F ✓
36	1	NA	*L/R QUARTER GLASS	0.00	0.00	*37.45 F Xnn
37	1	NA	*L/R UPPER DOOR HINGE	0.00	0.00	BF *110.00 F ✓
38	1	NA	*L/R WDW FRAME TRIM	0.00	0.00	nec *265.00 F ✓
39	1	NA	*L/R WHL-HOUSE COVER	0.00	0.00	DIS *110.00 F ✓
40	1	NA	*L/R WINDOW CHANNEL	0.00	0.00	nec *195.00 F ✓
41	1	NA	*L/R WING	0.00	0.00	DP *1,150.00 F ✓
42	1	NA	*LEFT FRONT DOOR	0.00	0.00	BF *1,050.00 F ✓
43	1	NA	*R/R BUMPER MOULDING	0.00	0.00	nec *80.00 F ✓
44	1	NA	*REAR BUMPER COVER	0.00	0.00	DIS *950.00 F ✓
45	1	NA	*RR BUMPER CLAMP KIT	0.00	0.00	nec 30 *35.00 F ✓

S & H Motor Pte Ltd/SDK72L/30/01/2018 18:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1	NA	*RR D/WDW BONDING KIT	0.00	0.00	<i>rec</i> *51.75 F ✓
			Sub Total (\$\$)			12,224.20
			+ Margin on L,N Items 5.00% (\$\$)			611.21
			Total Parts (\$\$)			12,835.41

F=Franchise part.

S & H Motor Pte Ltd/SDK72L/30/01/2018 18:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Audatex fees	42.00 ✓
2	1	ECU diagnostic	180.00 ✓
3	1	LH rear door quater glass inner rubber seal	18.00 ✓
4	1	LH rear door quater glass sealant	30.00 X
5	1	Rear windscreen inner rubber seal	38.00 ✓
6	1	Rear windscreen sealant	80.00 ✓
7	1	Sundry parts	100.00 ✓
8	1	Wheel alignment	65.00 ✓
Sub Total (S\$)			553.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	961.40 ✓
2	Total Paint Materials	New	384.42 ✓
3	Total Panel/Mechanical Labour	New	4,452.80
Gross Labour Cost (S\$)			5,798.62

S & H Motor Pte Ltd/SDK72L/30/01/2018 18:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3021361700	Date of Loss:	28/01/2018
Vehicle Reg. No.:	SDK72L	Driveable?	
Driver Age/Info:	65 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE TOON SEN	Contact No:	+6596816776
Driver:	LEE TOON SEN		
Make/Model:	MERCEDES-BENZ C180, 1.6 (A)	Vehicle Reg. Date:	15/04/2011
Vehicle Colour:	BROWN		
Engine No:	27191031343220	Chassis No:	WDD2040452A522836
Odometer:	190574 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & H MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	1,155.00
Miscellaneous Items	160.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,315.00
+ GST 7.00% (S\$)	92.05
Nett Amount (S\$)	1,407.05
+ Previous Estimates (S\$)	20,530.12
Claim Total (S\$)	21,937.17

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 May 2018)**Parts:** 143 MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** S & H Motor Pte Ltd/SDK72L/25/05/2018 17:05**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Left centre door pillar shocket	0.00	0.00	no *165.00 F ✓
2	1		*Rear left door pillar top & bottom hinge @\$125.00	0.00	0.00	Est *250.00 F ✓
3	1		*Left rear door iron channel	0.00	0.00	DD *115.00 F ✓
4	1		*Left front & rear door glass motor @\$285	78% 0.00	0.00	fm *570.00 F ipc

F=Franchise part.

Sub Total (S\$) 1,100.00

+ Margin on L,N Items 5.00% (S\$) 55.00

Total Parts (S\$) 1,155.00

S & H Motor Pte Ltd/SDK72L/25/05/2018 17:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Left front & rear door sound pua sticker @\$80	160.00
Sub Total (S\$)			160.00

Estimates on Labour

There are no labour items selected.

S & H Motor Pte Ltd/SDK72L/25/05/2018 17:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Workshop: 160 Sin Ming Drive #07-02, Sin Ming AutoCity, Sin Ming 575722 . Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg
Co. Reg. No.: 198701322K GST Reg. No.: M2-0076269-0

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: SH000200
Version: LKKAUTOC/7
Date Calculated: 22/10/2018 10:50

Full Report - V1
Registration: SDK72L
Printed: 22/10/2018 17:51

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	28/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3021361700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	C Class
Sub Model:	C 180 KOMPR BE
Model Sheet Number:	304 27
Registration:	SDK72L
Registration Month:	
Registration Year:	
VIN Number:	WDD2040452A522836
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FR A395./F500./R131.	MODEL 2011
RAIN SENSOR	DIPPING MIRROR
FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD
LEATHER UPHOLSTERY	ALU DESIGN PARTS
EQUIPMENT AVANTGARDE	STRG WHEEL LEATHER
LEATHER STRG WHEEL	H/DUTY ALTERNATOR
ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL
TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU
SPARE WHEEL	RIGHT HAND DRIVE
TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	30/01/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:



Addresses

Cost Summary

Total Labour	\$4,264.20
Total Paint/Material	\$384.42
Total Parts	\$13,394.84
Total of Additional Costs	\$553.00
Excess:	TBA
Grand Total Exc GST:	\$18,596.46
7 % GST:	\$1,301.75
Grand Total Inc GST:	\$19,898.21

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
88-3224 01)	RENEW L/DOOR MIRROR (REMOVED)	3.0	13.80
72-1450 01	RENEW L/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	156.40
72-1682 01	ADDITION TO RENEW L/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-2691 01	RENEW L/F DOOR HINGE/S	8.0	36.80
72-1690 01	ADDITION TO RENEW L/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-4570 01	R + R LEFT FRONT DOOR LOCK STRIKER	3.0	13.80
72-1750 01	ADDITION TO RENEW L/DOOR (2ND DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1760 01	ADDITION TO RENEW L/DOOR (2ND DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1590 01	RENEW L/R DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS	36.0	165.60
72-2696 01	RENEW LEFT REAR UPPER DOOR HINGE	7.0	32.20
72-2698 01	RENEW LEFT REAR LOWER DOOR HINGE	7.0	32.20
63-1430 01	RENEW L/B-PILLAR	105.0	483.00
60-2175 01	R + R ATTACHED PARTS AT REAR COVER PANEL TO REPLACE L/R WING INCLUDES: REAR PANEL TRIMS, BOOT COMPART, INTERIOR IN REAR, ON ENTR- ANCE, REAR BUMPER, TAILLAMP, PARTITION PANEL UNDER WING, HEAD- LINING, SEAT BELT AND REAR PANEL-	58.0	266.80

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: SH000200

Registration: SDK72L

Version: LKKAUTOC/7

Printed: 22/10/2018 17:51

Date Calculated: 22/10/2018 10:50

63-1882 01	WINDOW REMOVE AND REFIT		
88-8806 03)	RENEW L/R WING	109.0	501.40
88-8905 01	RENEW REAR BUMPER	2.0	9.20
	ADD TO RENEW REAR BUMPER CPL	3.0	13.80
	(LUXURY VERSION VEHICLE)		
60-1609 01	REMOVE/REFIT LH FRONT SEAT AND LOOSE	8.0	36.80
	CARPETS AND PLACE IN STORAGE		
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS	7.0	32.20
	AND PLACE IN STORAGE		
1713	REMOVE AND REFIT L/F DOOR TRIM	8.0*	36.80
1775	REMOVE AND REFIT L/F DOOR LAMP	2.0*	9.20
2013	REMOVE AND REFIT L/R DOOR TRIM	8.0*	36.80
2191	REMOVE AND REFIT L/F STEP PROTECTION	2.0*	9.20
2193	REMOVE AND REFIT L/F INNER SILL MLDG	2.0*	9.20
2197	REMOVE AND REFIT L/R STEP PROTECTION	3.0*	13.80
2199	REMOVE AND REFIT L/R INNER SILL MLDG	2.0*	9.20
2417	REMOVE AND REFIT L/ROOF FRAME MLDG	5.0*	23.00
2427	REMOVE AND REFIT L/ROOF CVR MOULDING	5.0*	23.00
3151	REMOVE AND REFIT REAR SCREEN	28.0*	128.80
4495	REMOVE AND REFIT L/F SEAT ASSY	8.0*	36.80
4660	REMOVE AND REFIT REAR SEAT CUSHION	10.0*	46.00
4661	REMOVE AND REFIT L/F SEAT BELT	8.0*	36.80
4685	REMOVE AND REFIT REAR BACKREST CPL	10.0*	46.00
4841	REMOVE AND REFIT L/R SEAT BELT	8.0*	36.80
4947	REMOVE AND REFIT L/B-PILLAR TRIM	2.0*	9.20
4949	REMOVE AND REFIT L/LWR B-PILLAR TRIM	3.0*	13.80
4957	REMOVE AND REFIT HEADLINING	30.0*	138.00
4959	REMOVE AND REFIT FRONT INTERIOR LAMP	10.0*	46.00
9689	REMOVE AND REFIT L/DOOR CONTROL UNIT	3.0*	13.80
9691	REMOVE AND REFIT L/DOOR CONTROL UNIT	2.0*	9.20
1000	LH REAR DOOR QUATER GLASS	10.0*	46.00
2101	REPAIR L/SILL PANEL	10.0*	46.00
2141	REPAIR L/INNER SILL	5.0*	23.00
2143	REPAIR L/INNER SILL REINF	5.0*	23.00
2227	REPAIR L/OUTER A-PILLAR	15.0*	69.00
2237	REPAIR L/INN A-PILLAR REINF	10.0*	46.00
2247	REPAIR L/INNER A-PILLAR	5.0*	23.00
2287	REPAIR L/INNER B-PILLAR	20.0*	92.00
2351	REPAIR ROOF	20.0*	92.00
2353	REPAIR L/ROOF COVER PANEL	5.0*	23.00
2387	REPAIR CTR ROOF FRAME	5.0*	23.00
2389	REPAIR RR INNER ROOF FRAME	5.0*	23.00
2399	REPAIR L/INNER ROOF FRAME	5.0*	23.00
2403	REPAIR L/OUTER ROOF FRAME	5.0*	23.00
4101	REPAIR L/INNER C-PILLAR	15.0*	69.00
4279	REPAIR L/INN SIDE MEMBER	5.0*	23.00
9573	REPAIR L/F DOOR WIRING	8.0*	36.80
9581	REPAIR L/R DOOR WIRING	10.0*	46.00
LABOUR COST			
	Total Work Units	718.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00

Claim Reference:

Assessment Number: SH000200

Version: LKKAUTOC/7

Date Calculated: 22/10/2018 10:50

Full Report - V1

Registration: SDK72L

Printed: 22/10/2018 17:51

Sub Total	71.8HRS	\$3,302.80
Paint Labour	20.9HRS	\$961.40
Total Labour	92.7HRS	\$4,264.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number Description WU Cost Price (\$)

- TWO COAT METALLIC
- PREPARE OFF VEHICLE

1481	LEFT FRONT DOOR NEW PART PAINTING	15.0
1781	L/R DOOR NEW PART PAINTING	13.0
2279	L/OUTER B-PILLAR NEW PART PAINTING	14.0
3481	L/R WING NEW PART PAINTING	26.0
1563	L/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0
1739	L/DOOR MIRROR HSG NEW PART PAINT K1R	3.0
1863	L/R DOOR OUT HANDLE NEW PART PAINT K1R	3.0
2583	REAR BUMPER COVER NEW PART PAINT K1R	12.0
2101	L/SILL PANEL REPAIR PAINTING <50%	9.0
2227	L/OUTER A-PILLAR REPAIR PAINTING <50%	12.0
2351	ROOF REPAIR PAINTING <50%	23.0
2353	L/ROOF COVER PANEL REPAIR PAINTING <50%	8.0
741	L/F WING SURFACE PAINT	5.0
2207	L/SILL PANELLING SURFACE PAINT PLAST.	6.0
2711	LWR REAR CENTRE PARTSURFACE PAINT	6.0
2931	BOOTLID/TAILGATE SURFACE PAINT	9.0
3482	R/R WING SURFACE PAINT	7.0
4101	L/INNER C-PILLAR SURFACE PAINT	5.0

LABOUR COST - PAINT

TIME(PAINT)

Preparation Main Work Plastic	179.0
Preparation Main Work Metal	5.0
Preparation Work Multi Layer Paint	25.0
Total Work Units (10WU/HR)	0.0
Total Paintwork Labour	209.0
	20.9HRS

MATERIAL COST - PAINT

New Part Painting	\$961.40
New Part Painting - Plastic K1R	\$119.99
Material-Constant Main Work Metal	\$64.94
Surface-/Blend Paint	\$28.60
Surface Paint Plastic	\$68.23
Repair Painting	\$16.47
Material-Const Main Work Plastic	\$77.19
Total Excluding Pearlescent Uplift	\$9.00
Pearlescent Uplift @ 0.0%	\$384.42
Total Paint Material Cost	\$0.00
	\$384.42

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
1479	1	L/F DOOR MODULE	212 720 1579		0%		420.00*
1481	1	LEFT FRONT DOOR	204 720 0105		0%		1,050.00*
1487	1	L/F UPPER DOOR HINGE	204 720 1537		0%		110.00*
1495	1	L/F LOWER DOOR HINGE	204 720 1737		0%		110.00*

Claim Reference:

Full Report - V1

Assessment Number: SH000200

Registration: SDK72L

Version: LKKAUTOC/7

Printed: 22/10/2018 17:51

Date Calculated: 22/10/2018 10:50

1509	1	L/F DOOR SEAL	204 727 1187	0%	170.00*
1519	1	L/F DOOR WINDOW	204 725 0700	0%	230.00*
1563	1	L/F DOOR OUT HANDLE	204 760 0170 9999	0%	295.00*
1567	1	L/F OUT HANDLE PLATE	204 760 2534	0%	125.00*
1577	1	L/F DOOR LOCK	204 720 1735	0%	190.00*
1581	1	L/F DOOR STRIKER	099 723 0300	0%	95.00*
1597	1	L/F WINDOW CHANNEL	204 725 1525	0%	195.00*
1655	1	L/F DOOR TRIM REAR	204 690 2587	0%	95.00*
1661	1	L/F OUT WINDOW SEAL	204 725 1565	0%	95.00*
1725	1	SCREW	001 984 7129	0%	0.00F
1727	2	SCREW	N000000 001476	0%	0.00F
1729	1	L/F MOUNTING KIT	USE SINGLE PARTS	0%	30.00F
1745	1	L/MIRROR BASE	204 810 3976	0%	1,050.00P
1765	9	L/DOOR TRIM CLIP	000 991 0198	0%	0.00G
1777	1	L/F DOOR FRAME SEAL	204 697 0951	0%	115.00*
			9B00		
1781	1	L/R DOOR	204 730 2100	0%	1,180.00*
1791	1	L/R UPPER DOOR HINGE	204 730 1037	0%	110.00*
1793	1	L/R DOOR MODULE	212 730 1779	0%	420.00*
1795	1	L/R LWR DOOR HINGE	204 730 1237	0%	110.00*
1809	1	L/R DOOR SEAL	204 727 1187	0%	170.00*
1819	1	L/R DOOR WINDOW	204 735 0300	0%	230.00*
1847	1	L/R QUARTER GLASS	204 730 3500	0%	0.00F
1849	1	RR D/WDW BONDING KIT	000 670 0100	0%	51.75F
1863	1	L/R DOOR OUT HANDLE	204 760 0170 9999	0%	280.00*
1877	1	L/R DOOR LOCK	204 730 3935	0%	190.00*
1897	1	L/R WINDOW CHANNEL	204 735 2125	0%	195.00*
1961	1	L/R DOOR WINDOW SEAL	204 735 1565	0%	95.00*
1971	1	L/R WDW FRAME TRIM	204 735 0171 9051	0%	265.00*
1981	1	L/R DOOR MOULDING	204 730 0180	0%	70.00*
2029	1	L/R MOUNTING KIT	USE SINGLE PARTS	0%	30.00F
2031	2	L/SCREW	N000000 001476	0%	0.00F
2033	1	L/FAIRING CLIP	124 988 0978	0%	0.00F
2035	2	L/NUT	001 990 0356	0%	0.00F
2037	8	L/FASTENING CLIP	000 991 0198	0%	0.00F
2063	1	L/R DOOR FRAME SEAL	204 697 0151	0%	115.00*
			9B00		
2279	1	L/OUTER B-PILLAR	204 637 1924	0%	780.00*
2583	1	REAR BUMPER COVER	204 885 1025 9999	0%	950.00*
2615	1	CTR REAR BUMPER MLDG	204 885 0421	0%	95.00*
2617	1	L/R BUMPER MOULDING	204 885 0921	0%	80.00*
2618	1	R/R BUMPER MOULDING	204 885 1021	0%	80.00*
2647	2	SCREW	N000000 000815	0%	0.00F
2648	2	NUT	003 994 9145	0%	0.00F
2649	2	NUT	004 994 1445	0%	0.00G
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	0%	30.00P
2651	2	SCREW	001 990 8000	0%	0.00F
2652	2	SCREW	N000000 000543	0%	0.00F
2659	2	SCREW	N000000 000461	0%	0.00F
3281	1	L/R LAMP ASSY	204 906 8502	0%	350.00*
3481	1	L/R WING	204 630 0921	0%	1,150.00*
3677	1	L/R WHL-HOUSE COVER	204 690 2330	0%	110.00*

Claim Reference:

Full Report - V1

Assessment Number: SH000200

Registration: SDK72L

Version: LKKAUTOC/7

Printed: 22/10/2018 17:51

Date Calculated: 22/10/2018 10:50

1000	1	DOOR FRAME STICKER	LH front door	0%	120.00*
1000	1	DOOR FRAME STICKER	LH front door	0%	120.00*
1000	1	HANDLE INNER BRACKET	LH front door	0%	95.00*
1000	1	LH PILLAR SOCKET	Renew	0%	165.00*
1000	1	DOOR PILLA HINGE TOP	Renew	0%	125.00*
1000	1	DOOR PILLA HINGE LWR	Renew	0%	125.00*
1000	1	WINDOW METAL CHANNEL	Renew	0%	115.00*
1851	1	L/R WINDOW MOTOR	Renew	0%	285.00*
f: OEM Parts			Saving		\$76.16
g: Original			Sub Total		\$12,661.75
h: Secondhand			Mark Up From Cost	(5 %)	\$633.09
p: Parallel			Sundry Parts	(Fixed)	\$100.00
x: Exchange			Total Parts		\$13,394.84

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEES SPECIALIST	0%	\$42.00
INNER RUBBER SEAL REAR WINDSCREEN		\$38.00
SEALANT REAR WINDSCREEN	0%	\$50.00
ECU DIAGNOSTIC SPECIALIST		\$180.00
WHEEL ALIGNMENT SPECIALIST	0%	\$65.00
QUA GLASS INNER LH REAR DOOR SEAL		\$18.00
LH FRONT DOOR SOUNDPROOF STIC	0%	\$80.00
LH REAR DOOR SOUNDPROOF STIC		\$80.00
Total Extras		\$553.00

Final Calculation

Total Parts	\$13,394.84
Labour	
Total Panel/Mechanical	\$3,302.80
Total Paintwork	\$961.40
Total Labour	\$4,264.20
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$553.00
Total of Additional Costs	\$553.00
Total Paint/Material Costs	\$384.42
Grand Total Excludes GST	\$18,596.46
GST @ 7 %	\$1,301.75
Grand Total Includes GST	\$19,898.21

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2018 Sendback Est	30 Jan 2018 18:02 S\$19,187.03	31 Jan 2018 09:29 Edit Adj Rpt	S\$14,700.00 Edit Estimates	S\$14,700.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	25 May 2018 17:00	25 May 2018 17:05 S\$1,315.00	25 May 2018 17:05			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEE TOON SEN , ID: S0021618F, Tel: +6596816776, Email: NOEMAIL		
Vehicle Reg. No.:	SDK72L	Date of Loss:	28/01/2018 13:00 - :59 [81 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D00495C01	Policy/Cover Note No.:	DMPCSN3021361700 (Comprehensive)
		Excess:	S\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 09/02/2018]		
Driver/Custodian:	LEE TOON SEN (65 / Male), NRIC: S0021618F, Tel: +6596816776		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (01/02/2018): **Alert - Adj Mandate Approved (S\$17825.54) - SDK72L - Claim Handler: Adeline Chng...**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SDK72L (SNM18D00495C01)

OD

Jan 28 2018 1:00PM

[LEE TOON SEN]

S & H Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/01/18 11:30	Accident Statement	 Load HTM	☐
2	30/01/18 18:02	Repairer Estimates	 Load HTM	☐
3	25/05/18 17:05	Repairer Estimates Suppl. #1	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 13:42	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
8	29/01/18 10:53	Accident Photo [Linked Accident Report Documents]		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/10/18 15:39	General View		Load JPG	
2	22/10/18 15:39	General View		Load JPG	
3	22/10/18 15:39	General View		Load JPG	
4	22/10/18 15:39	Odometer Reading		Load JPG	
5	22/10/18 15:39	General View		Load JPG	
6	22/10/18 15:39	Chassis Number		Load JPG	
7	22/10/18 15:39	General View		Load JPG	
8	22/10/18 15:39	General View		Load JPG	
9	22/10/18 15:39	General View		Load JPG	
10	22/10/18 15:39	General View		Load JPG	
11	22/10/18 15:39	General View		Load JPG	
12	22/10/18 15:39	General View		Load JPG	
13	22/10/18 15:39	General View		Load JPG	
14	22/10/18 15:39	General View		Load JPG	
15	22/10/18 15:39	General View		Load JPG	
16	22/10/18 15:39	General View		Load JPG	
17	22/10/18 15:39	General View		Load JPG	
18	22/10/18 15:39	General View		Load JPG	
19	22/10/18 15:39	General View		Load JPG	

Assessment Reports			1 per page ▾	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
20	22/10/18 15:39	General View	 Load JPG	☒
21	22/10/18 15:39	General View	 Load JPG	☒
22	22/10/18 15:39	General View	 Load JPG	☒
23	22/10/18 15:39	General View	 Load JPG	☒
24	22/10/18 15:39	General View	 Load JPG	☒
25	22/10/18 15:39	General View	 Load JPG	☒
26	22/10/18 15:39	General View	 Load JPG	☒
27	22/10/18 15:39	General View	 Load JPG	☒
28	22/10/18 15:39	General View	 Load JPG	☒
29	22/10/18 15:39	General View	 Load JPG	☒
30	22/10/18 15:39	General View	 Load JPG	☒
31	22/10/18 15:39	General View	 Load JPG	☒
32	22/10/18 15:39	General View	 Load JPG	☒
33	22/10/18 15:39	General View	 Load JPG	☒
34	22/10/18 15:39	General View	 Load JPG	☒
35	22/10/18 15:39	General View	 Load JPG	☒
36	22/10/18 15:39	General View	 Load JPG	☒
37	22/10/18 15:39	General View	 Load JPG	☒
38	22/10/18 15:39	General View	 Load JPG	☒
39	22/10/18 15:39	General View	 Load JPG	☒
40	22/10/18 15:39	General View	 Load JPG	☒
41	22/10/18 15:39	General View	 Load JPG	☒
42	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
43	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
44	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
45	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
46	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
47	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
48	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
49	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
50	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
51	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
52	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
53	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
54	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
55	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
56	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
57	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
58	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
59	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
60	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
61	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
62	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
63	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
64	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
65	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
66	22/10/18 15:39	Reinspection Photo	 Load JPG	☒
67	22/10/18 15:39	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	✓
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
68	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
69	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
70	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
71	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
72	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
73	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
74	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
75	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
76	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
77	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
78	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
79	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
80	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
81	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
82	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
83	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
84	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
85	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
86	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
87	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
88	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
89	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
90	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
91	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
92	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
93	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
94	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
95	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
96	22/10/18 15:39	Reinspection Photo	 Load JPG	✓
97	22/10/18 15:40	Reinspection Photo	 Load JPG	✓
98	22/10/18 15:40	Reinspection Photo	 Load JPG	✓
99	22/10/18 15:40	Reinspection Photo	 Load JPG	✓
100	22/10/18 15:40	Reinspection Photo	 Load JPG	✓
101	22/10/18 15:40	Reinspection Photo	 Load JPG	✓

Documentation			1 per page	✓
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/01/18 11:01	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	29/01/18 11:01	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	29/01/18 11:01	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	29/01/18 11:01	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	
5	29/01/18 11:01	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/02/18 15:58	Revised Estimate	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 13:47	ESTIMATE	 Load PDF	
2	01/02/18 13:47	REVISED AUDATEX	 Load PDF	
3	01/11/18 14:29	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

			View	View in Browser ▼
Assessment Reports			1 per page ▼	☑
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	29/01/18 11:30	Accident Statement	1	Load HTM
Photos/Images			3 per page ▼	☑
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	29/01/18 10:53	Accident Photo	1	Load JPG ☑
2	29/01/18 10:53	Accident Photo	1	Load JPG ☑
3	29/01/18 10:53	Accident Photo	1	Load JPG ☑
4	29/01/18 10:53	Accident Photo	1	Load JPG ☑
5	29/01/18 10:53	Accident Photo	1	Load JPG ☑
6	29/01/18 10:53	Accident Photo	1	Load JPG ☑
7	29/01/18 10:53	Accident Photo	1	Load JPG ☑
8	29/01/18 10:53	Accident Photo	1	Load JPG ☑
Documentation			1 per page ▼	☑
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	29/01/18 11:01	Sketch Plan	1	Load TIF
2	29/01/18 11:01	Sketch Plan #2	1	Load TIF
3	29/01/18 11:01	Sketch Plan #3	1	Load TIF
4	29/01/18 11:01	Sketch Plan #4	1	Load TIF
5	29/01/18 11:01	Sketch Plan #5	1	Load JPG ☑

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118001872/DQD3S2

Date: 01/11/2018

REFERENCE

Insured/Claimant: LEE TOON SEN Policy No: DMPCSN3021361700
Date of Loss: 28/01/2018 Nature of Claim: OD Claim No: SNM18D00495C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK72L**
Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27191031343220
Reg. Date: 15/04/2011 (Man. Year: 2011) Chassis No: WDD2040452A522836
Colour: Brown Odometer: 190574 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$60,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm
Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,990.41	13,294.84	695.57	4.97
Miscellaneous Items	713.00	653.00	60.00	8.42
Labour	5,798.62	4,648.62	1,150.00	19.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,502.03	18,596.46	1,905.57	9.29
Approved Total (Overridden) (S\$)		14,700.00		
(S\$)	20,502.03	14,700.00	5,802.03	28.30
+ GST 7.00/7.00% (S\$)	1,435.14	1,029.00	406.14	28.30
Nett Amount (S\$)	21,937.17	15,729.00	6,208.17	28.30

INSPECTION

Date of Assignment: 31/01/2018 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 31/01/2018 Inspected At: S & H Motor Pte Ltd (Sin Ming)
Estimated Period of Repair: 14.0 days 160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Adjuster: MA CHIN FOOK

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK72L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*CTR REAR BUMPER MLDG (WCP)	Necessary	95.00 F	*95.00 F
2	1	NA	*DOOR FRAME STICKER (WCP)	Necessary	120.00 F	*120.00 F
3	1	NA	*DOOR FRAME STICKER (WCP)	Necessary	120.00 F	*120.00 F
4	1	NA	*HANDLE INNER BRACKET (WCP)	Broken	95.00 F	*95.00 F
5	1	NA	*L/F DOOR FRAME SEAL (WCP)	Necessary	115.00 F	*115.00 F
6	1	NA	*L/F DOOR LOCK (WCP)	Bent	190.00 F	*190.00 F
7	1	NA	*L/F DOOR MODULE (WCP)	Cracked	420.00 F	*420.00 F
8	1	NA	*L/F DOOR MOULDING (WCP)	Not Necessary	70.00 F	*- F
9	1	NA	*L/F DOOR OUT HANDLE (WCP)	Distorted	295.00 F	*295.00 F
10	1	NA	*L/F DOOR SEAL (WCP)	Distorted	170.00 F	*170.00 F
11	1	NA	*L/F DOOR STRIKER (WCP)	Bent	95.00 F	*95.00 F
12	1	NA	*L/F DOOR TRIM REAR (WCP)	Necessary	95.00 F	*95.00 F
13	1	NA	*L/F DOOR WINDOW (WCP)	Bent	230.00 F	*230.00 F
14	1	NA	*L/F LOWER DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
15	1	NA	*L/F MOUNTING KIT (WCP)	Necessary	30.00 F	*30.00 F
16	1	NA	*L/F OUT HANDLE PLATE (WCP)	Distorted	125.00 F	*125.00 F
17	1	NA	*L/F OUT WINDOW SEAL (WCP)	Necessary	95.00 F	*95.00 F
18	1	NA	*L/F UPPER DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
19	1	NA	*L/F UPPER DOOR TRIM (WCP)	Not Necessary	265.00 F	*- F
20	1	NA	*L/F WINDOW CHANNEL (WCP)	Necessary	195.00 F	*195.00 F
21	1	NA	*L/MIRROR BASE (WCP)	Cut	1,050.00 F	*1,050.00 F
22	1	NA	*L/OUTER B-PILLAR (WCP)	Bent	780.00 F	*780.00 F
23	1	NA	*L/R BUMPER MOULDING (WCP)	Necessary	80.00 F	*80.00 F
24	1	NA	*L/R DOOR (WCP)	Dented	1,180.00 F	*1,180.00 F
25	1	NA	*L/R DOOR FRAME SEAL (WCP)	Necessary	115.00 F	*115.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	NA	*L/R DOOR LOCK (WCP)	Bent	190.00 F	*190.00 F
27	1	NA	*L/R DOOR MODULE (WCP)	Cracked	420.00 F	*420.00 F
28	1	NA	*L/R DOOR MOULDING (WCP)	Necessary	70.00 F	*70.00 F
29	1	NA	*L/R DOOR OUT HANDLE (WCP)	Distorted	280.00 F	*280.00 F
30	1	NA	*L/R DOOR SEAL (WCP)	Necessary	170.00 F	*170.00 F
31	1	NA	*L/R DOOR WINDOW (WCP)	Cut	230.00 F	*230.00 F
32	1	NA	*L/R DOOR WINDOW SEAL (WCP)	Necessary	95.00 F	*95.00 F
33	1	NA	*L/R LAMP ASSY (WCP)	Cut	350.00 F	*350.00 F
34	1	NA	*L/R LWR DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
35	1	NA	*L/R MOUNTING KIT (WCP)	Necessary	30.00 F	*30.00 F
36	1	NA	*L/R QUARTER GLASS (WCP)	Not Necessary	37.45 F	*- F
37	1	NA	*L/R UPPER DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
38	1	NA	*L/R WDW FRAME TRIM (WCP)	Necessary	265.00 F	*265.00 F
39	1	NA	*L/R WHL-HOUSE COVER (WCP)	Distorted	110.00 F	*110.00 F
40	1	NA	*L/R WINDOW CHANNEL (WCP)	Necessary	195.00 F	*195.00 F
41	1	NA	*L/R WING (WCP)	Dented	1,150.00 F	*1,150.00 F
42	1	NA	*LEFT FRONT DOOR (WCP)	Buckled	1,050.00 F	*1,050.00 F
43	1	NA	*R/R BUMPER MOULDING (WCP)	Necessary	80.00 F	*80.00 F
44	1	NA	*REAR BUMPER COVER (WCP)	Distorted	950.00 F	*950.00 F
45	1	NA	*RR BUMPER CLAMP KIT (WCP)	Necessary	35.00 F	*30.00 F
46	1	NA	*RR D/WDW BONDING KIT (WCP)	Necessary	51.75 F	*51.75 F
Supplementary #1						
47	1		*Left centre door pillar shocket (WCP)	Dented	165.00 F	*165.00 F
48	1		*Rear left door pillar top & bottom hinge @\$125.00 (WCP)	Bent	250.00 F	*250.00 F
49	1		*Left rear door iron channel (WCP)	Dented	115.00 F	*115.00 F
50	2		*Left front & rear door glass motor @\$285 (WCP)	Jammed 1pc Only	570.00 F	*285.00 F

F=Franchise part.

Sub Total (S\$)	13,324.20	12,661.75
+ Margin on L,N Items 5.00/5.00% (S\$)	666.21	633.09
Total Parts (S\$)	13,990.41	13,294.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Audatex fees	42.00	42.00
2	1	ECU diagnostic	180.00	180.00
3	1	LH rear door quater glass inner rubber seal (NECESSARY)	18.00	18.00
4	1	LH rear door quater glass sealant (NOT NECESSARY)	30.00	0.00
5	1	Rear windscreen inner rubber seal (NECESSARY)	38.00	38.00
6	1	Rear windscreen sealant (NECESSARY)	80.00	50.00
7	1	Sundry parts	100.00	100.00
8	1	Wheel alignment	65.00	65.00
Supplementary #1				
9	1	Left front & rear door sound pua sticker @\$80 (NECESSARY)	160.00	160.00
Sub Total (S\$)			713.00	653.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	961.40	961.40
2	Total Paint Materials	New	384.42	384.42
3	Total Panel/Mechanical Labour	New	4,452.80	3,302.80
Gross Labour Cost (S\$)			5,798.62	4,648.62

Report was unsubmitted during this print-out.

< END OF ESTIMATES >