

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18001872/DQD3S2**Date:** 02/11/2018REFERENCE

Insured/Claimant: LEE TOON SEN Policy No: DMPCSN3021361700
Date of Loss: 28/01/2018 Nature of Claim: OD Claim No: SNM18D00495C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK72L**
Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27191031343220
Reg. Date: 15/04/2011 (Man. Year: 2011) Chassis No: WDD2040452A522836
Colour: Brown Odometer: 190574 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$60,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm
Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,990.41	13,294.84	695.57	4.97
Miscellaneous Items	713.00	653.00	60.00	8.42
Labour	5,798.62	4,648.62	1,150.00	19.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,502.03	18,596.46	1,905.57	9.29
Approved Total (Overridden) (S\$)		14,700.00		
(S\$)	20,502.03	14,700.00	5,802.03	28.30
+ GST 7.00/7.00% (S\$)	1,435.14	1,029.00	406.14	28.30
Nett Amount (S\$)	21,937.17	15,729.00	6,208.17	28.30

INSPECTION

Date of Assignment: 31/01/2018 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 31/01/2018 Inspected At: S & H Motor Pte Ltd (Sin Ming)
Estimated Period of Repair: 12.0 days 160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK72L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*CTR REAR BUMPER MLDG (WCP)	Necessary	95.00 F	*95.00 F
2	1	NA	*DOOR FRAME STICKER (WCP)	Necessary	120.00 F	*120.00 F
3	1	NA	*DOOR FRAME STICKER (WCP)	Necessary	120.00 F	*120.00 F
4	1	NA	*HANDLE INNER BRACKET (WCP)	Broken	95.00 F	*95.00 F
5	1	NA	*L/F DOOR FRAME SEAL (WCP)	Necessary	115.00 F	*115.00 F
6	1	NA	*L/F DOOR LOCK (WCP)	Bent	190.00 F	*190.00 F
7	1	NA	*L/F DOOR MODULE (WCP)	Cracked	420.00 F	*420.00 F
8	1	NA	*L/F DOOR MOULDING (WCP)	Not Necessary	70.00 F	*- F
9	1	NA	*L/F DOOR OUT HANDLE (WCP)	Distorted	295.00 F	*295.00 F
10	1	NA	*L/F DOOR SEAL (WCP)	Distorted	170.00 F	*170.00 F
11	1	NA	*L/F DOOR STRIKER (WCP)	Bent	95.00 F	*95.00 F
12	1	NA	*L/F DOOR TRIM REAR (WCP)	Necessary	95.00 F	*95.00 F
13	1	NA	*L/F DOOR WINDOW (WCP)	Bent	230.00 F	*230.00 F
14	1	NA	*L/F LOWER DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
15	1	NA	*L/F MOUNTING KIT (WCP)	Necessary	30.00 F	*30.00 F
16	1	NA	*L/F OUT HANDLE PLATE (WCP)	Distorted	125.00 F	*125.00 F
17	1	NA	*L/F OUT WINDOW SEAL (WCP)	Necessary	95.00 F	*95.00 F
18	1	NA	*L/F UPPER DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
19	1	NA	*L/F UPPER DOOR TRIM (WCP)	Not Necessary	265.00 F	*- F
20	1	NA	*L/F WINDOW CHANNEL (WCP)	Necessary	195.00 F	*195.00 F
21	1	NA	*L/MIRROR BASE (WCP)	Cut	1,050.00 F	*1,050.00 F
22	1	NA	*L/OUTER B-PILLAR (WCP)	Bent	780.00 F	*780.00 F
23	1	NA	*L/R BUMPER MOULDING (WCP)	Necessary	80.00 F	*80.00 F
24	1	NA	*L/R DOOR (WCP)	Dented	1,180.00 F	*1,180.00 F
25	1	NA	*L/R DOOR FRAME SEAL (WCP)	Necessary	115.00 F	*115.00 F
26	1	NA	*L/R DOOR LOCK (WCP)	Bent	190.00 F	*190.00 F
27	1	NA	*L/R DOOR MODULE (WCP)	Cracked	420.00 F	*420.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1	NA	*L/R DOOR MOULDING (WCP)	Necessary	70.00 F	*70.00 F
29	1	NA	*L/R DOOR OUT HANDLE (WCP)	Distorted	280.00 F	*280.00 F
30	1	NA	*L/R DOOR SEAL (WCP)	Necessary	170.00 F	*170.00 F
31	1	NA	*L/R DOOR WINDOW (WCP)	Cut	230.00 F	*230.00 F
32	1	NA	*L/R DOOR WINDOW SEAL (WCP)	Necessary	95.00 F	*95.00 F
33	1	NA	*L/R LAMP ASSY (WCP)	Cut	350.00 F	*350.00 F
34	1	NA	*L/R LWR DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
35	1	NA	*L/R MOUNTING KIT (WCP)	Necessary	30.00 F	*30.00 F
36	1	NA	*L/R QUARTER GLASS (WCP)	Not Necessary	37.45 F	*- F
37	1	NA	*L/R UPPER DOOR HINGE (WCP)	Bent	110.00 F	*110.00 F
38	1	NA	*L/R WDW FRAME TRIM (WCP)	Necessary	265.00 F	*265.00 F
39	1	NA	*L/R WHL-HOUSE COVER (WCP)	Distorted	110.00 F	*110.00 F
40	1	NA	*L/R WINDOW CHANNEL (WCP)	Necessary	195.00 F	*195.00 F
41	1	NA	*L/R WING (WCP)	Dented	1,150.00 F	*1,150.00 F
42	1	NA	*LEFT FRONT DOOR (WCP)	Buckled	1,050.00 F	*1,050.00 F
43	1	NA	*R/R BUMPER MOULDING (WCP)	Necessary	80.00 F	*80.00 F
44	1	NA	*REAR BUMPER COVER (WCP)	Distorted	950.00 F	*950.00 F
45	1	NA	*RR BUMPER CLAMP KIT (WCP)	Necessary	35.00 F	*30.00 F
46	1	NA	*RR D/WDW BONDING KIT (WCP)	Necessary	51.75 F	*51.75 F
<u>Supplementary #1</u>						
47	1		*Left centre door pillar shocket (WCP)	Dented	165.00 F	*165.00 F
48	1		*Rear left door pillar top & bottom hinge @\$125.00 (WCP)	Bent	250.00 F	*250.00 F
49	1		*Left rear door iron channel (WCP)	Dented	115.00 F	*115.00 F
50	2		*Left front & rear door glass motor @\$285 (WCP)	Jammed 1pc Only	570.00 F	*285.00 F

F=Franchise part.

Sub Total (\$)	13,324.20	12,661.75
+ Margin on L,N Items 5.00/5.00% (\$)	666.21	633.09
Total Parts (\$)	13,990.41	13,294.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Audatex fees	42.00	42.00
2	1	ECU diagnostic	180.00	180.00
3	1	LH rear door quater glass inner rubber seal (NECESSARY)	18.00	18.00
4	1	LH rear door quater glass sealant (NOT NECESSARY)	30.00	0.00
5	1	Rear windscreen inner rubber seal (NECESSARY)	38.00	38.00
6	1	Rear windscreen sealant (NECESSARY)	80.00	50.00
7	1	Sundry parts	100.00	100.00
8	1	Wheel alignment	65.00	65.00
Supplementary #1				
9	1	Left front & rear door sound pua sticker @\$80 (NECESSARY)	160.00	160.00
Sub Total (\$\$)			713.00	653.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	961.40	961.40
2	Total Paint Materials	New	384.42	384.42
3	Total Panel/Mechanical Labour	New	4,452.80	3,302.80
Gross Labour Cost (\$\$)			5,798.62	4,648.62

Report was unsubmitted during this print-out.

< END OF ESTIMATES >