

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: DMCVSN1526821702
Vehicle Reg. No.: **GBC7055G**
Driver Age/Info: 58 / MALE
TP Injury Involved? NO
Insured/Claimant: HOE SENG (S.K) PTE LTD
Driver: WILSON S/O JOSEPH RAJOO

Ref. No:
Date of Loss: 25/01/2018
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA DYNA 150, 3.0 D (M)
Vehicle Colour: WHITE
Engine No: 1KD2309980
Odometer: 5 KM

Vehicle Reg. Date: 17/07/2013
Chassis No: JTFAT35Y10K202434

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 9

*Tanpin 77445747
Ex of 500 Perient.
1/2/18 @ 12pm. Lumpsum
6 days. Reopening after repair.*

Description of Accident/Loss: ON 25/01/2018 AT AROUND 1115HRS, I WAS TRAVELLING ALONG KAMPONG BAHRU RD AND I WAS ON THE EXTREME RIGHT 1ST LANE. WHILE DRIVING NEAR THE U TURN, SUDDENLY VEHICLE B JAMMED BRAKE AND I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO HIS VEHICLE REAR PORTION.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

sur @ lkhantokom

COST OF CLAIMS

	Amount
Parts	3,807.40
Miscellaneous Items	0.00
Labour	1,830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,637.40
+ GST 7.00% (S\$)	394.62
Nett Amount (S\$)	6,032.02

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jan 2018)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC7055G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt ✓ *20.00 FS
2	1		*FRT BUMPER	0.00	0.00	bt ✓ *140.00 F
3	1		*FRT BUMPER BRACKET	0.00	0.00	bt ✓ *50.00 F
4	2		*FRT HEADLAMP LH-X RH-ua ✓	0.00	0.00	*370.00 F
5	2		*FRT HEADLAMP LOWER SEAL LH-X, RH-de ✓	0.00	0.00	*30.00 F
6	1		*FRT GRILLE ASSY	0.00	0.00	mis ✓ *140.00 F
7	1		*FRT GRILLE EMBLEM	0.00	0.00	nel ✓ *28.00 F
8	10		*FRT GRILLE CLIP	0.00	0.00	nel ✓ *25.00 F
9	2		*FRT CORNER PANEL	0.00	0.00	*120.00 F
10	1		*FRT PANEL	0.00	0.00	Rp ✓ *300.00 F
11	1		*FRT PANEL DYNA LOGO	0.00	0.00	na ✓ *25.00 F
12	2		*FRT SUPPORT BEAM MOUNTING	0.00	0.00	? *140.00 F
13	2		*FRT SUPPORT BEAM MOUNTING BUSH	0.00	0.00	? *30.00 F
14	1		*FRT DOOR RH	0.00	0.00	Rp ✓ *550.00 F
15	1		*FRT DOOR HINGE RH	0.00	0.00	Rp ✓ *35.00 F
16	1		*FRT DOOR WEATHERSTRIPE RH	0.00	0.00	X ✓ *75.00 F
17	1		*FRT STEP GARNISH RH	0.00	0.00	out ✓ *95.00 F
18	1		*FRT SIDE MIRROR (ROUND) LH	0.00	0.00	X ✓ *35.00 F
19	1		*AIRCON BLOWER ASSY	0.00	0.00	X ✓ *450.00 F
20	1		*HEATER BLOWER ASSY	0.00	0.00	? *950.00 F
21	1		*ROC STICKER	0	0.00	ant ✓ *20.00 FS

F=Franchise part, S=SpcNett.

Sub Total (\$\$)	3,628.00
+ Margin on L,N Items 5.00% (\$\$)	179.40
Total Parts (\$\$)	3,807.40

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New	30.00
2	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	600 900.00
3	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	600 900.00
Gross Labour Cost (\$\$)			1,830.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >