

ASS. REC. BY: CS/FCI18001895/Rlr3n2 REF: CS/FCI18001895/Rlr3n2
 Surveyor: Rasul ASSIGNMENT (Office)
 From (Person): Eileen Lee of FCI Date/Time: 30/1/18 @ 3:57pm
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: GW4747Z Insured: SHD 4378T
 at Workshop: m/s Hwa peng Auto Tel: 96885655
 of Blk 70, woodlands Ind. Park. E
 Policy No: _____ Claim No: D18000766MFSH
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 23/01/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS 1wp H.O.D. Endorsement: _____
 Date/Time: 5:02pm @ 30/1/18 Person Contacted: Mr. Francis Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	GW4747Z - NA/INC10007020/r	D.O.A. = 30/03/2010
	SHD 4378T - cc3/FCI16608403/kgbd1	D.O.A. = 12/05/2016
2/2/18	Sent prelim thru email	
	confirm LIS \$1100 @ 4 days	
	Red. \$1656.40, 60%.	

Pam

FCI

9986A

LOB KPIA: 2018/June

ASSIGNMENT

31/01/18

GW 4747Z

2003 July

Estimate Code: 00
INS: TPRES CO RES EVA/INV/MT
To: Hwa Peng Auto
Blk 70, Woodlands Ind. Prk E
Vehicle: GW4747Z
Insured: Mr. Francis @ 96885655
Policy Condition: D
Remark: The Van had commenced its repair at the time of inspection.
Billion Market Value: 4K
DAG Accident Report: Consistent? Yes or No
DAG PR Report: Consistent? Yes or No
Est. Repair days: Repair Yes or No
Est. Survey: Survey Yes or No
CA / REV: 24-PRC/lwp
Date: Person Contacted: Vehicle IN/OUT

D	
NS	CS

Truck Trailer: C
Make: TOYOTA LITRALE
Color: Grey
SRP: 643135
Eng No: CR425006077
Gen Cond: Good
Steering: Jammed Leaked Burnt
Brake: Jammed Leaked Burnt
Mod: STD A/RUM
Tyre Size: 16SR13
BS/DUN/EXNOVA: GY/PS/LIZA/MIC/OHTSU/PR/SUMI
TOYO/YOKO: Falken
Front: 6
Rear: 6
DAG: 23/01/18
Surveyed at: Hwa Peng
Date of Damage: 31/01/18
The U/C / Chassis frame Body Structure affected due to collision

RECEIVED 1-1 JUN 2018

Days Of Repair: 4
Resurvey No. of Trip: -
Add Fee: 1100
Survey Fee: 110
50
27
187



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001895/R1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-01-2018	
		Code : FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM		
	Insured Veh. SHD 4378T	Veh. Inspected	GW 4747Z
	Policy No.	Coverage (\$)	0.00
	Claim No. D18000766MFSH	Excess (\$)	0.00
	Assign From CWS (EILEEN LEE)	Assign Date	31/01/2018
2.	Vehicle Particulars & Condition		
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3.	Conditions of Tyres		
	Size	Make	Balance
	R/H Front Tyre		mm
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4.	Description of Damages		
5.	General Information		
	Accident Date 23/01/2018	Inspection Date	31/01/2018
	Survey held at HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		
5a.	Remarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D18000766MFSH

Our Ref: CS/FCI18001895/R1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GW 4747Z .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31/01/2018 at the premises of M/s HWA PENG AUTO SERVICE and have the following to report:-

Workshop Estimate Amount	: S\$ 2,756.40 .
Revised Estimate Amount	: S\$ 1,400.88 .
"Check" Items Amount	: S\$ 302.48 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at n/s front portion.



Yours faithfully
RASUL
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	24-01-2018	Our Ref No. D18000766MFSH
Accident Date	23-01-2018	Claim Type. Third Party
Insured Vehicle	SHD4378T	Third Party Vehicle. GW4747Z
Survey Location	Blk 70 Woodlands Industrial Park E	
Contact Person.	MR FRANCIS	
Contact No.	96885655/ 96885655	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HWA PENG AUTO SERVICE (1996)	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, February 02, 2018 1:55 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000766MFSH/1
Attachments: GW 4747Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised for **GW 4747Z**.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, January 31, 2018 11:55 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000766MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 January, 2018 3:56 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000766MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9986A
Vehicle Details	
Vehicle No.:	GW4747Z
Vehicle to be Exported:	No
Intended De-registration Date:	01 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5DR
Primary Colour:	Silver
Manufacturing Year:	2003
Engine No.:	3C3976218
Chassis No.:	CR425006077
Maximum Power Output:	-
Open Market Value:	\$18,697.00
Original Registration Date:	17 Jul 2003
First Registration Date:	17 Jul 2003
Transfer Count:	4
Actual ARF Paid:	\$935.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	30 Jun 2018
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$28,039.00
COE Rebate Amount:	\$2,321.00
Total Rebate Amount:	\$2,321.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 01 Feb 2018

OK

4,000
2321

1679



華平汽車服務

HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

hwapengauto@singtel.com.sg

Janice

ESTIMATE REPORT

SEN Auto Trading
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : GW4747Z
Make And Model : Toyota Liteace
Date of Accident : 23 January 2018

S/No	Parts	QTY	Unit Price	List Price
1	Front bumper	1	\$ see	381.50
2	Front bumper side retainer LH & RH	2	\$ 65.00	130.00 X
3	Front bumper bracket LH & RH	2	\$ 55.70	111.40 X
4	Front bumper beam	1	\$ see	157.50 X
5	Front bumper spot light garnish	1	\$ Xmas	125.80
6	Front fender LH	1	\$ R	379.20
7	Front fender inner cowling LH	1	\$ at	138.70
8	Front headlamp LH	1	\$ X ?	277.50
9	Front headlamp garnish LH	1	\$ CR	126.80
10	Front side lamp LH	1	\$ BR	166.80
				\$ 1,995.20
				Less 25% \$ 498.80
				Total \$ 1,496.40
Special Nett Item				
11	Front bumper clips		\$ see	60.00
12	Front fender inner cowling clips		\$ see	40.00
				Total \$ 100.00
Labour & Misc Charges				
To dismantle, replace & panel beating affected parts for front portion.				\$ 300
To spray paint on affected areas for front portion.				\$ 200
To apply anti-rust on affected areas.				\$ 40
To refocus front headlamp.				\$ 30
To check electrical wiring.				\$ 30
				Total \$ 1,160.00
Grand Total :				\$ 2,756.40

Rasul

Hp 90010068

4 days

4s

31/01/18 @ 1615

Rosy after repair

934.50

25%

700.87

Less 25%

Total \$ 1,496.40

100

Total \$ 100.00

600

\$ 300
\$ 200
\$ 40
\$ 30
\$ 30

Total \$ 1,160.00

Grand Total : \$ 2,756.40

700.87

100.00

600.00


1400.87

20%

1120.69

43-1,100

4 days



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT

SEN Auto Trading
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : GW4747Z
Make And Model : Toyota Liteace
Date of Accident : 23 January 2018

S/No	Parts	QTY	Unit Price	List Price
1	Front bumper	1	\$ 500	381.50
2	Front bumper side retainer LH & RH	2	\$ 65.00	130.00 X
3	Front bumper bracket LH & RH	2	\$ 55.70	111.40 X
4	Front bumper beam	1	\$	157.50 X
5	Front bumper spot light garnish	1	\$	125.80 ?
6	Front fender LH	1	\$	379.20 R
7	Front fender inner cowling LH	1	\$	138.70 at the
8	Front headlamp LH	1	\$	277.50 ?
9	Front headlamp garnish LH	1	\$	126.80 car
10	Front side lamp LH	1	\$	166.80 800
				\$ 1,995.20
Less 25%				\$ 498.80
Total				\$ 1,496.40
Special Nett Item				
11	Front bumper clips		\$	60.00 net
12	Front fender inner cowling clips		\$	40.00 net
Total				\$ 100.00

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for front portion.
To spray paint on affected areas for front portion.
To apply anti-rust on affected areas.
To refocus front headlamp.
To check electrical wiring.

\$ 300 ~~600.00~~
\$ 200 ~~400.00~~
\$ 40 ~~60.00~~
\$ 30 ~~50.00~~
\$ 30 ~~50.00~~

Total \$ 1,160.00

Grand Total : \$ 2,756.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasue
Hp 90010068

4 days

4s

31/01/18 @ 1615

Rosy after repair

2/2/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001895/R1rd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 4378T	Veh. Inspected	GW 4747Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18000766MFSH	Excess (\$)	0.00
	Assign From	EILEEN	Assign Date	30/01/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA LITEACE	c.c	2184
	Engine No.	HIDDEN	Year of Reg.	2003
	Chassis No.	CR425006077	Colour	GREY
	Odometer	643135	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	165 R13	FALKEN	6 mm
	L/H Front Tyre	165 R13	FALKEN	6 mm
	R/H Rear Tyre	165 R13	FALKEN	6 mm
	L/H Rear Tyre	165 R13	FALKEN	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	23/01/2018	Inspection Date	31/01/2018
	Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 4747Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SCRATCHED	381.50	381.50
2	FRONT BUMPER SIDE RETAINER LH & RH @\$65.00	N/S NECESSARY / O/S NOT NECESSARY	130.00	65.00
2	FRONT BUMPER BRACKET LH & RH @\$55.70	N/S NECESSARY / O/S NOT NECESSARY	111.40	55.70
1	FRONT BUMPER BEAM	SERVICEABLE	157.50	-
1	FRONT BUMPER SPOT LIGHT GARNISH	SERVICEABLE	125.80	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	379.20	-
1	FRONT FENDER INNER COWLING LH	CUT	138.70	138.70
1	FRONT HEADLAMP LH	SERVICEABLE	277.50	-
1	FRONT HEADLAMP GARNISH LH	CRACKED	126.80	126.80
1	FRONT SIDE LAMP LH	BROKEN	166.80	166.80
	LESS 25% DISCOUNT		-498.80	-233.63
			1,496.40	700.87
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	FRONT FENDER INNER COWLING CLIPS (SN)	NECESSARY	40.00	40.00
			100.00	100.00
LABOUR				
	TO DISMANTLE, REPLACE & PANEL BEATING AFFECTED PARTS FOR FRONT PORTION. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		600.00	300.00
	TO SPRAY PAINT ON AFFECTED AREAS FOR FRONT PORTION.		400.00	200.00
	TO APPLY ANTI-RUST ON AFFECTED AREAS.		60.00	40.00
	TO REFOCUS FRONT HEADLAMP.		50.00	30.00
	TO CHECK ELECTRICAL WIRING.		50.00	30.00
			1,160.00	600.00
GRAND TOTAL			2,756.40	1,400.87

Report Ref No. CS/FCI18001895/R1rd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00
---	--	--	----------

Report Ref No. CS/FCI18001895/R1rd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.