

120000

ASS. REC BY

REF: CS/EG18001898/Drd3n2

120000

ASSIGNMENT

Bryan

ASSIGNMENT (Office)

From (Person)

Lee Pei Li

of

EGI

Date/Time

31/11/18 @ 9:37am

Estimated Cost

Bill to

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLH 544M

Insured

G2 338 G

at Workshop no

Tecmwork Garage

Tel

6844 2475

of

81K53, Ubi Ave 1 #01-24

Policy No

Claim No

G2338G/SE/PI

Sum Insured

Excess

Make of Veh

(Client's Record)

DOA

26/01/2018

CA / REV / REP. / REV 24 HRS

lwp

MOB Endorsed

Date/Time

10:01am @ 31/11/18

Person Contacted

chris

Vehicle IN/OUT

Date/Time

Action/Inspection

✓

Signature

SLH 544M - NA/INC18001761/24

DOA: 26/01/2018

G2 338 G - NA/INC18001761/24

DOA: 26/01/2018

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV:

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **SLH 544 M** Yr Regn: **2016 Oct**
 Type: **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Nissan Sylphy** C.C. **1598**
 Colour: **Grey** A/C: Insured / Std / NI / NA
 Sp. Reading: **146565** T/Radio: Insured / Std / NI / NA
 Eng/No: **HR 16990937B**
 C/No: **MNTBBAB1720027514**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / STD A/Rim or
 Tyre Size: F: **195/60 R16**
 R: **—**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Yokohama**
 Front Rear
 R/Bal. **5** mm R/Bal. **5** mm
 L/Bal. **5** mm L/Bal. **5** mm
 D.O.A. **26/01/2018** D.O.I. **31/01/2018**
 Survey held at **Teamwork Page Ubi**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Front y O/S Body y O/S Rr
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Ergo G2 338 G

20/04/18 Jmpt 4/5 83001 - with 6 days 8 m

Red. 8115.68, 491.

RECEIVED 20 APR 2018

Date/Time, File Pass to?

1) **typist**

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / L.B. (\$) **8300**Days Of Repair: **6**Resurvey No. of Trip: **2**

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Other

TOTAL

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GZ 338G/SE/pl
Our Ref: CS/EGI18001898/Drd3

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SLH 544M .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31/01/2018 at the premises of M/s TEAMWORK GARAGE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 16,415.68 .
Revised Estimate Amount	: S\$ 10,375.10 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages
at the o/s front, o/s rear portion and o/s body



Comments/ Present Status:
Damages Consistent.

Yours faithfully

BRYAN ANG
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 31 January 2018 9:37 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GZ338G / TP : SLH544M/LKK / DOA : 26/01/2018
Attachments: SLH544M - SAS.pdf; SLH544M - PRS FORM.pdf; RE: PRE-REPAIR INSPECTION FOR SLH544M (18.9 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **TEAMWORK GARAGE PTE LTD.**

ADDRESS : BLK 53 UBI AVENUE 1
#01-24 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : DARREN NG @ 6844 2475

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 30.01.2018
Our Reference: GZ 338G/SE/pl
Your Reference: 1801-41

Sent via Fax

or

Email

claims@teamworkgarage.com

To: TEAMWORK GARAGE PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLH 544M
Insured's Vehicle: GZ 338G
Date Of Accident: 26.01.2018


We acknowledge receipt of your request for PRS on: 29.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☒	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
3RD PARTY CLAIM ESTIMATION

ERGO Insurance Pte Ltd
302 Orchard Road #09-01
Tong Building
Singapore 238862

Vehicle number	SLH544M
Make / Model	NISSAN/SYLPHY
Chassis number	MNTBBAB17Z0027514
Accident date	26 January 2018
Reference	1801-41

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER <i>rg</i>	641.34 x
1	FRONT RH FENDER <i>Dented</i>	623.60 ✓
1	RH DOOR PILLAR <i>rg</i>	1109.20 x
1	FRONT RH DOOR PANEL <i>Dented</i>	895.90 1379.48 ✓
1	REAR RH DOOR PANEL <i>Dented</i>	885.90 1337.90 ✓
1	REAR RH FENDER <i>Dented</i>	1148.40 ✓
1	REAR BUMPER <i>rg</i>	619.38 x
		6859.30
3553.80 2487.66 Less 30%		2057.79
		4801.51
2	FRONT BUMPER RETAINER <i>sv</i>	62.20 x
1	FRONT RH FENDER INNER SHIELD <i>sv</i>	107.10 x
1	FRONT RH HEADLAMP <i>HL</i>	577.80 x
1	FRONT RH SHOCK ABSORBER <i>distorted</i>	577.60 ✓
1	FRONT RH SHOCK ABOSRBER TOP MOULDING <i>sv</i>	68.20 x
1	FRONT RH KNUCKLE ARM <i>distorted</i>	440.30 ✓
1	FRONT RH LOWER ARM <i>distorted</i>	346.20 ✓
1	FRONT RH WHEEL BEARING <i>D.</i>	299.70 ✓
1	FRONT RH WING MIRROR ASSY <i>broken</i>	712.30 ✓
1	FRONT RH DOOR FRAME STICKER <i>hlc</i>	58.20 ✓
1	FRONT RH DOOR CHROME PROTECTOR <i>hlc</i>	108.10 ✓
1	FRONT RH DOOR RUBBER <i>hlc</i>	91.10 ✓
1	FRONT RH DOOR LOCK ASSY <i>sv</i>	402.70 x
1	FRONT RH DOOR CATCH <i>sv</i>	50.00 x
2	FRONT RH DOOR HINGE <i>sv</i>	98.00 x
1	FRONT RH DOOR GLASS REGULATOR ASSY <i>HL</i>	517.10 x
1	FRONT RH DOOR INNER TRIM <i>HL</i>	1146.90 x
1	REAR RH DOOR FRAME STICKER <i>hlc</i>	48.20 ✓
1	REAR RH DOOR CHROME PROTECTOR <i>hlc</i>	106.00 ✓
1	REAR RH DOOR RUBBER <i>hlc</i>	91.10 ✓

1	REAR RH DOOR LOCK <i>SW</i>	402.70	X
1	REAR RH DOOR CATCH <i>SW</i>	50.00	X
2	REAR RH DOOR CHECKER <i>NH</i>	83.80	X
1	REAR RH DOOR REGULATOR ASSY <i>SW</i> <i>1st</i>	324.00	527.10 X ✓
1	REAR RH DOOR INNER TRIM <i>Hot mounting cradle</i>	549.30	989.90 X ✓
1	REAR RH WINDSCREEN MOULDING <i>NH</i>	150.50	✓
1	REAR RH KNUCKLE ARM <i>NH</i>	498.20	X
1	REAR RH LOWER ARM <i>NH</i>	370.10	X
1	REAR RH KNUCKLE ARM BEARING <i>NH</i>	290.48	X
1	REAR RH SHOCK ABSORBER <i>disturbed</i>	572.33	✓
2	REAR BUMPER RETAINER <i>SW</i>	62.40	X
		4474.93	
		4027.43	
		9906.31	
	Less 10 %	990.63	
	Subtotal	8915.68	
	Balance C/F	8915.68	
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8915.68	
1 SET	FRONT BUMPER CLIP <i>NH</i> <i>NH</i>	60.00	X
1 SET	FRONT DOOR INNER TRIM CLIP <i>NH</i>	50.00	X
1 SET	REAR BUMPER CLIP <i>NH</i>	60.00	X
1 SET	REAR DOOR INNER TRIM CLIP <i>NH</i>	50.00	X
1	JOINT SEALANT <i>NH</i>	150.00	40/-
1	WINDSCREEN SEALANT <i>NH</i>	150.00	40/-
2	RIM <i>cut</i>	1600.00	1000/-
1	BRAKE FULID <i>NH</i>	50.00	X
		1080/-	
	Subtotal	2170.00	
	Balance C/F	11085.68	
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	11085.68	
1	CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM	80.00	30/-
2	REMOVE AND REFIT LINING, TRIM AND GARNISH	200.00	120/-
3	REMOVE AND REFIT FRONT WINDSCREEN	150.00	NH
4	REMOVE AND REFIT REAR WINDSCREEN	150.00	120/-
5	REMOVE AND REFIT DASHBOARD	500.00	NH
6	CHECK FRONT AND REAR WHEEL ALIGNMENT	250.00	80/-
7	REMOVE, REPLACE FRONT AND REAR UNDERCARRIAGE PARTS	300.00	250/-
8	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW	200.00	60/-
9	TRANSFER PARTS, ATTACHMENT FROM REAR OLD DOOR TO NEW	200.00	60/-
10	PANEL BEATING ON AFFECTED AREAS	1500.00	1000/-
11	SPRAY PAINTING ON AFFECTED AREAS	1600.00	1000/-
12	APPLY ANTI RUST ON AFFECTED AREAS	200.00	60/-
		21217.19	
		5330.00	
	Grand total	16415.68	10325.09
			4158300/-

I hereby acknowledge the conditions and terms of this repair order and agree to the following conditions:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

31/01/2018 e 1030ms
 NH Author
 415ms 6 dgs
 2 KLC Auto
 Check part prices.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18001898/Drd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 24-04-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 338G	Veh. Inspected	SLH 544M	
Policy No.		Coverage (\$)	0.00	
Claim No.	GZ 338G/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MNTBBAB17Z0027514	Colour	GREY	
Odometer	146565	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	YOKOHAMA	5 mm	
L/H Front Tyre	195/60 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	195/60 R16	YOKOHAMA	5 mm	
L/H Rear Tyre	195/60 R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT, O/S REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/01/2018	Inspection Date	31/01/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 544M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	641.34	-
1	FRONT RH FENDER	DENTED	623.60	623.60
1	RH DOOR PILLAR	TO REPAIR SEE LABOUR	1,109.20	-
1	FRONT RH DOOR PANEL	DENTED	1,379.48	895.90
1	REAR RH DOOR PANEL	DENTED	1,337.90	885.90
1	REAR RH FENDER	DENTED	1,148.40	1,148.40
1	REAR BUMPER	TO REPAIR SEE LABOUR	619.38	-
	LESS 30% DISCOUNT		-2,057.79	-1,066.14
			4,801.51	2,487.66
NETT ITEMS				
2	FRONT BUMPER RETAINER (N)	SERVICEABLE	62.20	-
1	FRONT RH FENDER INNER SHIELD (N)	SERVICEABLE	107.10	-
1	FRONT RH HEADLAMP (N)	NOT NECESSARY	577.80	-
1	FRONT RH SHOCK ABSORBER (N)	DISTORTED	577.60	577.60
1	FRONT RH SHOCK ABSORBER TOP MOULDING (N)	SERVICEABLE	68.20	-
1	FRONT RH KNUCKLE ARM (N)	DISTORTED	440.30	440.30
1	FRONT RH LOWER ARM (N)	DISTORTED	346.20	346.20
1	FRONT RH WHEEL BEARING (N)	DAMAGED	299.70	299.70
1	FRONT RH WING MIRROR ASSY (N)	BROKEN	712.30	712.30
1	FRONT RH DOOR FRAME STICKER (N)	NECESSARY	58.20	58.20
1	FRONT RH DOOR CHROME PROTECTOR (N)	NECESSARY	108.10	108.10
1	FRONT RH DOOR RUBBER (N)	NECESSARY	91.10	91.10
1	FRONT RH DOOR LOCK ASSY (N)	SERVICEABLE	402.70	-
1	FRONT RH DOOR CATCH (N)	SERVICEABLE	50.00	-
2	FRONT RH DOOR HINGE (N)	SERVICEABLE	98.00	-
1	FRONT RH DOOR GLASS REGULATOR ASSY (N)	NOT NECESSARY	517.10	-
1	FRONT RH DOOR INNER TRIM (N)	NOT NECESSARY	1,146.90	-
1	REAR RH DOOR FRAME STICKER (N)	NECESSARY	48.20	48.20

Report Ref No. CS/EGI18001898/Drd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH DOOR CHROME PROTECTOR (N)	NECESSARY	106.00	106.00
1	REAR RH DOOR RUBBER (N)	NECESSARY	91.10	91.10
1	REAR RH DOOR LOCK (N)	SERVICEABLE	402.70	-
1	REAR RH DOOR CATCH (N)	SERVICEABLE	50.00	-
2	REAR RH DOOR CHECKER (N)	NOT NECESSARY	83.80	-
1	REAR RH DOOR REGULATOR ASSY (N)	BENT	527.10	324.00
1	REAR RH DOOR INNER TRIM (N)	MOUNTING CRACKED	989.90	549.30
1	REAR RH WINDSCREEN MOULDING (N)	NECESSARY	150.50	150.50
1	REAR RH KNUCKLE ARM (N)	NOT NECESSARY	498.20	-
1	REAR RH LOWER ARM (N)	NOT NECESSARY	370.10	-
1	REAR RH KNUCKLE ARM BEARING (N)	NOT NECESSARY	290.48	-
1	REAR RH SHOCK ABSORBER (N)	DISTORTED	572.33	572.33
2	REAR BUMPER RETAINER (N)	SERVICEABLE	62.40	-
	LESS 10% DISCOUNT		-990.63	-447.49
			8,915.68	4,027.44
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT DOOR INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET REAR DOOR INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
2	RIM (SN)	CUT	1,600.00	1,000.00
1	BRAKE FLUID (SN)	NOT NECESSARY	50.00	-
			2,170.00	1,080.00
	LABOUR			
	CHECK FRONT,REAR WIRING AND LIGHTING SYSTEM.		80.00	30.00
	REMOVE AND REFIT LINING,TRIM AND GARNISH.		200.00	120.00
	REMOVE AND REFIT FRONT WINDSCREEN.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	REMOVE AND REFIT DASHBOARD.	NOT NECESSARY	500.00	-
	CHECK FRONT AND REAR WHEEL ALIGNMENT.		250.00	80.00

Report Ref No. CS/EGI18001898/Drd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE, REPLACE FRONT AND REAR UNDERCARRIAGE PARTS.		300.00	250.00
	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW.		200.00	60.00
	TRANSFER PARTS, ATTACHMENT FROM REAR OLD DOOR TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS, INCLUSIVE OF THE REPAIR OF FRONT BUMPER, RH DOOR PILLAR AND REAR BUMPER.		1,500.00	1,000.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	1,000.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	60.00
			5,330.00	2,780.00
GRAND TOTAL			21,217.19	10,375.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,300.00

Report Ref No. CS/EGI18001898/Drd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.