

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 7173J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	1,245.50	788.00
1	O/S HEAD LAMP	CRACKED	768.00	768.00
1	O/S HEAD LAMP OUTER GARNISH	CRACKED	176.30	176.30
1	FRONT O/S FENDER	DENTED / BUCKLED	780.00	525.12
1	FRONT O/S FENDER SIGNAL LAMP	NOT NECESSARY	487.70	-
1	FRONT O/S FENDER COWLING	TORN	316.00	245.35
1	FRONT O/S FOG LAMP OUTER GARNISH	NOT NECESSARY	112.00	-
1	FRONT STEERING RACK	BENT / TWISTED	3,540.00	2,689.12
1	FRONT O/S LOWER ARM	BENT	648.00	648.00
1	FRONT O/S SUSPENSION	BENT / TWISTED	1,044.00	549.25
1	FRONT O/S KNUCKLE ARM	BENT	684.00	684.00
1	FRONT O/S KNUCKLE ARM BEARING	NECESSARY	175.00	175.00
	LESS 10% DISCOUNT		-	-724.81
			9,976.50	6,523.33
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	65.00	65.00
1	FRONT O/S WHEEL HUB-CAB (SN)	NOT FITTED	225.00	-
1	FRONT O/S WHEEL RIM (SN)	DENTED / BENT	230.00	50.00
1	FRONT O/S TYRE (@ \$180.00 DISC 60%) (SN)	CUT	180.00	108.00
			700.00	223.00
	LABOUR			
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		1,000.00	500.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		800.00	600.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		180.00	60.00
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE PARTS & COMPONENTS.		300.00	280.00

Report Ref No. CC6/EQI18001924/Uea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY RUST-PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		60.00	30.00
			2,340.00	1,470.00
	GRAND TOTAL		13,016.50	8,216.33

RECOMMENDED COST OF LUMP SUM REPAIRS		6,550.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/EQI18001924/Uea3s2

CHUA KANG SENG

Licensed Appraiser