



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI18001924/Uea3s2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX SINGAPORE 069110

Date : 06-05-2020



Code : EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SLC 9515P       | Veh. Inspected | GBA 7173J  |
| Policy No.   | DMPPHQ17-002729 | Coverage (\$)  | 0.00       |
| Claim No.    | DM18HO00304-JG  | Excess (\$)    | 0.00       |
| Assign From  |                 | Assign Date    | 31/01/2018 |

### 2. Vehicle Particulars & Condition

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | FIAT DOBLO (M)    | c.c          | 1910     |
| Engine No.   | HIDDEN            | Year of Reg. | 2007     |
| Chassis No.  | ZFA22300005534292 | Colour       | WHITE    |
| Odometer     | 314917            | Steering     | AFFECTED |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

### 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 185/65 R15 | TRIANGLE | 6 mm    |
| L/H Front Tyre | 185/65 R15 | TRIANGLE | 6 mm    |
| R/H Rear Tyre  | 185/65 R15 | TRIANGLE | 6 mm    |
| L/H Rear Tyre  | 185/65 R15 | TRIANGLE | 6 mm    |

### 4. Description of Damages

|                                                                                                                              |
|------------------------------------------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------------------------------------------------------------|

### 5. General Information

|                |                                                                                                                     |                 |            |
|----------------|---------------------------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 26/01/2018                                                                                                          | Inspection Date | 31/01/2018 |
| Survey held at | LIU'S BROTHER AUTO ENGINEERING WORKSHOP<br>1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT<br>SINGAPORE<br>417883 |                 |            |

### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|