



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address  | Owner Name & Vehicle Info |                           |
|---|---------------------------|---------------------------|
| MR TAY KIM HAI<br><br>1 CANBERRA DRIVE<br>#05-03<br>SINGAPORE 768101<br>Singapore 760754<br>Contact No Mobile: 86688006 | Cust No/Name              | LCV04102/MR TAY KIM HAI   |
|   | Reg No/Reg Date           | SLB8337Z / 25/04/201      |
|   | Date In/Mileage           | / 0                       |
|   | Chassis No                | KNAHU815VG7147640         |
|   | Engine No                 | D4FDFH102424              |
|   | Make/Model                | KIA/CARENS 1.7 A D EX GP7 |
|   | Colour/Trim               | TIM / WK                  |

| Account No   | Terms                          | Date/Time Printed | CSE  | Operator                               | WIP No     |       |                   |
|--|--------------------------------|-------------------|------|--|------------|-------|-------------------|
| CSM00081   | Cash                           | 30/01/2018/ 18:23 |      | 265 / AndreChow                        | 22516      |       |                   |
| Description of Goods / Services  |                                |                   |      | Qty                                    | Unit Price | Disc% | Amount            |
| A 54900099   |                                |                   |      |  |            |       | 80 100.00         |
| CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM   |                                |                   |      |  |            |       | ✓ 200.00          |
| A 10028901   |                                |                   |      |  |            |       | 20 50.00          |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST   |                                |                   |      |  |            |       | 140 80.00         |
| USING HI-SCAN PRO TEST   |                                |                   |      |  |            |       | 1375 1100 3300.00 |
| M SUNDRY   |                                |                   |      |  |            |       | 840 2100.00       |
| SUNDRIES   |                                |                   |      |  |            |       | 80 150.00         |
| M SUNDRY   |                                |                   |      |  |            |       | art- 201.00       |
| SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS  |                                |                   |      |  |            |       | del 576.00        |
| E PNT88000   |                                |                   |      |  |            |       | x 367.00          |
| RENEW REAR BUMPER, REPAIR REAR END PANEL, REPAIR LH REAR FENDER  |                                |                   |      |  |            |       | ? 116.00          |
| E PNT98000   |                                |                   |      |  |            |       | mer 25.00         |
| RESPRAY REAR BUMPER, REAR END PANEL, LH REAR FENDER AND OTHER AFFECTED   |                                |                   |      |  |            |       | ? 159.00          |
| PORTIONS   |                                |                   |      |  |            |       | CM ✓ 357.00       |
| E PNT88000   |                                |                   |      |  |            |       | x 213.00          |
| REMOVE AND INSTALL REVERSE SENSORS   |                                |                   |      |  |            |       |                   |
| M  | COVER-RR BUMPER LWR            |                   | 1.00 | 201.00                                 | 00.00      |       |                   |
| M  | COVER-RR BUMPER,UPR            |                   | 1.00 | 576.00                                 | 00.00      |       |                   |
| M  | BEAM-RR BUMPER                 |                   | 1.00 | 367.00                                 | 00.00      |       |                   |
| M  | LAMP ASSY-REAR FOG,LH          |                   | 1.00 | 116.00                                 | 00.00      |       |                   |
| M  | BRACKET ASSY-RR BUMPER SIDE,LH |                   | 1.00 | 25.00                                  | 00.00      |       |                   |
| M  | STAY-RR BUMPER LH              |                   | 1.00 | 159.00                                 | 00.00      |       |                   |
| M  | LAMP ASSY-REAR COMBINATION,LH  |                   | 1.00 | 357.00                                 | 00.00      |       |                   |
| M  | LAMP ASSY-REAR COMB INSIDE,LH  |                   | 1.00 | 213.00                                 | 00.00      |       |                   |
| <div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul></div> |                                |                   |      | SURVEYOR NAME: <u>Tanpin 97495749</u>  |            |       |                   |
|  |                                |                   |      | SURVEYOR SIGNATURE: <u>[Signature]</u> |            |       |                   |
|  |                                |                   |      | DATE: <u>1/2/18 @ 4pm</u>              |            |       |                   |
|  |                                |                   |      | REMARKS: <u>Repairing before paint</u> |            |       |                   |
| Confirm & accepted by  |                                |                   |      | swc @ Intanpin                         |            |       |                   |
| Acknowledged by Repairer   |                                |                   |      | 5-6 days.                              |            |       |                   |
| Signature:   |                                |                   |      | 7% GST on                              |            |       |                   |
| Date:  |                                |                   |      | Nett 7,994.00                          |            |       |                   |
|  |                                |                   |      | Total Payable 8,553.58                 |            |       |                   |
| Authorized signatory and company stamp   |                                |                   |      |  |            |       |                   |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.