



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 SUBARU IMPREZA 2.0R HATCHBACK (SJP6018H)

Date of Loss

29 January 2018

Time of Loss

10.05

Loss Description

SJP6018H (INSD) HIT SLH7924D (TP) INTO REAR

Comment

Workshop Details

Total Rebate Amount

10295

Nett Loss Amount

\$7,705.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/05/2018



Days of work completion *

104



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SJP6018H

Registration State

SINGAPORE

Mileage

177349

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

Purchase Date

dd/mm/yyyy



Registration Date *

30/03/2009



Age of Vehicle

8

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

S/O KADER HABIB SULTAN

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... SUBARU

ASSESSMENT INFO... SUBARU

CATEGORY Model

POLICY INFORMAT... IMPREZA 2.0R HATCHBACK

ASSESSMENT INFO... IMPREZA 4DR 2.0R-S AWD 4AT ABS

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JF1GE7KS59G005680

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI... 0

ASSESSMENT INFO... JF1GE7KS59G005680

CATEGORY Engine No

POLICY INFORMAT... EJ20D727116

ASSESSMENT INFO... EJ20D727116

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1994

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 18000

POST SURVEY INF...
CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... To be confirmed, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S9400366J

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

01/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

3400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/45ZR17

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

235/45ZR17

Front left side

RADAR6mm

Front right side

RADAR6mm

Rear left side

RADAR6mm

Rear right side

RADAR6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			BONNET			Buckled	480				480	Review
		2	1			BONNET HINGE LH			Bent	35				35	Review
		3	1			BONNET HINGE RH			Bent	35				35	Review
		4	1			BONNET FRONT SEAL			Necessary	35				35	Review
		5	1			BONNET FRONT SEAL (RADIATOR)			Necessary	30				30	Review
		6	1			BONNET LOCK			Bent	45				45	Review
		7	1			FRONT GRILLE LOGO - SUBARU			Necessary	60				60	Review
		8	1			FRONT GRILLE			Cracked	420				420	Review
		9	1			HEADLAMP LH			Cracked	550				550	Review
		10	1			HEADLAMP RH			Cracked	550				550	Review
		11	1			FRONT BUMPER			Deformed	400				400	Review
		12	1			FRONT BUMPER LOWER GRILLE			Serviceable	0	0	0	0	0	Deny
		13	1			FRONT BUMPER SIDE RETAINER LH			Necessary	20				20	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		14	1			FRONT BUMPER SIDE RETAINER RH			Necessary	20				20	Review
		15	1			FRONT BUMPER SPONGE			Cracked	90				90	Review
		16	1			FRONT BUMPER REINFORCEMENT			Bent	180				180	Review
		17	1			HORN			Serviceable	0	0	0	0	0	Deny
		18	1			FRONT SUPPORT PANEL ASSY			Bent	320				320	Review
		19	1			FRONT SUPPORT BRACE PANEL			Repair	0	0	0	0	0	Deny
		20	1			AIRCON CONDENSER (NPA)			Serviceable	0	0	0	0	0	Deny
		21	1			RADIATOR			Bent	620				620	Review
		22	2			RADIATOR TOP MOUNTING (RUBBER)			Damaged	6				12	Review
		23	1			AIRDUCT OUTLET			Cracked	55				55	Review
		24	1			FRONT FENDER LH (NPA)			Repair	0	0	0	0	0	Deny
		25	1			FRONT FENDER RH (NPA)			Repair	0	0	0	0	0	Deny

Labour

Add

Approve

Deny

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMARKS
		1		TO INSPECT FRONT LIGHTING MECHANISM	30	0	0	Reviewing		1

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		2		TO REMOVE & REPLACE AIRCON CONDENSER & REFILL GAS	80	0	0	Reviewing		1
		3		TO REMOVE & REPLACE RADIATOR & FITTING	60	0	0	Reviewing		1
		4		TO CUT OFF FRONT SUPPORT PANEL. TO KNOCK & STRAIGHTEN ON FRONT FENDER LH & RH. TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION	700	0	0	Reviewing		1
		5		TO SPRAY PAINT ON REPAIRED AREAS	800	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	1	DAYS OF REPAIR : 6 DAYS	Reviewing			
 	2	FRONT NUMBER PLATE	Reviewing	35	BENT	
 	3	COOLANT	Reviewing	40	NECESSARY	
 	4	RADIATOR BOTTOM MOUNTING (RUBBER) RH	Reviewing	7	TORN (SUPPLEMENTARY)	
 	5	RADIATOR TOP HOSE	Reviewing	35	CUT(SUPPLEMENTARY)	
 	6	FAN ASSY RH	Reviewing	350	CRACKED(SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	CLIP-FRONT BUMPER - 15 PCS	Reviewing	37.5	NECESSARY(SUPPLEMENTARY)	
		8	CLIP-FRONT FENDER - 10 PCS	Reviewing	25	NECESSARY(SUPPLEMENTARY)	
		9	CLIP-FRONT GRILLE-8 PCS	Reviewing	20	NECESSARY(SUPPLEMENTARY)	
		10	CLIP-FENDER COWLING- 10 PCS	Reviewing	25	NECESSARY(SUPPLEMENTARY)	
		11	CLIP-AIR DUCT (2 PCS)	Reviewing	5	NECESSARY(SUPPLEMENTARY)	
		12	CLIP-BUMPER CORNER - 2 PCS	Reviewing	5	NECESSARY(SUPPLEMENTARY)	
		13	BONNET NOZZLE - 2 PCS	Reviewing	60	CRACKED (SUPPLEMENTARY)	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$2,871.50

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,670.00	\$1,670.00
Spare Parts	\$3,957.00	\$3,957.00
Miscellaneous	\$644.50	\$644.50
Excess	-\$3,400.00	-\$3,400.00

Submit for Review